

SJS3377A

Jiale

Survey + repair
arranged 3/8/19

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

19 AUG 2019

E S T I M A T E

Estimate No. : b1 52362
Date Estimated : 17/08/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ng Yee Yong
30 Bukit Batok Street 21
#10-04

Singapore 659636

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS3377A	D828777	14/08/2015	520ia	0

DESCRIPTION

To replace rear bumper & attachments including to knock out
dented area cause by the accident

850 1,275.00

To respray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

all 7 ✓ 80.00

Total Labour 1: 2,570.00

DESCRIPTION

RR BUMPER CARRIER
ADAPTOR
REAR BUMPER CENTRE GUIDE
REAR BUMPER PRIMED (PDC)
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (A90 SOPHISTOGRAU

QTY	PRIC	VALUE
1	772.05	X 772.05
1	108.75	an 108.75
1	67.45	? 67.45
1	1,571.95	de 1,571.95
2	5.05	an 10.10
2	368.80	an X 737.60

Total Parts : 3,267.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 3/4/19/2040 Claim No.

Date 3/4/19/2040 Excess 00

Surveyor's Name Tan Jiah Sign Jiah

Surveyor's Tel 97495449 Authorised Yes / No

Authorised Date 17/8/19 Time

RESURVEY PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Tan Jiah @ Phantasia

No. of Working Days Recommend 3 days

Labour 1 : 2,570.00

Parts : 3,267.90

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 408.65

Grand Total : 6,246.55

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52362**
Date Estimated : **17/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Ng Yee Yong
30 Bukit Batok Street 21
#10-04

Singapore 659636

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS3377A	WBA5A32050D828777	14/08/2015	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper.	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (PDC)	1,571.95	1.00		1,571.95

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,571.95
Total Labour & Parts :	3,585.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,585.95
GST @7%:	251.02
Grand Total :	3,836.97

cor \$3585.95, 3 days
7/10 e-mail to Ton.