

SJS3377A

Survey + repair arranged 3/Sept

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

19 AUG 2019

ESTIMATE

Estimate No. : b1 52362	Page No. : 1 of 4
Date Estimated : 17/08/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Ng Yee Yong 30 Bukit Batok Street 21 #10-04 Singapore 659636	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJS3377A	D828777	14/08/2015	520iA	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area cause by the accident	850 1,275.00
To respray rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	7 80.00
Total Labour 1:	2,570.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER	1	772.05	772.05
ADAPTOR	1	108.75	108.75
REAR BUMPER CENTRE GUIDE	1	67.45	67.45
REAR BUMPER PRIMED (PDC)	1	1,571.95	1,571.95
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	10.10
BUMPER PDC SENSOR (A90 SOPHISTOGRAU	2	368.80	737.60
Total Parts :			3,267.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>3/1/1801040</u>	Claim No. _____
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>9249549</u>	Authorised Yes / No _____
Authorised Date <u>17/8</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR ☒ / No PML Yes / No _____	
Surveyor's E-mail <u>tanjiah@phandian.com</u>	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	2,570.00
Parts	:	3,267.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	408.65
Grand Total	:	6,246.55

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **