

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



# 26/8/2019  
Survey & repair

GST REG. NO : M2 - 0020081 - X

19 AUG 2019

## ESTIMATE

Estimate No. : <b>b1 52365</b>	Page No. : <b>1 of 4</b>
Date Estimated : <b>19/08/2019</b>	
Prepared By : <b>Chua Kee Sin</b>	

<p><b>- ESTIMATE REPAIR FOR -</b> <b>LIM KWANG JOO</b> <b>38 TOH TUCK ROAD</b> <b>#05-04</b>  <b>Singapore 596716</b></p>	<p><b>- ACCOUNT - 40000</b> <b>Cash Sales - Service</b> <b>Singapore</b></p>
-----------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
Replace rear bumper panel	850 <del>1,275.00</del>
Spray painting rear bumper	734 <del>1,038.00</del>
To check electrical wiring systems and lightings at the rear section for proper function.	150 <del>177.00</del>
Sundries.	? 150.00
<b>Total Labour 1: 2,640.00</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

DESCRIPTION	QTY	PRIC	VALUE
HEX BOLT ?	14	1.45	20.30
RR BUMPER CARRIER ?	1	493.85	493.85
REAR TRIM UNDERRIDE PROTECTION (X L) <i>scr</i>	1	105.40	105.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) <i>scr</i>	1	265.65	265.65
REAR BUMPER TRIM BOTTOM (LINES) <i>scr</i>	1	216.00	216.00
REAR BUMPER TOWING EYE COVER X	1	36.60	36.60
ULTRASONIC SENSOR BLACK ?	4	248.70	994.80
DECOUPLING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
<b>Total Parts :</b>			<b>2,152.80</b>

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Dated/Time 26/08/19 @ 12:40 Excess \$ \$ \_\_\_\_\_

Surveyor's Name RASUL Sign \_\_\_\_\_

Surveyor's Tel 9006368 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

Labour 1	:	<b>2,640.00</b>
Parts	:	<b>2,152.80</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>335.50</b>
<b>Grand Total</b>	:	<b>5,128.30</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*