

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

26/8/2019
Survey & repair



GST REG. NO : M2 - 0020081 - X

19 AUG 2019

ESTIMATE

Estimate No. : b1 52365	Page No. : 1 of 4
Date Estimated : 19/08/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - LIM KWANG JOO 38 TOH TUCK ROAD #05-04 Singapore 596716	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
Replace rear bumper panel			850 1,275.00
Spray painting rear bumper			734 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.			150 177.00
Sundries.			40? 150.00
Total Labour 1:			2,640.00
Total Parts :			2,152.80

LKK Auto Consultant, hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Routing / modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date of Time 26/08/19 @ 12:40 Excess \$S _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90016568 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PM Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	2,640.00
Parts	:	2,152.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	335.50
Grand Total	:	5,128.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52365**
Date Estimated : **19/08/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
38 TOH TUCK ROAD
#05-04

Singapore 596716

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:		NETT
	ORIGINAL PRICE	DISC. %	
To make good the rear bumper and replace damaged parts, To remove and install body parts in order to carry out painting	850.00	0	850.00 ✓
To respray rear bumper	934.00	0	934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries.	40.00	0	40.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR TRIM UNDERRIDE PROTECTION (X L	105.40	1	0	105.40 ✓
REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1	0	265.65 ✓
REAR BUMPER TRIM BOTTOM (LINES)	216.00	1	0	216.00 ✓
# EXPANDING RIVET BLACK	1.35	10	0	13.50 ✓ (CS)
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	600.55
Total Repair Costs less Excess:	<u>2,574.55</u>
GST @7%:	180.22
Grand Total :	<u>2,754.77</u>

DATE	QTY
Rasal UKR 3/9/19	3
CONFIRMED DATE	
PLEASE SIGNATURE	

LOSS OF USE = \$60 X 3 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52365**
Date Estimated : **19/08/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
38 TOH TUCK ROAD
#05-04

Singapore 596716

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:	
	ORIGINAL PRICE	DISC. %
		NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET BLACK <i>see /</i>	1.35	10	0	13.50
#				
#				

SUPPLEMENTARY ITEMS

Total Labour ;	
Total Parts :	13.50
Total Repair Costs less Excess:	13.50