Not Albert Nah L/S \$4000 | **FASTECT AUTO PTE LTD BLK1 KAKI BUKIT AVE 6** #01-46,48,50 AUTOBAY SINGAPORE 417883 **VEHICLE NO:SFW 7767H** QTY PARTICULAR (NETT ITEM) \$895.00 1 PCS BOOTLID NU \$45.80 BOOTLID REAR LOGO 1 PCS \$60.00 BOOTLID 'PMRE DRIVE' EMBLEM 1 PCS An \$62.00 -BOOTLID 'SYLPHY' EMBLEM 1 PCS SCALCIE \$315.00 BOOTLID LOWER CHROME MOULDING 1 PCS 8u \$105.000 BOOTLID INNER LOCK 1 PCS \$605.00 -625-80 REAR BUMPER 1 PCS \$95.00 REAR BUMPER BRACKET O/S 1 PCS \$32.00 -REAR BUMPER SIDE HOLDER O/S 1 PCS 10-1 \$165.00 -REAR BUMPER SPONGE 131.70 1 PCS N \$35.00 -1 SET REAR BUMPER CLIPS \$900.00 @ _ 0/some . 365.00 2 PCS TAILLAMPS @\$450.00 \$510.00 17 _ TAILLAMP HOUSING PANELS @\$255.00 2 PCS \$495.00 REAR END PANEL 1 PCS 455-10 YNI \$366.00_ REAR END PANEL TOP GARNISH 1 PCS 188.20 an \$288.00 -REAR END PANEL LOCK SENSOR 1 PCS 155.80 \$192.00 **BOOTLID WEATHERSTRIP** 1 PCS \$981.00 🔾 1 PCS REAR FENDER O/S 1 1 \$350.00 ℃ 1 PCS REAR FENDER INNER TRIM O/S \$215.00 REAR BUMPER LOWER GARNISH 1 PCS \$250.00 2005.N REAR REVERSE SENSOR 1 SET \$50.00 1 PCS REAR END PANEL SEALANT \$7,011.80 LABOUR CHARGES: \$80.00 30 TO CHECK WIRING \$80.00 TO DISMANTLE & REPLACING REVERSE SENSOR \$120.00 TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY \$100.00 TO SPRAY RUST PROOFING \$1,080.00 802 LABOUR FOR PANEL BEATING & REPLACING PARTS \$1,500.00 \$9,971.80 TO PUTTY & SPRAY PAINTING TOTAL

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- Partsprices are subject to confirmation
- Third per visurvey is on a "Without Prejudice" basis
- No the modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

2738.63 2738.63