

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 S569536

Hp 91004390 Tel 64846016 Fax 64841482

Email: lawmotoramk@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	19.08.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
1	pc	Front bumper / 00		\$181.90
2	pcs	Front bumper left & right hand side retainer / BR	\$27.82	\$55.64
2	pcs	Front bumper left & right hand side bracket X	\$58.85	\$117.70
1	pc	Front bumper reinforcement / 00		\$117.70
1	pc	Front bumper inner sponge ?		\$48.15
1	pc	Front bumper lower grille / CUT		\$53.50
1	pc	Front bumper right side fog lamp ?		\$96.30
1	pc	Front bumper right side fog lamp cover / CUT		\$53.50
1	pc	Front bonnet cover / 00		\$288.90
2	pcs	Front bonnet hinge / BT	\$32.10	\$64.20
1	pc	Front bonnet top lock X		\$69.55
1	pc	Front bonnet top lock cable X		\$29.96
1	pc	Front bonnet stand with clip / BR		\$18.19
1	pc	Front vertical panel X R		\$58.85
1	pc	Front support panel assy / 00		\$278.20
2	pcs	Front head lamp (left & right) (RH) / BR (LH) ?	\$224.70	\$449.40
1	pc	Front grille / BR		\$149.80
1	pc	Front grille top garnish ?		\$32.10
1	pc	Radiator ?		\$390.55
1	pc	Radiator top cowlng ?		\$37.45
1	pc	Radiator fan motor X		\$149.80
1	pc	Air con condenser / 00		\$342.40
		To top up gas, labour for checking air con system, Dismantle & replace air con condenser.	120	\$220.00
		To dismantle and replace radiator.	50	\$130.00
		To top up radiator coolant.	20	\$30.00
			Total	

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-277 S569536

Hp 91004390 Tel 64846016 Fax 64841482

Email: lawmotoramk@gmail.com

M/s AXA Insurance Singapore Pte Ltd	DATE	19.08.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
		Continue from page one.		\$3,463.74
		To provide labour, workmanship to re-align, straightening front left side fender, cutting front right side fender, top panel, dismantle & replace the above mentioned parts.	700	\$1,200.00
		Labour for respray front bumper, front top panel, front right/left side fender and front bonnet cover.	900	\$1,400.00
		Rust-proofing on the front accident affected	30	\$180.00
		To check front and rear electrical wiring system.	30	\$80.00
		Computer alignment.	X	\$100.00
		<i>Steve (LKK) 00 - Autoline</i> <i>8322 8813 EXCESS - \$2250</i> <i>20/8/19, 4.00pm</i> <i>P/P</i> <i>Resny Before spray</i>		
		<i>Page 2 of 2</i>	Total	6,423.74

National Automobile Service

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: