

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 AMK #01-277 (off AMK Ave 3)
Singapore 569536 HP 91004390/HP 91254449 Fax 64841482


Email : lawmotoramk@gmail.com

Invoice No : LM11098

M/s AXA Insurance Singapore Ltd Pte	DATE	17.09.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G (OD Claim)

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
		<u>Recommended Parts</u>		
1	pc	Front bumper		\$160.00
2	pcs	Front bumper LH & RH side reinforcement		\$25.00
1	pc	Front bumper reinforcement		\$95.00
1	pc	Front bumper inner sponge		\$45.00
1	pc	Front bumper lower grille		\$42.00
1	pc	Front bumper right side fog lamp cover		\$38.00
1	pc	Front bonnet cover		\$100.00
2	pcs	Front bonnet hinge	\$23.00	\$46.00
1	pc	Front bonnet stand with clip		\$8.00
1	pc	Front support panel assy		\$180.00
2	pcs	Front head lamp (left & right)	\$200.00	\$400.00
1	pc	Front grille		\$140.00
1	pc	Radiator		\$120.00
1	pc	Air-con condenser		\$120.00
1	pc	Front right side fender		\$180.00
				\$1,699.00
			Add 10%	\$169.90
			Parts Total	\$1,868.90
		<u>Recommended labour</u>		
		To top-up gas, labour for checking air-con system, dismantle and replace air-con condenser		\$120.00
		To dismantle and replace radiator		\$50.00
		To top-up radiator coolant		\$20.00
		continue on page 2		
			Page 1 of 2	Total


National Automobile Service

National Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 AMK #01-277 (off AMK Ave 3)
Singapore 569536 HP 91004390/HP 91254449 Fax 64841482


Email : lawmotoramk@gmail.com

Invoice No : LM11098

M/s AXA Insurance Singapore Ltd Pte	DATE	17.09.2019
8 Shenton Way #27-01 AXA Tower	CAR NO	SLK 5218 G
Singapore 068811	MAKE	Toyota Altis

FINAL COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLK 5218 G (OD Claim)

Pc	Pcs	MR053REH104561347	UNIT PRICE	AMOUNT
		continue from page 1		\$2,058.90
		<u>Recommended Labour</u>		
		To provide labour, workmanship to re-align, straightening front left side fender, cutting front right side fender, top panel, dismantle & replace the above mentioned parts.		\$700.00
		Labour for respray front bumper, front top panel, front left & right side fender, front bonnet cover.		\$900.00
		Rust-proofing on the front accident affected area.		\$30.00
		To check front and rear electrical wiring system		\$30.00
		Sub Total		\$3,718.90
		Add 7% GST (\$1579)		\$110.53
		Less Excess (\$2,250.00)		(\$2,250.00)
				\$1,579.43
Page 2 of 2			Total	\$1,579.43


National Automobile Service