

INS CASE OWNER:

CC4/EGI1901 4444, U d63/1

LKK:
IDAC:

Surveyor:

Mohd

DOI:

ASSIGNMENT

W/8/19

Date / Time:

19/8/19

Registered in Meritmen:

19/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 8888B

Name of Insured:

TAN PECK LAM

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

16/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: *KWEK 500 How*

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

0mp 01900 3704

MERCEDES

SLE TO YISHAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SHM 7097C



INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

2/10/19 - FILE PAS TO TYPE MANDATE
11/11/19 - FILE PAS TO LSP TO CLONE

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: *11/11/2019*

Confirm with *FACAZ*

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOILA S/N No. : *28*

If NO or B 28, Ass. Lia: *OK*

Repair Cost: *(1/6/19)*

\$5

7571.07

4 veh. C.C., 01 may 2nd

Loss of Rental (LOR): *(1/6/19)*

\$5

856.00

(*8* days) x \$100

Loss of Use (LOU):

\$5

-

(5 x days)

Loss of Income (LOI):

\$5

-

(5 x days)

LOR only ☒

LOU only ☐

LOR + LOU ☐

LOR + LO ☐

(Tick only one)

GIA/LTA Search

\$5

2.00

Medical:

\$5

-

1) Claim status: *Non-Report/Reject/Private Settle*

Disbursement:

\$5

-

(e.g. Tow/ Independent)

2) Report Format: *SP*

Legal Cost

\$5

-

3) Survey fee: *3400*

Total:

\$5

8429.07

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirms with:

Email ☐ Call ☐

Payee 1:

\$5

8429.07

Name 1:

Kah Motor Co. Sdn. Bhd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ISS. REC. BY:

REF:

EGE

d

ASSIGNMENT

From:

Date:

21/8/19

Estimated Cost:

Veh No:

SMM3597C

Vt Regn:

6.19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

CA /

To inspect Vehicle No:

SMM 3597C

Make:

Honda civic

C.C.

1597

at Workshop m/s

Kah Motor

Colour:

s.bur

A/C:

Insured / Std / NI / NA

ul

15 ubi Road 4

Sp. Reading

3867

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No

C/No:

MRHFC5650K-T000503

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

PO Soun@96786493

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

R:

215/55-216

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Bal. or Market Value:

956.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GA / PR Scan:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

7

days

Res.:

Yes or No

D.O.A.

16/8/19

D.O.I.

26/8/19

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

CA / REV / REP. / 24 HRS

LTA 41641

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P - \$7075.77 (Red \$2796.22 / 28%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + RS. 01

Photos

Others

TOTAL

Report Format:

Lump Sum / LBR:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: 560FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	1
	5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.8 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN QING WEI ALVIN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 16/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: ERGO INSURANCE PTE LTD						
	TP VEH: SLN8822B						
68500-TEA-N00ZZ	LID COMP TRUNK	22/Dec 1	486.20	25	364.65	25.53	390.18
75722-TBA-A90	EMBLEM SETRR.	rec 1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	rec 1	11.00	25	8.25	0.58	8.83
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	11 1	100.60	25	75.45	5.28	80.73
75701-TBA-A10	EMBLEM.H-MARK	rec 1	12.20	25	9.15	0.64	9.79
90301-ST0-003	NUTPUSH 3MM	rec 2	2.10	25	1.57	0.22	1.79
74851-TEA-003	LOCK ASSYTRUNK	rec 1	74.30	25	55.72	3.90	59.62
74855-TEA-T01	WEATHERSTRIPTRUNK LID	7/11 1	70.00	25	52.50	3.68	56.18
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	rec 1	44.80	25	33.60	2.35	35.95
68680-TEA-T10ZZ	HINGE COMPLTRUNK	rec 1	44.80	25	33.60	2.35	35.95
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	TD 1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	11 1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	11 1	11.50	25	8.62	0.60	9.22
71505-TBA-A90	BRACKETR.RR.BUMPER SIDE	rec 1	2.30	25	1.72	0.12	1.84
71555-TBA-A90	BRACKETL.RR.BUMPER SIDE	rec 1	2.30	25	1.72	0.12	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	sent 1	164.70	25	123.52	8.65	132.17
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	rec 1	122.10	25	91.57	6.41	97.98
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	sent 1	8.40	25	6.30	0.44	6.74
71506-TEA-T00	GARNISH,L.RR.BUMPER SIDE	rec 1	8.40	25	6.30	0.44	6.74

7075.77 confirmed 27/9/19

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S50FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	2
	: 5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	: #04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	: SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.8 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
91505-TMB-003	CLIP BUMPER	7	2.30	25	12.07	0.84	12.91
71506-TEA-T50	COVER,RR.TOWING HOOK	1	4.50	25	3.37	0.24	3.61
71504-TBA-A00	COVER,FINISHER	1	11.90	25	8.92	0.62	9.54
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL,RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSY,RR.PANEL	1	50.30	25	37.72	2.64	40.36
84601-TEA-Q01ZA	LINING ASSY,TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84651-TEA-Q01ZA	LINING ASSY,TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84542-TET-H00	BOX COMPTOOL	1	38.00	25	28.50	2.00	30.50
84521-TEA-Q01ZA	LID ASSY,SPARE TIRE	1	60.20	25	45.15	3.16	48.31
34150-TEX-Y01	LIGHT ASSY,RR.LID	1	122.30	25	91.72	6.42	98.14
34155-TEX-Y01	LIGHT ASSY,LID	1	122.30	25	91.72	6.42	98.14
33500-TEA-T01	TAILLIGHT ASSY,RR	1	281.40	25	198.05	13.72	209.77
33550-TEA-T01	TAILLIGHT ASSY,L	1	281.30	25	210.97	14.77	225.74
32131-TEA-R00	SUB CORD,RR.BUMPER CORNER SENS	1	28.10	25	21.07	1.47	22.54
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	145.80	25	437.40	30.52	468.02
38387-TZ5-A01	ANTENNA ASSY,L F	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSY,SMART	1	61.30	25	45.97	3.22	49.19
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	25	45.00	3.15	48.15
Sum Item					2971.99	208.03	3,180.02
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	80.00		80.00	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4PCS(N)	1	150.00		150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985
Registration No : SMM3597C
Chassis No : MRHFC5650KT000503
Model : CIVIC 1.8 VTI YM2019
Owner's Name : CHAN QING WEI, ALVIN
Ins Policy No. :
Date of Accident : 16/8/2019

Document No. : SQT19003605
Date : 17. Aug 2019
Customer No. : WZN004
Svc Advisor : YOU PO SOON
Engine No : R16B25510506
Date | Time : 17. Aug 2019 3:20:47 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00	300	320.00	22.40	342.40
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	380.00	350	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	300	350.00	24.50	374.50
BKRP21M	CUT OFF & RENEW RR PANEL STRAIGHTEN RR FENDERS AN	1	2400.00	1960	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	1	2400.00	1800	2400.00	168.00	2568.00
Sum Labor					6900.00	483.00	7383.00

Survey By : Marius Hal
Date & Time : 26/8/19 @ 1pm.
Excess :
Status : Not Accident
Signature : John

Total Amount 9,871.99 691.03 10,563.02
Total (Inclusive of GST) 10,563.02

Like Auto Consultants hence notify the Repairer of the following:

- Scratches, blemishes / spray painting
- To ensure damaged parts/during resurvey
- Parts used are subject to confirmation
- This survey is done on a "Without Prejudice" basis
- No further work is allowed
- Dispute arising should be resolved and referred to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$63.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

Attn: Marcus

WD: 7 Days

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S80FC1380G

Customer: CU0126288 / ERGO INSURANCE
 Chassis No: MRHFC5850KT000503
 License No: SMM3597C
 Mileage: 4082
 Engine No: R16B25510506

Document No: SVO19055778
 Printed By: PSYOU
 Order Date: 29. August 2019
 Order Time: 4:38:02 PM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO: 73341) OWNER: CHAN QING WEI ALVIN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 16/08/2019 SURVEYED BY: MARCUS DATE: 26/8/2019 REF NO: TP INSURER: ERGO INSURANCE PTE LTD TP VEH: SLN8822B						
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	122.10	25	91.57	6.41	97.98
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	8.40	25	6.30	0.44	6.74
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
71506-TEA-T50	COVER,RR.TOWING HOOK	1	4.50	25	3.37	0.24	3.61
	SUM PARTS:				1,455.77	101.91	1,557.68
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	1864 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BOBC	1865 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	0760 BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BP00R	1865 APPLY BODY UNDERSIDE COATING (N).	1	180.00		180.00	12.60	192.60
BA02R	1864 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	300.00		300.00	21.00	321.00
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	300.00		300.00	21.00	321.00

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0126288 / ERGO INSURANCE	Document No:	SVO19055778
Chassis No:	MRHFC5650KT000503	Printed By:	PSYOU
License No:	SMM3597C	Order Date:	29. August 2019
Mileage:	4082	Order Time:	4:38:02 PM
Engine No:	R16B25510506	Service Advisor:	YOU PO SOON

BKTRR	1864 REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.	1	350.00	350.00	24.50	374.50
BMI03D	1864 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	300.00	300.00	21.00	321.00
BKRP21M	1864 CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	1,960.00	1,960.00	137.20	2,097.20
BP05R	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	1,800.00	1,800.00	126.00	1,926.00
SUM LABOUR:				5,620.00	393.40	6,013.40
TOTAL SGD				7,075.77	495.31	7,571.08
Total Payable (SGD)						7,571.08

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	1
	5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.6 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN QING WEI ALVIN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 16/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: ERGO INSURANCE PTE LTD						
	TP VEH: SLN8822B						
68500-TEA-N00ZZ	LID COMP TRUNK	20/3uc	1	486.20	25	364.65	390.18
75722-TBA-A00	EMBLEM SETRR.	ru	1	11.80	25	8.85	9.47
75725-TEA-T01	EMBLEMRR.	ru	1	11.00	25	8.25	8.83
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	11	1	100.60	25	75.45	80.73
75701-TBA-A10	EMBLEM,H-MARK	ru	1	12.20	25	9.15	9.79
90301-ST0-003	NUTPUSH 3MM	ru	2	2.10	25	3.15	3.37
74851-TEA-003	LOCK ASSYTRUNK		1	74.30	25	55.72	59.62
74865-TEA-T01	WEATHERSTRIPTRUNK LID	T.M	1	70.00	25	52.50	56.18
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	Su	1	44.80	25	33.60	35.95
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	Su	1	44.80	25	33.60	35.95
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	TD	1	617.20	25	462.90	495.30
71593-TEA-T01	SPACERR,RR.BUMPER SIDE		1	11.50	25	8.62	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE		1	11.50	25	8.62	9.22
71505-TBA-A00	BRACKETR,RR.BUMPER SIDE	ru	1	2.30	25	1.72	1.84
71555-TBA-A00	BRACKETL,RR.BUMPER SIDE	ru	1	2.30	25	1.72	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER		1	164.70	25	123.52	132.17
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	de	1	122.10	25	91.57	97.98
71503-TEA-T00	GARNISH,R,RR.BUMPER SIDE	ser	1	8.40	25	6.30	6.74
71508-TEA-T00	GARNISH,L,RR.BUMPER SIDE		1	8.40	25	6.30	6.74

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	2
	5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.6 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71506-TEA-T50	COVER,RR.TOWING HOOK	1	4.50	25	3.37	0.24	3.61
71504-TBA-A00	COVER,FINISHER	1	11.90	25	8.92	0.62	9.54
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENER,LL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSY,RR.PANEL	1	50.30	25	37.72	2.64	40.36
84601-TEA-Q01ZA	LINING ASSY,RR.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84651-TEA-Q01ZA	LINING ASSY,LL.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84542-TET-H00	BOX COMPTOOL	1	38.00	25	28.50	2.00	30.50
84521-TEA-Q01ZA	LID ASSY,SPARE TIRE	1	60.20	25	45.15	3.16	48.31
34150-TEX-Y01	LIGHT ASSY,R.LID	1	122.30	25	91.72	6.42	98.14
34155-TEX-Y01	LIGHT ASSY,L.LID	1	122.30	25	91.72	6.42	98.14
33500-TEA-T01	TAILLIGHT ASSY,R.	1	261.40	25	196.05	13.72	209.77
33550-TEA-T01	TAILLIGHT ASSY,L.	1	281.30	25	210.97	14.77	225.74
32131-TEA-R00	SUB CORD,RR.BUMPER CORNER SENS	1	28.10	25	21.07	1.47	22.54
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	145.80	25	437.40	30.62	468.02
38387-TZ5-A01	ANTENNA ASSY,L.F.	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSY,SMART	1	61.30	25	45.97	3.22	49.19
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					2971.99	208.03	3,180.02
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
 5 TEMASEK BOULEVARD
 #04-01 OSUNTEC TOWER FIVE
 SINGAPORE 038985
Registration No : SMM3597C
Chassis No : MRHFC5650KT000503
Model : CIVIC 1.6 VTI YM2019
Owner's Name : CHAN QING WEI, ALVIN
Ins Policy No. :
Date of Accident : 16/8/2019

Document No. : SQT19003605 **Page** 3
Date : 17. Aug 2019
Customer No. : WZN004
Svc Advisor : YOU PO SOON
Engine No : R16B25510506
Date | Time : 17. Aug 2019 3:20:47 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00	300	320.00	22.40	342.40
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	380.00	350	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	300	350.00	24.50	374.50
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	2400.00	1960	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2400.00	1800	2400.00	168.00	2568.00
Sum Labor					6900.00	483.00	7,383.00

Survey By : Marcus Khat
Date & Time : 26/8/19 @ 1pm.

Excess :
Status : Not Adjust

Signature : [Signature]
 John

Total Amount 9,871.99 691.03 10,563.02
Total (Inclusive of GST) 10,563.02

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey damaged parts: spray painting
 • To display damaged parts during resurvey
 • To provide a written confirmation
 • This survey is on a "Without Prejudice" basis
 • No claim (deductible) is allowed
 • Repairer's warranty must be resurveyed and subject to the approval from Insurance Company

Acknowledged by Repairer

Signature

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 027B

Vehicle Details

Vehicle No.: SMM3597C

Vehicle to be Exported: No

Intended Deregistration Date: 26 Aug 2019

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6 VTI CVT

Primary Colour: Silver

Manufacturing Year: 2019

Engine No.: R16B25510506

Chassis No.: MRHFC5650KT000503

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$20,088.00

Original Registration Date: 26 Jun 2019

First Registration Date: 26 Jun 2019

Transfer Count: 0

Actual ARF Paid: \$20,124.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Jun 2029

PARF Rebate Amount: \$15,093.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$27,000.00

COE Rebate Amount: \$26,548.00

Total Rebate Amount: \$41,641.00

The information contained herein is correct as at 26 Aug 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Porsche Boxster S 3.2.



Brand New Paint, Many Wear
And Tear Parts Replaced. Call To
View.
Direct Owner StarAd

PRIME MOTOR & LEASING

JOHNSON HONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

StarAd

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Honda Civic

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Civic		Any	Any	2019	Any	Any	Any	Available
	Honda Civic	Honda Civic 1.6A VTI	\$90,800	\$8,530 /yr	13-Feb-2019	1,597 cc	5,900 km	Sedan	Available
		Upgraded With Full Bodykit! Fully Serviced And Maintained By Agent (Kah Motor). 5 Years Warranty And Free 5 Years Servicing Form Ag... Performance Carz Pte Ltd Posted: 24-Aug-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED
	Honda Civic	Honda Civic Type-R 2.0M VTEC Turbo GT	\$176,000	\$15,810 /yr	11-Jan-2019	1,996 cc	10,000 km	Sports	Available
		Posted: 13-Aug-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED
	Honda Civic	Honda Civic HB 1.0A VTEC Turbo	\$102,800	\$8,830 /yr	12-Jul-2019	988 cc	500 km	Hatchback	Available
		5 Years Warranty Included, High And Flexible Loan Available, Trade In Welcome, Call Now For An Appointment! Vincar Pte Ltd Posted: 17-Jul-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED
	Honda Civic	Honda Civic HB 1.0A VTEC Turbo	\$102,800	\$8,830 /yr	12-Jul-2019	988 cc	500 km	Hatchback	Available
		5 Years Warranty Included, High And Flexible Loan Available, Trade-In Welcome, Call Now For An Appointment! Vincar Pte Ltd Posted: 17-Jul-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED
		Extra Layer Of Protection For Car Doors Honda Freed 2017 Protective Door Moulding, your extra layer of protection from other cars doors swing open widely. Find out more!							
	Honda Civic	Honda Civic HB 1.0A VTEC Turbo SE	\$102,800	\$8,820 /yr	12-Jul-2019	988 cc	500 km	Hatchback	Available
		5 Years Warranty Included, High And Flexible Loan Available, Trade In Welcome, Call Now For An Appointment! Vincar Pte Ltd Posted: 17-Jul-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED
	Honda Civic	Honda Civic HB 1.0A VTEC Turbo	\$102,800	\$8,830 /yr	11-Jul-2019	988 cc	500 km	Hatchback	Available
		5 Years Warranty Included, High And Flexible Loan Available, Trade In Welcome, Call Now For An Appointment! Vincar Pte Ltd Posted: 17-Jul-2019 Tags: 2019 Honda Civic, 2019 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							PREMIUM ED

Compare

Nivitha (LKK Auto)

From: Pauline Soh <pauline.soh@ergo.com.sg>
Sent: Monday, 19 August 2019 10:58 AM
To: You Po Soon; Admin A (admin-a@lkkauto.com); Admin-D (LKKAuto (admin-d@lkkauto.com))
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SMM3597C AGAINST SLN8822B (Claims Ref No. CDMPG19001429)

Hi LKK,

Please conduct this survey request on without prejudice basis.

Please contact us if you are not able to make it.

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: You Po Soon [mailto:psyou@honda.com.sg]
Sent: Monday, August 19, 2019 10:15 AM
To: Pauline Soh
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SMM3597C AGAINST SLN8822B (Claims Ref No. CDMPG19001429)

Dear Pauline,

We would like to chose as per below for the survey,

6	LKK	LKK Auto Consultants Pte Ltd
---	-----	------------------------------

Thank You.

Best Regards,

11:26am 19/8/19
psyou poh
vehicle not in

You Po Soon
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : psyou@honda.com.sg
TEL : 9678 6493

From: Pauline Soh <pauline.soh@ergo.com.sg>
Sent: Monday, 19 August 2019 9:38 AM
To: You Po Soon <psyou@honda.com.sg>
Cc: Pauline Soh <pauline.soh@ergo.com.sg>
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SMM3597C AGAINST SLN8822B (Claims Ref No. CDMPG19001429)

Hi Po Soon

Please reply me here.

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: ERGO Insurance Pte. Ltd. (Claims Department)
Sent: Monday, August 19, 2019 9:37 AM
To: 'You Po Soon'
Cc: Ivy Yong; Phoebe Xie

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SMM3597C AGAINST SLN8822B (Claims Ref No. CDMPG19001429)

Dear Po Soon,

Please refer to our list of surveyors

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: You Po Soon [<mailto:psyoun@honda.com.sg>]
Sent: Monday, August 19, 2019 7:17 AM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SMM3597C AGAINST SLN8822B

To The Officer In Charge,


Please Refer The Above Attachment For Your Reference.

Kindly Help To Arrange Surveyor To Survey This Vehicle SMM3597C.


Your Insured vehicle number is SLN8822B, Accident Date 16/08/2019.

Best Regards,

You Po Soon
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : psyoun@honda.com.sg
TEL : 9678 6493



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

View Received Message

This mail is associated with :

***SMM3597C (CMPG19001429)
[SLN88228]**

TP
CHAN QING WEI ALVIN
Aug 16 2019 12:00AM
[TAN PECK LAN]
Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ERGO Insurance Pte. Ltd. (HQ) (ERGO_SG), sent on 11/11/2019 11:01 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8429.07) - SMM3597C - Claim Handler: Ivy Yong

Approved:8429.07.

DOCUMENTS SUMMARY

There are no documents.

Jia Le (LKK Auto)

From: Faeaz <faeaz@honda.com.sg>
Sent: Monday, 11 November 2019 2:26 PM
To: Jia Le (LKK Auto)
Cc: Lim Chou Siong
Subject: RE: ERGO-LKK Submission of Third Party Direct Settlement, Y/R: CDMPG19001429 : O/R: SMM3597C

Dear Jia Le,

We accepted your settlement offer.

Kindly let us have your payment soonest possible. Thank you.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Monday, 11 November, 2019 11:42 AM
To: Lim Chou Siong <cslim@honda.com.sg>
Cc: Faeaz <faeaz@honda.com.sg>
Subject: RE: ERGO-LKK Submission of Third Party Direct Settlement, Y/R: CDMPG19001429 : O/R: SMM3597C

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter.

We propose settlement as follows:-

1. Cost of Repair (w/GST)	\$ 7,571.07
2. Loss of Rental (8days x \$100)(w/GST)	\$ 856.00
4. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 8,429.07

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong [<mailto:cslim@honda.com.sg>]

Sent: Saturday, 12 October 2019 9:11 AM

To: Jia Le (LKK Auto)

Cc: Faeaz

Subject: ERGO-LKK Submission of Third Party Direct Settlement, Y/R: CDMPG19001429 : O/R: SMM3597C

Dear Jia Le,

ACCIDENT INVOLVING SMM3597C AND SLN8822B ON 16.08.19

Attached please find our repair invoice and other relevant documents for the direct settlement claim.

Kindly email me the DV as soon as possible.

Warmest Regards,

Cslim

DID: +65 6514 5684

Email: cslim@honda.com.sg

From: Printer Service <printservice@honda.com.sg>

Sent: Friday, 11 October 2019 6:20 pm

To: Lim Chou Siong <cslim@honda.com.sg>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Nov 2019 10:05 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$7,075.77 Edit Estimates	S\$7,075.77 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN PECK LAN, ID: S1545784H								
Main Claimant:	CHAN QING WEI ALVIN, ID: S8720027B								
Vehicle Reg. No.:	SMM3597C	Date of Loss:	16/08/2019 00:00 - :59 [1 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CDMPG19001429		Policy/Cover Note No.:						
Vehicle Reg. No. (Insured):	SLN8822B	Policy No. (Claimant):	19-MS007678-R00						
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Ivy Yong - 6829 9197]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
ERGO_SG (11/11/2019): Alert - Adj Mandate Approved (S\$8429.07) - SMM3597C - Claim Handler: Ivy Yong									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMM3597C (CDMPG19001429)
[SLN8822B]

TP
CHAN QING WEI ALVIN
Aug 16 2019 12:00AM
[TAN PECK LAN]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Letters/Correspondences									1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown										Edit		
Assessment Reports									1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	27/08/19 15:44	Adjuster Immediate Advice										Load HTM		
Photos/Images									3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	11/11/19 10:35	Odometer Reading										Load JPG ☒		
2	11/11/19 10:35	General View										Load JPG ☒		
3	11/11/19 10:35	Chassis Number										Load JPG ☒		
4	11/11/19 10:35	General View										Load JPG ☒		
5	11/11/19 10:35	General View										Load JPG ☒		
6	11/11/19 10:35	General View										Load JPG ☒		
7	11/11/19 10:35	General View										Load JPG ☒		
8	11/11/19 10:35	General View										Load JPG ☒		
9	11/11/19 10:35	General View										Load JPG ☒		
10	11/11/19 10:35	General View										Load JPG ☒		
11	11/11/19 10:35	General View										Load JPG ☒		
12	11/11/19 10:35	General View										Load JPG ☒		
13	11/11/19 10:35	General View										Load JPG ☒		
14	11/11/19 10:35	General View										Load JPG ☒		
15	11/11/19 10:35	General View										Load JPG ☒		
16	11/11/19 10:35	General View										Load JPG ☒		
17	11/11/19 10:35	General View										Load JPG ☒		
18	11/11/19 10:35	General View										Load JPG ☒		
19	11/11/19 10:35	General View										Load JPG ☒		
20	11/11/19 10:35	General View										Load JPG ☒		
21	11/11/19 10:35	General View										Load JPG ☒		
22	11/11/19 10:35	General View										Load JPG ☒		
23	11/11/19 10:35	General View										Load JPG ☒		
24	11/11/19 10:35	General View										Load JPG ☒		
25	11/11/19 10:35	General View										Load JPG ☒		
26	11/11/19 10:35	General View										Load JPG ☒		
27	11/11/19 10:35	General View										Load JPG ☒		
28	11/11/19 10:35	General View										Load JPG ☒		
29	11/11/19 10:35	General View										Load JPG ☒		
30	11/11/19 10:35	General View										Load JPG ☒		
31	11/11/19 10:35	General View										Load JPG ☒		
32	11/11/19 10:35	General View										Load JPG ☒		
33	11/11/19 10:35	General View										Load JPG ☒		
34	11/11/19 10:35	General View										Load JPG ☒		
35	11/11/19 10:35	General View										Load JPG ☒		
36	11/11/19 10:35	General View										Load JPG ☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	11/11/19 10:35	General View		☒
38	11/11/19 10:35	General View		☒
39	11/11/19 10:35	General View		☒
40	11/11/19 10:35	General View		☒
41	11/11/19 10:35	General View		☒
42	11/11/19 10:35	General View		☒
43	11/11/19 10:35	General View		☒
44	11/11/19 10:35	General View		☒
45	11/11/19 10:35	General View		☒
46	11/11/19 10:35	General View		☒
47	11/11/19 10:35	General View		☒
48	11/11/19 10:35	General View		☒
49	11/11/19 10:35	General View		☒
50	11/11/19 10:35	General View		☒
51	11/11/19 10:35	General View		☒
52	11/11/19 10:35	General View		☒
53	11/11/19 10:35	General View		☒
54	11/11/19 10:35	General View		☒
55	11/11/19 10:36	Reinspection Photo		☒
56	11/11/19 10:36	Reinspection Photo		☒
57	11/11/19 10:36	Reinspection Photo		☒
58	11/11/19 10:36	Reinspection Photo		☒
59	11/11/19 10:36	Reinspection Photo		☒
60	11/11/19 10:36	Reinspection Photo		☒
61	11/11/19 10:36	Reinspection Photo		☒
62	11/11/19 10:36	Reinspection Photo		☒
63	11/11/19 10:36	Reinspection Photo		☒
64	11/11/19 10:36	Reinspection Photo		☒
65	11/11/19 10:36	Reinspection Photo		☒
66	11/11/19 10:36	Reinspection Photo		☒
67	11/11/19 10:36	Reinspection Photo		☒
68	11/11/19 10:36	Reinspection Photo		☒
69	11/11/19 10:36	Reinspection Photo		☒
70	11/11/19 10:36	Reinspection Photo		☒
71	11/11/19 10:37	Reinspection Photo		☒
72	11/11/19 10:37	Reinspection Photo		☒
73	11/11/19 10:37	Reinspection Photo		☒
74	11/11/19 10:37	Reinspection Photo		☒
75	11/11/19 10:37	Reinspection Photo		☒
76	11/11/19 10:37	Reinspection Photo		☒
77	11/11/19 10:37	Reinspection Photo		☒
78	11/11/19 10:37	Reinspection Photo		☒
79	11/11/19 10:37	Reinspection Photo		☒
80	11/11/19 10:37	Reinspection Photo		☒
81	11/11/19 10:37	Reinspection Photo		☒
82	11/11/19 10:37	Reinspection Photo		☒
83	11/11/19 10:37	Reinspection Photo		☒
84	11/11/19 10:37	Reinspection Photo		☒
85	11/11/19 10:37	Reinspection Photo		☒
86	11/11/19 10:37	Reinspection Photo		☒
87	11/11/19 10:37	Reinspection Photo		☒
88	11/11/19 10:37	Reinspection Photo		☒
89	11/11/19 10:37	Reinspection Photo		☒
90	11/11/19 10:37	Reinspection Photo		☒
91	11/11/19 10:37	Reinspection Photo		☒
92	11/11/19 10:45	Reinspection Photo		☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
93	11/11/19 10:45	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/08/19 16:55	EMAIL FROM EGI DD 19082019		Load PDF	
2	20/08/19 11:24	TP GIA REPORT		Load PDF	
3	20/08/19 11:24	OI GIA REPORT		Load PDF	
4	27/08/19 17:56	TP ESTIMATE- MARKED		Load PDF	
5	06/11/19 13:32	LETTER TO OI		Load PDF	
6	11/11/19 10:49	LOD		Load PDF	
7	15/11/19 08:52	WORKSHOP INVOICE		Load PDF	
8	15/11/19 08:52	AUTHORISATION TO ACT FORM		Load PDF	
9	15/11/19 08:52	RENTAL RECEIPT		Load PDF	
10	15/11/19 08:52	GIA SEARCH		Load PDF	
11	15/11/19 08:52	LOD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN8822B (Insd veh)	Model:	HONDA CIVIC 1.6 VTI (A)
	SMM3597C (TP veh)		
Date of Accident:	16/08/2019		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		10,563.03
Final Repair Cost	: \$		7,571.07
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		856.00 8 days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		8,429.07

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ 0 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kah Motor Co.Sdn.Bhd.	: \$	8,429.07
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

15 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/EG19014444/UDB3Q2

Date: 15/11/2019

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMM3597C

Insured Vehicle No : SLN8822B

Date of Loss: 16/08/2019

Nature of Claim: TP

Claim No: CDMPG19001429

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM3597C

Make & Model: HONDA CIVIC, 1.6 VTI (A)

Engine No: R16B25510506

Reg. Date: 26/06/2019 (Man. Year: 2019)

Chassis No: MRHFC5650KT000503

Colour: Silver

Odometer: 3867 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size:

215/55 R16

Front Left Side: Hankook 8 mm

Rear Left Side:

Hankook 8 mm

Front Right Side: Hankook 8 mm

Rear Right Side:

Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,021.99	1,475.77	1,546.22	51.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	5,600.00	1,250.00	18.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,871.99	7,075.77	2,796.22	28.32
+ GST 7.00/7.00% (S\$)	691.04	495.30	195.74	28.33
Nett Amount (S\$)	10,563.03	7,571.07	2,991.96	28.32
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,429.07		

INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 26/08/2019 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
Parts: 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3597C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID COMP TRUNK	Dented / Buckled	364.65 FS	*364.65 FS
2	1		*EMBLEM SETRR	Necessary	8.85 FS	*8.85 FS
3	1		*EMBLEMRR	Necessary	8.25 FS	*8.25 FS
4	1		*GARNISH ASSYRR LICENSE	Not Necessary	75.45 FS	*- FS
5	1		*EMBLEM ,H-MARK	Necessary	9.15 FS	*9.15 FS
6	1		*NUTPUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
7	1		*LOCK ASSYTRUNK	Serviceable	55.72 FS	*- FS
8	1		*WEATHERSTRIPTRUNK LID	Twisted	52.50 FS	*52.50 FS
9	1		*HINGE COMPR .TRUNK	Serviceable	33.60 FS	*- FS
10	1		*HINGE COMPL .TRUNK	Serviceable	33.60 FS	*- FS
11	1		*FACE ASSY ,RR BUMPER	Dented	462.90 FS	*462.90 FS
12	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
13	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
14	1		*BRACKETR.RR.BUMPER SIDE	Necessary	1.72 FS	*1.72 FS
15	1		*BRACKETL.RR.BUMPER SIDE	Necessary	1.72 FS	*1.72 FS
16	1		*BEAM COMPRR.BUMPER	Bent	123.52 FS	*123.52 FS
17	1		*GARNISH ASSY,RR.BUMPER LOWER	Deformed	91.57 FS	*91.57 FS
18	1		*GARNISH.R.RR.BUMPER SIDE	Scratched	6.30 FS	*6.30 FS
19	1		*GARNISH.L.RR.BUMPER SIDE	Serviceable	6.30 FS	*- FS
20	1		*CLIP,BUMPER	Necessary	12.07 FS	*12.07 FS
21	1		*COVER ,RR TOWING HOOK	Deformed	3.37 FS	*3.37 FS
22	1		*COVERR.FINISHER	Not Necessary	8.92 FS	*- FS
23	1		*PANEL SETRR	Dented / Necessary	182.32 FS	*182.32 FS
24	1		*STIFFENER .R.RR.PANEL SIDE	Bent	20.02 FS	*20.02 FS
25	1		*STIFFENER .L.RR.PANEL SIDE	Bent	20.02 FS	*20.02 FS
26	1		*LINING ASSYRR.PANEL	Deformed	37.72 FS	*37.72 FS
27	1		*LINING ASSYR .TRUNK SIDE	Not Necessary	36.67 FS	*- FS
28	1		*LINING ASSYL .TRUNK SIDE	Not Necessary	36.67 FS	*- FS
29	1		*BOX COMPTOOL	Not Necessary	28.50 FS	*- FS
30	1		*LID ASSYSPARE TIRE	Not Necessary	45.15 FS	*- FS
31	1		*LIGHT ASSYR.LID	Not Necessary	91.72 FS	*- FS
32	1		*LIGHT ASSYL.LID	Not Necessary	91.72 FS	*- FS
33	1		*TAILLIGHT ASSYR	Not Necessary	196.05 FS	*- FS
34	1		*TAILLIGHT ASSYL	Not Necessary	210.97 FS	*- FS
35	1		*SUB CORDRR .BUMPER CORNER SENS	Not Necessary	21.07 FS	*- FS
36	1		*SENSOR ASSY .PARKING	Not Necessary	437.40 FS	*- FS
37	1		*ANTENNA ASSYL.F	Not Necessary	44.47 FS	*- FS
38	1		*BUZZER ASSYSMART	Cracked	45.97 FS	*45.97 FS
39	1		*NUMBER PLATE WITH CASING -L	Serviceable	45.00 FS	*- FS
40	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,021.99	1,475.77
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMSS PERFORM WATER	New	100.00	100.00
2	BODY UNDERSIDE COATING	New	100.00	100.00
3	BODY JOINT SEALANT	New	80.00	80.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & RENEW REVERSE SENSORS	New	150.00	130.00
6	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	320.00	300.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	320.00	300.00
8	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	380.00	350.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	300.00
10	CUT OFF & RENEW RR PANEL .STRAIGHTEN RR FENDERS AN	New	2,400.00	1,960.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,400.00	1,800.00
Gross Labour Cost (S\$)			6,850.00	5,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >