

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	1
	5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.6 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN QING WEI ALVIN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 16/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: ERGO INSURANCE PTE LTD						
	TP VEH: SLN8822B						
68500-TEA-N00ZZ	LID COMP TRUNK	2/Buc	1	486.20	25	364.65	390.18
75722-TBA-A00	EMBLEM SETRR.	ru	1	11.80	25	8.85	9.47
75725-TEA-T01	EMBLEMRR.	ru	1	11.00	25	8.25	8.83
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	ru	1	100.60	25	75.45	80.73
75701-TBA-A10	EMBLEM,H-MARK	ru	1	12.20	25	9.15	9.79
90301-ST0-003	NUTPUSH 3MM	ru	2	2.10	25	3.15	3.37
74851-TEA-003	LOCK ASSYTRUNK		1	74.30	25	55.72	59.62
74865-TEA-T01	WEATHERSTRIPTRUNK LID	7/ru	1	70.00	25	52.50	56.18
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	Su	1	44.80	25	33.60	35.95
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	Su	1	44.80	25	33.60	35.95
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	ru	1	617.20	25	462.90	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE		1	11.50	25	8.62	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE		1	11.50	25	8.62	9.22
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	ru	1	2.30	25	1.72	1.84
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	ru	1	2.30	25	1.72	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER		1	164.70	25	123.52	132.17
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	ru	1	122.10	25	91.57	97.98
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	SER	1	8.40	25	6.30	6.74
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE		1	8.40	25	6.30	6.74

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT19003605	Page	2
	5 TEMASEK BOULEVARD	Date	: 17. Aug 2019		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: YOU PO SOON		
Registration No	: SMM3597C	Engine No	: R16B25510506		
Chassis No	: MRHFC5650KT000503	Date Time	: 17. Aug 2019 3:20:47 PM		
Model	: CIVIC 1.6 VTI YM2019	Surveyor Name	:		
Owner's Name	: CHAN QING WEI, ALVIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71506-TEA-T50	COVER,RR.TOWING HOOK	1	4.50	25	3.37	0.24	3.61
71504-TBA-A00	COVERR.FINISHER	1	11.90	25	8.92	0.62	9.54
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	48.90	25	36.67	2.57	39.24
84542-TET-H00	BOX COMPTOOL	1	38.00	25	28.50	2.00	30.50
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	60.20	25	45.15	3.16	48.31
34150-TEX-Y01	LIGHT ASSYR.LID	1	122.30	25	91.72	6.42	98.14
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	25	91.72	6.42	98.14
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
33550-TEA-T01	TAILLIGHT ASSYL.	1	281.30	25	210.97	14.77	225.74
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	28.10	25	21.07	1.47	22.54
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	4	145.80	25	437.40	30.62	468.02
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					2971.99	208.03	3,180.02
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985
Registration No : SMM3597C
Chassis No : MRHFC5650KT000503
Model : CIVIC 1.6 VTI YM2019
Owner's Name : CHAN QING WEI, ALVIN
Ins Policy No. :
Date of Accident : 16/8/2019

Document No. : SQT19003605
Date : 17. Aug 2019
Customer No. : WZN004
Svc Advisor : YOU PO SOON
Engine No : R16B25510506
Date | Time : 17. Aug 2019 3:20:47 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00	300	320.00	22.40	342.40
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	380.00	350	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	300	350.00	24.50	374.50
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	2400.00	1960	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2400.00	1800	2400.00	168.00	2568.00
Sum Labor					6900.00	483.00	7,383.00

Survey By

Date & Time

Excess

Status

Signature

Marcus Lal
26/8/19 @ 1pm.
Not Agent
the 2nd Sep 2019
July.

Total Amount 9,871.99 691.03 10,563.02

Total (Inclusive of GST) 10,563.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/8/2019 4:35:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.