

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1908/005
Policy No:	PNMC2019-00000315	Date of Loss:	24/07/2019
Vehicle Reg. No.:	FBN9258S	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SH7044K
Any Injuries?	yes	Contact No:	
Insured/Claimant:	AILEEN LEOW SUYIN	Driver:	MOHAMAD NUFAIL BIN SURANI

Make/Model:	Yamaha, YZF-R15 - ME120P021A2005661	Vehicle Reg. Date:	07 Jan 2019
Vehicle Colour:	BLACK	Engine Number:	G3J6E0176151
Chassis No:	MH3RG4710KK093824	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - MAJOR/MINOR RD
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	10,863.00
Miscellaneous Items	650.00
Labour	1,120.00
Paintwork Labour	460.00
Towing	0.00
Gross Total(S\$):	13,093.00
GST 7.00%(S\$):	916.51
Nett Amount(S\$):	14,009.51

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP FAIRING	430.00	-10.00	387.00
2	1	FRONT HEADLAMP	480.00	-10.00	432.00
3	1	FRONT HEADLAMP INNER FAIRING	370.00	-10.00	333.00
4	1	FRONT HEADLAMP BRACKET	80.00	-10.00	72.00
5	1	FRONT HEADLAMP LOWER PROTECTOR LH	110.00	-10.00	99.00
6	1	FRONT HEADLAMP LOWER PROTECTOR RH	110.00	-10.00	99.00
7	1	FRONT VISOR	180.00	-10.00	162.00
8	1	FRONT SIDE MIRROR LH	170.00	-10.00	153.00
9	1	FRONT SIDE MIRROR RH	170.00	-10.00	153.00
10	1	FRONT SIDE FAIRING LH	440.00	-10.00	396.00
11	1	FRONT SIDE FAIRING RH	440.00	-10.00	396.00
12	1	FRONT SIDE INNER FAIRING LH	380.00	-10.00	342.00
13	1	FRONT SIDE INNER FAIRING RH	380.00	-10.00	342.00
14	1	FRONT SIDE FAIRING TOP PROTECTOR LH	110.00	-10.00	99.00
15	1	FRONT SIDE FAIRING TOP PROTECTOR RH	110.00	-10.00	99.00
16	1	FRONT SIGNAL LAMP LH	77.00	-10.00	69.30
17	1	FRONT SIGNAL LAMP RH	77.00	-10.00	69.30
18	1	FRONT SIDE LOWER FAIRING LH	270.00	-10.00	243.00
19	1	FRONT SIDE LOWER FAIRING RH	270.00	-10.00	243.00
20	1	FRONT CENTRE INNER COVER	120.00	-10.00	108.00
21	1	FRONT FORK LH	280.00	-10.00	252.00
22	1	FRONT FORK RH	280.00	-10.00	252.00
23	1	FRONT WHEEL CENTRE THRU AXLE	115.00	-10.00	103.50
24	1	FRONT BRAKE ROTOR	265.00	-10.00	238.50
25	1	FRONT BRAKE CALIPER	310.00	-10.00	279.00
26	1	FRONT FENDER	150.00	-10.00	135.00
27	1	SPEEDOMETER	1,400.00	-10.00	1,260.00
28	1	RADIATOR	700.00	-10.00	630.00
29	1	RADIATOR BRACKET	40.00	-10.00	36.00
30	1	RADIATOR SIDE COVER LH	80.00	-10.00	72.00
31	1	RADIATOR SIDE COVER RH	80.00	-10.00	72.00
32	1	RADIATOR SPARE TANK	190.00	-10.00	171.00
33	1	RADIATOR HOSE	30.00	-10.00	27.00
34	1	FRONT EXHAUST PIPE	1,650.00	-10.00	1,485.00
35	1	FRONT HANDLE BAR CENTRE	180.00	-10.00	162.00
36	1	FRONT HANDLE BAR LH	130.00	-10.00	117.00
37	1	FRONT HANDLE BAR RH	130.00	-10.00	117.00
38	1	FRONT STEERING STEM	140.00	-10.00	126.00
39	1	FRONT STEERING CONE AND BEARING	135.00	-10.00	121.50
40	1	FRONT STEERING UPPER BRACKET	70.00	-10.00	63.00
41	1	FRONT STEERING LOWER BRACKET	70.00	-10.00	63.00
42	1	BALANCER LH	20.00	-10.00	18.00
43	1	BALANCER RH	20.00	-10.00	18.00
44	1	FRONT CLUTCH LEVER LH	28.00	-10.00	25.20
45	1	FRONT BRAKE LEVER RH	28.00	-10.00	25.20
46	1	FRONT CHASSIS FRAME	0.00	0.00	0.00
47	1	FRONT FOOTREST LH	45.00	-10.00	40.50
48	1	FRONT FOOTREST BRACKET LH	140.00	-10.00	126.00
49	1	FRONT FOOT GEAR LEVER LH	60.00	-10.00	54.00
50	1	REAR SIDE FAIRING LH	280.00	-10.00	252.00
51	1	REAR SIGNAL LAMP LH	80.00	-10.00	72.00
52	1	REAR EXHAUST SILENCER COVER RH	110.00	-10.00	99.00

Estimates On Parts					
No.	Qty	Particulars	Amount	%Disc	After Disc
53	1	REAR EXHAUST SILENCER TAILPIPE	60.00	-10.00	54.00
			Total Parts (\$\$)		10,863.00

Estimates of Miscellaneous Items					
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE	30.00	0.00	30.00
2	1	FRONT WHEEL RIM	300.00	0.00	300.00
3	1	FRONT TYRE	260.00	0.00	260.00
4	1	RADIATOR COOLANT	60.00	0.00	60.00
			Sub Total (\$\$)		650.00

Estimates On Labour					
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
2	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00
3	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	0.00	120.00
4	1	Towing Charges.	80.00	0.00	80.00
5	1	To Conduct Wheel Balancing	60.00	0.00	60.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	650.00	0.00	650.00
			Gross Labour Cost (\$\$)		1,120.00

Estimates On Paint Work Labour					
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	0.00	400.00
			Gross Labour Cost (\$\$)		460.00

< END OF ESTIMATES >