

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 21 Aug 2019

## **Preliminary Advice**

Insured Vehicle No	: XB7771S		
TP Vehicle No	: SHA4299D	Accident Date	: 15/08/2019
Make	: HYUNDAI IONIQ HYBRID	Assignment Date	: 20/08/2019
Date of Inspection	: 17/08/2019	Est. Duration of Repair	: 6/Days
Inspection At	: CHUNNI MOTOR WORK PTE LTD		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...N/S Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,242.14
Revised Amount	:S\$	6,619.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,619.20

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.