

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 4299D

DATE : 15.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

62/90

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>broken</i>			\$ 459.40	✓
	Rear Bumper Centre Moulding Assy <i>Cut</i>			\$ 451.25	✓
	Rear Bumper Stay <i>NH</i>			\$ 138.10	X
	Rear Bumper Side Bracket (LH) <i>broken</i>			\$ 33.10	✓
	Rear Bumper Cover Clips <i>Nec</i>			\$ 22.00	✓
	Tail Lamp (LH) <i>scratched</i>			\$ 870.40	✓
	Rear Fender (LH) <i>Dented</i>			\$ 1,768.30	✓
	Rear Fender Inner Lining (LH) <i>deformed</i>			\$ 73.60	✓
	Rear Fender Air-Duct <i>NH</i>			\$ 51.60	X
	Rear Windscreen Moulding <i>Nec</i>			\$ 28.20	✓
	Rear Tyre Rim (LH) <i>NH</i>			\$ 1,124.20	X
	Rear Wheel Hup-Cap (LH) <i>Cut</i>			\$ 346.00	✓
	Rear Wheelbearing ING & Hub <i>Don</i>			\$ 454.00	✓
	Rear Trailing Arm (LH) <i>distorted</i>			\$ 121.00	✓
	Rear Assist (LH) <i>distorted</i>			\$ 92.80	✓
	Rear Shock Absorber (LH) <i>distorted</i>			\$ 230.50	✓
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 61.40	X
	Rear Upper Arm (LH) <i>distorted</i>			\$ 112.20	✓
	Rear Lower Arm (LH) <i>distorted</i>			\$ 393.10	✓
	Rear Knuckle Arm (LH) <i>distorted</i>			\$ 386.90	✓
	SUB TOTAL			\$ 7,218.05	
	LESS 20%			\$ 1,443.61	
	DISCOUNTED TOTAL			\$ 5,774.44	
	Rear Bumper Reverse Sensor <i>NH</i>			\$ 135.70	Nett X
	Rear Bumper Rubber Mat <i>Nec</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Nec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Nec</i>			\$ 46.00	Nett ✓
	Rear Tyre (LH) <i>S/L</i>			\$ 216.00	Nett X
				\$ 647.70	
	Labour Charge				
	Panel Beating			\$ 1,400.00	600/-
	Spray Painting Charge			\$ 200.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Remove/Refix Cushion & Upholstery <i>Rear</i>			\$ 150.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	NH
	Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
	Rear Wheel Alignment			\$ 120.00	60/-
	Re-set Rear ABS System			\$ 200.00	150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	
	TOTAL LABOUR			\$ 3,820.00	
	ESTIMATE TOTAL			\$ 10,242.14	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17/08/2019 @ 1130am

Not Andrew

L/Sunil

6 days.