



ASS. REC. BY:

REF: 4161

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV. REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJS 41P2J Yr Regn: 08, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 7m Vio c.c. 1497Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 139113 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NR053149305125571Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD / A/Rlm orTyre Size: F: 185/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 17/8/19 D.O.I. 19/8/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to30/9 11pm @ 5100k email to confirm read @ 7692.06, 75%

- RECEIVED 11 SEP 2019

Date/Time, File Pass to?

☐

: Prell. Report

11/03/19 Final☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Transportation: 250  
S + RS. SI 11Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Fuel

Others

TOTAL

261

Report Format:

Lump Sum / L.B. (\$

MER-TP5100

**PRE-REPAIR INSPECTION REQUEST – SJS7509E vs SLF7509E on 17.08.2019**

From: Parthiban, Theerthan  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinnul, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subram  
Sent: 8/19/2019 3:37:17 PM  
Attachments: 20190819115413445.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Claim no : 8514667455SG003  
Case Owner : NORSIAH BTE MD NOOR

If you have any queries/concerns, please let us know.  
Kindly assist to assign **Mr Kenneth Kong** as Single Joint Expert as requested.

Thank you.

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001208558 Ext: 1002217  
Theerthan.Parthiban@aig.com | www.aig.com.sg

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**This message is from an external sender; be cautious with links and attachments.**

Dear Sir

Our client has agreed to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,  
Janice Kee  
c/o Teo Keng Siang LLC  
111 North Bridge Road,  
#29-07/08 Peninsula Plaza,  
Singapore 179098  
Tel: 6333 4222 Fax: 6333 5676

From: Parthiban, Theerthan <Theerthan.Parthiban@aig.com>  
Sent: Monday, August 19, 2019 2:20 PM  
To: janice.kee@kstoptr.com  
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinnul <Yinnul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahxin.Tong@aig.com>  
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF7509E AND SJS7509E ON 17.08.2019

Without Prejudice

Your Reference : TKSF/M492-ACC-42350.19/sf  
Our Reference : 8514667455SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor      | Company Name                           |
|-----------------------|----------------------------------------|
| AIG In House Surveyor | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee  | Priority Services                      |
| Jeffrey Ong Leng Kiat | Priority Services                      |
| Jimmy Lee             | Priority Services                      |
| EC Looi               | Automobile Inspection Services Pte Ltd |

|                          |                              |
|--------------------------|------------------------------|
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd   |
| Ng You Han               | Formteam Adjusters Pte Ltd   |
| Soon HanXin (Gary)       | Formteam Adjusters Pte Ltd   |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd   |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd   |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd |
| Marcus Chua              | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd |
| Adrian Ling              | LKK Auto Consultants Pte Ltd |
| Mohammed Raul            | LKK Auto Consultants Pte Ltd |
| Kenneth Kong             | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Theerthar R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001206596 Ext: 1002217  
Theerthar.Parthiban@aig.com | [www.aig.com.sg](http://www.aig.com.sg)

#### IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**From:** Janice Kee (<mailto:janice.kee@kzteqtr.com>)  
**Sent:** Monday, August 19, 2019 11:56 AM  
**To:** Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Hor, Yinrul  
**Cc:** Anthony Cheong  
**Subject:** [EXTERNAL] Pre Repair Survey for S35 4192 J (Your Ref: SLF 7509 E Our Ref: TKSF/M492-ACC-42350.19/sf)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,  
Janice Kee  
c/o Teo Keng Siang LLC  
111 North Bridge Road,  
#29-07/08 Peninsula Plaza,  
Singapore 179098  
Tel: 6333 4222 Fax: 6333 5676

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098  
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688

Email: KSTEOCO@singnet.com.sg

(FAX – NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-42350.19/sf (mc)  
Your Ref : SLF 7509 E  
Date : 19 August 2019

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)

Fax : 6333 5676 / 6333 5688

Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way  
#07-16 Singapore 079120  
Attn: Motor Claims Dept

**WITHOUT PREJUDICE**

**BY PDX# 8181 & FAX 6835 7416 ONLY**

Cc: Tan Boon Tiong (Owner & Driver)  
Blk 682A Edgedale Plains  
#11-757  
Singapore 821682

**BY POST ONLY**

**PDX Intercompany Exchange Pte Ltd**



010808762307

FROM TEO KENG SIANG LLC  
PDX Box No. 8902

Dear Sirs

**RE: ACCIDENT INVOLVING SJS 4192 J / SLF 7509 E ON 17/8/19 ALONG BUANGKOK DR SLIP ROAD TO SENGKANG EAST DR**

We are instructed by Lau Han Leong to notify you of a road traffic accident on 17/8/19 at about 13:50 hours at **ALONG BUANGKOK DR SLIP ROAD TO SENGKANG EAST DR** involving our client's vehicle registration number **SJS 4192 J** and vehicle registration number **SLF 7509 E** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SJS 4192 J** is now at the following workshop:-

**Massive Trading & Auto**  
Blk 5038 Ang Mo Kio Industrial Park 2  
#01-405  
Singapore 569541  
Contact: 9108 2728 Anthony

Yours faithfully,

**M/s Teo Keng Siang LLC**  
encs

**\*\*Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

\_\_\_\_\_  
Signature

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                         |
|----------------------------|-----------------------------------------|
| Date Of Report             | 19/08/2019 10:39                        |
| Date Of Accident           | 17/08/2019 13:50                        |
| Exact Location Of Accident | BUANGKOK DR SLIP RD TO SENGKANG EAST DR |
| Country/State of Loss      | SINGAPORE                               |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJS4192J             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | LAU HAN LEONG        |
| NRIC No                     | S1577830Z            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-97391461 |
| Alternative Phone No        | OTHERS-97391461      |

### Vehicle Particulars

|                                                                              |             |
|------------------------------------------------------------------------------|-------------|
| Manufacturer                                                                 | TOYOTA      |
| Model                                                                        | VIOS        |
| Exact Purpose for which vehicle was being used at time of accident           |             |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO          |
| If No, Please state action to be taken                                       | THIRD PARTY |
| Vehicle Category                                                             | PRIVATE CAR |

### Insurance Company

|                           |                                        |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY                            |
| Fleet Policy              | NO                                     |
| Policy Number             | 5111877185                             |
| Cover Note Number         |                                        |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | LAU JUN HONG         |
| NRIC No              | S9631057I            |
| Date Of Birth        | 31/08/1996           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 31/10/2018           |
| Driving Experience   | 0 YEAR AND 9 MONTH   |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-98537072 |
| Fax Number           |                      |
| Contact Number       |                      |
| Email Address        | NOEMAIL              |

|                                                     |                                     |
|-----------------------------------------------------|-------------------------------------|
| Address                                             | BLK 122 SENGKANG EAST WAY<br>#10-13 |
| Postcode                                            | 540122                              |
| Was driver an employee of the Insured's Company     | NO                                  |
| If No, Relationship of the Driver with the Insured  | CHILDREN                            |
| Vehicle Registration Number of Driver's Own Vehicle | -                                   |
|                                                     | -                                   |
| Insurance Company of Driver's Own Vehicle           | -                                   |
|                                                     | -                                   |
|                                                     | -                                   |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |                                          |
|---------------------------------------------------------------------------------------------|------------------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                                       |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                                        |
| Was any body injured in the Accident?                                                       | NO                                       |
| Was any injured conveyed to hospital by ambulance?                                          | NO                                       |
| Was any other material or property damaged?                                                 | YES                                      |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                       |
| Number of Passengers (Including Driver)                                                     | 3                                        |
| Passenger 1                                                                                 | NAME: : LAU HAN LEONG<br>GENDER: : MALE  |
| Passenger 2                                                                                 | NAME: : TOH SIEW TIN<br>GENDER: : FEMALE |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

ON 17 AUG 2019 ARD 1350HRS, I WAS TRAVELLING ALONG BUANGKOK DRIVE. AT THE SLIP RD TO SENGKANG EAST DRIVE, I STOPPED AT THE GIVE WAY LINE WAITING FOR THE MAIN RD TRAFFIC TO CLEAR. WHILE WAITING, SUDDENLY I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I GOT OUT OF MY VEHICLE AND REALISED THAT VEH B (SLF 7509 E) HAD COLLIDED INTO MY VEHICLE REAR PORTION. I WISH TO STATE THAT MY PARENTS MR LAU HAN LEONG I/C S1577830Z AND MDM TOH SIEW TIN I/C S1811448H WAS IN THE CAR WITH ME AT THE TIME OF THIS ACCIDENT.

#### Attachment(s)

|                                               |                             |
|-----------------------------------------------|-----------------------------|
| Are accident photos available for attachment? | YES                         |
| Was there any video captured by Car Camera?   | YES                         |
| Remarks/ Reasons:                             | KIV, SUBMIT BY CLAIMANT W/S |
| Was there any audio recorded?                 | NO                          |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | SLF7509E    |
| Vehicle Make/Model/Colour   | TOYOTA WISH |
| Details Of Properties       |             |
| Vehicle Category            | PRIVATE CAR |

|                                     |                |
|-------------------------------------|----------------|
| Name of Driver                      | TAN BOON TIONG |
| NRIC/Passport Number                |                |
| Contact Number                      | 97295738       |
| Address                             |                |
| Postcode                            |                |
| Insurance Company Name              |                |
| Nature Of Damage                    |                |
| No. Of Passenger (Including Driver) |                |

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claim;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17 Aug 2019 @ ord 1350hrs, I was travelling along Buangkok Drive. At the slip rd to Sengkang East Drive, I stopped at the give way line waiting for the main rd traffic to clear. While waiting, suddenly I felt an strong impact from the rear of my vehicle. I got out of my vehicle and realised that veh B (SLF7509E) had collided into my vehicle rear portion. I wish to state that my parents Mr Han Han heong, 'c 15F18302 and Mdm Toh Siew Tim, 'c 1811448H' was in the car with me at the time of this accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Lau Han Leong  
Blk 122 Sengkang East Way  
#10-13  
Singapore 540122

Vehicle No : SJS 4192 J  
Make : Toyota Vios  
Year : 2009

*Not Authorized*  
*61 Sur & 5100h*  
*Resurvey After Painting*  
*7 days*

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |                                         |          |            |            |
|-------|-----------------------------------------|----------|------------|------------|
| 1 pc  | Rear boot lid                           |          | \$649.10   | —          |
| 1 pc  | Rear boot lid inner lock                |          | \$165.70   | —          |
| 1 pc  | Rear boot lid emblem " Logo "           |          | \$55.80    | —          |
| 1 pc  | Rear boot lid emblem " Vios "           |          | \$53.20    | —          |
| 1 pc  | Rear boot lid emblem " J "              |          | \$35.10    | —          |
| 1 pc  | Rear boot lid outer handle              |          | \$149.10   | X          |
| 1 pc  | Rear boot rubber                        |          | \$219.50   | 50h        |
| 2 pcs | Rear no plate lamp                      | \$79.40  | \$158.80   | X          |
| 2 pcs | Rear tail-lamp assy                     | \$354.90 | \$709.80   | ✓          |
| 2 pcs | Rear tail-lamp panel                    | \$124.80 | \$249.60   | ✓          |
| 1 pc  | Rear end panel                          |          | \$587.20   | ✓          |
| 1 pc  | Rear end panel inner garnish            |          | \$129.80   | ✓          |
| 1 pc  | Rear spare tyre cover board             |          | \$295.10   | ✓          |
| 2 pcs | Rear boot floor panel sponge ( side )   |          | \$404.20   | ✓          |
| 1 pc  | Rear boot floor panel sponge ( centre ) |          | \$272.10   | ✓          |
| 1 pc  | Rear bumper                             |          | \$429.55   | ✓          |
| 2 pcs | Rear bumper side retainer               |          | \$150.40   | ✓          |
| 2 pcs | Rear bumper bracket                     |          | \$171.00   | ✓          |
| 2 pcs | Rear bumper reflector                   |          | \$150.60   | ✓          |
| 2 pcs | Rear fender inner trim                  |          | \$816.20   | ✓          |
| 1 pc  | Rear exhaust silencer                   |          | \$550.90   | ✓          |
|       |                                         |          | \$6,402.75 |            |
|       |                                         |          | Less 25 %  | \$1,600.69 |
|       |                                         |          |            | \$4,802.06 |

## S. Nett Item

|        |                     |
|--------|---------------------|
| 1 pc   | Rear reverse sensor |
| 1 pc   | Rear no plate       |
| 20 pcs | Clip                |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|             |            |   |
|-------------|------------|---|
|             | \$200.00   | ✓ |
|             | \$40.00    | ✓ |
| \$2.00      | \$40.00    | ✓ |
| balance c/f | \$5,082.06 |   |

SJS 4192 J

balance b/f \$5,082.06

Labour Charges

Remove/renew the above parts including knocking, welding & cutting

\$1,200.00

9001

To putty & spray paint on rear accident affected portion.

\$1,200.00

10001

Check/reconnect wiring.

\$40.00

201

To spray anti rust on accident affected portion.

\$120.00

601

Remove/refit rear boot upholstery to facilitate repair

\$150.00

1001

Total

\$7,792.06

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19014455/KQD3N2

Date: 09/09/2019

### REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 2100480935   |
| Claimant Vehicle No : | SJS4192J                             | Insured Vehicle No : | SLF7509E     |
| Date of Loss:         | 17/08/2019                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 8514667455SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJS4192J                     | Engine No:  | 1NZX953362        |
| Make & Model:               | TOYOTA VIOS, 1.5 (A)         | Chassis No: | MR053HY9305125571 |
| Reg. Date:                  | 17/08/2009 (Man. Year: 2009) | Odometer:   | 139113 km         |
| Colour:                     | Metallic Silver              |             |                   |
| Engine Capacity:            | 1497 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 185/60R15        | Rear Tyre Size:  | 185/60R15        |
| Front Left Side:  | Bridgestone 8 mm | Rear Left Side:  | Bridgestone 8 mm |
| Front Right Side: | Bridgestone 8 mm | Rear Right Side: | Bridgestone 8 mm |

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

|                                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                     | 5,082.06        | 4,675.66        | 406.40          | 8.00         |
| Miscellaneous Items                       | 0.00            | 0.00            | 0.00            |              |
| Labour                                    | 2,710.00        | 2,080.00        | 630.00          | 23.25        |
| Paintwork Labour                          | 0.00            | 0.00            | 0.00            |              |
| Towing                                    | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>7,792.06</b> | <b>6,755.66</b> | <b>1,036.40</b> | <b>13.30</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                 | <b>5,100.00</b> |                 |              |
| <b>Nett Amount (\$\$)</b>                 | <b>7,792.06</b> | <b>5,100.00</b> | <b>2,692.06</b> | <b>34.55</b> |

### INSPECTION

|                             |            |                                         |
|-----------------------------|------------|-----------------------------------------|
| Date of Assignment:         | 19/08/2019 |                                         |
| Date Inspected:             | 19/08/2019 | Inspected At:                           |
|                             |            | Massive Trading & Auto                  |
|                             |            | Blk 5038 #01-405, Ang Mo Kio Industrial |
|                             |            | Pk 2                                    |
|                             |            | Singapore 569541                        |
| Estimated Period of Repair: | 7.0 days   |                                         |

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition                | Repairer's | Amount     |
|-----|-----|----------|----------------------------------------|--------------------------|------------|------------|
| 1   | 1   |          | *REAR BOOT LID                         | Buckled                  | 649.10 FL  | *649.10 FL |
| 2   | 1   |          | *REAR BOOT LID INNER LOCK              | Dented                   | 165.70 FL  | *165.70 FL |
| 3   | 1   |          | *REAR BOOT LID EMBLEM LOGO             | Necessary                | 55.80 FL   | *55.80 FL  |
| 4   | 1   |          | *REAR BOOT LID EMBLEM VIOS             | Necessary                | 53.20 FL   | *53.20 FL  |
| 5   | 1   |          | *REAR BOOT LID EMBLEM J                | Necessary                | 35.10 FL   | *35.10 FL  |
| 6   | 1   |          | *REAR BOOT LID OUTER HANDLE            | Serviceable              | 149.10 FL  | *- FL      |
| 7   | 2   |          | *REAR NO PLATE LAMP                    | Serviceable              | 158.80 FL  | *- FL      |
| 8   | 2   |          | *REAR TAIL-LAMP ASSY                   | Cracked                  | 709.80 FL  | *709.80 FL |
| 9   | 2   |          | *REAR TAIL-LAMP PANEL                  | Bent                     | 249.60 FL  | *249.60 FL |
| 10  | 1   |          | *REAR END PANEL                        | Bent                     | 587.20 FL  | *587.20 FL |
| 11  | 1   |          | *REAR END PANEL INNER GARNISH          | Dented                   | 129.80 FL  | *129.80 FL |
| 12  | 1   |          | *REAR SPARE TYRE COVER BOARD           | Cracked                  | 295.10 FL  | *295.10 FL |
| 13  | 2   |          | *REAR BOOT FLOOR PANEL SPONGE (SIDE)   | Dented/Deformed          | 404.20 FL  | *404.20 FL |
| 14  | 1   |          | *REAR BOOT FLOOR PANEL SPONGE (CENTRE) | Cracked                  | 272.10 FL  | *272.10 FL |
| 15  | 1   |          | *REAR BUMPER                           | Bent                     | 429.55 FL  | *429.55 FL |
| 16  | 2   |          | *REAR BUMPER SIDE RETAINER             | Distorted                | 150.40 FL  | *150.40 FL |
| 17  | 1   |          | *REAR BUMPER BRACKET                   | O/s Bent                 | 171.00 FL  | *85.50 FL  |
| 18  | 1   |          | *REAR BUMPER REFLECTOR                 | O/s Cracked              | 150.60 FL  | *75.30 FL  |
| 19  | 2   |          | *REAR FENDER INNER TRIM                | N/s Deformed/O/s Cracked | 816.20 FL  | *816.20 FL |
| 20  | 1   |          | *REAR EXHAUST SILENCER                 | Bent                     | 550.90 FL  | *550.90 FL |
| 21  | 1   |          | *REAR REVERSE SENSOR                   | Dented                   | 200.00 FS  | *200.00 FS |
| 22  | 1   |          | *REAR NO PLATE                         | Dented                   | 40.00 FS   | *40.00 FS  |
| 23  | 20  |          | *CLIP                                  | Necessary                | 40.00 FS   | *40.00 FS  |
| 24  | 1   |          | *REAR BOOT RUBBER (50%)                | Dented/Cut               | 164.62 FS  | *109.75 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>6,627.87</b> | <b>6,104.30</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | <b>1,545.81</b> | <b>1,428.64</b> |
| <b>Total Parts (S\$)</b>                                  | <b>5,082.06</b> | <b>4,675.66</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                       | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                   |          |                 |                 |
| 1                               | REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING | New      | 1,200.00        | 900.00          |
| 2                               | TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION          | New      | 1,200.00        | 1,000.00        |
| 3                               | CHECK/RECONNECT WIRING                                            | New      | 40.00           | 20.00           |
| 4                               | TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION                   | New      | 120.00          | 60.00           |
| 5                               | REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR            | New      | 150.00          | 100.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                   |          | <b>2,710.00</b> | <b>2,080.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >