



Automobile Integrated Management Pte Ltd
 Co. & G.S.T. Reg no. 201605297G
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933
 Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2019025/OD/YN5078Z-08.08.2019

Vehicle number: YN5078Z

Vehicle Made & Model: MITSUBISHI FUSO

Items	Qty	List Items	Amount \$
1	2	Rear taillamps - L/R @ 291.33	582.66
2	1	Rear spare wheel carrier ?	341.66
3	2	Rear shock absorbers - L/R @ 221.50 ?	443.00
4	2	Rear wheel guards - L/R @ 381.50	763.00
5	1 set	Rear wire harness ?	1,455.91
6	4	Rear brake hoses @ 89.50 ?	358.00
7	1 set	Rear handbrake cable ?	261.45
8	1	Rear gear box mounting ?	181.95
9	1	Rear diesel tank X	1,210.50
10	1	Rear diesel tank float ?	214.95
11	1	Rear diesel tank hose ?	142.65
12	1	Rear diesel tank filter ?	182.60
13	1	Rear diesel pump assy ?	1,150.50
14	1	Rear clutch pump ?	255.30
15	1	Rear windscreen glass ?	260.93
16	1	Rear windscreen rubber ?	180.91
17	2	Rear cabin mountings - L/R @ 271.50 ?	543.00
18	2	Rear cabin safety locks - L/R @ 245.50 ?	491.00
19	1	Rear cabin lock carrier ?	180.95
20	1	Air cleaner box assy ?	661.59
21	1	Air cleaner box hose ?	280.43
22	1	Air cleaner resonator X	215.30
23	1	Air cleaner intake duct X	441.50
24	1	Alternator assy X	1,381.11
25	1	Alternator belt X	142.60
26	1	Air con compressor X	1,055.90
27	1	Air con discharge pipe X	441.60
28	1	Air con suction pipe X	421.50
29	1	Radiator assy X	1,899.63
30	1	Radiator top hose X	89.62
31	1	Radiator bottom hose X	91.50
32	1	Radiator fan cowling X	231.45
33	1	Radiator fan blade X	191.65
34	1	Radiator fan clutch X	580.95
35	1	Radiator sub tank X	160.95
36	1	Starter assy X	1,095.50
37	2	Engine mountings - L/R @ 189.65 X	379.30

38	1 set	Engine wire harness assy ?		2,251.43
39	1	E.C.U control unit X		3,551.92
40	1	S.R.S control unit X		1,081.43
41	2	Battery cables @ 291.50 X		583.00
42	2	Front door glass outer mouldings - L/R @ 142.63 X		285.26
43	2	Front door glass run channels - L/R @ 180.92 X		361.84
44	2	Front door outer handles - L/R @ 126.20 X		252.40
45	2	Front door glass - L/R @ 280.91 X		561.82
46	2	Front door w/strips - L/R @ 141.20 X		282.40
47	2	Front door outer garnishes - L/R @ 263.21 X		526.42
48	2	Front wheel guards - L/R @ 286.92 X		572.84
			Sub-total	<u>29,273.76</u>
			Less 25%	<u>7,318.44</u>
			Total List	21,955.32

Special Nett Items

49	1 set	Rear canopy box assy / <i>Burnt</i>		12,000.00 ?
50	2	Rear chassis wooden planks - L/R @ 480 / <i>Burnt.</i>		960.00
51	1	Rear no. plate X		40.00
52	1	Rear licence lamp ?		80.00
53	1 set	Rear reverse sensor ?		250.00
54	4	Rear tyres - L/R @ 280 <i>LHX</i>		1,120.00
55	2	Rear spare tyres @ 280 <i>RH - Burnt.</i>		560.00
56	2	Rear spare wheels @ 180 ?		360.00
57	1 set	Hydraulic & electrical liftgate assy set / <i>Burnt.</i>		18,500.00 ?
58	2	Front tyres - L/R @ 280 X		560.00
59	1	Front speed gear box assy - USED X		2,500.00
60	2	Battery @ 350 X		700.00
			Total Special Nett	<u>37,630.00</u>

Vehicle number: YN5078Z

Vehicle Made & Model: MITSUBISHI FUSO

Labour charges

61	To check F/R electrical wiring / replacing wire harness	400.00	100
62	Towing charges	300.00	?
63	To remove, reinstall & realign rear canopy	800.00	200
64	To remove, reinstall & realign liftgate	650.00	100
65	To diagnos, erase fault memory after repair	450.00	?
66	To respray undercoating	150.00	X
67	To remove, refix A/C condenser & refill A/C gas	180.00	X
68	To remove, refix engine parts	450.00	X
69	To remove, refix diesel tank	120.00	?
70	To respray painting and etc	1,200.00	600
71	Panel beating, cut, weld remove & replacing above parts	1,200.00	600
	Total Labour	5,900.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

65,485.32

*Hidden, inaccessible damage parts shall be submitted through supplementary

10 Days.

Lumpsum repair.

After repair photos.

Guo Qiang - 82880282

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: