



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20190808/0929	LOCATION OF FIRE:		
FIRE REPORTED ON : 08 August 2019	Open space near Block 374		
TIME OF CALL : 23:19:24 hrs	Bukit Batok Street 31		
STATION COVERAGE : Bukit Batok Fire Station	Singapore 650374		
2. INCIDENT INFORMATION			
FIRE INVOLVED: A ceiling light at the cargo compartment of a Mitsubishi Fuso Canter lorry (YN5078Z).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet and a 38mm hose line jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the ceiling light)			
DAMAGE SUSTAINED: As a result of the fire, the ceiling light was damaged. The contents of the cargo compartment comprising a personal mobility device (PMD), two hand push trolleys, several printer toner cartridges and other items were also damaged. The ceiling, a sliding door, walls and liftgate, as well as other parts of the lorry, sustained heat and smoke damage. The tentage adjacent to the lorry sustained heat damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
CINDY HAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.