

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJL5922A

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 16/08/2019

TP Veh Reg No: SCL190K

Estimate No: ES1991886/YISHUN

Date: 19 Aug 2019

Policy No: DMPG18005625

Veh Reg No: SJL5922A

Make/Model: HONDA JAZZ 1.3L AT

Chassis No: JHMGE68509S209856

Engine No: L13Z11009850

Reg. Date: 03/12/2008

Estimate Repair Cost to Vehicle No :SJL5922A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	523.40	1 PC	523.40	—
2 REAR BUMPER SIDE RETAINERS	18.30	2 PCS	36.60	—
3 REAR BUMPER TOW COVER	19.60	1 PC	19.60	—
4 REAR BUMPER CLIPS	3.70	6 PCS	22.20	—
5 REAR CENTRE PANEL	276.40	1 PC	276.40	—
6 REAR CENTRE PANEL TOP GARNISH	68.50	1 PC	68.50	—
7 TAILLAMPS	238.50	2 PCS	477.00	—
8 REAR TAILGATE	781.50	1 PC	781.50	—
9 TAILGATE EMBLEM (JAZZ)	29.80	1 PC	29.80	—
10 TAILGATE INNER LOCK	189.50	1 PC	189.50	—
11 TAILGATE INNER RUBBER	93.20	1 PC	93.20	50.60
12 REAR TOOL BOX	129.10	1 PC	129.10	—
13 REAR SPARE TYRE TOP BOARD	190.50	1 PC	190.50	—
14 REAR SPARE TYRE COMPARTMENT	751.40	1 PC	751.40	—
15 REAR FENDER INNER GARNISHS	250.80	2 PCS	501.60	—
16 REAR WINDSCREEN GLASS MOULDING	90.70	1 PC	90.70	—
			4,181.00	
		Less 20%	836.20	3,344.80
Special Net				
17 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	—
18 REVERSE SENSOR	200.00	1 PC	200.00	—
			240.00	240.00
Labour				
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	—
20 REMOVE & REFIX REAR BUMPER	1,200.00	1 LA	1,200.00	1100
ASSY, TAILLAMPS, TAILGATE ASSY, REAR WIPER, THIRD BRAKE LIGHT, CUT, WELD & RENEW REAR PANEL, REAR SPARE TYRE COMPARTMENT, KNOCK & REPAIR REAR RH CHASSIS, REAR BOTH FENDERS & REALIGN THE SAME				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 16/08/2019
 TP Veh Reg No: SCL190K

Estimate No: ES1991886/YISHUN
 Date: 19 Aug 2019
 Policy No: DMPG18005625
 Veh Reg No: SJL5922A
 Make/Model: HONDA JAZZ 1.3L AT
 Chassis No: JHMGE68509S209856
 Engine No: L13Z11009850
 Reg. Date: 03/12/2008

Estimate Repair Cost to Vehicle No :SJL5922A

Description	U/Price	Quantity	List Price	Amount
21 REMOVE & REFIX REAR GARNISHS,SEAT,SPEAKER & BOARD,ETC	100.00	1 LA	100.00	✓
22 PUTTY & RESPRAY ON REAR BUMPER,TAILGATE,REAR FENDERS,REAR PANEL,REAR SPARE TYRE COMPARTMENT & REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000
23 REMOVE & REFIX REAR EXHAUST PIPE & CHECK LEAKING	60.00	1 LA	60.00	✓
24 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,640.00	2,640.00
			Total	S\$ 6,224.80
			Add GST @ 7%	435.74
			Total Amount Payable	S\$ 6,660.54

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Pack
 less 20%
 \$3897.30
 779.46
 \$3117.84
 46.60
 240
 2440
 \$5844.44
 45 \$4650 ✓ ok