

INS. CASE OWNER: CHAN KUAN HENG

CC4/AIG19014468/ K ha3

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

19/8/2019

Date / Time: 19/08/2019

Registered in Merimen: 19/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No.: SMG 7986T

Claim No.: 8313694135G

Name of Insured: Lee Smei Hau

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A: 15/08/2019

Place of Accident:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final? Yes / No

SMJ 8172C

INSRS:
WSP: HUI YANG
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SMJ 8172C - X	SMG 7986T - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
26/08/19	- PLUS FOLLOWED. OI RATE-ENDED TP.		Call OI:	
	- SEND LETTER TO OI.		After call ltr to OI:	26/08/19 - vic
	- BUAH CATERING CLERK		Documentation Check List:	Handler Typist
	- PINKETED		Notification ltr (if non-pickup)	☐
02/10/19	- TP LOD IN BY BUAH		After call ltr to OI:	☒
	- UPLOAD LA IN WORKMEN		Authorisation To Act:	☒
			Release Voucher:	☒
05/12/19	- MG APPROVED WORKMEN.		Final Repair Bill:	☒
10/12/19	- SEND ACCEPTANCE BUAH TO TP		Car Rental Invoice:	☒
11/12/19	- HU BOSS IN ORDER.		Towing Invoice:	☐
	- TO CLOSE		LTA / GIA:	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:		Confirm by:
FINALIZATION		Date/Time:	Confirm with:		Confirm by:
Repair Cost:	RIP	S\$ 3,228.56	(2 days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:		Email ☒ Call ☐
Final Liability:	%	100	(Assessed / Assessed) BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
Repair Cost: (w/ GST)	S\$	3,454.56	(OI RATE-ENDED TP)		
Loss of Rental (LOR) (w/ GST)	S\$	214.00	(2 days) X \$100		
Loss of Use (LOU):	S\$	-	(\$ x days)		
Loss of Income (LOI):	S\$	-	(\$ x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	S\$	2.00			
Medical:	S\$	-			
Disbursement:	S\$	-	(e.g. Tow/ Independent)		
Legal Cost	S\$	-			
Total:	S\$	3,670.56	Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:		Email ☐ Call ☐
Payee 1:	S\$	3,670.56	Name 1:	HUI YANG MOTOR PTE LTD	
Payee 2: (Strike if N.A.)	S\$	-	Name 2:	-	
Payee 3: (Strike if N.A.)	S\$	-	Name 3:	-	

ASS. REC. BY:

REF: AIG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMJ 8172C Yr Regn: 03, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

27384

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI 1312930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

215/80R16

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

15/8/19

D.O.I.

19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Fix parts to

P/P \$3,228.60

CRAB: \$4,286.60 (57%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

KH 辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

A/C mon
after 11am
19/08
(LKK)

15/08/2019

Owner: MIKMEG

Not Notation
1-21, 11 Sep 8?

8 3228.56

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SMJ8172C

1pc	rear tailgate	By \$	1,100.90	✓
1pc	rear tailgate "HONDA" logo	na \$	27.00	X
1pc	rear tailgate "VEZEL" emble	na \$	55.10	✓
1pc	rear tailgate "HYBRID" emblem	na \$	68.50	X
1set	rear tailgate windscreen moulding	na \$	120.00	✓
1pc	rear tailgate outer garnish	na \$	380.50	X
2pcs	rear tailgate reflector @\$350.80	na \$	701.60	X
1pc	rear tailgate inner lock	Ad \$	198.40	✓
1pc	rear tailgate inner rubber	na \$	135.20	X
1pc	rear tailgate inner garnish	na \$	252.70	X
1pc	rear tailgate inner handle garnish	na \$	20.70	X
1pc	rear bumper	na \$	986.30	✓
2pcs	rear bumper side bumper @\$195.20	na \$	390.40	X
2pcs	rear bumper side retainer @\$24.80	na \$	49.60	X
2pcs	rear bumper reflector @\$151.50	na \$	303.00	X
1pc	rear end panel	na \$	530.90	X
1pc	rear end panel inner garnish	na \$	109.90	X
1pc	rear end panel inner sensor	na \$	195.50	X
1pc	rear end panel outer sensor	na \$	180.25	X
		\$	5,806.45	
less 20%		\$	1,161.29	
		\$	4,645.16	
1set	rear reverse sensor	Shay s.nett \$	280.00	200.00
	remove & refix rear windscreen glass	\$	120.00	✓
	wiring	\$	200.00	200
	tuffkote	\$	150.00	300
	sealant	\$	120.00	400
	spray painting	\$	1,000.00	400
	labour charges	\$	1,000.00	450
Total		\$	7,515.16	

LKK Auto Consultants hereby notify the Repairer of the following:

- To reserve before/after spray painting
- To reserve damaged part(s) having reserve
- Parts price are subject to change
- Their policy survey is on a "Without Prejudice" basis
- No right modification is allowed
- All necessary repair should be reserved and approved by the Insurance Company



辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

15/08/2019

Owner: MIKMEG

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SMJ8172C

1pc	rear tailgate	Rs	\$ 1,100.90	✓
1pc	rear tailgate "HONDA" logo	Rs	\$ 27.00	X
1pc	rear tailgate "VEZEL" emble	Rs	\$ 55.10	✓
1pc	rear tailgate "HYBRID" emblem	Rs	\$ 68.50	X
1set	rear tailgate windscreen moulding	Rs	\$ 120.00	✓
1pc	rear tailgate outer garnish	Rs	\$ 380.50	X
2pcs	rear tailgate reflector @\$350.80	Rs	\$ 701.60	X
1pc	rear tailgate inner lock		\$ 198.40	?
1pc	rear tailgate inner rubber	Rs	\$ 135.20	X
1pc	rear tailgate inner garnish		\$ 252.70	?
1pc	rear tailgate inner handle garnish	Rs	\$ 20.70	X
1pc	rear bumper	Rs	\$ 986.30	✓
2pcs	rear bumper side bumper @\$195.20	Rs	\$ 390.40	X
2pcs	rear bumper side retainer @\$24.80	Rs	\$ 49.60	X
2pcs	rear bumper reflector @\$151.50	Rs	\$ 303.00	X
1pc	rear end panel		\$ 530.90	?
1pc	rear end panel inner garnish		\$ 109.90	?
1pc	rear end panel inner sensor		\$ 195.50	?
1pc	rear end panel outer sensor		\$ 180.25	?

\$ 5,806.45

less 20%

\$ 1,161.29

\$ 4,645.16

1set	rear reverse sensor	Rs	\$ 280.00	2000
	remove & refix rear windscreen glass		\$ 120.00	✓
	wiring		\$ 200.00	200
	tuffkote		\$ 150.00	?
	sealant		\$ 120.00	400
	spray painting		\$ 1,000.00	400
	labour charges		\$ 1,000.00	?
	Total		\$ 7,515.16	

Rs	\$ 280.00	2000
	\$ 120.00	✓
	\$ 200.00	200
	\$ 150.00	?
	\$ 120.00	400
	\$ 1,000.00	400
	\$ 1,000.00	?
	\$ 7,515.16	

LINK Auto Consultants hereby notify the Repairer of the following:

- To remove (refinish) spray painting
- To replace damaged parts using reserves
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No major modification(s) is allowed
- Customer's car should not be returned until it is approved by the Insurance Company

Prepared by: [Signature]
Date: [Signature]



AIQ mon
after 11am
19/08
(LKK)

Not in the car
1-hi, 61 Lmp & ?

TP Claim for SMJ8172C against SMG7986T / DOA: 15/08/2019

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 8/19/2019 8:42:13 AM
Attachments:  SKM_C28719081516010.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

9.42am @ 19/8/19
vehicle not in
person @ Bel

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Thursday, August 15, 2019 3:57 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] TP Claim for SMJ8172C against SMG7986T / DOA: 15/08/2019
Importance: High

This message is from an external sender; be cautious with links and attachments.

Hi,

We would like to arrange 19/08/2019 after 11 AM to survey the vehicle SMJ8172C.

Thank you & Regards,
Sandra

Thank you & Regards,
Bel
Tel: 6451 5752

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SMJ8172C (8343696943SG)**
[SMG7986T]
TP
CHEO THIAM HONG
Aug 15 2019 8:00AM
[LEE SWEE HAR]
Hui Yang Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/12/2019 17:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3670.56) - SMJ8172C - Claim Handler: Chan, Kian-Meng

Approved:3670.56.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	\$53,228.56 Edit Estimates	\$53,228.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LEE SWEE HAR, ID: S1267943B		
Main Claimant:	CHEO THIAM HONG, ID: S8817593Z		
Vehicle Reg. No.:	SMJ8172C	Date of Loss:	15/08/2019 08:00 - :59 [5 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8343696943SG	Policy/Cover Note No.:	1800153607 (Comprehensive)
Vehicle Reg. No. (Insured):	SMG7986T	Policy No. (Claimant):	5108324308
	Excess:		
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/08/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
AIG_SG_EXPRESS (05/12/2019): Alert - Adj Mandate Approved (\$53670.56) - SMJ8172C - Claim Handler: Chan, Kian-...			
ALL ASSOCIATED TASKS		View All	Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SMJ8172C (8343696943SG)
[SMG7986T]

TP
CHEO THIAM HONG
Aug 15 2019 8:00AM
[LEE SWEE HAR]
Hui Yang Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences				
			1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
			1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/19 16:32	Adjuster Immediate Advice		Load HTM
Photos/Images				
			3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/19 16:23	Odometer Reading		Load JPG
2	02/10/19 16:23	Chassis Number		Load JPG
3	02/10/19 16:23	General View		Load JPG
4	02/10/19 16:23	General View		Load JPG
5	02/10/19 16:23	General View		Load JPG
6	02/10/19 16:23	General View		Load JPG
7	02/10/19 16:23	General View		Load JPG
8	02/10/19 16:23	General View		Load JPG
9	02/10/19 16:23	General View		Load JPG
10	02/10/19 16:23	General View		Load JPG
11	02/10/19 16:23	General View		Load JPG
12	02/10/19 16:23	General View		Load JPG
13	02/10/19 16:25	Reinspection Photo		Load JPG
14	02/10/19 16:25	Reinspection Photo		Load JPG
15	02/10/19 16:25	Reinspection Photo		Load JPG
16	02/10/19 16:25	Reinspection Photo		Load JPG
17	02/10/19 16:25	Reinspection Photo		Load JPG
18	02/10/19 16:25	Reinspection Photo		Load JPG
19	02/10/19 16:25	Reinspection Photo		Load JPG
20	02/10/19 16:25	Reinspection Photo		Load JPG
Documentation				
			1 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/19 18:13	ACKNOWLEDGEMENT EMAIL TO AIG DD 19.08.2019		Load PDF
2	19/08/19 18:13	TP ESTIMATE + TP GIA REPORT		Load PDF
3	19/08/19 18:13	EMAIL FROM AIG DD 19.08.2019		Load PDF
4	23/08/19 10:26	TP ESTIMATE - MARKED		Load PDF
5	26/08/19 10:27	LETTER TO OI		Load PDF
6	02/10/19 16:18	TP ESTIMATE - FINALIZED		Load PDF
7	02/10/19 16:19	TP LOD		Load PDF
8	27/12/19 08:36	WORKSHOP INVOICE		Load PDF
9	27/12/19 08:36	AUTHORISATION TO ACT FORM		Load PDF
10	27/12/19 08:36	Release Voucher		Load PDF
11	27/12/19 08:36	RENTAL RECEIPT		Load PDF
12	27/12/19 08:36	LOD		Load PDF
13	27/12/19 08:36	GIA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/08/19 10:33	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMG7986T (Insd veh)	Model:	HONDA VEZEL 1.5 (A)
	SMJ8172C (TP veh)		
Date of Accident:	15/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	8,041.22
Final Repair Cost	:	\$	3,454.56
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	214.00 2 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,670.56

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hui Yang Motor Pte Ltd	:	\$ 3,670.56
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

27 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014468/KHA3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800153607
 Claimant: SMJ8172C Insured Vehicle No: SMG7986T
 Vehicle No: SMJ8172C
 Date of Loss: 15/08/2019 Nature of Claim: TP Claim No: 8343696943SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ8172C
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: HIDDEN
 Reg. Date: 01/03/2019 (Man. Year: 2019) Chassis No: RU11312930
 Colour: Metallic Black Odometer: 27384 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,045.16	2,208.56	2,836.60	56.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,020.00	1,450.00	58.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,515.16	3,228.56	4,286.60	57.04
+ GST 7.00/7.00% (S\$)	526.06	226.00	300.06	57.04
Nett Amount (S\$)	8,041.22	3,454.56	4,586.66	57.04
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,670.56		

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 19/08/2019 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming
 AutoCare
 Singapore 575721
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
2	1		*REAR TAILGATE HONDA LOGO	Not Necessary	27.00 FL	*- FL
3	1		*REAR TAILGATE VEZEL EMBLE	Necessary	55.10 FL	*55.10 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	68.50 FL	*- FL
5	1		*SET REAR TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
6	1		*REAR TAILGATE OUTER GARNISH	Serviceable	380.50 FL	*- FL
7	2		*REAR TAILGATE REFLECTOR	Serviceable	701.60 FL	*- FL
8	1		*REAR TAILGATE INNER LOCK	Dented	198.40 FL	*198.40 FL
9	1		*REAR TAILGATE INNER RUBBER	Serviceable	135.20 FL	*- FL
10	1		*REAR TAILGATE INNER GARNISH	Serviceable	252.70 FL	*- FL
11	1		*REAR TAILGATE INNER HANDLE GARNISH	Serviceable	20.70 FL	*- FL
12	1		*REAR BUMPER	Buckled	986.30 FL	*986.30 FL
13	2		*REAR BUMPER SIDE BUMPER	Serviceable	390.40 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	49.60 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	303.00 FL	*- FL
16	1		*REAR END PANEL	Repair	530.90 FL	*- FL
17	1		*REAR END PANEL INNER GARNISH	Serviceable	109.90 FL	*- FL
18	1		*REAR END PANEL INNER SENSOR	Serviceable	195.50 FL	*- FL
19	1		*REAR END PANEL OUTER SENSOR	Serviceable	180.25 FL	*- FL
20	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
21	1		*SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,206.45	2,700.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,161.29	492.14
Total Parts (\$\$)	5,045.16	2,208.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	200.00	20.00
3	TUFF KOTE	New	150.00	30.00
4	SPRAY PAINTING	New	1,000.00	400.00
5	LABOUR CHARGES	New	1,000.00	450.00
Gross Labour Cost (\$\$)			2,470.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >