

Jla le



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63685592
Estimator Telephone Number	68662623
Accident Reporting Number	68662672

Date Generated : 16/08/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB270Y
Case Reference Number	BUS08/19/7015
Registration Date	22/5/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Qin Tao
Type of Accident	Head On
Accident Date and Time	15/8/2019 8:45 AM
Accident Reported Date and Time	15/8/2019 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special instruction to ARC, if any	SMB270Y FRONT PORTION SLC2289M (TP) - INSURED WITH AIG LEFT CENTRE PORTION
Prepared Date and Time	16/8/2019 7:47 AM
Chassis Number	VMMA22222C7001323
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$5,318.46	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$5,318.46	\$0.00
Lump Sum Total	\$5,300.00	\$0.00
Number of Repair Days	5.0	4
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	16/08/2019 8:00 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve
8322 8813
with Mark 16/8/19
4 day 2.90 PM
By AL spj



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63885592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 16/08/2019
User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$2,120.00			1590				
Total Labour		\$2,120.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$786.00			528				
Total Spray Painting & Panel Beating		\$786.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
TOWING CHARGE		\$200.00			X ARC - (CHANGE)				
Total Other Costs		\$200.00							
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
8010151	Body	F01001-CE265	BUMPER FRONT CENTR E FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	/ OR (CAR)
8010154	Body	F01001-CW263	FLAP FRONT FOR MLN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	/ OR (CAR)
8010364			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	/ OR
8010306	VE	61-25320-6111	FLASHER AUX HEADLAMP LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	/ OR
8010183	Body	F01001-CW264	COVER HEADLAMP RT LH FOR MAN A22 BUS	1.00	\$874.70	10.00	\$787.23	Replace	/ OR
8009375	VM		RETAINER MALE & FEMALE REAR LID MAN BUS	1.00	\$74.80	0.00	\$74.80	Replace	/ BT
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	/ APC
8010073	Body	F01001-CW262	DOVE FRONT FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	X R
Total					\$10,187.80		\$6,648.07		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 23/08/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB270Y
Case Reference Number	BUS/08/19/7015
Registration Date	22/5/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Qin Tao
Type of Accident	Head On
Accident Date and Time	15/8/2019 8:45 AM
Accident Reported Date and Time	15/8/2019 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102865
Special Instruction to ARC,if any	SMB270Y - FRONT PORTION SLC2289M (TP) - INSURED WITH AIG LEFT CENTRE PORTION
Prepared Date and Time	16/8/2019 7:47 AM
Chassis Number	WMAA22Z2C7001323
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$786.00	\$528.00
Total Spare Part Cost	\$5,318.46	\$5,318.46
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$8,424.46	\$7,436.46
Lump Sum Total	\$8,400.00	\$7,450.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kok Khoon Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	16/08/2019 8:00 AM	16/08/2019 3:17 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/08/2019

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$2,120.00				\$1,590.00			
Total Labour		\$2,120.00				\$1,590.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$786.00				\$528.00			
Total Spray Painting & Panel Beating		\$786.00				\$528.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TOWING CHARGE		\$200.00				\$0.00			
Total Other Costs		\$200.00				\$0.00			
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010151	Body	F01001-CE265	BUMPER,FRONT,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	Replace
6010154	Body	F01001-CW263	FLAP,FRONT,FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	Replace
6010304			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010306	VE	81-25320-6111	FLASHER,AUX HEADLAMP,LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace
6010153	Body	F01001-CW264	COVER,HEADLAMP,FRT .LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6009375	VM		RETAINER,MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	0.00	\$74.80	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6010073	Body	F01001-CW262	DOME,FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
Total					\$10,187.60		\$6,648.07		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									