

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19014472/EDA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900004728
Claimant
Vehicle No : SMB270Y **Insured Vehicle No :** SLC2289M
Date of Loss: 15/08/2019 Nature of Claim: TP Claim No: 0465537300SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB270Y**
Make & Model: MAN NL320F (A22), 10.5 D (M) Engine No: 50330110193007
Reg. Date: 22/05/2012 (Man. Year: 2011) Chassis No: WMAA22ZZ2C7001323
Colour: Multi-colour Odometer: 637608 km
Engine Capacity: 10518 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5
Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm
Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,187.60	6,648.07	3,539.53	34.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,106.00	2,118.00	988.00	31.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,293.60	8,766.07	4,527.53	34.06
Approved Total (Overridden) (S\$)		7,450.00		
Nett Amount (S\$)	13,293.60	7,450.00	5,843.60	43.96
+ Loss of Use (6.0 x S\$260.00/day) (S\$)		1,560.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		9,017.00		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 16/08/2019
Date Inspected: 16/08/2019 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ,FRONT CENTR E.FOR MAN A22 BUS	Broken	1,868.80 F	*1,868.80 FL
2	1		*FLAP ,FRONT FOR MAN A22 BUS	Broken	1,868.80 F	*1,868.80 FL
3	1		*FRONT HEADLAMP LH	Broken	1,603.60 F	*1,603.60 FL
4	1		*FLASHER AUX HEADLAMP LH (MAN BUS)	Broken	904.40 F	*904.40 FL
5	1		*COVER ,HEADLAMP FRT ,LH FOR MAN A22 BUS	Broken	974.70 F	*974.70 FL
6	1		*DOME FRONT FOR MAN A22 BUS	Repair	2,817.50 F	*- FL
7	1		*RETAINER MALE & FEMALE REAR LID ,MAN BUS	Bent	74.80 FS	*74.80 FS
8	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,187.60	7,370.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	722.03
Total Parts (\$\$)	10,187.60	6,648.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	2,120.00	1,590.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	786.00	528.00
3	TOWING CHARGE	New	200.00	0.00
			Gross Labour Cost (S\$)	2,118.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >