

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0988/2019/NS
Date	:	20-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

Your Insured Vehicle : **SLU 9104 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Owner's Name	:	MR. HO SZE ONN
Address	:	21 SERANGOON AVE 3 #03-08 Singapore 556124
Telephone	:	HP +65 98316821
Type of Claim	:	Third Party Claim
Policy No.	:	GA252646/1
Vehicle No	:	SKK 6404 R
Model Code	:	A4 1.8 TFSI MU
Model / Year	:	Aug-13
Engine No	:	CJE 057699
Chassis No	:	WAUZZZ8K3DA254130
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Aug-19
Place of Accident	:	JUNCTION OF SERANGOON AVE 3 & SPRINGBLOOM CONDO EXIT

Automobiles

, Singapore 408699

3 Fax : 6841 1183

lefax

or Accident Vehicle. SKK 6404 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement test on car o-liner	S/N \$800.00	X.
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensore and headlight washer assy.	S/N \$ 360.00	X.
3	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	X.
4	To remove and transfer rhs front and rhs rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 560.00	✓
5	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	X
6	To renew solar film for door glass.	S/N \$ 400.00	X
SUB TOTAL LABOUR CHARGES		: \$3,000.00	

Automobiles

, Singapore 408699

!3 Fax : 6841 1183

elefax

or Accident Vehicle. SKK 6404 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$1,400.00	X
8	To remove and reinstall front and rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and	S/N \$ 1,800.00	✓
9	To place vehicle on o-liner.	S/N \$ 1,800.00	X
10	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door, rear bumper and rear lid. To cut out and weld rhs b-pillar, rhs sill panel and rhs rear fender. To renew rhs front fender, rhs front door, rhs rear door and rhs wing mirror assy. reinstall all parts removed.	\$ 12,250.00	3500.
11	To respray rhs front fender, rhs front door, rhs wing mirror cover, rhs rear door, rhs rear fender, rhs b-pillar, rhs sill panel, hinges, handles, door entrances, roof channel, drain channel, and end panelling. To carry out joint sealer works and carry out stone chip treatment.	3650 \$ 6,500.00	$6 \times 550 = 8300$ Handle x 2 = 200 Mirror : 150. <u>3650.</u>
12	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: <u><u>\$27,134.00</u></u>	

Automobiles

, Singapore 408699

3 Fax : 6841 1183

lefax

Vehicle Regn No. SKK 6404 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH <i>Distorted</i>	\$ 2,639.00	✓
2	OUTER DOOR SEAL <i>New</i>	NEC \$ 193.00	✓
3	BONDING AGENT ?	NEC \$ 45.00	?
4	CLEANING SOLUTION ?	NEC \$ 65.00	?
5	DOOR ATTACHMENT PARTS ?	\$ 81.00	?
6	DOOR CATCH <i>New</i>	\$ 109.00	x
7	DOOR HANDLE <i>New</i>	\$ 137.00	✓
8	DOOR HANDLE CAP <i>New</i>	\$ 36.00	x
9	DOOR MOUNTING BAR ?	\$ 286.00	?
10	DOOR LOCK CYLINDER ?	\$ 492.00	?
11	EXTERIOR MIRROR MOUNTING - RH <i>New</i>	\$ 1,226.00	+
12	MIRROR CAP <i>New</i>	\$ 522.00	+
13	TURN SIGNAL INDICATOR <i>New</i>	\$ 92.00	+
14	MIRROR GLASS - RH <i>New</i>	\$ 1,553.00	x
15	WINDOW REGULATOR ?	\$ 277.00	?
16	WINDOW REGULATOR MOTOR - RH ?	\$ 309.00	?
17	DOOR CONTROL UNIT <i>New</i>	\$ 685.00	x
18	WINDOW GUIDE ?	\$ 412.00	?
19	PILLAR B TRIM - RH <i>New</i>	\$ 194.00	x
20	WINDOW SLOT SEAL - RH FRONT <i>New</i>	\$ 280.00	x
SUB FRONT -TOTAL SPARE PARTS CHARGES		\$ 9,633.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Automobiles

, Singapore 408699

!3 Fax : 6841 1183

alefax

Vehicle Regn No. SKK 6404 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	TYRE PRESSURE DATA PLATE <i>new</i>	\$ 18.00	✓
22	DOOR WINDOW - RH <i>new</i>	\$ 240.00	+
23	ROOF MOLDING - RH <i>new</i>	\$ 574.00	+
24	DOOR ENTRANCE SILL TRIM STRIP - RH FRONT <i>new</i>	\$ 126.00	✓
25	REAR DOOR <i>Distorted</i>	\$ 2,639.00	✓
26	DOOR ATTACHMENT PARTS <i>3/4</i>	\$ 76.00	✓
27	OUTER DOOR SEAL - RH <i>3/4</i>	\$ 201.00	✓
28	BONDING AGENT ?	NEC \$ 45.00	?
29	CLEANING SOLUTION ?	NEC \$ 65.00	?
30	DOOR HINGE - RH UPPER / LOWER <i>Bent</i>	\$ 140.00	✓
31	DOOR CATCH <i>Damaged</i>	\$ 109.00	✓
32	EXTERIOR DOOR HANDLE <i>Regr</i>	\$ 137.00	+
33	DOOR HANDLE CAP <i>Regr</i>	\$ 27.00	+
34	DOOR HANDLE HOUSING <i>3/4</i>	\$ 16.00	+
35	DOOR HANDLE SENSOR <i>new</i>	\$ 237.00	+
36	DOOR MOUNTING BAR <i>3/4</i>	\$ 286.00	+
37	WINDOW REGULATOR ?	\$ 277.00	?
38	WINDOW REGULATOR MOTOR ?	\$ 322.00	?
39	DOOR CONTROL UNIT <i>new</i>	\$ 685.00	+
40	PILLAR B TRIM - RH <i>new</i>	\$ 204.00	+
SUB-FRONT -TOTAL SPARE PARTS CHARGES		\$ 6,424.00	

Automobiles

, Singapore 408699
Fax : 6841 1183

Telefax

Vehicle Regn No. SKK 6404 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	WINDOW GUIDE ?	\$ 412.00	?
42	CORNER TRIM - RH OUTER <i>new</i>	\$ 86.00	X.
43	WINDOW WELL CHROME TRIM STRIP - RH REAR <i>new</i>	\$ 270.00	X
44	SILL TRIM STRIP - RH REAR <i>new</i>	\$ 81.00	✓
45	DOOR WINDOW - RH REAR <i>new</i>	\$ 240.00	X.
46	SIDE PANEL FRAME - RH <i>Dented.</i>	\$ 3,432.00	✓
47	REAR WINDOW <i>new</i>	\$ 1,030.00	X
48	PRIMER <i>new</i>	\$ 19.00	✓
49	SIDE WINDOW - RH <i>new</i>	\$ 278.00	X
50	SIDE WINDOW TRIM STRIPS - RH REAR <i>new</i>	\$ 298.00	X
51	FRONT FENDER - RH <i>Repair</i>	\$ 904.00	X
52	FENDER ATTACHMENT PARTS <i>new</i>	\$ 52.00	X
53	STONE CHIP GUARD } <i>new</i>	NEC \$ 67.00	✓
54	ADHESIVE TAPE }	NEC \$ 50.00	✓
55	ACRYLIC SEALANT }	S/N \$ 360.00	✓
56	CAVITY WAX }	S/N \$ 280.00	✓
57	STONE CHIP GUARD }	S/N \$ 360.00	✓
58	METAL FILLER POWDER }	S/N \$ 280.00	✓
59	REAR WINDSCREEN SEALANT } <i>for</i>	S/N \$ 200.00	X
60	1/4 GLASS SEALANT }	S/N \$ 100.00	X
	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS CHARGES		: \$ 25,856.00	
TOTAL LABOUR CHARGES		: \$ 27,134.00	
GRAND TOTAL		: \$ 52,990.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 22/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, 13 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant