

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms MSIG Insurance (Singapore) Pte Ltd
Date 16/8/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLR9794X
CHASSIS NO : GM41105408
MAKE / MODEL : Honda Grace 1.5 Hybrid DX Auto
DATE OF ACCIDENT : 09/08/2019
YOUR INSURED VEHICLE NUMBER : FBE8992J
MILEAGE : 198529km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PARTS DESCRIPTION		QTY	UNIT PRICE	LIST PRICE	
1	F/L fender / Blue.	1PC	\$470.60	\$470.60	270.6
2	F/L fender inner liner / ee	1PC	\$196.60	\$196.60	84
3	F/L door / BT	1PC	\$875.10	\$875.10	722
Type / part					
Rim / BT.					
\$60 SN					
\$100 SN					
LIST TOTAL S\$:				\$1,542.30	1076.6
20.00% DISCOUNT S\$:				\$308.46	
				\$1,233.84	861.28

SPECIAL NETT

1	Fender clips / MC.	1 SET	\$80.00	20
Special Nett Total S\$:			\$80.00	450.

LABOUR CHARGES

1	To labour charge for removing F/L fender and F/L door out to facilitate repairs and replacement of damaged parts	\$800.00	2800 fee
2	To respray F/L fender, F/L door and LH rocker panel	\$800.00	600
3	Remove and transfer F/L door mechanism	\$100.00	60
LABOUR TOTAL S\$:		\$1,700.00	1110
TOTAL S\$:		\$3,013.84	
7% GST		\$210.97	
GRAND TOTAL S\$:		\$3,224.81	2151.28

4 Days.

-20%: 1700

Gino Qiang - 82880282
(LKK)

20/8/19.

part by part.

before paint photos.