

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0976/2019/GW  
Date : 16-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Taufikh*

*14 days exclude 2 Sundays - jb*

*16-Jan-20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Simon Thomas Wise  
Address : 861 Old Holland Road  
Singapore 278684  
Telephone : 96634302  
Type of Claim : Own Damage Claims  
Policy No. : 1800018608  
Vehicle No : **SLW 4633 J**  
Model Code : Audi A5 SB 2.0 TFS  
Model / Year : 12/2/2018  
Engine No : CVK 050740  
Chassis No : WAUZZZF57JA049452  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 23-Mar-19  
Place of Accident : 861 Old Holland Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLW 4633 J

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00	\$ 360.00
2	To renew lhs 1/4 glass to facillitate fender renewal.	S/N	\$ 300.00	\$ 300.00
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 360.00	\$ 360.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relays, electrical and audio equipment.	S/N	\$ 1,400.00	\$ 1,400.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	\$ 1,400.00
6	To dismantle rear bumper, rear lid, lhs sill panel trim and lhs rear door. Cut out and weld lhs rear fender, lhs rear inner side panel. Renew lhs rear door and lhs sill panel trim . Re-organize rear crash management components. Reinstall all parts removed.		\$ 10,400.00	\$ 4,000.00
<b>SUB LABOUR CHARGES</b>			<b>\$ 14,220.00</b>	<b>\$ 7,820.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLW 4633 J

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
		<i>c/f</i>		\$ 7,820.00
7	To respray lhs rear fender, lhs rear door, lhs sill panel, lhs sill panel trim, door entrances, roof channel, drain panel, end panelling and lhs side inner panel. To carry out stone chip treatment and joint sealer works.		\$ 6,900.00	\$ 3,575.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
10	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
	<b>SUB LABOUR CHARGES</b>	:	<u>\$ 21,592.00</u>	<u>\$ 11,867.00</u>

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SLW 4633 J**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR FENDER-LH	\$ 2,285.00	\$ 1,828.00
2	REAR SIDE PANEL INNER-LH	\$ 1,087.00	
3	REAR SIDE WINDOW-LH	\$ 653.00	\$ 522.40
4	REAR DOOR-LH	\$ 2,829.00	\$ 2,263.20
5	REAR DOOR OUTER SEAL-LH	\$ 201.00	\$ 160.80
6	BONDING AGENT	\$ 45.00	\$ 35.92
7	CLEANING SOLUTION	\$ 65.00	
8	REAR DOOR CATCH-LH	\$ 109.00	
9	REAR DOOR ATTACHMENT PARTS	\$ 117.00	
10	REAR SIDE MEMBER TRIM-LH	\$ 754.00	\$ 602.80
11	REAR SIDE MEMBER ATTACHMENT PARTS	\$ 118.00	\$ 94.00
12	1 SET OF ADHESIVE TAPES	\$ 192.00	\$ 153.20
13	REAR DOOR HANDLE TRIM PLATE-LH	\$ 80.00	\$ 63.52
14	REAR DOOR HANDLE CHROME TRIM-LH	\$ 124.00	
15	REAR DOOR HANDLE HOUSING-LH	\$ 7.00	
16	REAR DOOR HANDLE SENSOR-LH	\$ 208.00	
17	REAR DOOR HANDLE COVER-LH	\$ 6.00	
18	REAR DOOR HANDLE EXTERIOR-LH	\$ 35.00	
19	REAR WHEEL HOUSING LINER-LH	\$ 256.00	
20	REAR WHEEL HOUSING LINER ATTACHMENT PARTS-LH	\$ 82.00	
<b>SUB FRONT SPARE PARTS</b>		<b>\$ 9,253.00</b>	<b>\$ 5,723.84</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Material List for Accident Vehicle Regn No. SLW 4633 J**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 5,723.84
21	REAR ALUMINIM RIM-LH	\$ 943.00	\$ 770.80
22	RUBBER VALVE	4 \$ 13.00	
23	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
24	CAVITI WAX	S/N \$ 140.00	\$ 140.00
25	STONE CHIP	S/N \$ 180.00	\$ 180.00
26	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
27	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
28	SUNDRIES	\$ 500.00	
	<b>FRONT TOTAL SPARE PARTS</b>	<b>: \$ 11,589.00</b>	<b>\$ 7,374.64</b>
	<b>FRONT TOTAL LABOUR CHARGES</b>	<b>: \$ 21,592.00</b>	<b>\$ 11,867.00</b>
	<b>GRAND TOTAL</b>	<b>: \$ 33,181.00</b>	<b>\$ 19,241.64</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.