

INSURANCE

INS. CASE OWNER

Bundari

CC 9/III1901

4523, K

LKK
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

19/8/19

Date / Time:

19/8/19

Registered in Merimen:

10/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 7933T

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

17/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Umm Wateh Tek

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

sjk 8249X



INSRS:
WSP:
Tel:
Liability:
RMKS:

Umm
KOL



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup):	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	(Tick only one)		
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
13/10/20

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

ASS. REC. BY:

REF: TU /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

08

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1
19/8File pass to
EM not ready1/5 461501 - (Red - 112000.72 / 257.2)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

\$ + RS. \$

Fuel \$

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Veh No: SJK 824PXYr Regn: 11, 08Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic

c.c.

1595Colour: M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: 181936

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF0462099200141Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

205/55R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orContinental

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 17/8/19D.O.I. 19/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S FR & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Kw
Arthur Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

SJK8249X
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100
ATTN: Motor Claim Department
WS Ref: TP/INDIA/YS

FAX: 62247743

Claim Type: Third Party
Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN
Date: 19 Aug 2019
Policy No: 5102519161
Veh Reg No: SJK8249X
Make/Model: HONDA CIVIC 1.6L 5AT
Chassis No: JHMFD46209S00141
Engine No: R16A14000741
Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 FRONT BUMPER	638.00	1 PC	638.00	—
2 FRONT BUMPER REINFORCEMENT	218.40	1 PC	218.40	—
3 FRONT BUMPER CENTRE LOWER GRILLE	194.50	1 PC	194.50	—
4 FRONT BUMPER UNDER COVER	62.40	1 PC	62.40	—
5 FRONT BUMPER UNDER COVER CLIPS	3.90	8 PCS	31.20	—
6 FRONT BUMPER CLIPS	3.90	6 PCS	23.40	—
7 FRONT RH FOG LAMP	303.50	1 PC	303.50	—
8 FRONT RH FOG LAMP GARNISH	95.10	1 PC	95.10	—
9 FRONT BUMPER SIDE RETAINERS	13.60	2 PCS	27.20	—
10 FRONT RH FENDER	537.50	1 PC	537.50	—
11 FRONT RH FENDER INNER SHIELD	94.80	1 PC	94.80	—
12 FRONT RH FENDER INNER SHIELD CLIPS	3.90	6 PCS	23.40	—
13 FRONT RH FENDER LAMP	38.10	1 PC	38.10	—
14 FRONT RH FENDER INNER GARNISH CLIPS	3.90	3 PCS	11.70	—
15 AIR-CON CONDENSER	729.40	1 PC	729.40	—
16 RADIATOR	1,507.40	1 PC	1,507.40	—
17 RADIATOR FAN COWLING	109.40	1 PC	109.40	—
18 FRT SUPPORT PANEL	426.30	1 PC	426.30	—
19 FRONT SUPPORT PANEL TOP GARNISH CLIPS	3.90	4 PCS	15.60	—
20 FRONT NUMBER PLATE GARNISH	51.80	1 PC	51.80	—
21 FRONT WIPER TANK	72.90	1 PC	72.90	—
22 FRONT RH SPORT RIM	753.70	1 PC	753.70	—
23 FRONT RH SHOCK ABSORBER	334.50	1 PC	334.50	—
24 FRONT RH KNUCKLE ARM	243.50	1 PC	243.50	—
25 FRONT RH WHEEL BEARING	129.40	1 PC	129.40	—
			6,673.10	
			1,334.62	5,338.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

118 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E KCB NO: 201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN

Date: 19 Aug 2019

Policy No: 5102519161

Veh Reg No: SJK8249X

Make/Model: HONDA CIVIC 1.6L 5AT

Chassis No: JHMFD46209S00141

Engine No: R16A14000741

Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
Labour			S\$	S\$
26 TOWING	50.00	1 LA	50.00	✓
27 REMOVE & REFIX FRT BUMPER ASSY, FOG LAMP, GRILLE, FRT RH FENDER, HEADLAMPS, RADIATOR & MOTOR, STRAIGHTEN, KNOCK & REPAIR FRT BOTH CHASSIS, BONNET, FENDER INNER HOUSING, CUT, WELD & RENEW FRT SUPPORT PANEL & REALIGN THE SAME	1,100.00	1 LA	1,100.00	900 ✓
28 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
29 REMOVE & REFIX FRT RH UNDER CARRIAGE, CHECK DRIVE SHAFT & STEERING	200.00	1 LA	200.00	? 160 ✓
30 PUTTY & RESPRAY ON FRT SUPPORT PANEL, FRT BUMPER, REINFORCEMENT, BONNET, HINGES, FRT FENDERS, FENDER INNER PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
31 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
32 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,470.00	2,470.00
			Total	S\$ 2,808.48
			Add GST @ 7%	546.59
			Total Amount Payable	S\$ 3,355.07

Parts \$ 6525.60

Add supp \$ 465.30

\$ 6990.90

Less 20%

1398.18

\$ 5592.72

Add lab

\$ 2130.00

\$ 7722.72

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

✓ \$ 6,150 ✓ ok

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

SJK 8249X

TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893

Date: 24 Aug 2019

Policy No: 5102519161

Veh Reg No: SJK8249X

Make/Model: HONDA CIVIC 1.6L 5AT

Chassis No: JHMF46209S00141

Engine No: R16A14000741

Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>

Supplementary 1

List Price

- 1 AIR-CON CONDENSER FAN COWLING
- 2 AIR-CON CONDENSOR FAN MOTOR
- 3 FRONT RH TIE ROD END

85.60	1 PC	CM	85.60	—
301.80	1 PCS	Zn	301.80	—
77.90	1 PCS	R	77.90	—
			465.30	
Less 20%			93.06	372.24

Total S\$ 372.24

GST Amount S\$ 26.06

Total Amount Payable S\$ 398.30

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

#8180.72

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJK 8249X
TP/India

M/S: INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN

Date: 19 Aug 2019

Policy No: 5102519161

Veh Reg No: SJK8249X

Make/Model: HONDA CIVIC 1.6L 5AT

Chassis No: JHMFD46209S00141

Engine No: R16A14000741

Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 FRONT BUMPER	638.00	1 PC	CM 638.00	—
2 FRONT BUMPER REINFORCEMENT	218.40	1 PC	B 218.40	—
3 FRONT BUMPER CENTRE LOWER GRILLE	194.50	1 PC	Diy 194.50	—
4 FRONT BUMPER UNDER COVER	62.40	1 PC	CM 62.40	—
5 FRONT BUMPER UNDER COVER CLIPS	3.90	8 PCS	MC 31.20	—
6 FRONT BUMPER CLIPS	3.90	6 PCS	MC 23.40	—
7 FRONT RH FOG LAMP	303.50	1 PC	MC 303.50	?
8 FRONT RH FOG LAMP GARNISH	95.10	1 PC	MC 95.10	—
9 FRONT BUMPER SIDE RETAINERS	13.60	2 PCS	CM 27.20	—
10 FRONT RH FENDER	537.50	1 PC	B 537.50	—
11 FRONT RH FENDER INNER SHIELD	94.80	1 PC	CM 94.80	—
12 FRONT RH FENDER INNER SHIELD CLIPS	3.90	6 PCS	MC 23.40	—
13 FRONT RH FENDER LAMP	38.10	1 PC	MC 38.10	?
14 FRONT RH FENDER INNER GARNISH CLIPS	3.90	3 PCS	MC 11.70	—
15 AIR-CON CONDENSER	729.40	1 PC	B 729.40	—
16 RADIATOR	1,507.40	1 PC	1,507.40	?
17 RADIATOR FAN COWLING	109.40	1 PC	109.40	?
18 FRT SUPPORT PANEL	426.30	1 PC	B 426.30	—
19 FRONT SUPPORT PANEL TOP GARNISH CLIPS	3.90	4 PCS	MC 15.60	—
20 FRONT NUMBER PLATE GARNISH	51.80	1 PC	MC 51.80	—
21 FRONT WIPER TANK	72.90	1 PC	MC 72.90	—
22 FRONT RH SPORT RIM	753.70	1 PC	MC 753.70	—
23 FRONT RH SHOCK ABSORBER	334.50	1 PC	334.50	?
24 FRONT RH KNUCKLE ARM	243.50	1 PC	243.50	?
25 FRONT RH WHEEL BEARING	129.40	1 PC	129.40	?
			6,673.10	
			1,334.62	5,338.48

Less 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN

Date: 19 Aug 2019

Policy No: 5102519161

Veh Reg No: SJK8249X

Make/Model: HONDA CIVIC 1.6L 5AT

Chassis No: JHMFD46209S00141

Engine No: R16A14000741

Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
Labour			SS	SS
26 TOWING	50.00	1 LA	50.00	✓
27 REMOVE & REFIX FRT BUMPER ASSY,FOG LAMP,GRILLE,FRT RH FENDER,HEADLAMPS,RADIATOR & MOTOR,STRAIGHTEN,KNOCK & REPAIR FRT BOTH CHASSISS,BONNET,FENDER INNER HOUSING,CUT,WELD & RENEW FRT SUPPORT PANEL & REALIGN THE SAME	1,100.00	1 LA	1,100.00	900 ✓
28 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
29 REMOVE & REFIX FRT RH UNDER CARRIAGE,CHECK DRIVE SHAFT & STEERING	200.00	1 LA	200.00	?
30 PUTTY & RESPRAY ON FRT SUPPORT PANEL,FRT BUMPER,REINFORCEMENT,BONNET,HINGES,FRT FENDERS,FENDER INNER PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800 ✓
31 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
32 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,470.00	2,470.00
			Total	SS 7,808.48
			Add GST @ 7%	546.59
			Total Amount Payable	SS 8,355.07

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SJK 8249X

TP/Indici

1 m for bumper cm ✓

_____ reinforcement Br ✓

_____ Centre lower grille Dr ✓

_____ under cover cm ✓

8 v _____ under cover clips, re ✓

6 v _____ clips, re ✓

1 m for R/H fog lamp

_____ garnish re ✓

2 m for bumper side retainers cm ✓

1 m for R/H fender Br ✓

_____ inner shield cm ✓

_____ inner shield clips re ✓

3 v _____ lamp. ?
inner top garnish clips re ✓

1 m air-con condenser Br ✓

1 m radiator ?
_____ fan cowling. ?

1 m for support panel Br ✓

4 m for _____ top garnish clips re ✓

1 m for no plate garnish Dr ✓

1 m for viper tank Dr ✓

SK 8249X

Wst/mg

- 1 pc for R/H sport Rim Det-
- 1 pc for R/H shock absorber ?
- 1 pc for R/H knuckle arm ?
- 1 pc for R/H wheel bearing ?

SSK8249X

① Towing

#50/✓

② RAR for bumper assy, fog lamps, grille,
for R/L fender, head lamps, radiator & motor,
To straighten KAR for both chassis, bonnet,
fender mechanism, Caster, weedy and renew for support
panel and re-align the same

Pool
#1100/✓

③ RAR air-con, checks, Vacuum & refill gas #100/✓

④ RAR for R/L under carriage
and checks drive shaft and
steering

#200/✓?

⑤ Body is missing on for support panel,
for bumper, reinforcement, bonnet,
wings, for fenders and ~~the~~ fender
inner panel and all affected area

Pool
#900/✓

⑥ To conduct computer wheel align

#60/✓

⑦ Rustproof

#60/✓

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	073H
Vehicle Details	
Vehicle No.:	SJK8249X
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L 5AT
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	R16A14000741
Chassis No.:	JHMFD46209S200141
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,211.00
Original Registration Date:	05 Nov 2008
First Registration Date:	05 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$20,211.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$30,284.00
COE Rebate Amount:	\$27,858.00
Total Rebate Amount:	\$27,858.00

The information contained herein is correct as at 19 Aug 2019

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 20 August 2019 9:44 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); sur@lkkauto.com; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: Repair Survey (Single Joint Expert) - SJK8249X & SHD3533T(III) on 17/8/2019

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJK8249X and let us have your report urgently.

This claim will be handled by Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Daniel Pooi
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company

-----Original Message-----

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Monday, 19 August, 2019 2:35 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Repair Survey (Single Joint Expert) - SJK8249X

Dear Sirs,

Our selection as below :-

- LKK Auto Consultants Pte Ltd

Pls assist to arrange for survey asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

-----Original Message-----

From: Motor Claim - III
Sent: Monday, August 19, 2019 2:10 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: Repair Survey (Single Joint Expert) - SJK8249X

11:09am @ 20/8/19
motor@shuron
vehicle in
Suro Kenneth

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Daniel Pooi
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company

-----Original Message-----

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Monday, 19 August, 2019 12:47 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Repair Survey (Single Joint Expert) - SJK8249X

Dear Sir,

OUR CLIENT – SJK8249X
DOA : 17/8/19 @7pm
YOUR INSURED : SHD3533T

(A) Pls provide us your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

AUDIT TRAIL				
No.	On	Audit	Remarks	By
21	12 Sep 2019 18:46	Video Downloaded	Downloaded Video - Accident (OIV)	[A] OI SUN PIN
22	12 Sep 2019 18:48	Video Downloaded	Downloaded Video - Accident	[A] OI SUN PIN
23	12 Sep 2019 18:50	Video Downloaded	Downloaded Video - Accident (OIV)	[A] OI SUN PIN
24	16 Oct 2019 17:08	Video Downloaded	Downloaded Video - Accident	[A] Chong Pui Lin
25	16 Oct 2019 17:08	Video Downloaded	Downloaded Video - Accident (OIV)	[A] Chong Pui Lin
26	16 Oct 2019 17:12	Adj Mandate Request	Cur,Req:0.00:PODS LIABILITY: 0% REMARKS: WE ARE IN THE VIEW OF REJECTING TP CLAIM. AS COLLISI ON HAPPEN STILL IN A SINGLE LANE ROAD. THUS, TP SHOULD NOT JUST DRIVE PASS OIV IN SUCH RECKL ESS MANNER, ON TOP OF THAT, OI HAS SIGNAL INDICATOR ON THAT HE	[A] Chong Pui Lin
27	16 Oct 2019 17:50	Video Downloaded	Downloaded Video - Accident (OIV)	[I] Sundari Nagaraajan
28	16 Oct 2019 17:52	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/29. Mandate Remarks: Video Uploaded into merimen.	[I] Sundari Nagaraajan
29	16 Oct 2019 17:52	Adj Mandate Set	Approved:0.00:Video Uploaded into merimen.	[I] Sundari Nagaraajan
30	21 Oct 2019 15:32	Adj Mandate Request	Cur,Req:0.00:PODS HI KINDLY LET US HAVE YOUR APPROVAL / INSTRUCTION TO REJECT TP CLAIM. THANK S	[A] Chong Pui Lin
31	22 Oct 2019 09:45	Video Downloaded	Downloaded Video - Accident (OIV)	[I] Sundari Nagaraajan
32	22 Oct 2019 09:46	Adj Mandate Set	Approved:0.00.	[I] Sundari Nagaraajan
33	23 Oct 2019 17:44	Video Downloaded	Downloaded Video - Accident (OIV)	[A] Chong Pui Lin
34	23 Oct 2019 17:45	Video Downloaded	Downloaded Video - Accident	[A] Chong Pui Lin
35	23 Oct 2019 17:50	Video Downloaded	Downloaded Video - Accident (OIV)	[A] Chong Pui Lin
36	23 Oct 2019 17:51	Video Downloaded	Downloaded Video - Accident (OIV)	[A] Chong Pui Lin
37	23 Oct 2019 17:55	Video Downloaded	Downloaded Video - Accident	[A] Chong Pui Lin
38	23 Oct 2019 18:01	Adj Mandate Request	Cur,Req:0.00:PODS LIABILITY: 100% REMARKS: TP DISAGREE REJECTION. AS THEIR CLIENT DID NOT OVE RTAKE OIV. ALONG TPV IS IN FRONT OF OIV FIRST. AND IS MAKING A RIGHT TURN. THUS RE-SEEK LIABILI TY APPROVAL.	[A] Chong Pui Lin
39	24 Oct 2019 10:02	Video Downloaded	Downloaded Video - Accident (OIV)	[I] Sundari Nagaraajan
40	24 Oct 2019 10:05	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/29. Mandate Remarks: Maintain rejection	[I] Sundari Nagaraajan
41	24 Oct 2019 10:05	Adj Mandate Set	Maintained:Maintain rejection	[I] Sundari Nagaraajan
42	24 Oct 2019 11:41	Video Downloaded	Downloaded Video - Accident	[I] Sundari Nagaraajan
43	26 Oct 2019 11:09	Video Downloaded	Downloaded Video - Accident (OIV)	[A] Chong Pui Lin
44	29 Oct 2019 10:30	Adj Mandate Request	Cur,Req:0.00:PODS HI, TP DISAGREE REJECTION. TP REPLY: --> Video indicated that our client has put on r ight signal and subsequently step brake to slow down making right turning. This is a single lane. Case falls u nder Bola scenario 33. KINDLY LET U	[A] Chong Pui Lin
45	04 Nov 2019 11:49	Video Downloaded	Downloaded Video - Accident (OIV)	[I] Sundari Nagaraajan
46	04 Nov 2019 12:04	Video Downloaded	Downloaded Video - Accident (OIV)	[I] Sundari Nagaraajan
47	07 Nov 2019 10:04	Video Downloaded	Downloaded Video - Accident	[I] Sundari Nagaraajan

Print Received Message

This mail is associated with :

*SJK8249X (MCT19080397)

[SHD3533T]

TP

TAN YOKE JEE

Aug 17 2019 7:00PM

[COMFORT TRANSPORTATION PTE LTD]

Cheng Hoe Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/10/2019 09:46 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SJK8249X - Claim Handler: Sundari Nagarajan

Approved:0.00.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Saturday, 26 October 2019 11:16 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: VIDEO - LOD- SJK8249X & SHD3533T(III) on 17/8/2019
Attachments: OI GIA REPORT.pdf; Video - Accident (OIV) (9).MP4

Your Ref: **SJK 8249X**
Our Ref: CC4/III19014523/Kgb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SHD 3533T (III) & SJK 8249X ON 17/08/2019

We refer to the above matter.

Attached is a copy of our insured car video footage and accident statement for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Our Insured is driving straight and your client fail to check the road before turning right.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd


Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Saturday, 26 October 2019 10:52 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: VIDEO - LOD- SJK8249X & SHD3533T(III) on 17/8/2019



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 15 OCT 2019

India Int'l Insurance Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SJK8249X & SHD3533T ON 17/08/2019
PETAIN RD.**

We are authorized by SJK8249X for their above matter.

Record reveals that you are the insurer of SHD3533T. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 6580.50
2. Loss of Use (S\$ 60.00 /- x 10 days)	S\$ 600.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 0.00
TOTAL	S\$ 7180.50

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Final Repair Bill

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department
WS Ref: TP/INDIA/YS
Claim Type: Third Party
Accident Date: 17/08/2019
TP Veh Reg No: SHD3533T

Claim No: ES1991893
NO: PS1902193
Date: 15 Oct 2019
Policy No: 5102519161
Veh Reg No: SJK8249X
Make/Model: HONDA CIVIC 1.6L 5AT

PAGE:1			
Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 6,150.00	S\$ 6,150.00

Total	S\$ 6,150.00
Add GST @ 7%	430.50
Total Amount payable	<u>S\$ 6,580.50</u>

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5102519161

Cover : drive CLASSIC

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SJK8249X |
| Chassis Number | : JHMF0462095200141 |
| 2. Name of Policyholder | : TAN YOKE JEE |
| 3. Effective Date of Insurance | : 20 Jul 2018 |
| 4. Expiry Date of Insurance | : 04 Nov 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TAN YOKE JEE
NAMED DRIVER (1)	: CHEN SHITONG
NAMED DRIVER (2)	: CHEN JINGYAN
HIRE PURCHASE COMPANY	: MAYBANK SINGAPORE LIMITED
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TELESales-DIRECT MARKETING (00000601661)
Date of Issue : 20 Jul 2018 11:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 11:56
Date Of Accident	17/08/2019 19:00
Exact Location Of Accident	PETAIN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK8249X
Insured/Policyholder	
Name Of Registered Owner	TAN YOKE JEE
NRIC No	S0070073H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98357698
Alternative Phone No	OTHERS-98357698

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.6L 5AT
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102519161
Cover Note Number	20/07/2018- 04/11/2019


Driver

Name of Driver	CHEN JINGYAN
NRIC No	S9309012H
Date Of Birth	11/03/1993
Occupation	INDOOR
Date Of Driving Pass	23/08/2017
Driving Experience	1 YEAR AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91297263
Fax Number	
Contact Number	
EMail Address	YENJINGYAN@GMAIL.COM

4

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident occurred along Petam Rd on 17/8/19 at about 7pm
M/taxi (B) overtook my vehicle while I was making a right
turning into Stander Rd and collided onto my vehicle.
The impact then pushes my vehicle to the left side of the road.
I was alone at that time.
Traffic police came and later told us to settle amongst
ourselves. After the accident, I felt uncomfortable and I proceed
to see doctor the next day and was given (day me (whiplash)).


Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time _____

Reporting Centre Personnel's Signature
Name: 
ABC/TIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

LETTER OF AUTHORISATION
(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim SJK8249X
in respect of the traffic accident on 17/8/2019
at/along Petain Road

I/We, Tan Yoke Jee
NRIC S0070073H of Blk 757 Yishun St 72 #09-482
Singapore 760757
owner of motor vehicle SJK8249X, insured by NIUC Income Insurance
Co-operative Ltd under policy no. 5102519161

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle SHD3533T in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 
Date : 19/8/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$6,150.00 Edit Estimates	S\$6,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	TAN YOKE JEE, ID: S0070073H								
Vehicle Reg. No.:	SJK8249X	Date of Loss:	17/08/2019 19:00 - :59 [129 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19080397	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD3533T	Policy No. (Claimant):	5102519161						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bldg 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (04/03/2020): Alert - Adj Mandate Maintained - SJK8249X - Claim Handler: Sundari Nagarajan III_SG (06/12/2019): Alert - Adj Mandate Maintained - SJK8249X - Claim Handler: Sundari Nagarajan III_SG (07/11/2019): Alert - Adj Mandate Maintained - SJK8249X - Claim Handler: Sundari Nagarajan III_SG (24/10/2019): Alert - Adj Mandate Maintained - SJK8249X - Claim Handler: Sundari Nagarajan III_SG (22/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SJK8249X - Claim Handler: Sundari Nagara... III_SG (16/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SJK8249X - Claim Handler: Sundari Nagara... III_SG (28/08/2019): Alert - Adj Mandate Maintained - SJK8249X - Claim Handler: Sundari Nagarajan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK8249X (MCT19080397)
[SHD3533T]
TP
TAN YOKE JEE
Aug 17 2019 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 18:04	Video - Accident (OIV)	Load MP4	
2	28/08/19 09:58	Video - Accident	Load MP4	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/03/20 12:54	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
21	04/03/20 12:54	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
22	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
23	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
24	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
25	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>
26	04/03/20 12:54	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 15:13	EMAIL FROM III DD 20082019	Load PDF	
2	20/08/19 19:19	TP ESTIMATE- MARKED	Load PDF	
3	20/08/19 19:19	TP GIA REPORT	Load PDF	
4	04/03/20 12:53	REJECTION EMAIL TO TP	Load PDF	

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 10:50	Singapore Accident Statement IV SHD3533T	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014523/KGA3Q2

Date: 10/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SJK8249X Insured Vehicle No: SHD3533T
 Vehicle No : SJK8249X
 Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: MCT19080397

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK8249X
 Make & Model: HONDA CIVIC, 1.6 L (A) Engine No: R16A14000741
 Reg. Date: 05/11/2008 (Man. Year: 2008) Chassis No: JHMFD46209S200141
 Colour: Metallic Blue Odometer: 191934 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R15 Rear Tyre Size: 205/55 R15
 Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,710.72	5,592.72	118.00	2.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	2,130.00	340.00	13.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,180.72	7,722.72	458.00	5.60
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	8,180.72	6,150.00	2,030.72	24.82
+ GST 7.00/7.00% (S\$)	572.65	430.50	142.15	24.82
Nett Amount (S\$)	8,753.37	6,580.50	2,172.87	24.82
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 19/08/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2020)
Parts:	143	HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8249X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	638.00 FL	*638.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	218.40 FL	*218.40 FL
3	1		*FRONT BUMPER CENTRE LOWER GRILLE	Distorted	194.50 FL	*194.50 FL
4	1		*FRONT BUMPER UNDER COVER	Cracked	62.40 FL	*62.40 FL
5	8		*FRONT BUMPER UNDER COVER CLIPS	Necessary	31.20 FL	*31.20 FL
6	6		*FRONT BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
7	1		*FRONT RH FOG LAMP	Mtg Cracked	303.50 FL	*303.50 FL
8	1		*FRONT RH FOG LAMP GARNISH	Dented	95.10 FL	*95.10 FL
9	2		*FRONT BUMPER SIDE RETAINERS	Cracked	27.20 FL	*27.20 FL
10	1		*FRONT RH FENDER	Bent	537.50 FL	*537.50 FL
11	1		*FRONT RH FENDER INNER SHIELD	Cracked	94.80 FL	*94.80 FL
12	6		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	23.40 FL	*23.40 FL
13	1		*FRONT RH FENDER LAMP	Serviceable	38.10 FL	*- FL
14	3		*FRONT RH FENDER INNER GARNISH CLIPS	Necessary	11.70 FL	*11.70 FL
15	1		*AIR-CON CONDENSER	Bent	729.40 FL	*729.40 FL
16	1		*RADIATOR	Punctured	1,507.40 FL	*1,507.40 FL
17	1		*RADIATOR FAN COWLING	Serviceable	109.40 FL	*- FL
18	1		*FRT SUPPORT PANEL	Bent	426.30 FL	*426.30 FL
19	4		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	15.60 FL	*15.60 FL
20	1		*FRONT NUMBER PLATE GARNISH	Dented	51.80 FL	*51.80 FL
21	1		*FRONT WIPER TANK	Dented	72.90 FL	*72.90 FL
22	1		*FRONT RH SPORT RIM	Dented	753.70 FL	*753.70 FL
23	1		*FRONT RH SHOCK ABSORBER	Bent	334.50 FL	*334.50 FL
24	1		*FRONT RH KNUCKLE ARM	Bent	243.50 FL	*243.50 FL
25	1		*FRONT RH WHEEL BEARING	Necessary	129.40 FL	*129.40 FL
26	1		*AIR-CON CONDENSER FAN COWLING	Cracked	85.60 FL	*85.60 FL
27	1		*AIR-CON CONDENSOR FAN MOTOR	Jammed	301.80 FL	*301.80 FL
28	1		*FRONT RH TIE ROD END	Bent	77.90 FL	*77.90 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	7,138.40	6,990.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,427.68	1,398.18
Total Parts (\$\$)	5,710.72	5,592.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE & REFIX FRT BUMPER ASSY ,FOG LAMP ,GRILLE ,FRT RH FENDER ,HEADLAMPS ,RADIATOR & MOTOR ,STRAIGHTEN ,KNOCK & REPAIR FRT BOTH CHASSIS ,BONNET ,FENDER INNER HOUSING ,CUT ,WELD & RENEW FRT SUPPORT PANEL & REALIGN THE SAME	New	1,100.00	900.00
3	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
4	REMOVE & REFIX FRT RH UNDER CARRIAGE ,CHECK DRIVE SHAFT & STEERING	New	200.00	160.00
5	PUTTY & RESPRAY ON FRT SUPPORT PANEL ,FRT BUMPER,REINFORCEMENT ,BONNET ,HINGES ,FRT FENDERS ,FENDER INNER PANEL & ALL AFFECTED AREAS	New	900.00	800.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
7	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			2,470.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >