

Vehicle No. SMN 457 M

HONDA SHUTTLE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Tailgate	Body	1425.00	/
1	Tailgate centre chrome garnish	11	488.00	X
1set	Tailgate centre chrome garnish clips	11	40.00	X
1	Tailgate inner lock 245.50	Tw	278.00	/
1	Tailgate inner trim board 320.00	Cr	545.00	/
2	Tailgate dampers @\$185	11	370.00	X
2	Tailgate rubber stopper @5.80	11	11.60	X
1	Tailgate Honda badge 38.50	Ne	72.00	/
1	Tailgate SHUTTLE emblem 58.00	Ne	98.00	/
1	Tailgate HYBRID emblem	Ne	48.00	/
2	Tailgate reflector @395.00	11	790.00	X
2	RHS & LHS Taillamp @782.00	11	1564.00	X
1	Rear bumper 1150.60	De/Trim	1242.00	/
2	Rear bumper reflectors @\$120	11	240.00	X
2	Rear bumper reflector cover @\$105	11	210.00	X
1	Rear bumper inner sponge	NS	42.00	X
1	Rear end panel 595.30	Body	762.00	/
1	Rear end panel top garnish 215.00	Tw	298.00	/
1	Rear boot edge weatherstrip 168.50	Tw	184.00	/
			8707.60	
		less 20%	1741.52	20%
			6966.08	
	SPECIAL NETT ITEMS			
1 set	Rear Bumper clips	Ne	60.00	50 S.N
1	Rear windscreen sealant	Ne	100.00	40 "
1 set	Reverse sensor	shipped	280.00	200 "
1 set	Tailgate inner trim clips	Ne	60.00	50 "
1	Rear end panel sealant	Ne	100.00	50 "
	TOTAL PARTS		7566.08	

Not Authorized
 19/8/19
 4500
 521

P-4264.4
 202
 9-3611.5
 S.N-390
 L-1830
 5631.5
 4005

Vehicle No. SMN 457 M HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00 —	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00 —	900
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	150.00 —	20
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear	150.00 —	80
5	To remove and replace reverse sensors	120.00 —	50
6	To remove and refix rear tailgate windscreen	140.00 —	120
7	To provide anti-rust treatment on affected areas	120.00 —	60
	Labour Total :	2880.00	
	TOTAL (PARTS & LABOUR):	10446.08	1830

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: