

& Charn's Customeraft

Accident Claim Repair, Corrosion Welding, Body Dent Repair Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

FWD/III(SH6441D) DOA: 03/08/2019@1400

INDIA INTERNATIONAL INSURANCE PTE LTD

19/08/2019

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SFV 5949 T - MERCEDES BENZ E 250CGI

CHASSIS NO: WDD2120472A409777 (07/2011)

1 pc	Rear bumper Con	(NETT)	\$ 1,520.00
1 pc	Rear bumper chrome LH M	(NETT)	\$ 145.00
1 pc	Rear bumper chrome RH	(NETT)	\$ 145.00
1 pc	Rear bumper chrome CTR NEW/	(NETT)	\$ 175.00
1 pc	Reverse sensor Nw/	(NETT)	\$ 265.00
			\$ 2,250.00
	LESS 10%		\$ 225.00
			\$ 2,025.00

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel and rear bumper.

Putty and respray rear inner panel, rear end panel and rear bumper.

ADD 7% GST

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT the Repairer of the following:

LKK Auto Consultants hence notify

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

\$ 194.95 \$ 2,979.95

Resure & Per Capair