

ASS. REC. BY:

REF:

CF/MS419014531/Cgd3

Special Instruction:

n2

Supervisor: Simon

ASSIGNMENT (Office)

Meimien

From (Person): christina wong

of

MSLA

Date/Time:

14/8/19 @ 4:59pm

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SM36D

Insured:

SMG1507H

at Workshop m/s

MBM wheel/power

Tel:

62628888

of

160 Sin Ming Drive #06-02

Policy No:

A29117892APO

Claim No:

601483

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Cassandra

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Technician /
	SM36D-X
	SMG1507H-X
22/8/19 @ 2:29pm	confirmed with Cassandra final fig @ 3946.80, 5 days. (Red @ 5333.76, 57%).

RECEIVED 04 SEP 2019

**MSIG**

MSIG Insurance (Singapore Pte. Ltd)

(Co. Reg. No 200412212G)

4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sgExecutive
Claims Services**Inspection Report****Type of Survey:**

OD - Excess	☒
TP Without Prejudice	☒

Vehicle Details:

Vehicle Reg No

Make

Model

Passenger capacity

Paint colour & code

Paint type

SM 36 D
Honda
Vezel 1.5 A
05
Gold

Vehicle Extras:

In-built camera

Modification

Yes / No

Yes / No

Vehicle Data:

Odometer reading

Engine No

VIN No

Engine capacity

Engine modification

37569 km

Vehicle Condition:

Serviceable

Yes / No

Handbrake

Footbrake

Steering

Body

Paint

Tyre Condition:

Tread mm

Size

Condition

Front right

Front left

Rear left

Rear right

5	Dunlop	215 / 60 R16	
5		"	
4		"	
4		"	

General Data:

Date of accident

Date of inspection

Date of assignment

Inspection location

30-07-19
02-08-2019
01-08-2019
MBM

Painting Process:

Prepare off vehicle

Painting off vehicle

Neither (default)

Cost Details:

Parts

Supplementary

Miscellaneous

Body Labour

Paint labour

Paint material

TOTAL

Towing

Excess

Total less excess

Estimated days for repair

Repairer

Adjuster

Body Panel Repair:

Panel repair calculator used

Yes / No

--

150
11
161**Remarks:**

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Christina Wong

Date: 07 Aug 2019

Preliminary Advice

Insured Vehicle No	: SMG1507H	Accident Date	: 30/07/2019
TP Vehicle No	: SM36D	Assignment Date	: 07/08/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 02/08/2019		
Inspection At	: MBM WHEELPOWER PTE LTD (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion.

Repairer's Estimate (Gross)	:S\$	9,280.56
Revised Amount	:S\$	3,946.80
Check Items (Estimated)	:S\$	3,853.76
Total	:S\$	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	44,816.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

(x) The vehicle is economical/~~not economical~~ for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019		14 Aug 2019 16:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LI SHIWEN RICHARD, ID: S6882008A, Tel: +6581811339, Email: RICHLI8818@GMAIL.COM		
Main Claimant:	CHUA MAY KWONG MAUREEN, ID: S0171543G		
Vehicle Reg. No.:	SM36D	Date of Loss:	30/07/2019 09:00 - :59 [33 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 601483	Policy/Cover Note No.:	A29117892APO (Comprehensive) Coverage: 25/02/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SMG1507H	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	LI SHIWEN RICHARD (51 / Male) , NRIC: S6882008A, Tel: +6581811339 Email: RICHLI8818@GMAIL.COM		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. Assign: IHS. Contact: Cassandra @ 6262 8888 / 8686 5188.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: cassandra.chua@mbmwheelpower.com.sg
Sent: Tuesday, 27 August 2019 2:29 PM
To: Shiau Chan (LKKAUTO)
Cc: 'Danny Ong '
Subject: RE: Finalisation for SM 36 D

Dear Shiau Chan,

Amount confirmed.

Thank you.

Best Regards,
Cassandra Chua | Claims Advisor

T 6262 8888 | F 6250 9015 | M 8686 5188
Email: cassandra.chua@mbmwheelpower.com.sg
MBM Wheelpower PTE. LTD.
160 Sin Ming Drive • #06-02
Sin Ming Autocity • Singapore 575722
www.mbmwheelpower.com.sg

-----Original Message-----

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 27 August 2019 1:33 PM
To: cassandra.chua@mbmwheelpower.com.sg
Subject: RE: Finalisation for SM 36 D

Dear Cassandra,

WITHOUT PREJUDICE

Offer final fig \$3,946.80 before GST and 5 repair days.

Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: KKLau <kklau@lkkauto.com>
Sent: Saturday, 17 August 2019 4:02 PM
To: Jason Sim <Jason_Sim@sg.msiga-asia.com>
Cc: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Winnie Chua <pingping_chua@sg.msiga-asia.com>;
cassandra.chua@mbmwheelpower.com.sg; SUR <sur@lkkauto.com>; Celine Fong (LKKAUTO)
<celinefong@lkkauto.com>

Subject: Re: Finalisation for SM 36 D

Hi Jason,

To speed up the process, please add Sur and Celine in the loop.

Regards,
k K Lau
LKK Auto Consultants P L.

Sent from my iPad

> On 17 Aug 2019, at 11:05 AM, Jason Sim <Jason_Sim@sg.msig-asia.com> wrote:
>
> Hi LKK
>
> This case was re-assigned to you. Kindly help to finalise with workshop.
>
> Thanks
>
> Have a nice day
>
> Jason Sim
> Manager, Claims Services (Motor)
> D: +65 6643 1325 | F: +65 6225 7402 | jason_sim@sg.msig-asia.com<mailto:jason_sim@sg.msig-asia.com>
>
> [cid:image038.png@01D480C2.40700180]
>
> MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220
9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg<https://www.msig.com.sg/> [fb msig sg]
<https://www.facebook.com/msigsg/> [cid:image039.png@01D480C2.40700180]
<https://www.instagram.com/msigsg/> [in msig sg] <https://www.linkedin.com/company/msigsg/>
[MSIGSingapore] <https://www.youtube.com/user/MSIGSingapore>
>
> [MS&AD_Extract 150%]
>
> From: cassandra.chua@mbmwheelpower.com.sg [mailto:cassandra.chua@mbmwheelpower.com.sg]
> Sent: Saturday, 17 August, 2019 10:42 AM
> To: Jason Sim <Jason_Sim@sg.msig-asia.com>
> Cc: 'Danny Ong' <danny.ong@mbmwheelpower.com.sg>
> Subject: Finalisation for SM 36 D
>
> EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).
>
> Dear Jason,
>
> Refer to attached.
>
> Part by Part: \$4,436.80/- (Before GST) 05 Repair Days
>
> Thank you.
>
>
>
> Best Regards,

> Cassandra Chua | Claims Advisor

>

> [cid:image001.png@01D5537C.1F6D8920]

> T 6262 8888 | F 6250 9015 | M 8686 5188

> Email: cassandra.chua@mbmwheelpower.com.sg<mailto:cassandra.chua@mbmwheelpower.com.sg>

> MBM Wheelpower PTE. LTD.

> 160 Sin Ming Drive • #06-02

> Sin Ming Autocity • Singapore 575722

> www.mbmwheelpower.com.sg<https://protect2.fireeye.com/url?k=0feb1220-53f88ab6-0fec1e75-0cc47a6d1990-d2444a32f12babfb&q=1&u=http%3A%2F%2Fwww.mbmwheelpower.com.sg%2F>

>

>

>

>

> **CONFIDENTIALITY NOTICE**

> This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> <image001.png>

> <image002.png>

> <image003.png>

> <image004.png>

> <image005.png>

> <image006.png>

> <image007.jpg>

> <20190815151126224.pdf>

> <Before Repair Photo 17 SM 36 D.jpg>

> <Before Repair Photo 11 SM 36 D.jpg>

> <Before Repair Photo 12 SM 36 D.jpg>

> <Before Repair Photo 13 SM 36 D.jpg>

> <Before Repair Photo 14 SM 36 D.jpg>

> <Before Repair Photo 15 SM 36 D.jpg>

> <Before Repair Photo 16 SM 36 D.jpg>

> <Before Repair Photo 18 SM 36 D.jpg>

Celine Fong (LKKAUTO)

From: Jason Sim <Jason_Sim@sg.msig-asia.com>
Sent: Saturday, 17 August 2019 11:05 AM
To: KKLau; Bryan Ang (LKKAUTO)
Cc: Winnie Chua; cassandra.chua@mbmwheelpower.com.sg
Subject: FW: Finalisation for SM 36 D
Attachments: 20190815151126224.pdf; Before Repair Photo 17 SM 36 D.jpg; Before Repair Photo 11 SM 36 D.jpg; Before Repair Photo 12 SM 36 D.jpg; Before Repair Photo 13 SM 36 D.jpg; Before Repair Photo 14 SM 36 D.jpg; Before Repair Photo 15 SM 36 D.jpg; Before Repair Photo 16 SM 36 D.jpg; Before Repair Photo 18 SM 36 D.jpg

Importance: High

Hi LKK

This case was re-assigned to you. Kindly help to finalise with workshop.

Thanks

Have a nice day

Jason Sim
Manager, Claims Services (Motor)
D: +65 6643 1325 | F: +65 6225 7402 | jason_sim@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: cassandra.chua@mbmwheelpower.com.sg [mailto:cassandra.chua@mbmwheelpower.com.sg]
Sent: Saturday, 17 August, 2019 10:42 AM
To: Jason Sim <Jason_Sim@sg.msig-asia.com>
Cc: 'Danny Ong' <danny.ong@mbmwheelpower.com.sg>
Subject: Finalisation for SM 36 D

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Jason,

Refer to attached.

Part by Part: \$4,436.80/- (Before GST) 05 Repair Days

Thank you.

Best Regards,
Cassandra Chua | Claims Advisor



T 6262 8888 | F 6250 9015 | M 8686 5188

Email: cassandra.chua@mbmwheelpower.com.sg

MBM Wheelpower PTE. LTD.

160 Sin Ming Drive • #06-02

Sin Ming Autocity • Singapore 575722

www.mbmwheelpower.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____

Insured Vehicle No : SMR 1507H

Date of Accident : 30-07-2019

TP Vehicle No : SM 36D

Place of Survey : MBM

Make & Model : Honda Vezel

Date of Survey : 02-08-2019

Point of Impact / Damages :


Rear

Recommended Reserve :

Repairer's Estimate : \$ 9280.56

Interim Adjustment : \$ 3946.80

Check Items : \$ 3853.76



Proposed : Part by Part / Lump Sum Repair

Excess : \$ _____

Estimate Repair Period : 05 days

Pre-accident Market Value (for total loss consideration) : \$ 68000.00

COE / PARF to owner : \$ 44816.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. SM 36 D

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 02-08-19

Victor - Seng @ sg.msig-asia.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 543G

Vehicle Details

Vehicle No.: SM36D
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Jul 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X A
Primary Colour: Brown
Manufacturing Year: 2016
Engine No.: L15B4403362
Chassis No.: RU11203363
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,387.00
Original Registration Date: 03 Oct 2016
First Registration Date: 03 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$11,942.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Oct 2026
PARF Rebate Amount: \$8,956.00

Intended COE Rebate Details

COE Expiry Date: 02 Oct 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,000.00
COE Rebate Amount: \$35,860.00
Total Rebate Amount: \$44,816.00

The information contained herein is correct as at 30 Jul 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SM36D
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Chassis No.:	RU11203363
Propellant:	Petrol
Engine No.:	L15B4403362
Engine Capacity:	1496 cc
Maximum Power Output:	96.0 kW (128 bhp)
Maximum Laden Weight:	1465 kg
Unladen Weight:	1190 kg
Year Of Manufacture:	2016
Original Registration Date:	03 Oct 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$50,000.00
COE Expiry Date:	02 Oct 2026
Road Tax Expiry Date:	02 Oct 2019
PARF Eligibility Expiry Date:	02 Oct 2026
Inspection Due Date:	02 Oct 2021
Intended Transfer Date:	05 Sep 2019
CO2 Emission:	117.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 02 Oct 2019. You may renew the road tax from 03 Jul 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 Oct 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 03 Oct 2019 to 02 Apr 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 03 Oct 2019 to 02 Oct 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMG 1507 H

OUR REF.: SM 36 D

mbm wheelpower

TO: MSIG

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 1/8/2019

FROM: CASSANDRA

FAX: 6452 5333

CONTACT: 8686 5188

MAKE & MODEL: HONDA VEZEL

CHASSIS NO.: RU11203363

ENGINE NO.: L15B4403362

YEAR MADE: 2016

ACCIDENT DATE: 30 July 2019

ESTIMATE FOR VEHICLE NO.: SM 36 D

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE / <i>Deformed</i>		1	\$ 1,338.00 /
2	TAILGATE WEATHERSTRIP / <i>deformed</i>		1	\$ 158.00 /
3	REAR WINDSCREEN MOULDING / <i>necc</i>		2	\$ 164.80 /
4	TAILGATE MOULDING / <i>neu</i>		1	\$ 350.00 /
5	TAILGATE LAMP RH ?		1	\$ 400.00 X
6	TAILGATE LAMP LH ?		1	\$ 400.00 X
7	TAILGATE "H" LOGO / <i>necc</i>		1	\$ 71.60 /
8	TAILGATE "VEZEL" EMBLEM / <i>necc</i>		1	\$ 104.80 /
9	TAILGATE LOCK ASSY ?		1	\$ 168.80 X
10	TAILGATE INNER TRIM ?		1	\$ 254.40 X
11	TAILLAMP RH ?		1	\$ 552.80 X
12	TAILLAMP LH ?		1	\$ 552.80 X
13	REAR BUMPER / <i>Deformed</i>		1	\$ 528.80 /
14	REAR BUMPER CLIP / <i>necc</i>		10	\$ 80.00 /
15	REAR BUMPER REFLECTOR RH ?		1	\$ 185.60 X
16	REAR BUMPER REFLECTOR LH ?		1	\$ 185.60 X
17	END PANEL ?		1	\$ 756.40 X
18	END PANEL RH ?		1	\$ 258.80 X
19	END PANEL LH ?		1	\$ 258.80 X
20	END PANEL TOP GARNISH ?		1	\$ 155.60 X
21	REAR TOP BOARD ?		1	\$ 350.00 X
22	REAR TOOL BOX GARNISH ?		1	\$ 337.60 X
23	REAR FENDER INNER TRIM RH X		1	\$ 350.00 X
24	REAR FENDER INNER TRIM LH X		1	\$ 350.00 X
TOTAL:				\$ 8,313.20
LESS 20%:				\$ (1,662.64)
PARTS TOTAL:				\$ 6,650.56

SPECIAL NETT

BODY SEALANT
WINDSCREEN SEALANT
REAR NUMBER PLATE WITH HOLDER
REVERSE SENSOR (1 SET)

NE	1	\$	40	80.00
NE	1	\$	80	150.00
	1	\$	60	80.00
	1	\$	200	300.00

Handwritten: SP 60, 200, 300.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT,
WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO APPLY ANTI RUST COATING
TO REMOVE & REFIT REAR WINDSCREEN
TO CONDUCT CHASSIS ALIGNMENT
TO REMOVE & INSTALL REVERSE SENSOR
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	500	600.00
	\$	50	120.00
	\$	100	250.00
	\$	100	150.00
	\$	80	120.00
	\$	50	80.00
	\$	450	700.00
TOTAL:	\$		9,280.56
7% GST:	\$		649.64
GRAND TOTAL:	\$		9,930.20

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMG 1507 H


OUR REF.: SM 36 D

TO: MSIG

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 1/8/2019
FROM: CASSANDRA
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: HONDA VEZEL
CHASSIS NO.: RU11203363
ENGINE NO.: L15B4403362
YEAR MADE: 2016
ACCIDENT DATE: 30 July 2019



FINALISED ESTIMATE FOR VEHICLE NO.: SM 36 D

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE		1	\$ 1,338.00
2	TAILGATE WEATHERSTRIP		1	\$ 158.00
3	REAR WINDSCREEN MOULDING		2	\$ 164.80
4	TAILGATE MOULDING		1	\$ 350.00
5	TAILGATE "H" LOGO		1	\$ 71.60
6	TAILGATE "VEZEL" EMBLEM		1	\$ 104.80
7	REAR BUMPER		1	\$ 528.80
8	REAR BUMPER CLIP		10	\$ 80.00
TOTAL:				\$ 2,796.00
LESS 20%:				\$ (559.20)
PARTS TOTAL:				\$ 2,236.80

<u>SPECIAL NETT</u>			
BODY SEALANT	1	\$	40.00
WINDSCREEN SEALANT	1	\$	80.00
REAR NUMBER PLATE WITH HOLDER	1	\$	60.00
REVERSE SENSOR (1 SET)	1	\$	200.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	500.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	50.00
TO APPLY ANTI RUST COATING	\$	100.00
TO REMOVE & REFIT REAR WINDSCREEN	\$	100.00
TO CONDUCT CHASSIS ALIGNMENT	\$	80.00
TO REMOVE & INSTALL REVERSE SENSOR	\$	540.00 ??
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	450.00
TOTAL:	\$	4,436.80
7% GST:	\$	310.58
GRAND TOTAL:	\$	4,747.38

PART BY PART: \$ 4,436.80

BEFORE GST

05 REPAIR DAYS

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014531/CQD3N2

Date: 18/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29117892APO
Claimant Vehicle No :	SM36D	Insured Vehicle No :	SMG1507H
Date of Loss:	30/07/2019	Nature of Claim:	TP
		Claim No:	601483

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SM36D	Engine No:	L15B4403362
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11203363
Reg. Date:	03/10/2016 (Man. Year: 2016)	Odometer:	37569 km
Colour:	Gold		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,260.56	2,616.80	4,643.76	63.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,330.00	690.00	34.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,280.56	3,946.80	5,333.76	57.47
+ GST 7.00/7.00% (S\$)	649.64	276.28	373.36	57.47
Nett Amount (S\$)	9,930.20	4,223.08	5,707.12	57.47

INSPECTION

Date of Assignment:	14/08/2019	
Date Inspected:	02/08/2019	Inspected At:
		MBM Wheelpower Pte Ltd (HQ)
		160 Sin Ming Drive #06-02, Sin Ming
		AutoCity
		Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SM36D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Deformed	1,338.00 FL	*1,338.00 FL
2	1		*TAILGATE WEATHERSTRIP	Deformed	158.00 FL	*158.00 FL
3	2		*REAR WINDSCREEN MOULDING	Necessary	164.80 FL	*164.80 FL
4	1		*TAILGATE MOULDING	Necessary	350.00 FL	*350.00 FL
5	1		*TAILGATE LAMP RH	Not Necessary	400.00 FL	*- FL
6	1		*TAILGATE LAMP LH	Not Necessary	400.00 FL	*- FL
7	1		*TAILGATE H LOGO	Necessary	71.60 FL	*71.60 FL
8	1		*TAILGATE VEZEL EMBLEM	Necessary	104.80 FL	*104.80 FL
9	1		*TAILGATE LOCK ASSY	Not Necessary	168.80 FL	*- FL
10	1		*TAILGATE INNER TRIM	Not Necessary	254.40 FL	*- FL
11	1		*TAILLAMP RH	Not Necessary	552.80 FL	*- FL
12	1		*TAILLAMP LH	Not Necessary	552.80 FL	*- FL
13	1		*REAR BUMPER	Deformed	528.80 FL	*528.80 FL
14	10		*REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
15	1		*REAR BUMPER REFLECTOR RH	Not Necessary	185.60 FL	*- FL
16	1		*REAR BUMPER REFLECTOR LH	Not Necessary	185.60 FL	*- FL
17	1		*END PANEL	Not Necessary	756.40 FL	*- FL
18	1		*END PANEL RH	Not Necessary	258.80 FL	*- FL
19	1		*END PANEL LH	Not Necessary	258.80 FL	*- FL
20	1		*END PANEL TOP GARNISH	Not Necessary	155.60 FL	*- FL
21	1		*REAR TOP BOARD	Not Necessary	350.00 FL	*- FL
22	1		*REAR TOOL BOX GARNISH	Not Necessary	337.60 FL	*- FL
23	1		*REAR FENDER INNER TRIM RH	Not Necessary	350.00 FL	*- FL
24	1		*REAR FENDER INNER TRIM LH	Not Necessary	350.00 FL	*- FL
25	1		*BODY SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
27	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	80.00 FS	*60.00 FS
28	1		*SET REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,923.20	3,176.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,662.64	559.20
Total Parts (\$\$)	7,260.56	2,616.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS,INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	600.00	500.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	50.00
3	TO APPLY ANTI RUST COATING	New	250.00	100.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	100.00
5	TO CONDUCT C/JASSIS ALIGNMENT	New	120.00	80.00
6	TO REMOVE & INSTALL REVERSE SENSOR	New	80.00	50.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	450.00
Gross Labour Cost (\$\$)			2,020.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >