

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road,#17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Steve Lim

Date: 21 Aug 2019

Preliminary Advice

Insured Vehicle No : SLV4583A
TP Vehicle No : GBF2974X
Make : NISSAN NP300 NAVARA
Date of Inspection : 20/08/2019
Inspection At : Soc Leon Motor Works (Kaki Bukit)
1 Kaki Bukit Ave 6,#01-91, AutoBay@Kaki Bukit
Singapore 417883

Accident Date : 15/08/2019
Assignment Date : 19/08/2019
Est. Duration of Repair : 2 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,872.09
Revised Amount	:S\$	1,050.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,050.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.