

Soc Leon Motor Works (Co.Reg.No:20663900K)

1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit
Singapore 417883
Tel: 6747 7858 Fax: 6742 0012 Email: slmoi@singnet.com.sg

TP INSURER:
0

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/08/2019
Vehicle Reg. No.:	GBF2974X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG WEE SIONG (HUANG WEIXIONG)		
Make/Model:	NISSAN NP300 NAVARA, 2.3 D (M)	Vehicle Reg. Date:	27/08/2016
Vehicle Colour:	WHITE	Chassis No:	MNTCB4D23Z0000038
Engine No:	0		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	SOC LEON MOTOR WORKS (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	744.70
Miscellaneous Items	47.39
Labour	1,080.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	1,872.09

This claim is handled by: IRENE LEONG SUM PHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Not Allowed
20/8/19
1050
20/8/19
Wang...

Insurer's representative hereby notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Resurvey to be subject to confirmation
- Resurvey to be on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Aug 2019)
Parts: N/A NISSAN NP300 NAVARA 2.3 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF2974X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER (LH) <i>Rep/Sec</i>	0.00	0.00	*265.00 F ✓
2	1		*FENDER INNERSHIELD <i>Dis</i>	0.00	0.00	*80.00 F ✓
3	1		*INNERSHIELD CLIPS (10 PCS) @S\$2.50 <i>1 ec</i>	0.00	0.00	*25.00 F ✓
4	1		*FRONT BUMPER <i>Re/00</i>	0.00	0.00	*285.00 F ✓
5	1		*BUMPER SIDE RETAINER (LH) <i>1-1</i>	0.00	0.00	*22.00 F X
Sub Total (S\$)						677.00
+ Margin on L,N Items 10.00% (S\$)						67.70
Total Parts (S\$)						744.70

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

658
12

720.90

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	7% GST FROM SUPPLIER BILL	47.39
Sub Total (S\$)			47.39

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO SPRAY ANTI-RUST	New	80.00
2	LABOUR TO REMOVE & REPLACE PARTS	New	600.00
3	SPRAYPAINTING	New	400.00
Gross Labour Cost (S\$)			1,080.00

Handwritten notes:
 30
 220
 350

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

1320.5