

ASS. REC. BY:

REP:

CF/MSG19014335/dqd30

Special Instructions:

Surveyor:

Maimen

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MS16

Date/Time:

14/01/19 @ 4:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH8192K

Insured:

YN8539R

at Workshop m/s

Dynamic Autowork

Tel:

9856 4815

of

8 Kerk Bukit Ave 4 # 08-09

Policy No:

27937347

Claim No:

600337

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Michelle

Vehicle:

IN/OUT

Date/Time

Action/Instruction

1. Submit

GBH8192K - NA / TMS19012725/13

D.O.A: 18/7/2019

YN8539R - NA / TMS19012725/13

D.O.A: 18/7/2019

- Re-survey photos

17/01/20 @ 4:33pm confirmed with Michelle is \$9500, 8 days by email.

(led \$11965.75, 56%)

RECEIVED 20 JAN 2020

150
11
161



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	☒

Vehicle Data:

Odometer reading	9810 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

GBH 8192K
Toyota
Proace
02
black

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / No

Vehicle Condition:

Seviceable Yes / No

Handbrake	
Footbrake	
Steering	
Body	
Paint	

Tyre Condition:

Tread mm Size Condition

Front right	5	Michelin 215 / 65 / 16	
Front left	5	"	
Rear left	4	"	
Rear right	4	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

18-07-19
24-07-19
23-07-19
Dynamic

Painting Process:

Prepare off vehicle	
Painting off vehicle	
Neither (default)	

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used	
Yes / No	

Remarks:

Lump / Global Sum	
-------------------	--

Reason(s) Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2019 16:10		14 Aug 2019 16:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FULLHOUSE HOME FURNISHINGS PTE LTD, Co. Reg. No.: 200800889D		
Main Claimant:	CHOW YI WEN, ID: S8004547F		
Vehicle Reg. No.:	GBH8192K	Date of Loss:	18/07/2019 14:00 - :59 [9 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 600337	Policy/Cover Note No.:	27937347 (Comprehensive) Coverage: 20/07/2018 - 19/07/2019
Vehicle Reg. No. (Insured):	YN8539R	Policy No. (Claimant):	
		Excess:	
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	DIDAR MUSTAKIM BILLAH {}, NRIC: G6515481T Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP, Liab: 100%, Assign: IHS, Contact: Michelle @ 9856 4815.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Dynamic Autowork <dynamicautowork@gmail.com>
Sent: Friday, 11 October 2019 1:47 PM
To: Shiau Chan (LKKAUTO)
Cc: Admin A; Jason Sim; Muhd Ashik B Madi; Claims
Subject: Re: KINDLY ADVISE THE STATUS OF GBH 8192K (DOA: 18/07/2019)

Dear Shiau Chan,

We refer to the above matter.

We are unable to accept the COR that you offered on 10/10/2019, as there was a huge difference between the amount that recommended by the **MSIG-In House Surveyor** based on the markings on estimate (when he physically conducted the survey on the vehicle) and what you offered.

According to NIMA protocol, the appointed **MSIG-In House Surveyor** is agreed between the insurers (MSIG) and us (the workshop) to conduct the pre repair survey (SJE). Thus, there shouldn't be any dispute on the items that were recommended by the **MSIG In-House Surveyor** and marked with ticks. Furthermore the labour section also had been adjusted by the MSIG In-House Surveyor prior to confirmation.

Please re-adjust the cost of repair fair and reasonably; and note the photos of those items with question marking (clearly shown the damages) we sent to you on 02/09/2019.

We shall looking ahead for your reply soon.

On Thu, Oct 10, 2019 at 12:07 PM Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Michelle,

As spoken with you.

Re-offer Lump Sum \$8,750.00 before GST and 8 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Dynamic Autowork <dynamicautowork@gmail.com>
Sent: Friday, 17 January 2020 4:33 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: KINDLY ADVISE THE STATUS OF GBH 8192K (DOA: 18/07/2019)

Dear Shiau Chan,

Lump Sum 9,500.00 before GST and 8 repair days--OFFER ACCEPT.

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

On Fri, Jan 17, 2020 at 4:00 PM Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Michelle,

WITHOUT PREJUDICE

Re-offer Lump Sum 9,500.00 before GST and 8 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.



YARVBB

Shiau Chan (LKKAuto)

From: Dynamic Autowork <dynamicautowork@gmail.com>
Sent: Thursday, 22 August 2019 1:13 PM
To: Shiau Chan (LKKAuto)
Subject: Re: KINDLY ADVISE THE STATUS OF GBH 8192K (DOA: 18/07/2019)
Attachments: 22082019130743.pdf; Picture1.jpg; Picture2.jpg; Picture3.jpg

Dear Shiau Chan,

Please refer to attach document and after repair photos.

Can we close the case at **\$10,700.00 (8 days)**?

On Thu, Aug 22, 2019 at 12:06 PM Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Sir/Madam,

Kindly advise the status of GBH 8192K (MSIG-TP).

If done of repair, kindly send us the before or after paint photos and final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)

Celine Fong (LKKAUTO)

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Wednesday, 14 August 2019 9:53 AM
To: assignments
Subject: FW: GBH8192K (Finalize) for Victor Seng's case
Attachments: 02082019101209.pdf; Picture3.jpg; Picture1.jpg; Picture2.jpg

Dear Denise,

As spoken, please assist to finalise for this case. Tks.

Best Regards

Winnie Chua
Senior Admin Officer, Claims Services (In-House Survey)
Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Jason Sim
Sent: Wednesday, 14 August 2019 9:25 AM
To: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: FW: GBH8192K (Finalize)

Hi Winnie

Please check our listing and forward to OIC to resolve this

Thanks

Have a nice day

Jason Sim
Manager, Claims Services (Motor)
D: +65 6643 1325 | F: +65 6225 7402 | jason_sim@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]
Sent: Tuesday, 13 August, 2019 5:21 PM

To: Jason Sim <Jason_Sim@sg.msig-asia.com>

Subject: Fwd: GBH8192K (Finalize)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Jason,

We understand Victor Seng is no longer with MSIG.

Please refer to attach document and after repair photos.

Can we close the said case at **\$10,700.00 (8 days)**?

Kindly assist and we are looking ahead for your reply.

----- Forwarded message -----

From: **Dynamic Autowork** <dynamicautowork@gmail.com>

Date: Fri, Aug 2, 2019 at 10:14 AM

Subject: GBH8192K (Finalize)

To: <victor_seng@sg.msig-asia.com>

Dear Victor,

Please refer to attach estimate and after repair photo.

Can we close the case at \$10,700 (8days)

Please note the above vehicle is under DYNAMIC AUTOWORK PTE.LTD. and sorry for typing error

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Muhd Ashik B Madi

Date: 25 Jul 2019

Preliminary Advice

Insured Vehicle No	: YN8539R	Accident Date	: 18/07/2019
TP Vehicle No	: GBH8192K	Assignment Date	: 22/07/2019
Make	: TOYOTA PROACE	Est. Duration of Repair	: 8.00
Date of Inspection	: 24/07/2019		
Inspection At	: DYNAMIC AUTOWORK PTE. LTD (HQ) 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages Rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,465.75
Revised Amount	:S\$	8,864.50
Check Items (Estimated)	:S\$	3,635.00
Total	:S\$	

Lump Sum Repair	:S\$	10,000.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (x) The vehicle is economical/~~not economical~~ for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	547F
Vehicle Details	
Vehicle No.:	GBH8192K
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PROACE COMFORT COMPACT 1.6 MANUAL
Primary Colour:	Black
Secondary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	BH020023913
Chassis No.:	YARVBBHVBGZ104428
Maximum Power Output:	-
Open Market Value:	\$31,761.00
Original Registration Date:	28 Sep 2018
First Registration Date:	28 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$1,589.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,104.00
COE Rebate Amount:	\$24,559.00
Total Rebate Amount:	\$24,559.00

The information contained herein is correct as at 05 Sep 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBH8192K		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	PROACE COMFORT COMPACT 1.6 MANUAL		
Chassis No. :	YARVBBHVBGZ104428		
Propellant :	Diesel		
Engine No. :	BH020023913		
Engine Capacity :	1560 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2610 kg		
Unladen Weight :	1580 kg		
Year Of Manufacture :	2017		
Original Registration Date :	28 Sep 2018		
Lifespan Expiry Date :	27 Sep 2038		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$27,104.00		
COE Expiry Date :	27 Sep 2028		
Road Tax Expiry Date :	27 Sep 2019		
Inspection Due Date :	27 Sep 2020		
Intended Transfer Date :	05 Sep 2019		
CO2 Emission :	144.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	0.259000 (g/km)		
HC Emission :	0.021400 (g/km)		
NOx Emission :	0.048200 (g/km)		
PM Emission :	0.150000 (mg/km)		
The current road tax expiry is 27 Sep 2019. You may renew the road tax from 28 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 28 Sep 2019 to 27 Mar 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Amount Payable (From 28 Sep 2019 to 27 Sep 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$50.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg**PRELIMINARY ADVICE**

OD Claim / TP Claim

Attn : _____

Date : _____

Policy No : _____

Claim No : _____

Insured Vehicle No : YN 8539R Date of Accident : 18-02-19TP Vehicle No : LBH 8192K Place of Survey : DynamicMake & Model : Toyota Proace Date of Survey : 24-07-19

Point of Impact / Damages :

Rear

Recommended Reserve :

Repairer's Estimate : \$ 21465.75Interim Adjustment : \$ 8864.50Check Items : \$ 3635.00

Proposed : Part by Part / Lump Sum Repair \$10000/-

Excess : \$ -Estimate Repair Period : 08 daysPre-accident Market Value (for total loss consideration) : \$ -COE / PARF to owner : \$ -Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. EBH 8192K

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 08 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 24-07-19

Victor - Seng @ sg.msig-asia.com

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 23.07.19

TO : **MSIG** MOTOR CLAIMS DEPTS

VEHICLE NO : **GBH8192K**

MODEL : **TOYOTA PROACE**

DATE OF ACCIDENT : 18.07.19

TIME OF ACCIDENT : 14:20HRS

YARYBB

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / Deformed.	1	\$ 1,361.00	\$ 1,361.00
2	REAR BUMPER REFLECTOR ? LH-CRA	2	\$ 87.00	\$ 174.00
3	REAR BUMPER TOW HOOK COVER ?	1	\$ 65.00	\$ 65.00
4	REAR BUMPER SIDE RETAINER ? LH-DIS	2	\$ 115.00	\$ 230.00
5	REAR BUMPER CENTER BEAM / Dented	1	\$ 355.00	\$ 355.00
6	REAR BUMPER REINFORCEMENT / Dented	1	\$ 823.00	\$ 823.00
7	TAIL LAMP ? CRA	2	\$ 378.00	\$ 756.00
8	BACK DOOR LH / Deformed.	1	\$ 1,850.00	\$ 1,850.00
9	BACK DOOR GLASS LH X NN	1	\$ 795.00	\$ 795.00
10	BACK DOOR LOGO LH / recc	1	\$ 59.00	\$ 59.00
11	BACK DOOR EMBLEM 'TOYOTA' LH / reccc	1	\$ 79.00	\$ 79.00
12	BACK DOOR NUMBER PLATE LAMP ?	2	\$ 105.00	\$ 210.00
13	BACK DOOR OUTER HANDLE LH ? CVT	1	\$ 81.00	\$ 81.00
14	BACK DOOR INNER TRIM LH / cracked	1	\$ 145.00	\$ 145.00
15	BACK DOOR KEY LOCK LH ? BT	1	\$ 124.00	\$ 124.00
16	BACK DOOR AUTO LOCK MOTOR LH ?	1	\$ 285.00	\$ 285.00
17	BACK DOOR RH / Dented	1	\$ 1,850.00	\$ 1,850.00
18	BACK DOOR GLASS RH X NN	1	\$ 795.00	\$ 795.00
19	BACK DOOR EMBLEM 'PROACE' RH / recc	1	\$ 89.00	\$ 89.00
20	BACK DOOR INNER TRIM RH ? BT CRA	1	\$ 145.00	\$ 145.00
21	BACK DOOR FRAME WEATHERSTRIP / torn	1	\$ 220.00	\$ 220.00
22	BACK DOOR UPPER LOCK ?	2	\$ 245.00	\$ 490.00
23	BACK DOOR LOWER LOCK ?	2	\$ 275.00	\$ 550.00
24	BACK DOOR HINGE ?	4	\$ 185.00	\$ 740.00
25	BACK DOOR CHECKER ?	2	\$ 180.00	\$ 360.00
26	BACK DOOR WEATHERSTRIP CENTER ?	1	\$ 170.00	\$ 170.00
27	REAR END PANEL / Dented	1	\$ 780.00	\$ 780.00
28	REAR END PANEL (INNER) X repair.	1	\$ 670.00	\$ 670.00
29	REAR END PANEL TOP GARNISH / cracked	1	\$ 195.00	\$ 195.00

950.50

X NN

682

X NN

X SVC

X SVC

BT

X NN

X NN

DD

MSIG

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBH8192K**
 MODEL : **TOYOTA PROACE**
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

30	REAR FLOOR PANEL <i>X repair</i>	1	\$ 2,375.00	\$ 2,375.00
----	----------------------------------	---	-------------	-------------

TOTAL PRICE \$ 16,821.00
 LESS 25% \$ 4,205.25
SUB TOTAL PRICE \$ 12,615.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>✓ Dentab</i>	1	\$ 50.00	\$ 50.00 <i>✓</i>
2	REAR BUMPER CLIP (SET) <i>✓ recc</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	TAIL LAMP CLIP (SET) <i>✓ recc</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
4	REAR DOOR SEALANT <i>✓ NEC</i>	2	\$ 150.00	\$ 300.00 <i>150</i>
5	REAR DOOR GLASS SEALANT <i>✓ NEC</i>	2	\$ 80.00	\$ 160.00 <i>100</i>
6	REAR DOOR GLASS INNER SEAL <i>✓ NEC</i>	2	\$ 60.00	\$ 120.00 <i>60</i>
7	REAR DOOR GLASS SOLAR FILM <i>X NN</i>	2	\$ 400.00	\$ 800.00 <i>X</i>
8	REAR DOOR INNER BOARD CLIP (SET) <i>✓ NEC</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
9	REAR DOOR STICKER '70KM/H' <i>✓ recc</i>	1	\$ 30.00	\$ 30.00 <i>✓</i>
10	REAR DOOR STICKER 'WHAT VAN 2017' <i>✓ recc</i>	1	\$ 80.00	\$ 80.00 <i>✓</i>
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>✓ recc</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
12	REAR END PANEL INSULATION SEAL <i>✓ recc</i>	1	\$ 150.00	\$ 150.00 <i>100</i>
13	REAR FLOOR PANEL INSULATION SEAL <i>X NN</i>	1	\$ 350.00	\$ 350.00 <i>X</i>
14	REAR FLOOR TOP COVER BOARD (SPECIAL TYPE) <i>✓ craft</i>	1	\$ 650.00	\$ 650.00 <i>450</i>
15	REVERSE SENSOR <i>✓ short</i>	1	\$ 250.00	\$ 250.00 <i>200</i>
16	REVERSE CAMERA <i>?</i>	1	\$ 480.00	\$ 480.00 <i>350? X NN</i>

TOTAL \$3,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	100
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	X
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	30
8	REMOVE & REINSTALL VIDEO RECORDER	\$ 120.00	70

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBH8192K**
 MODEL : **TOYOTA PROACE**
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

9	TRANSFER REAR DOOR MECHANISM X2	\$ 160.00 100	
10	REMOVE & REINSTALL REAR DOOR GLASS X2	\$ 160.00 100	
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
13	REMOVE AND REFIX REAR FLOOR BOARD	\$ 250.00 50	
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$5,170.00

ESTIMATE REPORT

TOTAL PARTS COST : \$16,295.75
 TOTAL LABOUR COST : \$5,170.00
 TOTAL REPAIR COST : \$21,465.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP : 9856 4815

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)
8 Kaki Bukit Ave 4, #06-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail: dynamicautowork@gmail.com

DATE : 22.07.19

TO : MSIG MOTOR CLAIMS DEPTS
VEHICLE NO : GBH8192K
MODEL : TOYOTA PROACE
DATE OF ACCIDENT : 18.07.19
TIME OF ACCIDENT : 14:20HRS

11 10700.00

WE APPEND HEREBY THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / Deformed	1	\$ 1,361.00	\$ 1,361.00
2	REAR BUMPER REFLECTOR 2	2	\$ 87.00	\$ 174.00
3	REAR BUMPER TOW HOOK COVER	1	\$ 65.00	\$ 65.00
4	REAR BUMPER SIDE RETAINER 2	2	\$ 115.00	\$ 230.00
5	REAR BUMPER CENTER BEAM / Deformed	1	\$ 355.00	\$ 355.00
6	REAR BUMPER REINFORCEMENT / Deformed	1	\$ 823.00	\$ 823.00
7	TAIL LAMP 2	2	\$ 378.00	\$ 756.00
8	BACK DOOR LH / Deformed	1	\$ 1,850.00	\$ 1,850.00
9	BACK DOOR GLASS LH X	1	\$ 795.00	\$ 795.00
10	BACK DOOR LOGO LH / recc	1	\$ 59.00	\$ 59.00
11	BACK DOOR EMBLEM TOYOTA LH / recc	1	\$ 79.00	\$ 79.00
12	BACK DOOR NUMBER PLATE LAMP 2	2	\$ 105.00	\$ 210.00
13	BACK DOOR OUTER HANDLE LH	1	\$ 81.00	\$ 81.00
14	BACK DOOR INNER TRIM LH / cracked	1	\$ 145.00	\$ 145.00
15	BACK DOOR KEY LOCK LH	1	\$ 124.00	\$ 124.00
16	BACK DOOR AUTO LOCK MOTOR LH 2	1	\$ 265.00	\$ 265.00
17	BACK DOOR RH / Deformed	1	\$ 1,850.00	\$ 1,850.00
18	BACK DOOR GLASS RH	1	\$ 795.00	\$ 795.00
19	BACK DOOR EMBLEM 'PROACE' RH / recc	1	\$ 59.00	\$ 59.00
20	BACK DOOR INNER TRIM RH	1	\$ 145.00	\$ 145.00
21	BACK DOOR FRAME WEATHERSTRIP / torn	1	\$ 220.00	\$ 220.00
22	BACK DOOR UPPER LOCK 2	2	\$ 248.00	\$ 496.00
23	BACK DOOR LOWER LOCK	2	\$ 275.00	\$ 550.00
24	BACK DOOR HINGE 2	4	\$ 155.00	\$ 620.00
25	BACK DOOR CHECKER 2	2	\$ 180.00	\$ 360.00
26	BACK DOOR WEATHERSTRIP CENTER	1	\$ 172.00	\$ 172.00
27	REAR END PANEL / Deformed	1	\$ 780.00	\$ 780.00
28	REAR END PANEL (INNER) X	1	\$ 670.00	\$ 670.00
29	REAR END PANEL TOP GARNISH / cracked	1	\$ 195.00	\$ 195.00

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH8192K
 MODEL : TOYOTA PROACE
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

30	REAR FLOOR PANEL	X repair	1	\$ 2,375.00	\$ 2,375.00
----	------------------	----------	---	-------------	-------------

TOTAL PRICE \$ 18,821.00
 LESS 25% \$ 4,205.25
 SUB TOTAL PRICE \$ 12,615.75

12186
 2.048.25
 9127.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE / Dentet	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) / rec	1	\$ 80.00	\$ 80.00
3	TAIL LAMP CLIP (SET) / rec	1	\$ 50.00	\$ 50.00
4	REAR DOOR SEALANT	2	\$ 150.00	\$ 300.00
5	REAR DOOR GLASS SEALANT	2	\$ 80.00	\$ 160.00
6	REAR DOOR GLASS INNER SEAL	2	\$ 60.00	\$ 120.00
7	REAR DOOR GLASS SOLAR FILM X	2	\$ 400.00	\$ 800.00
8	REAR DOOR INNER BOARD CLIP (SET) /	1	\$ 80.00	\$ 80.00
9	REAR DOOR STICKER '70KM/H' / rec	1	\$ 30.00	\$ 30.00
10	REAR DOOR STICKER 'WHAT VAN 2017' / rec	1	\$ 80.00	\$ 80.00
11	REAR END PANEL TOP GARNISH CLIP (SET) / rec	1	\$ 50.00	\$ 50.00
12	REAR END PANEL INSULATION SEAL / rec	1	\$ 150.00	\$ 150.00
13	REAR FLOOR PANEL INSULATION SEAL X	1	\$ 350.00	\$ 350.00
14	REAR FLOOR TOP COVER BOARD (SPECIAL TYPE) / cradle	1	\$ 650.00	\$ 650.00
15	REVERSE SENSOR / short	1	\$ 250.00	\$ 250.00
16	REVERSE CAMERA R	1	\$ 480.00	\$ 480.00
TOTAL				\$3,680.00

30
 20
 150
 100
 60
 X
 40
 20
 100
 X
 450
 200
 350? X
 1680

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	3 TUFF COAT	\$ 280.00	100
4	4 WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 50.00	X
6	REMOVE AND REPAIR REVERSE SENSOR AND DISTANCE SETTING	\$ 300.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 300.00	30
8	REMOVE & REINSTALL VIDEO RECORDER	\$ 120.00	70

1300

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH8192K
 MODEL : TOYOTA PROACE
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

9	TRANSFER REAR DOOR MECHANISM X2	\$ 180.00	100
10	REMOVE & REINSTALL REAR DOOR GLASS X2	\$ 180.00	100
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
13	REMOVE AND REFIX REAR FLOOR BOARD	\$ 250.00	\$0
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$5,170.00 2540 /

ESTIMATE REPORT

TOTAL PARTS COST : \$16,295.75
 TOTAL LABOUR COST : \$5,170.00
 TOTAL REPAIR COST : \$21,465.75

1740

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

1131.50

1680

2840

13959.50

2671.90

16631.40 /

\$514.70

1020.00

2340.00

11584.70

5711.60

17296.30

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 23.07.19

TO : MSIG MOTOR CLAIMS DEPTS
VEHICLE NO : GBH8192K
MODEL : TOYOTA PROACE
DATE OF ACCIDENT : 18.07.19
TIME OF ACCIDENT : 14:20HRS

COR 8 days
\$ 10700.00 offer \$9500

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER / Deformed	1	\$ 1,361.00	\$ 1,361.00
2	REAR BUMPER REFLECTOR ? LH CFA	12	\$ 87.00	\$ 174.00
3	REAR BUMPER TOW HOOK COVER ?	1	\$ 65.00	\$ 65.00
4	REAR BUMPER SIDE RETAINER ? LH DIS	12	\$ 115.00	\$ 230.00
5	REAR BUMPER CENTER BEAM / Deformed	1	\$ 355.00	\$ 355.00
6	REAR BUMPER REINFORCEMENT / Deformed	1	\$ 823.00	\$ 823.00
7	TAIL LAMP ?	2	\$ 378.00	\$ 756.00
8	BACK DOOR LH / Deformed	1	\$ 1,850.00	\$ 1,850.00
9	BACK DOOR GLASS LH X	1	\$ 795.00	\$ 795.00
10	BACK DOOR LOGO LH / recc	1	\$ 59.00	\$ 59.00
11	BACK DOOR EMBLEM 'TOYOTA' LH / reccc	1	\$ 79.00	\$ 79.00
12	BACK DOOR NUMBER PLATE LAMP ?	2	\$ 105.00	\$ 210.00
13	BACK DOOR OUTER HANDLE LH ?	1	\$ 81.00	\$ 81.00
14	BACK DOOR INNER TRIM LH / cracked	1	\$ 145.00	\$ 145.00
15	BACK DOOR KEY LOCK LH ?	1	\$ 124.00	\$ 124.00
16	BACK DOOR AUTO LOCK MOTOR LH ?	1	\$ 285.00	\$ 285.00
17	BACK DOOR RH / Deformed	1	\$ 1,850.00	\$ 1,850.00
18	BACK DOOR GLASS RH X	1	\$ 795.00	\$ 795.00
19	BACK DOOR EMBLEM 'PROACE' RH / recc	1	\$ 89.00	\$ 89.00
20	BACK DOOR INNER TRIM RH ?	1	\$ 145.00	\$ 145.00
21	BACK DOOR FRAME WEATHERSTRIP / torn	1	\$ 220.00	\$ 220.00
22	BACK DOOR UPPER LOCK ?	2	\$ 245.00	\$ 490.00
23	BACK DOOR LOWER LOCK ?	2	\$ 275.00	\$ 550.00
24	BACK DOOR HINGE ?	4	\$ 185.00	\$ 740.00
25	BACK DOOR CHECKER ?	2	\$ 180.00	\$ 360.00
26	BACK DOOR WEATHERSTRIP CENTER ?	1	\$ 170.00	\$ 170.00
27	REAR END PANEL / Deformed	1	\$ 780.00	\$ 780.00
28	REAR END PANEL (INNER) X repair	1	\$ 670.00	\$ 670.00
29	REAR END PANEL TOP GARNISH / cracked	1	\$ 195.00	\$ 195.00

X NH

682 Dm

X X NH

X NH

Dm

Dm

X NH

X X NH

Dm

X NH

Dm

X NH

X NH

Dm

X NH

Dm

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH8192K
 MODEL : TOYOTA PROACE
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

30	REAR FLOOR PANEL	X repair	1	\$ 2,375.00	\$ 2,375.00
----	------------------	----------	---	-------------	-------------

TOTAL PRICE \$ 16,821.00
 LESS 25% \$ 4,205.25
 SUB TOTAL PRICE \$ 12,615.75

12186
 3046.50
 9131.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE / Dented	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) / recc	1	\$ 80.00	\$ 80.00
3	TAIL LAMP CLIP (SET) / recc	1	\$ 50.00	\$ 50.00
4	REAR DOOR SEALANT /	2	\$ 150.00	\$ 300.00
5	REAR DOOR GLASS SEALANT /	2	\$ 80.00	\$ 160.00
6	REAR DOOR GLASS INNER SEAL /	2	\$ 60.00	\$ 120.00
7	REAR DOOR GLASS SOLAR FILM X	2	\$ 400.00	\$ 800.00
8	REAR DOOR INNER BOARD CLIP (SET) /	1	\$ 80.00	\$ 80.00
9	REAR DOOR STICKER '70KM/H' / recc	1	\$ 30.00	\$ 30.00
10	REAR DOOR STICKER 'WHAT VAN 2017' / recc	1	\$ 80.00	\$ 80.00
11	REAR END PANEL TOP GARNISH CLIP (SET) / recc	1	\$ 50.00	\$ 50.00
12	REAR END PANEL INSULATION SEAL / recc	1	\$ 150.00	\$ 150.00
13	REAR FLOOR PANEL INSULATION SEAL X	1	\$ 350.00	\$ 350.00
14	REAR FLOOR TOP COVER BOARD (SPECIAL TYPE) / cracker	1	\$ 650.00	\$ 650.00
15	REVERSE SENSOR / short	1	\$ 250.00	\$ 250.00
16	REVERSE CAMERA ?	1	\$ 480.00	\$ 480.00

30
 20
 150 MC
 100 MC
 60 MC
 X NN
 40 MC
 20
 100
 X NN
 450
 200
 350? XNN
 1680

TOTAL \$3,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000 + 200 = 1200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	1000
3	TUFF COAT	\$ 250.00	100
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	X
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	30
8	REMOVE & REINSTALL VIDEO RECORDER	\$ 120.00	70

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH8192K
 MODEL : TOYOTA PROACE
 DATE OF ACCIDENT : 18.07.19
 TIME OF ACCIDENT : 14:20HRS

9	TRANSFER REAR DOOR MECHANISM X2	\$ 160.00	100
10	REMOVE & REINSTALL REAR DOOR GLASS X2	\$ 160.00	100
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
13	REMOVE AND REFIX REAR FLOOR BOARD	\$ 250.00	50
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL

\$5,170.00

(2540)

ESTIMATE REPORT

TOTAL PARTS COST : \$16,295.75
 TOTAL LABOUR COST : \$5,170.00
 TOTAL REPAIR COST : \$21,465.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

1137.50
 1680
 2540
 13759.50
 2671.90
 10687.60

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2019 16:10		14 Aug 2019 16:37 Edit Adj Rpt	S\$9,500.00 Edit Estimates	S\$9,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	FULLHOUSE HOME FURNISHINGS PTE LTD, Co. Reg. No.: 200800889D								
Main Claimant:	CHOW YI WEN, ID: S8004547F								
Vehicle Reg. No.:	GBH8192K	Date of Loss:	18/07/2019 14:00 - :59 [9 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600337	Policy/Cover Note No.:	27937347 (Comprehensive) Coverage: 20/07/2018 - 19/07/2019						
Vehicle Reg. No. (Insured):	YN8539R	Policy No. (Claimant):							
		Excess:							
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	DIDAR MUSTAKIM BILLAH () , NRIC: G6515481T Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. Assign: IHS. Contact: Michelle @ 9856 4815.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH8192K (600337)
[YN8539R]
TP
CHOW YI WEN
Jul 18 2019 2:00PM
[FULLHOUSE HOME FURNISHINGS PTE LTD]
Dynamic Autowork Pte. Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)					Thumbnail	Print	
1	25/07/19 11:38	Adjuster Immediate Advice				1	Load HTML		
Photos/Images						3 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)					Thumbnail	Print	
1	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
2	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
3	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
4	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
5	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
6	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
7	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
8	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
9	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
10	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
11	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
12	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
13	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
14	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
15	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
16	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
17	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
18	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
19	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
20	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
21	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
22	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
23	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
24	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
25	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
26	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
27	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
28	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
29	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
30	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
31	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
32	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
33	24/07/19 23:24	SURVEY PHOTO				1	Load JPG	☒	
34	24/07/19 23:24	SURVEY PHOTO				1	Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
				☒
35	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
36	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
37	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
38	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
39	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
40	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
41	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
42	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
43	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
44	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
45	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
46	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
47	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
48	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
49	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
50	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
51	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
52	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
53	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
54	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
55	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
56	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
57	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
58	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
59	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
60	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
61	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
62	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
63	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
64	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
65	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
66	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
67	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
68	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
69	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
70	24/07/19 23:24	SURVEY PHOTO	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/07/19 16:12	GBH8192K GIA Rpt	 Load PDF	
2	19/07/19 16:12	YN8539R GIA Rpt	 Load PDF	
3	19/07/19 16:13	Email - PRI	 Load PDF	
4	19/07/19 16:14	Notice of PRI	 Load PDF	
5	22/07/19 09:42	Email to workshop for direct settlement	 Load PDF	
6	22/07/19 09:57	Agree on SJE	 Load PDF	
7	23/09/19 15:51	Approval by GK to repudiate	 Load PDF	
8	14/10/19 11:07	email from workshop	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	25/07/19 14:25	Preliminary Loss Advise	 Load PDF	
2	14/08/19 10:04	email to LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014535/DQD3E2

Date: 31/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27937347

Claimant Vehicle No : GBH8192K

Insured Vehicle No : YN8539R

Date of Loss: 18/07/2019

Nature of Claim: TP

Claim No: 600337

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH8192K

Make & Model: TOYOTA PROACE, 1.6 (A)

Engine No: BH020023913

Reg. Date: 28/09/2018 (Man. Year: 2017)

Chassis No: YARVBBHVBGZ104428

Colour: Black

Odometer: 9810 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65/16

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,295.75	9,152.50	7,143.25	43.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	2,740.00	2,430.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,465.75	11,892.50	9,573.25	44.60
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	21,465.75	9,500.00	11,965.75	55.74
+ GST 7.00/7.00% (S\$)	1,502.60	665.00	837.60	55.74
Nett Amount (S\$)	22,968.35	10,165.00	12,803.35	55.74

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 24/07/2019 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Jan 2020)	
Parts:	N/A	TOYOTA PROACE 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH8192K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,361.00 FL	*1,361.00 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked	174.00 FL	*87.00 FL
3	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	65.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	230.00 FL	*115.00 FL
5	1		*REAR BUMPER CENTER BEAM	Dented	355.00 FL	*355.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	823.00 FL	*823.00 FL
7	2		*TAIL LAMP	Damaged	756.00 FL	*682.00 FL
8	1		*BACK DOOR LH	Deformed	1,850.00 FL	*1,850.00 FL
9	1		*BACK DOOR GLASS LH	Not Necessary	795.00 FL	*- FL
10	1		*BACK DOOR LOGO LH	Necessary	59.00 FL	*59.00 FL
11	1		*BACK DOOR EMBLEM TOYOTA LH	Necessary	79.00 FL	*79.00 FL
12	2		*BACK DOOR NUMBER PLATE LAMP	Not Necessary	210.00 FL	*- FL
13	1		*BACK DOOR OUTER HANDLE LH	Damaged	81.00 FL	*81.00 FL
14	1		*BACK DOOR INNER TRIM LH	Cracked	145.00 FL	*145.00 FL
15	1		*BACK DOOR KEY LOCK LH	Damaged	124.00 FL	*124.00 FL
16	1		*BACK DOOR AUTO LOCK MOTOR LH	Not Necessary	285.00 FL	*- FL
17	1		*BACK DOOR RH	Dented	1,850.00 FL	*1,850.00 FL
18	1		*BACK DOOR GLASS RH	Not Necessary	795.00 FL	*- FL
19	1		*BACK DOOR EMBLEM PROACE RH	Necessary	89.00 FL	*89.00 FL
20	1		*BACK DOOR INNER TRIM RH	Damaged	145.00 FL	*145.00 FL
21	1		*BACK DOOR FRAME WEATHERSTRIP	Torn	220.00 FL	*220.00 FL
22	2		*BACK DOOR UPPER LOCK	Not Necessary	490.00 FL	*- FL
23	2		*BACK DOOR LOWER LOCK	Damaged	550.00 FL	*550.00 FL
24	4		*BACK DOOR HINGE	Not Necessary	740.00 FL	*- FL
25	2		*BACK DOOR CHECKER	Not Necessary	360.00 FL	*- FL
26	1		*BACK DOOR WEATHERSTRIP CENTER	Damaged	170.00 FL	*170.00 FL
27	1		*REAR END PANEL	Dented	780.00 FL	*780.00 FL
28	1		*REAR END PANEL (INNER)	Damaged	670.00 FL	*670.00 FL
29	1		*REAR END PANEL TOP GARNISH	Cracked	195.00 FL	*195.00 FL
30	1		*REAR FLOOR PANEL	Repair	2,375.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET TAIL LAMP CLIP	Necessary	50.00 FS	*20.00 FS
34	2		*REAR DOOR SEALANT	Necessary	300.00 FS	*150.00 FS
35	2		*REAR DOOR GLASS SEALANT	Necessary	160.00 FS	*100.00 FS
36	2		*REAR DOOR GLASS INNER SEAL	Necessary	120.00 FS	*60.00 FS
37	2		*REAR DOOR GLASS SOLAR FILM	Not Necessary	800.00 FS	*- FS
38	1		*SET REAR DOOR INNER BOARD CLIP	Necessary	80.00 FS	*40.00 FS
39	1		*REAR DOOR STICKER 70KM/H	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR DOOR STICKER WHAT VAN 2017	Necessary	80.00 FS	*80.00 FS
41	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
42	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*100.00 FS
43	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
44	1		*REAR FLOOR TOP COVER BOARD (SPECIAL TYPE)	Cracked	650.00 FS	*450.00 FS
45	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
46	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,501.00	11,760.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,205.25	2,607.50
Total Parts (\$\$)	16,295.75	9,152.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,800.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	100.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	New	150.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	30.00
8	REMOVE & REINSTALL VIDEO RECORDER	New	120.00	70.00
9	TRANFER REAR DOOR MECHANISM X2	New	160.00	100.00
10	REMOVE & REINSTALL REAR DOOR GLASS X2	New	160.00	100.00
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	80.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
13	REMOVE AND REFIX REAR FLOOR BOARD	New	250.00	50.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			5,170.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >