

INSURANCE

INS. CASE OWNER:

CC 6/AIG1901 4537, Aeb3/

LKK  
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

16/8/19

Date/Time:

16/8/19

Registered in Merimen:

20/8/19

Pre-assign / CCU / FTE



Insured Vehicle No. :

GBB 1644T

Claim No. :

622820407250

Name of Insured :

UNITED PARCEL SERVICE (S) PU

Policy No. :

0100 + 27841

Insured Tel No. :

HP:

Make / Model :

TOYOTA

Excess Sec II : \$5

D.O.A. :

1/8/19

Place of Accident :

11 TOR PERVONIOR 3

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

YAN YUAN YUAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability :

% Final ? Yes / No

SLG 13AAP



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Hua  
Ming



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

| Date/Time | STAGE                            | DATE / PIC                          |
|-----------|----------------------------------|-------------------------------------|
| 23.08.19  | BRMIL WSP LMBURY 650K            |                                     |
|           | Documentation Check List:        | Handler Typist                      |
|           | Notification ltr (if non-pickup) | <input type="checkbox"/>            |
|           | After call ltr to OI             | <input checked="" type="checkbox"/> |
|           | Authorisation To Act             | <input checked="" type="checkbox"/> |
|           | Release Voucher                  | <input checked="" type="checkbox"/> |
|           | Final Repair Bill                | <input checked="" type="checkbox"/> |
|           | Car Rental Invoice               | <input type="checkbox"/>            |
|           | Towing Invoice                   | <input type="checkbox"/>            |
|           | LTA / GIA                        | <input checked="" type="checkbox"/> |
|           | Medical Bill                     | <input type="checkbox"/>            |
|           | PIR                              | <input type="checkbox"/>            |
|           | Mandate/Reject Instruction       | <input checked="" type="checkbox"/> |
|           | LOD                              | <input checked="" type="checkbox"/> |
|           | Payment Breakdown Form           | <input type="checkbox"/>            |
|           | Post-Repair Photos               | <input type="checkbox"/>            |
|           | Other:                           | <input type="checkbox"/>            |

|   |  |                        |  |
|---|--|------------------------|--|
| <b>PRELIMINARY ADVICE</b>   | Date/Time:   | Sent By:               | Confirm by: WOP  |
| <b>FINALIZATION</b>   | Date/Time: 15.08.19  | Confirm with: JWC      | Confirm by: WOP  |
| Repair Cost:  | 4/3 \$53,000   | ( 5 days) Reduction:   | 63 % Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |
| <b>FINAL SETTLEMENT</b>   | Date/Time: 15.08.19  | Confirm with: JWC      | Confirm by: WOP  |
| Final Liability:  | % 100 (Agreed / Assessed)  | BOLA S/N No.:          | ML   |
| Repair Cost:  | \$53,000.00  | OID HA TP S/N/NO:      | 21/11/19   |
| Loss of Rental (LOR):   | \$5 - ( 5 days)  |                        |  |
| Loss of Use (LOU):  | \$5360.00 (5 HO x 6 days)  |                        |  |
| Loss of Income (LOI):   | \$5 - (5 x days)   |                        |  |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> | <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> |                        |  |
| GIA/LTA Search  | \$57.49  |                        |  |
| Medical:  | \$5 -  |                        |  |
| Disbursement:   | \$5 - (e.g. Tow/Independent)   |                        |  |
| Legal Cost:   | \$5 -  |                        |  |
| <b>Total:</b>   | \$53,367.49  | <b>Global Sum \$5:</b> |  |
| <b>FINAL PAYMENT</b>  | Date/Time: 15.08.19  | Confirm with: JWC      | Confirm by: WOP  |
| Payee 1:  | \$53,367.49  | Name 1:                | Hua Ming Spray Painting Workshop   |
| Payee 2: (Strike if N.A.)   | \$5  | Name 2:                |  |
| Payee 3: (Strike if N.A.)   | \$5  | Name 3:                |  |

ASSIGNED BY

REF:

Adnan

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| /   |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLG 1399P Yr Regn: 2016 / Sept.

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading 113510 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: Jm63m42AGG 0338499

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 16/08/19.

Survey held at Huey Meng.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                     |
|-------------|--|
|             | <u>TP AIG.</u>                           |
|             | <u>45: +3,000 (RED) = 5,157.20 (3/1)</u> |
|             | <u>MV :</u>                              |
|             | <u>PV :</u>                              |
|             | <u>Nett:</u>                             |

|                          |                            |                    |     |                              |   |  |  |  |  |
|--------------------------|----------------------------|--------------------|-----|------------------------------|---|--|--|--|--|
| Date/Time, File Pass to? | Date/Time, File Return to? | Part Prices Check: |     | Survey Fee:                  | Date:   |  |  |  |  |
| 1)                       | 2)                         | IN                 | OUT | Basic & Add.                 | <table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table> |  |  |  |  |
|                          |                            |                    |     |                              |   |  |  |  |  |
|                          |                            |                    |     |                              |   |  |  |  |  |
|                          |                            |                    |     |                              |   |  |  |  |  |
|                          |                            |                    |     |                              |   |  |  |  |  |
| 3)                       | 4)                         |                    |     | <u> </u> S + RS, <u> </u> \$ |   |  |  |  |  |
| 5)                       | 6)                         |                    |     | Photos                       |   |  |  |  |  |
|                          |                            |                    |     | Others                       |   |  |  |  |  |
|                          |                            |                    |     | TOTAL                        |   |  |  |  |  |

Prep. Report  
Final Report

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

JM6BM47A860338499

LEF SERVICES

122D RIVERVALE DRIVE

#12-448

S 544122

TPA 16  
Ashes

Date :23.08.2019

Vehicle No :SLG 1399 P

Make/Model :MAZDA 3

Accident date :02.08.2019

| No | DESCRIPTION | Qty | Amount (\$\$) |
|----|-------------|-----|---------------|
|----|-------------|-----|---------------|

### List Items

|    |  |   |                                  |
|----|--|---|----------------------------------|
| 1  | Rear bumper <i>Distorted</i>                       | 1 | \$ 1182.3 <i>1028</i>            |
| 2  | Rear bumper side holder @ \$ 41.90 <i>new</i>      | 2 | \$ 83.8 ✓                        |
| 3  | Rear bumper reflector @ \$ 55.40 <i>2H cracked</i> | 2 | \$ 110.8 <i>55.40</i>            |
| 4  | Rear bumper towing hook cover <i>Missing</i>       | 1 | \$ 20 ✓                          |
| 5  | Rear bumper reverse sensor (1 set) <i>Damaged</i>  | 1 | \$ <del>418</del> <i>200(SN)</i> |
| 6  | Rear bumper reinforcement <i>Bent</i>              | 1 | \$ 591 ✓                         |
| 7  | Rear bumper clips (1 set) <i>NEC</i>               | 1 | \$ <del>68</del> <i>30</i>       |
| 8  | Rear end panel <i>Dented</i>                       | 1 | \$ 599.6 ✓                       |
| 9  | Rear end panel inner top garnish <i>Deformed</i>   | 1 | \$ 104.6 ✓                       |
| 10 | Rear bootlid <i>Repair</i>                         | 1 | \$ 1086.1 ✓                      |
| 11 | Rear bootlid hinges @ \$ 181.90 <i>NEC NEC</i>     | 2 | \$ 363.8 ✓ <i>2731.70</i>        |
| 12 | Rear bootlid centre emblem                         | 1 | \$ 86.2 ✓                        |
| 13 | Rear bootlid Mazda emblem <i>NEC</i>               | 1 | \$ } <i>2185.36</i>              |
| 14 | Rear bootlid 3 emblem                              | 1 | \$ } 60.9 ✓                      |
| 15 | Rear bootlid SkyActive emblem <i>NEC</i>           | 1 | \$ 72.2 ✓ <i>SN 200</i>          |
| 16 | Rear bootlid reflector @ \$ 559.90 <i>NEC NEC</i>  | 2 | \$ 1119.8 ✓                      |
| 17 | Rear bootlid weather strip <i>NEC NEC</i>          | 1 | \$ 127.4 ✓                       |

\$ 6092.5

Less 20% Disc

\$ 1205.3

Total

\$ 4887.2

### Labour Cost

|   |   |                               |
|---|---|-------------------------------|
| 1 | To supply rear end panel inner sealant              | \$ 50 ✓                       |
| 2 | Remove & reinstall bootlid inner garnish            | \$ <del>150</del> <i>50</i>   |
| 3 | Remove & reinstall reverse sensor                   | \$ <del>150</del> <i>50</i>   |
| 4 | Remove, replace & repair consistent to the accident | \$ <del>1500</del> <i>600</i> |
| 5 | Respray painting                                    | \$ <del>1300</del> <i>600</i> |
| 6 | Tuff kote   | \$ <del>100</del> <i>60</i>   |
|   | Total   | \$ 3250                       |

Grand Total

\$ 8137.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 3755.36

L/S 3K

05 Days

3K

## **Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Friday, 23 August 2019 12:55 PM  
**To:** Hua Meng  
**Subject:** Accident Involving SLG 1399P & GBB 1549T on 02/08/2019

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Your Ref: SLG 1399P  
Our Ref: CC6/AIG19014537/Aeb3

Dear Sir/Madam,

### **Accident Involving SLG 1399P & GBB 1549T on 02/08/2019**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.  
Attn : MdNoor, NorsiahYour Ref : 6338608672SG  
Our Ref : CC6/AIG19014537/AEB3  
Date : 08 Nov 2019**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING GBB1549T & SLG1399P ON 02/08/2019**

Refer to the above accident.

The accident occurred when insured hit third party stationary vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. GBB1549T) and third party claimant (vehicle no. SLG1399P).

Summary of offer made to workshop Hua Meng Spray Painting Workshop is as follows :

|                             | Claimed     | Revised     |
|-----------------------------|-------------|-------------|
| Cost of Repairs             | \$ 8,137.20 | \$ 3,000.00 |
| Loss of Use (6days x \$150) | \$ 900.00   | \$ 360.00   |
| LTA Search Fee              | \$ 7.49     | \$ 7.49     |

Amount of claim at **Liability 100%** \$ 3,367.49

Our surveyor recommend 5days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,  
Asher Sng Rong Yi  
LKK Auto Consultants Pte Ltd

11/13/2019

Merimen e-Claims

## Print Received Message

This mail is associated with :

**\*SLG1399P (6338608672SG)**  
**[GBB1549T]**

TP

LEF SERVICES

Aug 2 2019 4:00PM

[UNITED PARCEL SERVICE SINGAPORE PTE LTD]  
Hua Meng Spray Painting Workshop

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 12/11/2019 10:07 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3367.49) - SLG1399P - Claim Handler: MdNoor, Norsiah

Approved:3367.49.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 03 Aug 2019<br><a href="#">Edit Reg</a> |               | 16 Aug 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,000.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,000.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details  | Documents  | Show All |         |             |              |            |       |
|---|---|--|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>  |   | [Created by adjuster]  |  |          |         |             |              |            |       |
| Insured:  | <b>UNITED PARCEL SERVICE SINGAPORE PTE LTD</b> , Co. Reg. No.: 198801949D   |  |  |          |         |             |              |            |       |
| Main Claimant:  | <b>LEF SERVICES</b> , Co. Reg. No.: 53334624W   |  |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SLG1399P</b>   | Date of Loss:  | 02/08/2019 16:00 - :59<br>[34 Months and 12 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / 63386086725G</b>  | Policy/Cover Note No.:   | (Third Party Only)   |          |         |             |              |            |       |
| Vehicle Reg. No. [Insured]:   | <b>GBB1549T</b>   | Policy No. (Claimant):   | 5098364307-01  |          |         |             |              |            |       |
| Repairer:   | <b>Hua Meng Spray Painting Workshop (HQ)</b> No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519 |  |  |          |         |             |              |            |       |
| Handling Insurer:   | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com     |  |  |          |         |             |              |            |       |
| Claimant's Insurer:   | <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:   |  |  |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 29/08/2019]                 |  |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>   |   | <a href="#">View All</a> <a href="#">Compose Case Mail</a>   |  |          |         |             |              |            |       |
| • AIG_SG_EXPRESS (12/11/2019): Alert - Adj Mandate Approved (S\$3367.49) - SLG1399P - Claim Handler: MdNoor, Nor... |   |  |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>   |   | <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |  |          |         |             |              |            |       |
| Due Date  | Priority  | Type   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |  |  |          |         |             |              |            |       |

## Claim Documents

\*SLG1399P (6338608672SG)  
 [GBB1549T]  
 TP  
 LEF SERVICES  
 Aug 2 2019 4:00PM  
 [UNITED PARCEL SERVICE SINGAPORE PTE LTD]  
 Hua Meng Spray Painting Workshop

| Upload Documents               |                 |  | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       | View in Browser                     |
|--------------------------------|-----------------|--|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-------------------------------------|
| <b>Letters/Correspondences</b> |                 |  |               |  |  |                    |  |  |              |  |  |              |  |  | 1 per page | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |               |  |  |                    |  |  |              |  |  | Thumbnail    | Print  |  |            |                                     |
| 1                              | (Draft)         | Third Party Express Settlement - Payment Breakdown |               |  |  |                    |  |  |              |  |  |              | Edit   |  |            |                                     |
| <b>Assessment Reports</b>      |                 |  |               |  |  |                    |  |  |              |  |  |              |  |  | 1 per page | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |               |  |  |                    |  |  |              |  |  | Thumbnail    | Print  |  |            |                                     |
| 1                              | 08/11/19 13:00  | Adjuster Immediate Advice                          |               |  |  |                    |  |  |              |  |  |              | Load HTM                                     |  |            |                                     |
| <b>Photos/Images</b>           |                 |  |               |  |  |                    |  |  |              |  |  |              |  |  | 3 per page | <input checked="" type="checkbox"/> |
| No                             | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |               |  |  |                    |  |  |              |  |  | Thumbnail    | Print  |  |            |                                     |
| 1                              | 15/10/19 16:09  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 2                              | 15/10/19 16:09  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 3                              | 15/10/19 16:09  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 4                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 5                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 6                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 7                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 8                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 9                              | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 10                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 11                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 12                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 13                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 14                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 15                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 16                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 17                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 18                             | 15/10/19 16:10  | General View                                       |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 19                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 20                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 21                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 22                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 23                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 24                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 25                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 26                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 27                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 28                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 29                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 30                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 31                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 32                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 33                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 34                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 35                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |
| 36                             | 15/10/19 16:10  | Reinspection Photo                                 |               |  |  |                    |  |  |              |  |  |              | Load JPG <input checked="" type="checkbox"/> |  |            |                                     |

| Letters/Correspondences |                |                                   | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 37                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 38                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 39                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 40                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 41                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 42                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 43                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 44                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 45                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 46                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 47                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |
| 48                      | 15/10/19 16:10 | Reinspection Photo                |            | <input checked="" type="checkbox"/> |

  

| Documentation |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 20/08/19 18:58  | TP GIA REPORT                     |            | <input type="checkbox"/>            |
| 2             | 23/08/19 12:55  | LETTER TO OI                      |            | <input type="checkbox"/>            |
| 3             | 08/11/19 12:55  | TP ESTMATE - MARKED               |            | <input type="checkbox"/>            |
| 4             | 08/11/19 12:55  | TP LOD                            |            | <input type="checkbox"/>            |
| 5             | 02/12/19 09:39  | WORKSHOP INVOICE                  |            | <input type="checkbox"/>            |
| 6             | 02/12/19 09:39  | AUTHORISATION TO ACT FORM         |            | <input type="checkbox"/>            |
| 7             | 02/12/19 09:39  | Release Voucher                   |            | <input type="checkbox"/>            |
| 8             | 02/12/19 09:39  | LTA SEARCH                        |            | <input type="checkbox"/>            |
| 9             | 02/12/19 09:39  | LOD                               |            | <input type="checkbox"/>            |

  

| No | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print                    |
|----|----------------|---|-----------|--------------------------|
| 1  | 21/08/19 10:05 | OI GIA REPORT                             |           | <input type="checkbox"/> |

### Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

|                   |                     |        |                                       |
|-------------------|---------------------|--------|---------------------------------------|
| Vehicle No:       | GBB1549T (Insd veh) | Model: | MAZDA 3 1.4 SEDAN 1.5L<br>SP.6EAT (A) |
|                   | SLG1399P (TP veh)   |        |                                       |
| Date of Accident: | 02/08/2019          |        |                                       |

|   |   |                              |  |                              |
|---|---|------------------------------|--|------------------------------|
| Global Sum Settlement   | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |                              |
| Repair Estimate   | : | \$                           | 8,124.00                               |                              |
| Final Repair Cost   | : | \$                           | 3,000.00                               |                              |
| Loss of Use   | : | \$                           | 360.00                                 | 6.00 days at \$60.00 per day |
| Rental (if any)   | : | \$                           | 0.00                                   | days                         |
| LTA / GIA Search Fee  | : | \$                           | 7.49                                   |                              |
| Others:   | : | \$                           | 0.00                                   |                              |
|   | : | \$                           |  |                              |
| Final Settlement Sum  | : | \$                           | 3,367.49                               |                              |
| Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below) |   |                              |  |                              |
| A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)  |   |                              |  |                              |
| B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____  |   |                              |  |                              |
| BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)   |   |                              |  |                              |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                                |   |                              |  |                              |
| Remarks _____   |   |                              |  |                              |

| Payment Instruction: Payee's Breakdown |                                  |   |             |
|--|----------------------------------|---|-------------|
| 1)                                     | Hua Meng Spray Painting Workshop | : | \$ 3,367.49 |
| 2)                                     |                                  | : | \$          |
| 3)                                     |                                  | : | \$          |
| 4)                                     |                                  | : | \$          |

JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

02 Dec  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014537/AEB3Q2

Date: 02/12/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant**  
**Vehicle No :** SLG1399P **Insured Vehicle No :** GBB1549T  
**Date of Loss:** 02/08/2019 **Nature of Claim:** TP **Claim No:** 6338608672SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLG1399P**  
 Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A) Engine No: P520358296  
 Reg. Date: 21/09/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0338499  
 Colour: Silver Odometer: 113510 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 4,874.00        | 2,385.36        | 2,488.64        | 51.06        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 3,250.00        | 1,410.00        | 1,840.00        | 56.62        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,124.00</b> | <b>3,795.36</b> | <b>4,328.64</b> | <b>53.28</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>3,000.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>8,124.00</b> | <b>3,000.00</b> | <b>5,124.00</b> | <b>63.07</b> |
| + Loss of Use (6.0 x S\$60.00/day) (S\$) |                 | 360.00          |                 |              |
| + Doc/Search Fee (S\$)                   |                 | 7.49            |                 |              |
| <b>Nett Liability (S\$)</b>              |                 | <b>3,367.49</b> |                 |              |

## INSPECTION

Date of Assignment: 16/08/2019  
 Date Inspected: 16/08/2019 Inspected At: Hua Meng Spray Painting Workshop (HQ)  
 No 1 Kaki Bukit Avenue 6, #01-61  
 Autobay@Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                      | Distorted     | 1,182.30 FL | *1,028.00 FL |
| 2   | 2   |          | *REAR BUMPER SIDE HOLDER          | Necessary     | 83.80 FL    | *83.80 FL    |
| 3   | 1   |          | *REAR BUMPER REFLECTOR            | N/S Cracked   | 110.80 FL   | *55.40 FL    |
| 4   | 1   |          | *REAR BUMPER TOWING HOOK COVER    | Missing       | 20.00 FL    | *20.00 FL    |
| 5   | 1   |          | *SET REAR BUMPER REVERSE SENSOR   | Damaged       | 334.40 FS   | *200.00 FS   |
| 6   | 1   |          | *REAR BUMPER REINFORCEMENT        | Bent          | 591.00 FL   | *591.00 FL   |
| 7   | 1   |          | *SET REAR BUMPER CLIPS            | Necessary     | 66.00 FL    | *30.00 FL    |
| 8   | 1   |          | *REAR END PANEL                   | Dented        | 599.60 FL   | *599.60 FL   |
| 9   | 1   |          | *REAR END PANEL INNER TOP GARNISH | Deformed      | 104.60 FL   | *104.60 FL   |
| 10  | 1   |          | *REAR BOOTLID                     | Repair        | 1,086.10 FL | *- FL        |
| 11  | 2   |          | *REAR BOOTLID HINGES              | Not Necessary | 363.80 FL   | *- FL        |
| 12  | 1   |          | *REAR BOOTLID CENTRE EMBLEM       | Necessary     | 86.20 FL    | *86.20 FL    |
| 13  | 1   |          | *REAR BOOTLID MAZDA EMBLEM }      | Necessary     | 60.90 FL    | *60.90 FL    |
| 14  | 1   |          | *REAR BOOTLID 3 EMBLEM }          | Necessary     | 0.00 FL     | *- FL        |
| 15  | 1   |          | *REAR BOOTLID SKYACTIVE EMBLEM    | Necessary     | 72.20 FL    | *72.20 FL    |
| 16  | 2   |          | *REAR BOOTLID REFLECTOR           | Not Necessary | 1,119.80 FL | *- FL        |
| 17  | 1   |          | *REAR BOOTLID WEATHER STRIP       | Not Necessary | 127.40 FL   | *- FL        |

F=Franchise part. S=SpcNett. L=ListitemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,008.90</b> | <b>2,931.70</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>1,134.90</b> | <b>546.34</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>4,874.00</b> | <b>2,385.36</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | TO SUPPLY REAR END PANEL INNER SEALANT             | New      | 50.00           | 50.00           |
| 2                              | REMOVE & REINSTALL BOOTLID INNER GARNISH           | New      | 150.00          | 50.00           |
| 3                              | REMOVE & REINSTALL REVERSE SENSOR                  | New      | 150.00          | 50.00           |
| 4                              | REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT | New      | 1,500.00        | 600.00          |
| 5                              | RESPRAY PAINTING                                   | New      | 1,300.00        | 600.00          |
| 6                              | TUFF KOTE  | New      | 100.00          | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>3,250.00</b> | <b>1,410.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >