

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5377P**AAD1908-101***Not Notation
Pursuing Bepaint*

Vehicle No.: 19 AUG 2019
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD 5377P
 JTDKB3FU503078562
 TOYOTA
 PRIUS
 14.8.19
AIG
 19/12/2018

PART			LIST	
1	1	REAR BUMPER	\$ Bu	458.60 ✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	318.80 ?
3	1	REAR BUMPER TOWING COVER	\$ Sn	14.70 X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ Nulm	552.60 ✓
5	1	ANTENNA, ELECTRICAL KEY	\$ Sn	61.40
6	1	REAR BUMPER SIDE RETAINER LH	\$ Sn	112.70
7	1	REAR BUMPER SIDE RETAINER RH	\$ Sn	112.70
8	1	REAR TAILGATE	\$ N	1,547.27
9	1	REAR TAILGATE OUTER GARNISH	\$ Sn	910.40
10	1	COVER, REAR COMBINATION LAMP, RH	\$ Sn	54.70
11	1	COVER, REAR COMBINATION LAMP, LH	\$ Sn	54.70
12	1	GARNISH, BACK DOOR SIDE, LH	\$ Sn	93.60
13	1	GARNISH, BACK DOOR SIDE, RH	\$ Sn	93.60
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ Sn	55.40
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ Sn	55.40
16	1	BOARD ASSY, BACK DOOR TRIM	\$ Sn	254.40
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ Sn	51.20
18	1	REAR TAILGATE WEATHERSTRIP	\$ Sn	365.20
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$ N	641.50
20	1	TAILLAMP LOWER RH	\$ Sn	548.40
21	1	TAILLAMP UPPER RH	\$ Sn	557.90
22	1	REAR BUMPER SIDE RH	\$ Sn	232.00
23	1	REAR BUMPER SIDE LH	\$ Sn	232.00
24	1	TAILLAMP LOWER LH	\$ Sn	548.40
25	1	TAILLAMP UPPER LH	\$ Sn	557.90
26	1	REAR RH FENDER PANEL	\$ N	836.70
27	1	REAR LH FENDER PANEL	\$ N	836.70
28	1	LINER, REAR WHEEL HOUSE, LH	\$ Sn	138.10
29	1	LINER, REAR WHEEL HOUSE, RH	\$ Sn	138.10

X

Trans-cab Auto Services Pte Ltd**AAD1908-101**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5377P

30	1	BOARD, BACK DOOR TRIM	\$	Sn	222.00	} X
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Sn	351.10	
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	Sn	351.10	
33	1	COVER, FLOOR UNDER, NO.1	\$	Sn	172.60	
34	1	COVER, FLOOR UNDER, NO.2	\$	Sn	238.70	
35	1	COVER, REAR FLOOR	\$	Sn	226.80	
36	1	COVER, DECK TRIM, REAR	\$	Sn	125.00	
TOTAL			\$		12,122.37	
25%			\$		3,030.59	
			\$		9,091.78	

Special Nett

1	1SET	PARKING AID	\$	Phot	700.00	250sn	} X
2	1SET	REAR BUMPER CLIP	\$	na	22.00	✓	
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00		
4	1	WINDSCREEN MOULDING	\$	na	100.00		
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00		
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90		
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50		
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00		
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00		
11	1	REAR BUMPER PROTECTOR	\$	na	100.00		
12	1	REAR WHEEL RIM	\$	Sn	1,570.55		
13	1	REAR WHEEL RIM COVER	\$	Sn	175.80		
14	1	SPARE WHEEL RIM	\$	Sn	1,570.55		
15	1	SPARE WHEEL RIM COVER	\$	Sn	175.80		
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
TOTAL			\$		4,978.10		
TOTAL PARTS			\$		14,069.88		

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 2202

Trans-cab Auto Services Pte Ltd**AAD1908-101**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5377P

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2001 4,500.00	
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	4 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	4 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To Check Electrical Lighting Concerned.	\$	4 170.00	X

TOTAL \$ 12,100.00**Over All Total \$ 26,169.88**

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(PART-BY-PART) Repair Days**15 Days**
2 days