



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-07/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : GX58955

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition	Per Unit	Our Estimates
1	1 pc	Rear Box Door LH			R 1,850.00 X
2	1 pc	Rear Box Door Inner Plywood LH			nn 650.00 X
3	1 pc	Rear Box Door Hinge LH			12 250.00 X
4	1 pc	Rear Box Door Pillar LH			nn/34 1,250.00 600
5	1 pc	Rear Box End Member			S-6.0 1,200.00 600
6	1 pc	Side Box Run Rail Member			cm 1,500.00 75-0
7	1 pc	Tail Lamp LH	175.10		cm 320.00 ✓
8	1 pc	Tail Lamp Bracket LH	165.00		31 202.00 ✓
9	1 pc	Tail Lamp Wire Harness LH			17 152.00 X
10	1 pc	Foot Step LH			17 250.00 X
11	1 pc	Spare Tyre Carrier			17 425.00 X
12	1 pc	Company emblems sticker			nn 650.00 500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts Total :

\$8,699.00

Not Authorized
2/1/19

L/S
Therphio Ather 119-
Hm
Tel. 62563561
21/8/19



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : GX5895S

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	600 1,400.00
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	400 800.00
3	To remove, replace tail lamp wire harness and check light system	20 100.00
4	To transfer rear door components	100 100.00

Labour Total : \$2,400.00

Total (Parts & Labour) : \$11,099.00

For Lump Sum Repairs

*Prices Quoted Above Are Before GST

The estimated amount calculated is \$11,099.00

Under normal circumstances, the repairs should be completed within a reasonable period
Of 5 Working Days. (Exclude waiting days of PRI, Sunday and Public Holiday)