

ASS. REC. BY:

REF:

CS/FC2190145461

02

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Serrano

of

FCI

Date/Time:

20.8.19 3.08p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 4114

Insured:

SHA 2093

at Workshop m/s

K. Kim Hin

Tel:

64527018

of 160 sin ming Drive #02-20

Policy No:

Claim No:

D19005378MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

20.8.19 4.14p.m

Person Contacted:

Sandra

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 2019A-CC3/LCRA7014347/K12h3q2 D.O.A. 22/07/2019

SJW 4114/CS/A2G10016111/AF-2 D.O.A. 11/08/2010

18/10 Repair Emp & 6800 email & confirm (Red: 7282.36/53%)

(EST)

MV: \$85K - LTA: \$64,486.00 - Net: 20,514.00

ASS. REC. BY:

REF:

FCZ

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop nvs

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

85k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days Res.: Yes or No

Lum Sum:

1-B.1

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

Simon said 1-B.1, unable to locate 2nd parts

RECEIVED 2 OCT 2019

Date/Time, File Pass to?

11/2/10 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 68001-

☐ : Prel. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + P.S. SI

F. + P.S.

Others

21/10/19

TOTAL

4x15= 60

1700
60
50
50
100
24
404

Veh No:

STW 41117

Yr Regn:

02, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A7

c.c.

3597

Colour:

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

108917

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU 88842XAD0015425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

275/45R20

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/8/19

D.O.I.

26/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

MOTOR SURVEY ASSIGNMENT

Date	20-08-2019	Our Ref No. D19005378MFSH
Accident Date	17-08-2019	Claim Type. Third Party
Insured Vehicle	SHA2019J	Third Party Vehicle. SJW411H
Survey Location	160 SIN MING DRIVE #02-20SIN MING AUTOCITY	
Contact Person.	SANDRA	
Contact No.	64527018/ 96222116	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	307A
Vehicle Details	
Vehicle No.:	SJW411H
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	Q7 3.6 FSI QU S-LINE FACELIFT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	BHK113041
Chassis No.:	WAUZZZ4LXAD015425
Maximum Power Output:	206.0 kW (276 bhp)
Open Market Value:	\$69,723.00
Original Registration Date:	26 Feb 2010
First Registration Date:	26 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$69,723.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2020
PARF Rebate Amount:	\$34,861.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$29,625.00
Total Rebate Amount:	\$64,486.00

The information contained herein is correct as at 17 Aug 2019

OK

TP: FIRST LAP
LKK



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30677

Vehicle Insured : SHA 2019 J
Accident Date : 17-Aug-2019

Date : 20-Aug-2019

Our Ref : 190470 (FIRST) / LAVENDER

PAGE : 1

WILLIE GOH (MR)
Singapore

Not Notified
61 Day & 7
Return After Pain 4 days

ESTIMATED COST OF REPAIR FOR AUDI Q7 3.6 (2010) SJW411H

1 pc	rear bumper - top		1,688.60	✓
1 pc	rear bumper - bottom		1,599.71	✓
1 pc	rear bumper centre grille		200.37	✓
1 pc	rear bumper under cover		233.96	✓
1 pc	rear bumper clips & rivet set		275.90	✓
2 pcs	rear bumper side bracket	@ S\$ 99.77	199.54	X
1 pc	rear bumper centre bracket		133.76	✓
1 pc	rear bumper reinforcement		1,419.67	?
2 pcs	rear bumper lamp (LH/RH) <i>olsem</i>	@ S\$488.70	977.40	✓
4 pcs	rear bumper parking sensor	@ S\$233.96	935.84	?
4 pcs	rear bumper parking sensor seal	@ S\$ 11.71	46.84	?
1 pc	rear bumper parking sensor wire harness		800.93	?
1 pc	rear bumper towing cover		89.87	✓
1 pc	tailgate logo		168.78	✓
1 pc	tailgate "Q7" emblem		149.69	✓
1 pc	tailgate "3.6" emblem		149.69	✓
1 pc	tailgate "quattro" emblem		149.69	✓
1 pc	driver seat back rest back cover		662.50	?
1 pc	rear exhaust muffler		3,375.10	?
2 pcs	rear exhaust muffler clamp	@ S\$195.60	391.20	?
2 pcs	rear exhaust muffler chrome pipe (LH/RH)	@ S\$337.90	675.80	?
			14,324.84	
Less 10% :			-1,432.48	
			12,892.36	

LKK Auto Consultants hence notify the Repairer of the following:


Cont Page 2

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/claim(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHA 2019 J
Our Ref : 190470

Page : 2
No. : 30677

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

700.00 ?

To apply undersealing

nn 120.00 X

To remove and renew exhaust
silencer box

120.00 601

To putty and respray on affected
portions.

850.00 7501

Total : S\$14,682.36
=====

Singapore Dollars Fourteen Thousand Six Hundred
and Eighty Two and Cents Thirty Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

TP: FIRST CLAP
LKK

K. Kim Hin

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHA 2019 J
Accident Date : 17-Aug-2019

No. : 30677

Date : 20-Aug-2019

Our Ref : 190470 (FIRST) / LAVENDER

PAGE : 1

WILLIE GOH (MR)
Singapore

RP

Not Notified

11 Sep & 7
Returning After Repair

4 days

ESTIMATED COST OF REPAIR FOR AUDI Q7 3.6 (2010) SJW411H

1 pc	rear bumper - top		Ben	1,688.60	✓
1 pc	rear bumper - bottom		Ben	1,599.71	✓
1 pc	rear bumper centre grille		R	200.37	✓ R
1 pc	rear bumper under cover		nd/br	233.96	✓
1 pc	rear bumper clips & rivet set		ru	275.90	✓
2 pcs	rear bumper side bracket	@ S\$ 99.77	sn	199.54	X
1 pc	rear bumper centre bracket		cm	133.76	✓
1 pc	rear bumper reinforcement		m	1,419.67	✓
2 pcs	rear bumper lamp (LH/RH) d/crm	@ S\$488.70		977.40	✓ 488.70
4 pcs	rear bumper parking sensor	@ S\$233.96	sn	935.84	✓ X
4 pcs	rear bumper parking sensor seal	@ S\$ 11.71	sn	46.84	✓ X
1 pc	rear bumper parking sensor wire harness		sn	800.93	✓ X
1 pc	rear bumper towing cover		bu	89.87	✓
1 pc	tailgate logo		ru	168.78	✓
1 pc	tailgate "Q7" emblem		ru	149.69	✓
1 pc	tailgate "3.6" emblem		ru	149.69	✓
1 pc	tailgate "quattro" emblem		ru	149.69	✓
1 pc	driver seat back rest back cover		R	662.50	✓ X
1 pc	rear exhaust muffler		R	3,375.10	✓ X 6548.02
2 pcs	rear exhaust muffler clamp	@ S\$195.60	R	391.20	✓ X
2 pcs	rear exhaust muffler chrome pipe (LH/RH)	@ S\$337.90	R	675.80	✓ X
				14,324.84	
Less 10% :				-1,432.48	
				12,892.36	

Con't Page 2 ...

K. Kim Hin

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHA 2019 J
Our Ref : 190470

Page : 2
No. : 30677

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

~~500~~ 700.00 *500*

To apply undersealing

nn 120.00 *X*

To remove and renew exhaust
silencer box

120.00 *600*

To putty and respray on affected
portions.

850.00 *7500*

Total : S\$14,682.36
=====

Singapore Dollars Fourteen Thousand Six Hundred
and Eighty Two and Cents Thirty Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

6548.02
- 10%
5893.22 s/parts
+ 1350.00 labour
7243.22
Global Rep @ 6800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014546/Ktf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2019J	Veh. Inspected	SJW 411H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005378MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	20/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q7 (A)	c.c	3597	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ4LXAD015425	Colour	METALLIC BLACK	
Odometer	108917	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/45 R20	GOODYEAR	8 mm	
L/H Front Tyre	275/45 R20	GOODYEAR	8 mm	
R/H Rear Tyre	275/45 R20	GOODYEAR	8 mm	
L/H Rear Tyre	275/45 R20	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2019	Inspection Date	26/08/2019	
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 411H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER-TOP	BUCKLED	1,688.60	1,688.60
1	REAR BUMPER-BOTTOM	BUCKLED	1,599.71	1,599.71
1	REAR BUMPER CENTRE GRILLE	TO REPAIR SEE LABOUR	200.37	-
1	REAR BUMPER UNDER COVER	DENTED / CUT	233.96	233.96
1	REAR BUMPER CLIPS & RIVET SET	NECESSARY	275.90	275.90
2	REAR BUMPER SIDE BRACKET @\$99.77	SERVICEABLE	199.54	-
1	REAR BUMPER CENTRE BRACKET	CRACKED	133.76	133.76
1	REAR BUMPER REINFORCEMENT	BENT	1,419.67	1,419.67
2	REAR BUMPER LAMP (LH/RH) @\$488.70	O/S CRACKED	977.40	488.70
4	REAR BUMPER PARKING SENSOR @\$233.96	SERVICEABLE	935.84	-
4	REAR BUMPER PARKING SENSOR SEAL @\$11.71	SERVICEABLE	46.84	-
1	REAR BUMPER PARKING SENSOR WIRE HARNESS	SERVICEABLE	800.93	-
1	REAR BUMPER TOWING COVER	DENTED	89.87	89.87
1	TAILGATE LOGO	NECESSARY	168.78	168.78
1	TAILGATE "Q7" EMBLEM	NECESSARY	149.69	149.69
1	TAILGATE "3.6" EMBLEM	NECESSARY	149.69	149.69
1	TAILGATE "QUATTRO" EMBLEM	NECESSARY	149.69	149.69
1	DRIVER SEAT BACK REST BACK COVER	TO REPAIR SEE LABOUR	662.50	-
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	3,375.10	-
2	REAR EXHAUST MUFFLER CLAMP @\$195.60	TO REPAIR SEE LABOUR	391.20	-
2	REAR EXHAUST MUFFLER CHROME PIPE (LH/RH) @\$337.90	TO REPAIR SEE LABOUR	675.80	-
	LESS 10% DISCOUNT		-1,432.48	-654.80
			12,892.36	5,893.22

Report Ref No. CS/FCI19014546/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER CENTRE GRILLE,DRIVER SEAT BACK REST BACK COVER,REAR EXHAUST MUFFLER,REAR EXHAUST MUFFLER CLAMP AND REAR EXHAUST MUFFLER CHROME PIPE (LH/RH). TO APPLY UNDERSEALING. TO REMOVE AND RENEW EXHAUST SILENCER BOX. TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	NOT NECESSARY	700.00 120.00 120.00 850.00 1,790.00	500.00 - 60.00 750.00 1,310.00
	GRAND TOTAL		14,682.36	7,203.22
RECOMMENDED COST OF REPAIR SUM				6,800.00

Report Ref No. CS/FCI19014546/Ktf3n2

MARKET VALUE: \$85,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$64,486.00=NETT VALUE: \$20,514.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.