

08/11/13 wef

REF:

ASS. REC. BY: Marcus

FWD/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 6671L

at Workshop m/s precise

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 23

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJM 6671L Yr Regn: 1.09

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Vios C.C. 1497

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 188170 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY 9325086 229

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/8/19 D.O.I. 21/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 1144/ cor 12-1-2024

L/S \$2000 - (Red) \$3496.08 / 6177

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1) _____
Date/Time, File Return to?
☐

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

TOTAL

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

31-12-19

Accident Date : 17-08-2019

OUR REF : SJM 6671L (3) /T/19

JASON LEE ZHENG DE

Blk 663A Yishun Ave 4

#03-223

Singapore 761663

ESTIMATE BILL ON VEH. NO. : SJM 6671L

MODEL : TOYOTA VIOS

CHASSIS NO : MR053HY9305086229

LIST ITEM

Boot Lid		2	337.10	X
Boot Lid Lock		11	63.90	X
Boot Lid Lock Striker		11	43.10	X
Boot Lid Stopper	2pcs @ 43.90	11	87.80	X
Boot Lid Weatherstripe		1W1	53.90	/
Rear Bumper Fascia		2c/10.1	283.20	/
Rear Bumper Side Retainer	2pcs @ 43.90	21	87.80	/
Rear Bumper Clips	10pcs @ 12.90	50	129.00	/
Tail Lamp Assy RH & LH	2pcs @ 183.00	11	366.00	X
Tail Lamp Sealant	2pcs @ 50.00	11	100.00	X
Tail Lamp Clips	2pcs @ 12.90	11	25.80	X
Rear End Panel		1	689.20	X
Rear End Panel Top Trim		11	63.90	X
Rear End Panel Top Trim Clips	6pcs @ 12.90	11	77.40	X
	474.9		2,408.10	
	356.17	Less Discount 25%:	602.03	
			1,806.08	

SPECIAL NETT ITEM

Rear Bumper Lower Spoiler		11	580.00	/
Boot Lid Badge		11	80.00	/
Reverse Sensor With Control Unit		shut	380.00	200
Tail Lamp Black Sticker	2pcs @ 60.00	11	120.00	X

LABOUR CHARGE

Towing

17 80.00 X

To check wiring system

80.00 20

To tuff coat affected areas

17 180.00 X

To remove & refix interior upholstery

100.00 80

To remove & transfer boot lid mechanism

17 120.00 X

To remove & refix reverse sensor

120.00 50

To respray affected areas

1,100.00 800

To renew damaged parts, straighten & repair rear fender o/s, rear floor panel
rear chassis frame member and aligned all parts

950.0 600

5,696.08

GST 7% : 398.73

AMOUNT DUE : 6,094.80

2766.17.

2212.94

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	686C
Vehicle Details	
Vehicle No.:	SJM6671L
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1NZX817320
Chassis No.:	MR053HY9305086229
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	13 Jan 2009
First Registration Date:	13 Jan 2009
Transfer Count:	5
Actual ARF Paid:	\$11,834.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$11,441.00
Total Rebate Amount:	\$11,441.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Aug 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Vios

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Direct Owners > Toyota Vios 1.5A E (COE till 01/2024)

Toyota Vios 1.5A E (COE till 01/2024)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER









100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER



Shortlist

Compare

Add note

Report Error

More Actions

Price

\$24,800

Depreciation

\$5,600 /yr

Reg Date

23-Jan-2009
(4yrs 5mths 1day COE left)

Mileage

N.A.

Manufactured

2008

Road Tax

\$684 /yr

Transmission

Auto

Dereg Value

\$11,525 as of today (change)

OMV

\$11,834

COE

\$13,024

ARF

\$11,834

Engine Cap

1,497 cc

Power

80.0 kW (107 bhp)

Curb Weight

1,095 kg

No. of Owners

3

Type of Vehicle

Mid-Sized Sedan

Features

1.5L VVT-i Four Cylinder In-line DOHC 16 Valves Engine. View specs of the Toyota Vios (2007-2013)

Accessories

Newly Change Tyres And Rims. Leather Seats. Retractable Side Mirror. Fog Lamps.

Description

Well Maintained Vehicle. Low Risk Purchase, An Ideal Choice For Daily Commute. Changing Vehicle As I'm Buying A New One. Low Depreciation And Good Vehicle. Contact Me For Viewing And Details.

Category

COE Car, Direct Owner Sale

Status

Available

Resources

 Car Valuation - Free
Find out the market value of your existing car for free. Get started

 Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Upfront Payment

Transfer Fee

\$25

Compare

more Financial info

Seller Information

Contact Person(s)

Siu / Liang

Contact No.

81318655 / 90211697

ESSENTIAL TRANSACTION FORMS

• Indemnity form

• Sales agreement

• Receipt

• Hand-over form

• Ownership Transfer

 GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Monday, 19 August 2019 4:25 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: clara.li@fwd.com; motorclaims.sg@fwd.com
Subject: Pre-repair Inspection for SJM 6671L (You Insured no : SKN 6296U) / Policy No: PNPV2016-00000699
19082019153431.pdf

Attachments:

10:53am @ 20/8/2019
VNI
Aine

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & our insured has yet to report


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: Monday, August 19, 2019 4:01 PM
To: Motor Claims SG - SG Common
Subject: Pre-repair Inspection for SJM 6671L (You Insured no : SKN 6296U)

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for SJM 6671L in our workshop ASAP.

Cecilia Chong (LKK Auto)

From: Shu Pei (LKKAuto)
Sent: Monday, 30 December 2019 8:36 AM
To: Cecilia Chong (LKK Auto)
Subject: FW: Hi, please submit survey report in Merimen as we have received TPPD LOD from lawyer. Thank you.

FYI

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 30 December 2019 7:58 AM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: Hi, please submit survey report in Merimen as we have received TPPD LOD from lawyer. Thank you.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [<mailto:do-not-reply@merimen.com>]

Sent: Saturday, 28 December 2019 10:00 AM

To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com;

AsherSng@lkkauto.com

Cc: clara.li@fwd.com; motorclaims.sg@fwd.com

Subject: Hi, please submit survey report in Merimen as we have received TPPD LOD from lawyer. Thank you.

This mail is associated with :
*SJM6671L (1201900024549)
[SKN6296U]

TP
JASON LEE ZHENG DE
Aug 17 2019 12:00AM
[Chow Zheng Yuan]
Precise Auto Services

This is an auto-generated email. Do not reply to this email.

Sent by : Clara Li Zi Rong (FWD Singapore Pte. Ltd.)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019 Edit Reg		19 Aug 2019 00:00 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Chow Zheng Yuan , ID: S85600373									
Main Claimant: JASON LEE ZHENG DE , ID: S8931686C									
Vehicle Reg. No.: SJM6671L		Date of Loss: 17/08/2019 00:00 - :59 [127 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201900024549		Policy/Cover Note No.: PNPV2016-00000699-02 (Comprehensive) Coverage: 30/12/2018 - 29/12/2019							
Vehicle Reg. No. (Insured): SKN6296U		Policy No. (Claimant):							
		Excess:							
Repairer: Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (13/01/2020): Alert - Adj Mandate Maintained - SJM6671L - Claim Handler: Clara Li Zi Rong - FWD_SG (30/12/2019): Alert - Adj Mandate Maintained - SJM6671L - Claim Handler: Clara Li Zi Rong									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM6671L (1201900024549)
[SKN6296U]

TP
JASON LEE ZHENG DE
Aug 17 2019 12:00AM
[Chow Zheng Yuan]
Precise Auto Services

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	30/12/19 10:26	Odometer Reading							 Load JPG	☒		
2	30/12/19 10:26	Chassis Number							 Load JPG	☒		
3	30/12/19 10:26	General View							 Load JPG	☒		
4	30/12/19 10:26	General View							 Load JPG	☒		
5	30/12/19 10:26	General View							 Load JPG	☒		
6	30/12/19 10:26	General View							 Load JPG	☒		
7	30/12/19 10:26	General View							 Load JPG	☒		
8	30/12/19 10:26	General View							 Load JPG	☒		
9	30/12/19 10:26	General View							 Load JPG	☒		
10	30/12/19 10:26	General View							 Load JPG	☒		
11	30/12/19 10:26	General View							 Load JPG	☒		
12	30/12/19 10:26	General View							 Load JPG	☒		
13	30/12/19 10:26	General View							 Load JPG	☒		
14	30/12/19 10:26	General View							 Load JPG	☒		
15	30/12/19 10:26	General View							 Load JPG	☒		
16	30/12/19 10:26	General View							 Load JPG	☒		
17	30/12/19 10:26	General View							 Load JPG	☒		
18	30/12/19 10:26	General View							 Load JPG	☒		
19	30/12/19 10:26	General View							 Load JPG	☒		
20	30/12/19 10:26	General View							 Load JPG	☒		
21	30/12/19 10:26	General View							 Load JPG	☒		
22	30/12/19 10:26	General View							 Load JPG	☒		
23	30/12/19 10:26	General View							 Load JPG	☒		
24	30/12/19 10:26	General View							 Load JPG	☒		
25	30/12/19 10:26	General View							 Load JPG	☒		
26	30/12/19 10:26	General View							 Load JPG	☒		
27	30/12/19 10:26	General View							 Load JPG	☒		
28	30/12/19 10:26	General View							 Load JPG	☒		
29	30/12/19 10:26	General View							 Load JPG	☒		
30	30/12/19 10:26	General View							 Load JPG	☒		
31	30/12/19 10:26	General View							 Load JPG	☒		
32	30/12/19 10:26	General View							 Load JPG	☒		
33	30/12/19 10:26	General View							 Load JPG	☒		
34	30/12/19 10:26	General View							 Load JPG	☒		
35	30/12/19 10:26	General View							 Load JPG	☒		
36	30/12/19 10:26	General View							 Load JPG	☒		
37	30/12/19 10:26	General View							 Load JPG	☒		
38	30/12/19 10:26	General View							 Load JPG	☒		
39	30/12/19 10:26	General View							 Load JPG	☒		
40	30/12/19 10:27	Reinspection Photo							 Load JPG	☒		
41	30/12/19 10:27	Reinspection Photo							 Load JPG	☒		
42	30/12/19 10:27	Reinspection Photo							 Load JPG	☒		
43	30/12/19 10:27	Reinspection Photo							 Load JPG	☒		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/12/19 10:27	Reinspection Photo		☒
45	30/12/19 10:27	Reinspection Photo		☒
46	30/12/19 10:27	Reinspection Photo		☒
47	30/12/19 10:27	Reinspection Photo		☒
48	30/12/19 10:27	Reinspection Photo		☒
49	30/12/19 10:27	Reinspection Photo		☒
50	30/12/19 10:27	Reinspection Photo		☒
51	30/12/19 10:27	Reinspection Photo		☒
52	30/12/19 10:27	Reinspection Photo		☒
53	30/12/19 10:27	Reinspection Photo		☒
54	30/12/19 10:27	Reinspection Photo		☒
55	30/12/19 10:27	Reinspection Photo		☒
56	30/12/19 10:27	Reinspection Photo		☒
57	30/12/19 10:27	Reinspection Photo		☒
58	30/12/19 10:27	Reinspection Photo		☒
59	30/12/19 10:27	Reinspection Photo		☒
60	30/12/19 10:27	Reinspection Photo		☒
61	30/12/19 10:27	Reinspection Photo		☒
62	30/12/19 10:27	Reinspection Photo		☒
63	30/12/19 10:27	Reinspection Photo		☒
64	30/12/19 10:27	Reinspection Photo		☒
65	30/12/19 10:27	Reinspection Photo		☒
66	30/12/19 10:27	Reinspection Photo		☒
67	30/12/19 10:27	Reinspection Photo		☒
68	30/12/19 10:27	Reinspection Photo		☒
69	30/12/19 10:27	Reinspection Photo		☒
70	30/12/19 10:27	Reinspection Photo		☒
71	30/12/19 10:27	Reinspection Photo		☒
72	30/12/19 10:27	Reinspection Photo		☒
73	30/12/19 10:27	Reinspection Photo		☒
74	30/12/19 10:27	Reinspection Photo		☒
75	30/12/19 10:27	Reinspection Photo		☒
76	30/12/19 10:27	Reinspection Photo		☒
77	30/12/19 10:27	Reinspection Photo		☒
78	30/12/19 10:27	After Repair Photo		☒
79	30/12/19 10:27	After Repair Photo		☒
80	30/12/19 10:27	After Repair Photo		☒
81	30/12/19 10:27	After Repair Photo		☒
82	30/12/19 10:27	After Repair Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 16:49	EMAIL FROM FWD DD 20082019		☒
2	20/08/19 16:49	WKSP NOTICE		☒
3	22/08/19 17:35	TP GIA REPORT		☒
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/19 09:46	SKN6296U OI GIA		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19014548/UGS3Q2

Date: 26/02/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2016-00000699-02

Claimant Vehicle No : SJM6671L Insured Vehicle No : SKN6296U

Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: 1201900024549

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM6671L	Engine No:	1NZX817320
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305086229
Reg. Date:	13/01/2009 (Man. Year: 2008)	Odometer:	188170 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,966.07	1,216.17	1,749.90	59.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,550.00	1,180.00	43.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,696.07	2,766.17	2,929.90	51.44
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	5,696.07	2,200.00	3,496.07	61.38
+ GST 7.00/7.00% (S\$)	398.72	154.00	244.72	61.38
Nett Amount (S\$)	6,094.79	2,354.00	3,740.79	61.38
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 21/08/2019 Inspected At:

Precise Auto Services (HQ)
NO.1 KAKI BUKIT AVE 6 #02-34/36
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2020)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM6671L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	337.10 FL	*- FL
2	1		*BOOT LID LOCK	Not Necessary	63.90 FL	*- FL
3	1		*BOOT LID LOCK STRIKER	Not Necessary	43.10 FL	*- FL
4	2		*BOOT LID STOPPER	Not Necessary	87.80 FL	*- FL
5	1		*BOOT LID WEATHERSTRIPE	Twisted	53.90 FL	*53.90 FL
6	1		*REAR BUMPER FASCIA	Deformed / Torn	283.20 FL	*283.20 FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	87.80 FL	*87.80 FL
8	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*50.00 FL
9	2		*TAIL LAMP ASSY RH & LH	Not Necessary	366.00 FL	*- FL
10	2		*TAIL LAMP SEALANT	Not Necessary	100.00 FL	*- FL
11	2		*TAIL LAMP CLIPS	Not Necessary	25.80 FL	*- FL
12	1		*REAR END PANEL	Repair	689.20 FL	*- FL
13	1		*REAR END PANEL TOP TRIM	Not Necessary	63.90 FL	*- FL
14	6		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	77.40 FL	*- FL
15	1		*REAR BUMPER LOWER SPOILER	Cracked	580.00 FS	*580.00 FS
16	1		*BOOT LID BADGE	Necessary	80.00 FS	*80.00 FS
17	1		*REVERSE SENSOR WITH CONTROL UNIT	Shorted	380.00 FS	*200.00 FS
18	2		*TAIL LAMP BLACK STICKER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,568.10	1,334.90
- List Item Discount on L Items 25.00/25.00% (S\$)	602.03	118.73
Total Parts (S\$)	2,966.07	1,216.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	20.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	100.00	80.00
5	TO REMOVE & TRANSFER BOOT LID MECHANISM	New	120.00	0.00
6	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
7	TO RESPRAY AFFECTED AREAS	New	1,100.00	800.00
8	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR FENDER O/S ,REAR FLOOR PANEL REAR CHASSIS FRAME MEMBER AND ALIGNED ALL PARTS	New	950.00	600.00
Gross Labour Cost (\$\$)			2,730.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >