

ASS. REC. BY:

REF: CS/PC19014549/K913N2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Srane

of

FC1

Date/Time:

20.2.19 3.08p.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKL 3876B

Insured: SHC 1399H

at Workshop m/s Alan's United Auto Pte Ltd

Tel: 6453 8686

of Blk 7 Sin Ming Industrial Estate #01-76

Policy No:

Claim No: D19005366 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20.8.19. 4.03p.m.

Person Contacted:

Janice

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 1399H: CC4/ASM19003666/K1H3Q2 D.O.A: 25/02/2019

SKL 3876B: X

22/8/19 @ 4.16pm revised to Srane ltr by email.

12/9 11pm & 800d Confirmed (Ref 66514.72, 45%)

ASS. REC. BY:

REF:

F021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

RECEIVED 12 SEP 2019

Veh No:

PK2 38788 Yr Regn: 11113

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Comm

c.c

1998

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

89138

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053BK5104020125

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

16/8/19

D.O.I.

20/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2 Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1) 12/9/19

Date/Time, File Return to?

2)

Days Of Repair:

16

Resurvey No. of Trlp:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

4x15=60

170+60

50

50

39

369

Report Format :

TP

Lump Sum / I.B.I. (\$)

8000



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005366MFSH

Date: 22 August 2019

Our Ref: CS/FCI19014549/Kqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKL 3876B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/08/2019 at the premises of M/s ALAN'S UNITED AUTO. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 14,514.72</u> .
Revised Estimate Amount	: <u>S\$ 11,749.00</u> .
"Check" Items Amount	: <u>S\$ 1,649.40</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	19-08-2019	Our Ref No. D19005366MFSH
Accident Date	16-08-2019	Claim Type. Third Party
Insured Vehicle	SHC1399H	Third Party Vehicle. SKL3876B
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 0	Fax No. 64596550
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. \$14,514.72)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 22 August 2019 4:16 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005366MFSH/1
Attachments: CSFCI19014549Kqf3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SKL 3876B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 21 August 2019 9:10 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005366MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 August 2019 2:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005366MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	854Z
Vehicle Details	
Vehicle No.:	SKL3876B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1AZE277311
Chassis No.:	MR053BK5104020125
Maximum Power Output:	109.0 kW (146 bhp)
Open Market Value:	\$25,033.00
Original Registration Date:	01 Nov 2013
First Registration Date:	01 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$27,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2023
PARF Rebate Amount:	\$18,932.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$87,910.00
COE Rebate Amount:	\$36,841.00
Total Rebate Amount:	\$55,773.00

The information contained herein is correct as at 22 Aug 2019

OK

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: S1208854Z
 Owner ID Type: Singapore NRIC
 Owner Name: CHER LEW HIONG JAMES
 Registered Address: 42A WAN THO AVENUE SINGAPORE 347604
 Mailing Address: -
 Birth Date: 04 Jun 1956

Vehicle Particulars

Vehicle No.: SKL3876B
 Previous Vehicle No.: -
 Effective Date of Ownership: 01 Nov 2013
 Original Regn Date: 01 Nov 2013
 Registration Date: 01 Nov 2013
 Year of Manufacture: 2013
 Vehicle Type: Passenger Motor Car
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: TOYOTA
 Vehicle Model: CAMRY 2.0 AUTO
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: MR053BK5104020125
 Engine No.: 1AZE277311
 Engine Capacity / Power Rating: 1998 cc / -
 Maximum Power Output: 109.0 kW (146 bhp)
 Propellant: Petrol
 Max Unladen Weight: 1445 kg
 Maximum Laden Weight: 2000 kg
 Open Market Value: \$25,033.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 31 Oct 2023
 Minimum PARF Benefit: \$13,523.00
 No. of Transfers: 0
 IU Label No.: 1125145276
 COE No.: 2013110103000668G
 COE Expiry Date: 31 Oct 2023
 COE Category: B - Car (1601cc & above)
 COE Registration Category: B - Car (1601cc & above)
 Quota Premium (QP) / Prevailing Quota Premium: \$87,910.00 / -
 Actual QP Paid: \$87,910.00
 QP (Regn Cat): \$87,910.00
 OPC Cash Rebate Eligibility: No
 QP during COE Bidding Exercise: \$87,910.00
 Additional Registration Fee Rate: First \$20,000.00 (100%), next \$5,033.00 (140%)
 Actual ARF Paid: \$27,047.00
 Vehicle Lifespan Expiry Date: No Lifespan
 CO2 Emission: 198.00 (g/km)
 CEV/VES Rebate Utilised Amount: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 Message: To renew the COE, the Prevailing Quota Premium payable is that of Category B.

Print

OK

Save as PDF

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg No.: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmsis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP

FORM MX1

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 18-MU010799-R01 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SKL3876B **Chassis No.:** MR053BK5104020125
2. **Name of Policyholder** MR CHER LEW HIONG JAMES
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 01/11/2018
4. **Date of Expiry of Insurance** 31/10/2019
5. **Persons or Class of Persons entitled to drive***
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 2397DDA

Insurance Plan:	Comprehensive Approved Workshop Plan
Limit for total loss or theft:	Prevailing Market Value
Policy Excess:	Own Damage Claims SGD 800
	Windscreen Excess SGD 100

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06036

Vehicle Insured : SHC 1399H

Accident Date : 16-Aug-2019

Date : 19-Aug-2019

Our Ref : 219134 (FIRST) / CHAN

PAGE : 1

CHER LEW HIONG JAMES
42A WAN THO AVENUE
Singapore 347604

Not Authorised
11 Sep 8?
Repair After Paint

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.0 SKL3876B

1 pc	Rear bumper fascia		<i>At</i>	569.20	✓
2 pcs	Rear bumper reflector	@ S\$ 54.10	<i>CM</i>	108.20	✓
4 pcs	Rear bumper parking sensor	<i>shay</i> @ S\$381.60	<i>1,</i>	526.40	✓
1 pc	Rear bumper under cover		<i>Bu</i>	374.20	✓
10 pcs	Rear bumper under cover clip	@ S\$ 3.80	<i>mu</i>	38.00	✓
1 pc	Rear o/s bumper screw cover		<i>mu</i>	12.80	x
2 pcs	Taillamp	<i>MSM / GT</i> @ S\$416.10		832.20	✓
2 pcs	Taillamp lower bracket	@ S\$ 19.90	<i>mu</i>	39.80	✓
2 pcs	Taillamp side clip	@ S\$ 3.80	<i>mu</i>	7.60	✓
1 pc	Rear o/s taillamp corner panel		<i>mu</i>	143.10	x
1 pc	Rear end panel		<i>At</i>	581.20	✓
1 pc	End panel top garnish		<i>D.I</i>	295.10	✓
1 pc	Rear spare tyre panel		<i>BT/An</i>	825.20	✓
1 pc	O/s spare tyre side panel		<i>mu</i>	186.60	x
1 pc	Rear o/s chassis member		<i>mu</i>	822.60	x
2 pcs	Rear bumper side retainer-long	@ S\$104.40	<i>CM</i>	208.80	✓
2 pcs	Rear bumper side retainer-shot	@ S\$ 51.70	<i>CM</i>	103.40	✓
1 pc	Rear o/s fender		<i>Bu</i>	892.10	✓
1 pc	Rear w/s glass moulding		<i>mu</i>	80.30	✓
1 pc	Rear exhaust silencer box		<i>mu</i>	865.70	x
1 pc	Rear exhaust box chrome pipe		<i>mu</i>	142.80	✓
1 pc	Boot lid		<i>At</i>	892.10	✓
1 pc	Boot lid inner lock		<i>mu</i>	360.40	✓
1 pc	Boot lid rubber		<i>Dis/du</i>	204.60	50% in
2 pcs	Boot lid lamp	<i>MSM</i> @ S\$360.90		721.80	4
1 pc	Boot lid "CAMRY" emblem		<i>mu</i>	49.90	✓
1 pc	Boot lid "2.0" emblem		<i>mu</i>	38.90	✓
1 pc	Front bumper fascia		<i>Bin</i>	511.20	✓
1 pc	Front bumper no.plate garnish		<i>mu</i>	82.90	✓

LKK Auto Consultants hence notify

the Repairer of the following:

Con't Page 2 ...

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC 1399H

Page : 2

- 1 pc Front bumper reinforcement
- 1 pc Front bumper sponge
- 1 pc Brace panel
- 1 pc Front bumper lower grille
- 1 pc Radiator grille
- 1 pc Radiator grille logo
- 1 pc Front top cover
- 8 pcs Front top cover clip

	<i>Bz</i>	421.70	✓
	<i>sn</i>	88.30	✓
	<i>sn</i>	91.70	✓
	<i>sn</i>	144.30	✓
	<i>cm</i>	530.50	✓
	<i>sn</i>	72.20	✓
	<i>sn</i>	230.10	✓
	<i>sn</i>	30.40	✓
@ S\$	3.80		
		13,126.30	
Less 25% :		3,281.58	

- 1 pc Front w/s glass sealant
- 1 pc Front no.plate with box

sn 9,844.72 *4012*
Ret 60.00 *sn*
 50.00 *sn*
4552

To remove & refix rear windscreen glass and conduct water leak test.

120.00 ✓

To remove roof lining, front and rear seats, trim board and carpet

180.00 *1201*

To apply undersealing

200.00 *1201*

To remove and renew exhaust silencer box

60.00 ✓

To putty and spray replaced parts

1,800.00 *16001*

To remove, cut-out damaged parts, panel beating, welding, align,

2,200.00 *20001*

Total : S\$14,514.72
 =====

Singapore Dollars Fourteen Thousand Five Hundred and Fourteen and Cents Seventy Two Only




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014549/Kqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1399H	Veh. Inspected	SKL 3876B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005366MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	20/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	MR053BK5104020125	Colour	METALLIC SILVER	
Odometer	89136	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2019	Inspection Date	20/08/2019	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			16 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 3876B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER FASCIA	BENT	569.20	569.20
2	REAR BUMPER REFLECTOR @\$54.10	CRACKED	108.20	108.20
4	REAR BUMPER PARKING SENSOR @\$381.60	SHORTED	1,526.40	1,526.40
1	REAR BUMPER UNDER COVER	BUCKLED	374.20	374.20
10	REAR BUMPER UNDER COVER CLIP @\$3.80	NECESSARY	38.00	38.00
1	REAR O/S BUMPER SCREW COVER	SERVICEABLE	12.80	-
2	TAILLAMP @\$416.10	MTG CRACKED / CUT	832.20	832.20
2	TAILLAMP LOWER BRACKET @\$19.90	NECESSARY	39.80	39.80
2	TAILLAMP SIDE CLIP @\$3.80	NECESSARY	7.60	7.60
1	REAR O/S TAILLAMP CORNER PANEL	TO REPAIR SEE LABOUR	143.10	-
1	REAR END PANEL	BENT	581.20	581.20
1	END PANEL TOP GARNISH	DISTORTED	295.10	295.10
1	REAR SPARE TYRE PANEL	BENT / BUCKLED	825.20	825.20
1	O/S SPARE TYRE SIDE PANEL	TO REPAIR SEE LABOUR	186.60	-
1	REAR O/S CHASSIS MEMBER	TO REPAIR SEE LABOUR	822.60	-
2	REAR BUMPER SIDE RETAINER-LONG @\$104.40	CRACKED	208.80	208.80
2	REAR BUMPER SIDE RETAINER-SHOT @\$51.70	CRACKED	103.40	103.40
1	REAR O/S FENDER	BUCKLED	892.10	892.10
1	REAR W/S GLASS MOULDING	NECESSARY	80.30	80.30
1	REAR EXHAUST SILENCER BOX	TO REPAIR SEE LABOUR	865.70	-
1	REAR EXHAUST BOX CHROME PIPE	DENTED	142.80	142.80
1	BOOT LID	BENT	892.10	892.10
1	BOOT LID INNER LOCK	DENTED	360.40	360.40
2	BOOT LID LAMP @\$360.90	N/S CRACKED	721.80	360.90
1	BOOT LID "CAMRY" EMBLEM	NECESSARY	49.90	49.90
1	BOOT LID "2.0" EMBLEM	NECESSARY	38.90	38.90
1	FRONT BUMPER FASCIA	BUCKLED	511.20	511.20

Report Ref No. CS/FCI19014549/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER NO PLATE GARNISH	DENTED	82.90	82.90
1	FRONT BUMPER REINFORCEMENT	BENT	421.70	421.70
1	FRONT BUMPER SPONGE	SERVICEABLE	88.30	-
1	BRACE PANEL	TO REPAIR SEE LABOUR	91.70	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	144.30	-
1	RADIATOR GRILLE	CRACKED	530.50	530.50
1	RADIATOR GRILLE LOGO	NECESSARY	72.20	72.20
1	FRONT TOP COVER	SERVICEABLE	230.10	-
8	FRONT TOP COVER CLIP @\$3.80	NECESSARY	30.40	30.40
	LESS 25% DISCOUNT		-3,230.43	-2,493.90
			9,691.27	7,481.70
1	BOOT LID RUBBER (50%)(SN)	DISTORTED / DENTED	204.60	102.30
	LESS 25% DISCOUNT		-51.15	-
			153.45	102.30
	SPECIAL NETT ITEMS			
1	FRONT W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	FRONT NO PLATE WITH BOX (SN)	DENTED	50.00	45.00
			110.00	85.00
	LABOUR			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET.		180.00	120.00
	TO APPLY UNDERSEALING.		200.00	120.00
	TO REMOVE AND RENEW EXHAUST SILENCER BOX.		60.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		1,800.00	1,600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN.INCLUSIVE OF THE REPAIR OF REAR O/S TAILLAMP CORNER PANEL,O/S SPARE TYRE SIDE PANEL,REAR O/S CHASSIS MEMBER,REAR EXHAUST SILENCER BOX AND BRACE PANEL.		2,200.00	2,000.00
			4,560.00	4,020.00
GRAND TOTAL			14,514.72	11,689.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CS/FCI19014549/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.