

Springer

Tanpin

REF:

A19 CC3/A1419014555/T19-30

ASSIGNMENT

From:

Date:

20.8.2019

Estimated Cost:

OD: /WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1900058142

Claims No.

767655872956

26/8/19

Sum Insured:

Excess:


1600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8130K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Vein No:

SMJ6962C

Yr Regn:

2019, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

c.c

1395

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

1921

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAM 22 E8V9K (009145)

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 55K16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

20/8/19

Survey held at

Premium Bond

Des. of Damages (Frt)

Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit 875K

21/8/19 @ 11.47am revert to Victor via Mennan.

22/8/19 @ 3.53pm 2nd revert to Victor via Mennan. (repairer writing COR: 875K)

23/8/19 @ 3.19pm Andy Fong informed C/A not more than 875K via Mennan.

26/8/19 @ 9.11am Informed Ezzuan C/A not more than 875K & Ex: 680 by email.

06/9/19 @ 1.50pm 3rd revert to Victor via Mennan. (Supplementary).

09/9/19 @ 11.03am Victor informed that the repair cost not exceeding 875K.

10/12/19 @ 5.03pm confirmed with Mr Bao final fig 860003.44, 20 days.

10/12/19 @ 3.200.12, 39%

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

20

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

11

211

Report Format:

MER-00

Lump Sum / I.B.I: (\$

60003.44

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 December 2019 5:07 PM
To: Boo seng yak; SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SMJ6962C - OD AIG - SURVEYED 20 AUG 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$60,003.44 before excess \$600.00 & GST and 20 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 25 November 2019 2:08 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMJ6962C - OD AIG - SURVEYED 20 AUG 19

Hi Adrian, Taufikh and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$60,003.44 @ 21 days exclude 3 Sundays.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Aug 2019 09:13	Clim Veh Model Changed	(206272) AUDI A3 1.4 SEDAN TFSI COD S-TRONIC (A).	[] Merimen Administrator
2	15 Aug 2019 09:13	Clim Created	Reg No: SMJ6962C, Policy No: 1900058142, Acct Date: 2019/08/14, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Created from SAS:MPA119106601	[I] Merimen Administrator
3	20 Aug 2019 17:15	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	20 Aug 2019 17:15	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	20 Aug 2019 17:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	20 Aug 2019 17:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] LEE SU THING
7	20 Aug 2019 17:15	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	20 Aug 2019 17:15	Clim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	20 Aug 2019 17:15	Clim Veh Model Changed	(206272) -> (204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] LEE SU THING
10	20 Aug 2019 17:17	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
11	21 Aug 2019 09:14	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mithoo Singh, Ashweenjeet Kaur
12	21 Aug 2019 10:55	Adj Rpt Initiated		[A] SHIAU CHAN
13	21 Aug 2019 10:55	Clim Dtl Modified	JPJ Reg. Date: -> 2019/03/15.	[A] SHIAU CHAN
14	21 Aug 2019 10:55	Clim Details Notified		[A] SHIAU CHAN
15	21 Aug 2019 11:47	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] SHIAU CHAN
16	21 Aug 2019 11:47	Adj Mandate Request	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
17	21 Aug 2019 15:18	Clim Veh Model Changed	(204616) -> (204858) AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A).	[] Merimen Administrator
18	21 Aug 2019 17:11	Adj Adjuster Assigned	MOHD RASUL -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
19	22 Aug 2019 08:28	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	22 Aug 2019 15:48	Adj Mandate Request Cancelled		[A] SHIAU CHAN
21	22 Aug 2019 15:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] SHIAU CHAN
22	22 Aug 2019 15:53	Adj Mandate Request	Cur.Req:84791.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
23	23 Aug 2019 15:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29. Mandate Remarks: Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Fong, Andy-SY
24	23 Aug 2019 15:19	Adj Mandate Set	Approved:56000.00:Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Fong, Andy-SY
25	06 Sep 2019 13:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] SHIAU CHAN
26	06 Sep 2019 13:52	Adj Mandate Request	Cur.Req:94660.00:DAMAGES CONSISTENT. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00 KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
27	06 Sep 2019 15:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/29. Mandate Remarks: Upload photos. Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Koh, Victor-CK
28	06 Sep 2019 15:56	Adj Mandate Set	Maintained:Upload photos. Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Koh, Victor-CK
29	09 Sep 2019 09:17	Adj Mandate Request	Cur.Req:75000.00:PLEASE BE INFORMED THAT THE RELEVANT DOCUMENTS UPLOADED.	[A] SHIAU CHAN
30	09 Sep 2019 11:03	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/29. Mandate Remarks: Kindly advise what is Mechatronic with software and damage photos> Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident	[I] Koh, Victor-CK
31	09 Sep 2019 11:03	Adj Mandate Set	Maintained:Kindly advise what is Mechatronic with software and damage photos> Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Koh, Victor-CK
32	05 Dec 2019 09:15	Adj Mandate Request	Cur.Req:60003.44:KINDLY APPROVE REPAIR COST OF \$60,003.44.	[A] SHIAU CHAN
33	05 Dec 2019 16:35	Adj Mandate Set	Approved:60003.44.	[I] Fong, Andy-SY

Audit Type

View Sent Message

This mail is associated with :

***SMJ6962C (7676558729SG)**
OD

Aug 14 2019 6:15AM
[MOHAMAD IDRIS BIN ASMURI]
Premium Automobiles Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **11/09/2019 12:02 PM.**
To AIG_SG; Victor_KohCK
Subject **Re: Alert - Adj Mandate Maintained - SMJ6962C - Claim Handler: Mithoo Singh, Aashweenjeet Kaur**

Dear Victor,

Please refer to the photo no. 128, 129 & 130 of MECHATRONIC WITH SOFTWARE in Merimen System.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 09/09/2019 11:03 AM

Subject: Alert - Adj Mandate Maintained - SMJ6962C - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Maintained: Kindly advise what is Mechatronic with software and damage photos > Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMJ6962C (7676558729SG)**

OD

Aug 14 2019 6:15AM

[MOHAMAD IDRIS BIN ASMURI]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/09/2019 11:03 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SMJ6962C - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Maintained: Kindly advise what is Mechatronic with software and damage photos > Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.

SMJ6962 (RESURVEY) folder
DS(N 2071
n 2072
n 2073

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	15 Aug 2019 09:13	Clim Veh Model Changed	(206272) AUDI A3 1.4 SEDAN TFSI COD S-TRONIC (A).		[] Merimen Administrator
2	15 Aug 2019 09:13	Clim Created	Reg No: SMJ6962C, Policy No: 1900058142, Acct Date: 2019/08/14, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Created from SAS:MPA119106601		[1] Merimen Administrator
3	20 Aug 2019 17:15	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[] LEE SU THING
4	20 Aug 2019 17:15	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] LEE SU THING
5	20 Aug 2019 17:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] LEE SU THING
6	20 Aug 2019 17:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29		[A] LEE SU THING
7	20 Aug 2019 17:15	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] LEE SU THING
8	20 Aug 2019 17:15	Clim Registration Modified	Rep:1137->200611.		[A] LEE SU THING
9	20 Aug 2019 17:15	Clim Veh Model Changed	(206272) -> (204616) AUDI A4 1.4 TFSI S TRONIC (A).		[A] LEE SU THING
10	20 Aug 2019 17:17	Adj Adjuster Assigned	[None] -> MOHD RASUL		[A] LEE SU THING
11	21 Aug 2019 09:14	Clim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.		[1] Mithoo Singh, Aashweenjeet Kaur
12	21 Aug 2019 10:55	Adj Rpt Initiated			[A] SHIAU CHAN
13	21 Aug 2019 10:55	Clim Dtl Modified	JPJ Reg. Date: -> 2019/03/15.		[A] SHIAU CHAN
14	21 Aug 2019 10:55	Clim Details Notified			[A] SHIAU CHAN
15	21 Aug 2019 11:47	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29		[A] SHIAU CHAN
16	21 Aug 2019 11:47	Adj Mandate Request	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.		[A] SHIAU CHAN
17	21 Aug 2019 15:18	Clim Veh Model Changed	(204616) -> (204858) AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A).		[] Merimen Administrator
18	21 Aug 2019 17:11	Adj Adjuster Assigned	MOHD RASUL -> MOHD TAUFIKH BIN HAMID		[A] Nivitha Govindasamy
19	22 Aug 2019 08:28	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
20	22 Aug 2019 15:48	Adj Mandate Request Cancelled			[A] SHIAU CHAN
21	22 Aug 2019 15:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29		[A] SHIAU CHAN
22	22 Aug 2019 15:53	Adj Mandate Request	Cur.Req:84791.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
23	23 Aug 2019 15:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29. Mandate Remarks: Repairs not to exceed economical repair limit of \$75.000. To commence OD repairs. Re seek mandate after dismantling accident portion.		[1] Fong, Andy-SY
24	23 Aug 2019 15:19	Adj Mandate Set	Approved:56000.00:Repairs not to exceed economical repair limit of \$75.000. To commence OD repairs. Re seek mandate after dismantling accident portion.		[1] Fong, Andy-SY
25	06 Sep 2019 13:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29		[A] SHIAU CHAN
26	06 Sep 2019 13:52	Adj Mandate Request	Cur.Req:94660.00:DAMAGES CONSISTENT. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00 KINDLY APPROVE ON SUPPLEMENTARY.		[A] SHIAU CHAN
27	06 Sep 2019 15:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/08/29. Mandate Remarks: Upload photos. Repairs not to exceed economical repair limit of \$75.000. To commence OD repairs. Re seek mandate after dismantling accident portion.		[1] Koh, Victor-CK
28	06 Sep 2019 15:56	Adj Mandate Set	Maintained:Upload photos. Repairs not to exceed economical repair limit of \$75.000. To commence OD repairs. Re seek mandate after dismantling accident portion.		[1] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2252209	21 Aug 2019 10:55:23	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMJ6962C		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 06 Sep 2019

Preliminary Advice

Vehicle No	: SMJ6962C	Accident Date	: 14/08/2019
Make	: AUDI A3	Policy No.	: 1900058142
Assignment Date	: 20/08/2019	Excess	: S\$600.00
Date of Inspection	: 20/08/2019	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	112,254.00	(ESTIMATE \$102,385.00 + SUPPLEMENTARY \$9,869.00)
Revised Amount	:S\$	64,925.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	29,735.00	
Total	:S\$	94,660.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	54,050.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	82,410.00
Margin for Repair (Pre-Accident Value)	:S\$	75,950.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00
KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 26 August 2019 9:11 AM
To: claims@premiumauto.com.sg
Cc: nora.khai@premiumauto.com.sg; SUR
Subject: RE: OD CLAIM FOR SMJ 6962 C ON 14/8/2019

Dear Ezuwan,

As instructed by our client, please proceed to repair the insured vehicle **SMJ 6962C** at repair cost not more than **\$75,000.00 on part by part basis (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 22 August 2019 3:22 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: nora.khai@premiumauto.com.sg; claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SMJ 6962 C ON 14/8/2019

Hi Shiau,

We accepted the repair for above vehicle not more than \$75,000.00 on part by part basis.
Please advise on the excess and the approval.

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223


Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Aug 2019 09:13	Clim Veh Model Changed	(206272) AUDI A3 1.4 SEDAN TFSI COD S-TRONIC (A).	[] Merimen Administrator
2	15 Aug 2019 09:13	Clim Created	Reg No: SMJ6962C. Policy No: 1900058142. Acct Date: 2019/08/14. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119106601	[I] Merimen Administrator
3	20 Aug 2019 17:15	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	20 Aug 2019 17:15	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	20 Aug 2019 17:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	20 Aug 2019 17:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] LEE SU THING
7	20 Aug 2019 17:15	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	20 Aug 2019 17:15	Clim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	20 Aug 2019 17:15	Clim Veh Model Changed	(206272) -> (204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] LEE SU THING
10	20 Aug 2019 17:17	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
11	21 Aug 2019 09:14	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mithoo Singh, Aashweenjeet Kaur
12	21 Aug 2019 10:55	Adj Rpt Initiated		[A] SHIAU CHAN
13	21 Aug 2019 10:55	Clim Dtl Modified	JPJ Reg. Date: -> 2019/03/15.	[A] SHIAU CHAN
14	21 Aug 2019 10:55	Clim Details Notified		[A] SHIAU CHAN
15	21 Aug 2019 11:47	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] SHIAU CHAN
16	21 Aug 2019 11:47	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
17	21 Aug 2019 15:18	Clim Veh Model Changed	(204616) -> (204858) AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A).	[] Merimen Administrator
18	21 Aug 2019 17:11	Adj Adjuster Assigned	MOHD RASUL -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
19	22 Aug 2019 08:28	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	22 Aug 2019 15:48	Adj Mandate Request Cancelled		[A] SHIAU CHAN
21	22 Aug 2019 15:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/08/29	[A] SHIAU CHAN
22	22 Aug 2019 15:53	Adj Mandate Request	Cur.Reg:84791.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
23	23 Aug 2019 15:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/29. Mandate Remarks: Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Fong, Andy-SY
24	23 Aug 2019 15:19	Adj Mandate Set	Approved:56000.00:Repairs not to exceed economical repair limit of \$75,000. To commence OD repairs. Re seek mandate after dismantling accident portion.	[I] Fong, Andy-SY

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2252209	21/08/2019 10:55	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMJ6962C		11.77

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 22 Aug 2019

Preliminary Advice

Vehicle No	: SMJ6962C	Accident Date	: 14/08/2019
Make	: AUDI A3	Policy No.	: 1900058142
Assignment Date	: 20/08/2019	Excess	: S\$600.00
Date of Inspection	: 20/08/2019	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

RePAIRER'S Estimate (Gross)	:S\$	102,385.00
Revised Amount	:S\$	55,180.00
Check Items (Estimated)	:S\$	29,611.00
Total	:S\$	84,791.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	54,050.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	82,410.00
Margin for Repair (Pre-Accident Value)	:S\$	75,950.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$75,000.00.

Shiau Chan (LKKAuto)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 22 August 2019 3:22 PM
To: Shiau Chan (LKKAuto)
Cc: nora.khai@premiumauto.com.sg; claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SMJ 6962 C ON 14/8/2019

Hi Shiau,

We accepted the repair for above vehicle not more than \$75,000.00 on part by part basis.
Please advise on the excess and the approval.

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 21 August 2019 10:08 AM
To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Cc: claims@premiumauto.com.sg; nora.khai@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SMJ 6962 C ON 14/8/2019

Hi Shiau,

Noted on your remark. Will discuss with my team and I shall get back to you. Thank you

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 21 Aug 2019

Preliminary Advice

Vehicle No	: SMJ6962C	Accident Date	: 14/08/2019
Make	: AUDI A4	Policy No.	: 1900053142
Assignment Date	: 20/08/2019	Excess	: S\$600.00
Date of Inspection	: 20/08/2019	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	102,385.00
Revised Amount	:S\$	55,180.00
Check Items (Estimated)	:S\$	29,611.00
Total	:S\$	84,791.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	54,050.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	82,410.00
Margin for Repair (Pre-Accident Value)	:S\$	75,950.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0975/2019/NS
Date : 16-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR MOHAMAD IDRIS BIN ASMURI
Address : BLK 273B PUNGGOL PLACE
#07-864
Singapore 822273
Telephone : HP +65 96312500
Type of Claim : Own Damage Claims
Policy No. : 1900058142
Vehicle No : **SMJ 6962 C**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Mar-19
Engine No : CZE 846955
Chassis No : WAUZZZ8V9K1009145
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-19
Place of Accident : BLK 274B PUNGGOL PLACE SERVICE RD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6962 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X nn
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00	photo X nn
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain airbags and knee airbag.	S/N \$ 3,600.00	✓
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs	S/N \$ 2,800.00	? photo X nn
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00	? photo X nn
SUB TOTAL LABOUR CHARGES		: \$ 11,440.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6962 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To renew exhaust manifold turbo charger and other engine components.	S/N \$ 980.00 ?	
9	To place vehicle on car o-liner.	S/N \$ 1,800.00 ? photo	
10	To dismantle and renew front bumper , bonnet and both headlights. Align both front chasis frames to specification of origin. To repair both front fenders. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	3500. \$ 7,000.00	
11	To respray front bumper, bonnet, both front fenders and engine compartment.	2200. \$ 4,500.00	
12	to carry out wheel alignment.	S/N \$ 240.00 ?	
13	To carry out diagnostic checks.	S/N \$ 384.00 ✓	
SUB TOTAL LABOUR CHARGES		: <u>\$ 26,344.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 6962 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,830.00	de ✓
2	BUMPER FIXING PARTS		\$ 170.00	?
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 70.00	LH?, RH-de ✓
4	FRONT BUMPER GRILLE - CENTRE		\$ 146.00	de ✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 488.00	mis ✓
6	FRONT BUMPER CLOSING ELEMENT - LH / RH		\$ 540.00	LH-de-, RH?
7	FRONT BUMPER COVER TRIM - LH / RH	2	\$ 296.00	?
8	WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 68.00	?
9	RADIATOR GRILLE		\$ 1,301.00	an ✓
10	RADIATOR GRILLE CLOSING ELEMENT		\$ 174.00	de ✓
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 342.00	LH-de ✓, RH-?
12	FRONT BUMPER IMPACT BAR		\$ 660.00	bt ✓
13	FRONT BUMPER FOAM FILLER PIECE		\$ 172.00	de ✓
14	FRONT BUMPER COVER		\$ 111.00	de ✓
15	SIGNAL HORN - LH HIGH TONE		\$ 182.00	?
16	SIGNAL HORN - RH LOW TONE		\$ 182.00	?
17	BONNET		\$ 2,898.00	bt ✓
18	BONNET ATTACHMENT PARTS		\$ 149.00	?
19	BONNET LID HINGE - LH / RH - photo	2	\$ 112.00	bt ✓
20	GAS FILLED STRUT		\$ 109.00	?
SUB TOTAL SPARE PARTS		:	\$ 10,000.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
21	BONNET CATCH HOOK	\$	81.00	bt ✓
22	BONNET STRIKER - LH / RH	2 \$	200.00	bt ✓
23	BONNET EDGE PROTECTION	NEC \$	25.00	at ✓
24	BONNET HINGE COVER - LH / RH	2 \$	74.00	X
25	BONNET LID LOCK	2 \$	367.00	bt ✓
26	LID LOCK SWITCH CONNECTOR HOUSING	\$	12.00	?
27	BONNET BOWDEN CABLE - CENTRE	\$	53.00	?
28	LID LOCK CABLE	\$	67.00	?
29	WATER BOX ADAPTER SEAL - LH / RH	2 \$	24.00	?
30	WATER BOX SEAL - LH / RH	2 \$	24.00	?
31	BONNET SOUND ABSORBER	\$	201.00	de ✓
32	PLENUM CHAMBER COVER	\$	164.00	?
33	PLENUM CHAMBER TOP COVER	\$	15.00	?
34	LED HEADLIGHT - LH / RH	2 \$	10,058.00	cm ✓
35	HEADLIGHT POWER MODULE	\$	693.00	?
36	LIGHT SYSTEM CONTROL UNIT	\$	508.00	?
37	LED HEAT SINK - RH	\$	666.00	?
38	HEADLIGHT HOSE - LH / RH	2 \$	72.00	?
39	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / R	2 \$	256.00	?
40	LIFT CYLINDER HOSE	\$	61.00	?
SUB TOTAL SPARE PARTS		:	<u>\$ 13,621.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	COOLANT RADIATOR LOCK CARRIER MOUNTING	\$ 663.00	can✓
42	A/C CONDENSER - photo	\$ 503.00	bt✓
43	REFRIGERANT LINE - COMPRESSOR TO CONDENSER	\$ 461.00	?
44	REFRIGERANT LINE - CONDENSER TO CUT-OFF POINT	\$ 601.00	?
45	REFRIGERANT LINE - COMPRESSOR TO CUT-OFF POINT	\$ 461.00	?
46	COOLANT PIPE	\$ 461.00	?
47	RADIATOR - photo	\$ 878.00	bt✓
48	ADDITIONAL RADIATOR - photo	\$ 837.00	bt✓
49	RADIATOR BUSH - LOWER	2 \$ 18.00	de✓
50	RADIATOR BRACKET	2 \$ 77.00	de✓
51	COOLANT	4 \$ 165.00	can✓
52	RADIATOR FAN - photo	\$ 1,046.00	?
53	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	?
54	RADIATOR AIR GUIDE - UPPER CENTRE	2 \$ 11.00	?
55	RADIATOR HOSE	\$ 218.00	?
56	AIR INTAKE AIR GUIDE	\$ 53.00	can✓
57	AIR INTAKE COVER	\$ 27.00	can✓
58	AIR INTAKE AIR GUIDE	\$ 19.00	de✓
59	AIR INTAKE WATER DRAINAGE HOSE	\$ 31.00	de✓
60	AIR INTAKE AIR GUIDE	\$ 32.00	?
61	AIR INTAKE AIR FILTER	\$ 259.00	?
62	AIR INTAKE AIR DUCT	\$ 45.00	can✓
63	AIR INTAKE MANIFOLD	\$ 113.00	can✓
64	EXHAUST MANIFOLD	\$ 4,865.00	?
SUB TOTAL SPARE PARTS		\$ 11,888.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 6962 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
65	TURBOCHARGER GASKET	\$ 14.00	?
66	GASKET CONNECTOR TUBE	2 \$ 26.00	?
67	CONVERTER AND PIPE GASKET	\$ 19.00	?
68	CONVERTER AND PIPE CLAMP	\$ 47.00	?
69	ENGINE COMPARTMENT COVER	\$ 103.00	?
70	VENT HOSE	\$ 78.00	?
71	NOISE INSULATION	\$ 239.00	?
72	NOISE INSULATION FIXING PARTS	\$ 101.00	?
73	STEERING WHEEL AIR BAG UNIT	\$ 3,141.00	act ✓
74	AIRBAG UNIT	\$ 4,238.00	act ✓
75	HEAD AIRBAG UNIT - LH / RH	2 \$ 3,416.00	act ✓
76	KNEE AIRBAG UNIT	\$ 1,708.00	act ✓
77	AIRBAG CONTROL UNIT	\$ 1,606.00	act ✓
78	AIRBAG CRASH SENSOR	\$ 1,145.00	act ✓
79	STEERING WHEEL AIR BAG UNIT	3 \$? 2,169.00	act ✓
80	DASHBOARD WITH AIR DUCT	\$ 3,887.00	de ✓
81	AIR VENT - CENTRE	\$ 138.00	?
82	LOUDSPEAKER COVER	\$ 86.00	?
83	DASHBOARD LOWER PANEL UNDERTRAY - RH	\$ 413.00	de ✓
84	MOULDED HEADLINER	\$ 1,613.00	de ✓
85	A-PILLAR TRIM - LF	\$ 147.00	?
86	A-PILLAR TRIM - RH UPPER	\$ 147.00	?
87	B-PILLAR TRIM - LH RH UPPER	2 \$ 396.00	?
88	C-PILLAR TRIM - LH / RH UPPER	2 \$ 276.00	?
89	D-PILLAR TRIM - LH / RH UPPER	2 \$ 212.00	?
SUB TOTAL SPARE PARTS		: \$ 25,365.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SM1 6962 C

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
90	FOLDING GRAB HANDLE - LH FRONT	2	\$ 258.00	?
91	FOLDING GRAB HANDLE - LH / RH REAR	2	\$ 258.00	?
92	SEAT BELT - LH / RH	2	\$ 2,010.00	?
93	SEAT BELT HEIGHT ADJUSTER	2	\$ 361.00	?
94	FRONT NO PLATE	S/N	\$ 40.00	HA ✓
95	SUNDRIES		\$ 800.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 64,601.00	
TOTAL LABOUR CHARGES		:	\$ 37,784.00	
GRAND TOTAL		:	\$ 102,385.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183


21/8/19

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Jiah 97495749
20/8/19 @ 345 pm
Not Authorise
Ex: to be advise
Resurvey before paint
surellkauto.com
18 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0975/2019/NS
Date : 16-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian, Taufikh

21 days exclude 3 Sunday

Added repairs - jb - 23 Nov 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR MOHAMAD IDRIS BIN ASMURI
Address : BLK 273B PUNGGOL PLACE
#07-864
Singapore 822273
Telephone : HP +65 96312500
Type of Claim : Own Damage Claims
Policy No. : 1900058142
Vehicle No : **SMJ 6962 C**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Mar-19
Engine No : CZE 846955
Chassis No : WAUZZZ8V9K1009145
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-19
Place of Accident : BLK 274B PUNGGOL PLACE SERVICE RD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6962 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	\$ 280.00	na
2	To carry out first measurement test on car o-liner.	S/N	\$ 800.00	na
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	\$ 1,200.00
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain airbags and knee airbag.	S/N	\$ 3,600.00	\$ 3,600.00
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs	S/N	\$ 2,800.00	na
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,400.00	na
SUB TOTAL LABOUR CHARGES		:	\$ 11,440.00	\$ 5,160.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6962 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 5,160.00
8	To renew exhaust manifold turbo charger and other engine components.	S/N \$ 980.00	
9	To place vehicle on car o-liner.	S/N \$ 1,800.00	
10	To dismantle and renew front bumper , bonnet and both headlights. Align both front chasis frames to specification of origin. To repair both front fenders. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	\$ 7,000.00	\$ 3,500.00
11	To respray front bumper, bonnet, both front fenders and engine compartment.	\$ 4,500.00	\$ 2,200.00
12	to carry out wheel alignment.	S/N \$ 240.00	
12a	Added labour - see attached	S/N \$ 1,960.00	\$ 1,960.00
13	To carry out diagnostic checks.	S/N \$ 384.00	\$ 384.00
SUB TOTAL LABOUR CHARGES		: \$ 28,304.00	\$ 13,204.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 70.00	\$ 55.04
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	\$ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	\$ 390.00
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	\$ 540.00	\$ 216.00
7	FRONT BUMPER COVER TRIM - LH / RH	2 \$ 296.00	
8	WHEEL HOUSING LINER ADAPTER - LH / RH	2 \$ 68.00	
9	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.00
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	\$ 136.40
12	FRONT BUMPER IMPACT BAR	\$ 660.00	\$ 527.60
13	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	\$ 137.60
14	FRONT BUMPER COVER	\$ 111.00	\$ 88.80
15	SIGNAL HORN - LH HIGH TONE	\$ 182.00	
16	SIGNAL HORN - RH LOW TONE	\$ 182.00	
17	BONNET	\$ 2,898.00	\$ 2,318.40
18	BONNET ATTACHMENT PARTS	\$ 149.00	
19	BONNET LID HINGE - LH / RH	2 \$ 112.00	\$ 88.48
20	GAS FILLED STRUT	\$ 109.00	
	SUB TOTAL SPARE PARTS	\$ 10,000.00	\$ 6,717.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	6,717.52
21	BONNET CATCH HOOK		\$ 81.00	\$	64.72
22	BONNET STRIKER - LH / RH	2	\$ 200.00	\$	159.04
23	BONNET EDGE PROTECTION	NEC	\$ 25.00	\$	19.92
24	BONNET HINGE COVER - LH / RH	2	\$ 74.00		
25	BONNET LID LOCK	2	\$ 367.00	\$	293.60
26	LID LOCK SWITCH CONNECTOR HOUSING		\$ 12.00		
27	BONNET BOWDEN CABLE - CENTRE		\$ 53.00	\$	41.68
28	LID LOCK CABLE		\$ 67.00		
29	WATER BOX ADAPTER SEAL - LH / RH	2	\$ 24.00		
30	WATER BOX SEAL - LH / RH	2	\$ 24.00		
31	BONNET SOUND ABSORBER		\$ 201.00	\$	160.80
32	PLENUM CHAMBER COVER		\$ 164.00		
33	PLENUM CHAMBER TOP COVER		\$ 15.00		
34	LED HEADLIGHT - LH / RH	2	\$ 10,058.00	\$	8,046.40
35	HEADLIGHT POWER MODULE		\$ 693.00		
36	LIGHT SYSTEM CONTROL UNIT		\$ 508.00		
37	LED HEAT SINK - RH		\$ 666.00		
38	HEADLIGHT HOSE - LH / RH	2	\$ 72.00		
39	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH /	2	\$ 256.00		
40	LIFT CYLINDER HOSE		\$ 61.00	\$	48.16
	SUB TOTAL SPARE PARTS		\$ 13,621.00	\$	15,551.84

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	15,551.84
41	COOLANT RADIATOR LOCK CARRIER MOUNTING		\$ 663.00	\$ 530.40
42	A/C CONDENSER		\$ 503.00	\$ 402.00
43	REFRIGERANT LINE - COMPRESSOR TO CONDENSER		\$ 461.00	
44	REFRIGERANT LINE - CONDENSER TO CUT-OFF POINT		\$ 601.00	
45	REFRIGERANT LINE - COMPRESSOR TO CUT-OFF POINT		\$ 461.00	\$ 368.80
46	COOLANT PIPE		\$ 461.00	
47	RADIATOR		\$ 878.00	\$ 702.40
48	ADDITIONAL RADIATOR		\$ 837.00	\$ 669.60
49	RADIATOR BUSH - LOWER	2	\$ 18.00	\$ 14.24
50	RADIATOR BRACKET	2	\$ 77.00	\$ 61.28
51	COOLANT	4	\$ 165.00	\$ 131.84
52	RADIATOR FAN		\$ 1,046.00	\$ 836.80
53	RADIATOR AIR GUIDE - LH / RH	2	\$ 44.00	\$ 34.24
54	RADIATOR AIR GUIDE - UPPER CENTRE	2	\$ 11.00	\$ 8.32
55	RADIATOR HOSE		\$ 218.00	
56	AIR INTAKE AIR GUIDE		\$ 53.00	\$ 41.84
57	AIR INTAKE COVER	2	\$ 27.00	\$ 21.36
58	AIR INTAKE AIR GUIDE	2	\$ 19.00	\$ 14.48
59	AIR INTAKE WATER DRAINAGE HOSE	2	\$ 31.00	\$ 24.48
60	AIR INTAKE AIR GUIDE		\$ 32.00	\$ 25.20
61	AIR INTAKE AIR FILTER		\$ 259.00	\$ 207.20
62	AIR INTAKE AIR DUCT		\$ 45.00	
63	AIR INTAKE MANIFOLD		\$ 113.00	
64	EXHAUST MANIFOLD		\$ 4,865.00	
	SUB TOTAL SPARE PARTS		\$ 11,888.00	\$ 19,646.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	19,646.32
65	TURBOCHARGER GASKET		\$ 14.00	
66	GASKET CONNECTOR TUBE	2	\$ 26.00	
67	CONVERTER AND PIPE GASKET		\$ 19.00	
68	CONVERTER AND PIPE CLAMP		\$ 47.00	
69	ENGINE COMPARTMENT COVER		\$ 103.00	
70	VENT HOSE		\$ 78.00	
71	NOISE INSULATION		\$ 239.00	\$ 191.20
72	NOISE INSULATION FIXING PARTS		\$ 101.00	
73	STEERING WHEEL AIR BAG UNIT		\$ 3,141.00	\$ 2,512.80
74	AIRBAG UNIT		\$ 4,238.00	\$ 3,390.40
75	HEAD AIRBAG UNIT - LH / RH	2	\$ 3,416.00	\$ 2,732.80
76	KNEE AIRBAG UNIT		\$ 1,708.00	\$ 1,366.40
77	AIRBAG CONTROL UNIT		\$ 1,606.00	\$ 1,284.80
78	AIRBAG CRASH SENSOR	3	\$ 1,145.00	\$ 915.60
79	STEERING WHEEL AIR BAG UNIT		\$ 2,169.00	\$ 1,735.20
80	DASHBOARD WITH AIR DUCT		\$ 3,887.00	\$ 3,109.60
81	AIR VENT - CENTRE		\$ 138.00	
82	LOUDSPEAKER COVER		\$ 86.00	
83	DASHBOARD LOWER PANEL UNDERTRAY - RH		\$ 413.00	\$ 330.40
84	MOULDED HEADLINER		\$ 1,613.00	\$ 1,290.40
85	A-PILLAR TRIM - LF		\$ 147.00	\$ 117.20
86	A-PILLAR TRIM - RH UPPER		\$ 147.00	\$ 117.20
87	B-PILLAR TRIM - LH RH UPPER	2	\$ 396.00	
88	C-PILLAR TRIM - LH / RH UPPER	2	\$ 276.00	
89	D-PILLAR TRIM - LH / RH UPPER	2	\$ 212.00	
	SUB TOTAL SPARE PARTS	:	\$ 25,365.00	\$ 38,740.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
			\$ 38,740.32
90	FOLDING GRAB HANDLE - LH FRONT	2 \$ 258.00	
91	FOLDING GRAB HANDLE - LH / RH REAR	2 \$ 258.00	
92	SEAT BELT - LH / RH	2 \$ 2,010.00	\$ 1,608.00
93	SEAT BELT HEIGHT ADJUSTER	2 \$ 361.00	\$ 144.40
94	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
95	<i>Added parts - see attached</i>	\$ 7,909.00	\$ 6,174.56
96	SUNDRIES	\$ 800.00	\$ 92.16
TOTAL SPARE PARTS CHARGES		: \$ 72,510.00	\$ 46,799.44
TOTAL LABOUR CHARGES		: \$ 39,744.00	\$ 13,204.00
GRAND TOTAL		: \$ 112,254.00	\$ 60,003.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0975/2019/NS 28-Aug-19 Glory Tan 1 of 1 SMJ 6962 C Audi A3 Sedan 1.4 TFSI CO
Quantity	Description	Unit Price	Amount
Parts			
1	Sign "Caution" sticker	\$ 13.00	\$ 9.76 (A)
2	Air cond sticker	\$ 7.00	\$ 5.12 (A)
3	Wheel housing liner LHS	\$ 158.00	\$ 126.00 (A)
4	Wheel housing liner RHS	\$ 158.00	\$ 126.00 (A)
5	Radiator seal RHS outer	\$ 8.00	\$ 5.68 (A)
6	External temperature sensor	\$ 54.00	\$ 42.96 (A)
7	Cover for bonnet lock	\$ 9.00	\$ 7.12 (A)
8	Bonnet catch hook	\$ 58.00	\$ 45.76 (A)
9	High lubricity engine oil	\$ 270.00	\$ 215.60 (A)
10	oil filter	\$ 20.00	\$ 15.44 (A)
11	Mechatronic with software	\$ 3,690.00	\$ 2,952.00 (A)
12	Transmission fluid	\$ 120.00	\$ 96.00 (A)
13	Coolant pump	\$ 561.00	\$ 448.80 (A)
14	Intake connection	\$ 597.00	\$ 429.20 (A)
15	Throttle valve adapter	\$ 1,067.00	\$ 853.60 (A)
16	Charged air cooler	\$ 663.00	\$ 530.40 (A)
17	Coolant hose with quick release coupling	\$ 218.00	\$ 174.40 (A)
18	Cover for crankcase housing	\$ 13.00	\$ 10.32 (A)
19	Coolant hose with quick release coupling	\$ 124.00	
20	Oil separator	\$ 101.00	\$ 80.40 (A)
		\$ 7,909.00	\$ 6,174.56
Labours			
1	To renew mechatronic with software. To carry out gearbox adaptation.	S/N \$ 980.00	\$ 980.00 (A)
2	To renew intake manifold and charged air cooler assy.	S/N \$ 980.00	\$ 980.00 (A)
			\$ 1,960.00
		LABOUR TOTAL	\$ 1,960.00
		PART TOTAL	\$ 7,909.00
		GRAND TOTAL	\$ 9,869.00
			\$ 8,134.56

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant