

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0975/2019/NS
Date : 16-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR MOHAMAD IDRIS BIN ASMURI
Address : BLK 273B PUNGGOL PLACE
#07-864
Singapore 822273
Telephone : HP +65 96312500
Type of Claim : Own Damage Claims
Policy No. : 1900058142
Vehicle No : **SMJ 6962 C**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Mar-19
Engine No : CZE 846955
Chassis No : WAUZZZ8V9K1009145
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Aug-19
Place of Accident : BLK 274B PUNGGOL PLACE SERVICE RD

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SM1 6962 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X nn
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00	photo? X nn
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	//
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	//
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain airbags and knee airbag.	S/N \$ 3,600.00	✓
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs	S/N \$ 2,800.00	? photo X nn
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00	? photo X nn
SUB TOTAL LABOUR CHARGES		: \$ 11,440.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6962 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To renew exhaust manifold turbo charger and other engine components.	S/N \$ 980.00	? x nn
9	To place vehicle on car o-liner.	S/N \$ 1,800.00	? photo x nn
	To dismantle and renew front bumper, bonnet and both headlights. Align both front chasis frames to specification of origin. To repair both front fenders. Renew front lock carrier and align to position. Re-organise front crash management components. reinstall all parts removed.	3500. / \$ 7,000.00	
10		2200. /	
11	To respray front bumper, bonnet, both front fenders and engine compartment.	\$ 4,500.00	
12	to carry out wheel alignment.	S/N \$ 240.00	? x nn
13	To carry out diagnostic checks.	S/N \$ 384.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 26,344.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SM1 6962 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
1	FRONT BUMPER	S	1,830.00	de / 1464
2	BUMPER FIXING PARTS	S	170.00	? X nn
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 S	70.00	LH? , RH - de - 55.04
4	FRONT BUMPER GRILLE - CENTRE	S	146.00	de / 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	S	488.00	nn / 390 nn
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	1 X S	540.00	LH - de - , RH 2 216
7	FRONT BUMPER COVER TRIM - LH / RH	2 S	296.00	? X nn
8	WHEEL HOUSING LINER ADAPTER - LH / RH	2 S	68.00	? X nn
9	RADIATOR GRILLE	S	1,301.00	one / 1040
10	RADIATOR GRILLE CLOSING ELEMENT	S	174.00	de / 138.80 nn
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	1 X S	342.00	LH - de - , RH - ? X 136.40
12	FRONT BUMPER IMPACT BAR	S	660.00	bt / 579.60
13	FRONT BUMPER FOAM FILLER PIECE	S	172.00	de / 139.60
14	FRONT BUMPER COVER	S	111.00	de / 88.80
15	SIGNAL HORN - LH HIGH TONE	S	182.00	? X nn
16	SIGNAL HORN - RH LOW TONE	S	182.00	? X nn
17	BONNET	S	2,898.00	bt / 2318.40
18	BONNET ATTACHMENT PARTS	S	149.00	? X nn
19	BONNET LID HINGE - LH / RH - photo	2 S	88.48	112.00 bt / ? send photo to Adnan
20	GAS FILLED STRUT	S	109.00	? X nn
SUB TOTAL SPARE PARTS			: \$ 10,000.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 6962 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
21	BONNET CATCH HOOK	\$	81.00	66-64.72
22	BONNET STRIKER - LH / RH	2 \$	200.00	66-159.04
23	BONNET EDGE PROTECTION	NEC \$	25.00	at-19.92
24	BONNET HINGE COVER - LH / RH	2 \$	74.00	X nn
25	BONNET LID LOCK	2 \$	367.00	66-293.60
26	LID LOCK SWITCH CONNECTOR HOUSING	\$	12.00	? X nn
27	BONNET BOWDEN CABLE - CENTRE	\$	53.00	? at-41.68
28	LID LOCK CABLE	\$	67.00	? X
29	WATER BOX ADAPTER SEAL - LH / RH	2 \$	24.00	? X } nn
30	WATER BOX SEAL - LH / RH	2 \$	24.00	? X }
31	BONNET SOUND ABSORBER	\$	201.00	de-160.80
32	PLENUM CHAMBER COVER	\$	164.00	? X } nn
33	PLENUM CHAMBER TOP COVER	\$	15.00	? X }
34	LED HEADLIGHT - LH / RH	2 \$	10,058.00	cm-8046.40
35	HEADLIGHT POWER MODULE	\$	693.00	? X }
36	LIGHT SYSTEM CONTROL UNIT	\$	508.00	? X }
37	LED HEAT SINK - RH	\$	666.00	? X } nn
38	HEADLIGHT HOSE - LH / RH	2 \$	72.00	? X }
39	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH / R	2 \$	256.00	? X }
40	LIFT CYLINDER HOSE	\$	61.00	? at-48.16
SUB TOTAL SPARE PARTS		:	\$ 13,621.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMI 6962 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
41	COOLANT RADIATOR LOCK CARRIER MOUNTING	S	663.00	cm ✓ 530.40
42	A/C CONDENSER - photo ✓	S	503.00	bl ✓ 402
43	REFRIGERANT LINE - COMPRESSOR TO CONDENSER	S	461.00	? x nn
44	REFRIGERANT LINE - CONDENSER TO CUT-OFF POINT	S	601.00	? x nn
45	REFRIGERANT LINE - COMPRESSOR TO CUT-OFF POINT	S	461.00	? bl ✓ 368.80
46	COOLANT PIPE	S	461.00	? x nn
47	RADIATOR - photo ✓	S	878.00	bl ✓ 702.40
48	ADDITIONAL RADIATOR - photo ✓	S	837.00	bl ✓ 669.60
49	RADIATOR BUSH - LOWER	2 S	18.00	dy ✓ 14.24
50	RADIATOR BRACKET	2 S	77.00	dy ✓ 61.28
51	COOLANT	4 S	165.00	cm ✓ 131.84
52	RADIATOR FAN - photo ✓	S	1,046.00	? cm ✓ 836.80
53	RADIATOR AIR GUIDE - LH / RH	2 S	44.00	? cm ✓ 34.24
54	RADIATOR AIR GUIDE - UPPER CENTRE	2 S	11.00	? de ✓ 8.32
55	RADIATOR HOSE	S	218.00	? x nn
56	AIR INTAKE AIR GUIDE	S	53.00	cm ✓ 41.84
57	AIR INTAKE COVER	S	27.00	cm ✓ 21.36
58	AIR INTAKE AIR GUIDE	S	19.00	de ✓ 14.48
59	AIR INTAKE WATER DRAINAGE HOSE	S	31.00	de ✓ 24.48
60	AIR INTAKE AIR GUIDE	S	32.00	? cm ✓ 25.20
61	AIR INTAKE AIR FILTER	S	259.00	? cm ✓ 207.20
62	AIR INTAKE AIR DUCT	S	45.00	as ✓ x
63	AIR INTAKE MANIFOLD	S	113.00	cm ✓ x
64	EXHAUST MANIFOLD	S	4,865.00	? x
SUB TOTAL SPARE PARTS			S 11,888.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SM1 6962 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
65	TURBOCHARGER GASKET	\$ 14.00	? X
66	GASKET CONNECTOR TUBE	2 \$ 26.00	? X
67	CONVERTER AND PIPE GASKET	\$ 19.00	? X
68	CONVERTER AND PIPE CLAMP	\$ 47.00	? X
69	ENGINE COMPARTMENT COVER	\$ 103.00	? X
70	VENT HOSE	\$ 78.00	? X
71	NOISE INSULATION	\$ 239.00	? con 191.20
72	NOISE INSULATION FIXING PARTS	\$ 101.00	? X n
73	STEERING WHEEL AIR BAG UNIT	\$ 3,141.00	act ✓ 2592.80
74	AIRBAG UNIT	\$ 4,238.00	act ✓ 3390.40
75	HEAD AIRBAG UNIT - LH / RH	2 \$ 3,416.00	act ✓ 2732.80
76	KNEE AIRBAG UNIT	\$ 1,708.00	act ✓ 1366.40
77	AIRBAG CONTROL UNIT	\$ 1,606.00	act ✓ 1284.80
78	AIRBAG CRASH SENSOR	\$ 1,145.00	act ✓ 915.60
79	STEERING WHEEL AIR BAG UNIT	3 \$ 2,169.00	act ✓ 1735.20 ✓ bt
80	DASHBOARD WITH AIR DUCT	\$ 3,887.00	de ✓ 3109.60
81	AIR VENT - CENTRE	\$ 138.00	? X n
82	LOUDSPEAKER COVER	\$ 86.00	? X n
83	DASHBOARD LOWER PANEL UNDERTRAY - RH	\$ 413.00	de ✓ 330.40
84	MOULDED HEADLINER	\$ 1,613.00	de ✓ 1290.40
85	A-PILLAR TRIM - LF	\$ 147.00	? de 117.20 ✓
86	A-PILLAR TRIM - RH UPPER	\$ 147.00	? de 117.20 ✓
87	B-PILLAR TRIM - LH RH UPPER	2 \$ 396.00	? X
88	C-PILLAR TRIM - LH / RH UPPER	2 \$ 276.00	? X
89	D-PILLAR TRIM - LH / RH UPPER	2 \$ 212.00	? X
	SUB TOTAL SPARE PARTS	\$ 25,365.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMJ 6962 C

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
90	FOLDING GRAB HANDLE - LH FRONT	2	\$ 258.00	? X 47
91	FOLDING GRAB HANDLE - LH / RH REAR	2	\$ 258.00	? X 47
92	SEAT BELT - LH / RH	2	\$ 2,010.00	? 1608 ✓ act ✓
93	SEAT BELT HEIGHT ADJUSTER	2	\$ 361.00	? 144.40 act ✓
94	FRONT NO PLATE	S/N	\$ 40.00	69 ✓ net ✓
95	SUNDRIES		\$ 800.00	? 926 ✓
TOTAL SPARE PARTS CHARGES		:	\$ 64,601.00	
TOTAL LABOUR CHARGES		:	\$ 37,784.00	26344
GRAND TOTAL		:	\$ 102,385.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Rasul
04/09/19

112619-56

99203-56

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97495744
20/8/19 @ 345 pm
Not Authorise
Ex: to be advise
Resurvey before paint
surellauto.com
18 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0975/2019/NS 28-Aug-19 Glory Tan 1 of 1 SMJ 6962 C Audi A3 Sedan 1.4 TFSI CO
Quantity	Description	Unit Price	Amount
Parts			
1	Sign "Caution" sticker <i>ae</i>	\$ 13.00	9.76
2	Air cond sticker <i>ae</i>	\$ 7.00	5.12
3	Wheel housing liner LHS <i>con</i>	\$ 158.00	126
4	Wheel housing liner RHS <i>ex</i>	\$ 158.00	126
5	Radiator seal RHS outer <i>ae</i>	\$ 8.00	5.68
6	External temperature sensor <i>de</i>	\$ 54.00	42.96
7	Cover for bonnet lock <i>bt</i>	\$ 9.00	7.12
8	Bonnet catch hook <i>bt</i>	\$ 58.00	45.76
9	High lubricity engine oil <i>ae</i>	\$ 270.00	215.60
10	oil filter <i>bt</i>	\$ 20.00	15.44
11	Mechatronic with software <i>bt</i>	\$ 3,690.00	2952
12	Transmission fluid <i>ae</i>	\$ 120.00	96
13	Coolant pump <i>con</i>	\$ 561.00	4485.80
14	Intake connection <i>con</i>	\$ 597.00	479.20
15	Throttle valve adapter <i>at</i>	\$ 1,067.00	853.60
16	Charged air cooler <i>bt</i>	\$ 663.00	530.40
17	Coolant hose with quick release coupling <i>at</i>	\$ 218.00	174.40
18	Cover for crankcase housing <i>con</i>	\$ 13.00	10.32
19	Coolant hose with quick release coupling?	\$ 124.00	x n n
20	Oil separator <i>ae</i>	\$ 101.00	80.40
		\$ 7,909.00	
Labours			
1	To renew mechatronic with software. To carry out gearbox adaptation.	S/N \$ 980.00	//
2	To renew intake manifold and charged air cooler assy.	S/N \$ 980.00	//
LABOUR TOTAL		\$ 1,960.00	
PART TOTAL		\$ 7,909.00	
GRAND TOTAL		\$ 9,869.00	

Resume
04/07/19

For Premium Automobiles Pte Ltd

Authorised Signature