

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE
 SECTOR C #101/103/105/107/109
 SINGAPORE 575636
 Tel: +65 6552 5588 Fax: +65 6552 7750
 Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ9789**Quotation Date : **2019-08-19**

Vehicle Reg No : SFF6818R
 Name : NA

Make & Model : B.M.W. - 730LI AT ABS D/AB 2WD
 : 4DR NAV HID SR
 Chassis No : WBAKB22030C951364
 Mileage : 62553 KM
 Officer-In-Charge : CHRIS
 Page : 1 of 1

No	Description	Unit Price	Qty	Amount
1	RH DOOR INNER RUBBER SEAL - <i>4 m/c</i>	310.00	1.00	<i>225.1</i> 310.00
2	RH DOOR OUTER RUBBER SEAL - <i>4 m/c</i>	180.00	1.00	<i>/</i> 180.00
3	RH FENDER TOP RUBBER SEAL - <i>1 m/c</i>	185.00	1.00	<i>107.75</i> 185.00
4	RH FENDER CLIPS - <i>1 m/c</i>	8.00	10.00	<i>30</i> 80.00
5	WIPER WASHER TANK - <i>4 m/c</i>	355.00	1.00	<i>133.4</i> 355.00
6	WIPER WASHER TANK NECK - <i>4 m/c</i>	145.00	1.00	<i>81.8</i> 145.00

26/8/19
Em Ang

758.05
5%: 220.15

Sub-Total : 1,255.00
 Add GST 7% : 87.85
Estimated Total Amt (SGD) : 1,342.85

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed.

CUSTOMER'S AUTHORISATION I agree to this quotation and hereby authorize to proceed with the above listed repairs. CUSTOMER'S SIGNATURE _____ (& Co's Stamp, WHERE NECESSARY)
--

Veron Chen (LKKAuto)

From: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Sent: Wednesday, 9 October 2019 8:49 AM
To: Guo Qiang (LKKAuto)
Subject: RE: check part price

Good morning Guo Qiang,

SFF6818R

1. Front Door RH inner rubber- 225.10
2. Front Door RH outer rubber -173.95
3. Front Fender RH Top rubber – 107.75
4. Front Fender RH Top Garnish Clips -0.50 X 6pcs
5. Wiper Washer Tank -133.40
6. Wiper Washer Tank Neck – 81.80

Thank you.

Warm regards

Inthiran
Motor Claim Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 81214600 | Fax (+65)64794601
Inthiran.thurasamy@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Guo Qiang (LKKAuto) [mailto:GuoQiang@lkkauto.com]
Sent: Monday, 30 September, 2019 11:22 AM
To: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Subject: check part price

Dear Inthiran,

SFFG818R

1. Front Door RH inner rubber
2. Front Door RH outer rubber
3. Front Fender RH Top rubber
4. Front Fender RH Top Garnish Clips
5. Wiper Washer Tank
6. Wiper Washer Tank Neck

Thanks for your help.

Regards,
Guo Qiang

Veron Chen (LKKAuto)


From: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Sent: Friday, 8 November 2019 1:38 PM
To: Veron Chen (LKKAuto)
Subject: RE: CHECK PARTS PRICES-SFF 6818R

Dear Veron,

Below is the part price :

- 1) Front RH fender side signal lamp -135.80
- 2) Front RH fender side signal lamp protector -72.50
- 3) Front RH door upper hinge – 58.90
- 4) Front RH door lower hinge – 53.65
- 5) Front RH door chrome protector – 173.95 (outer w/stripe with chrome moulding) (Item no.2 on diagram)
- 6) Front RH door window upper chrome ???
- 7) Front RH door window lower chrome ???
- 8) Front RH knuckle – 662.70
- 9) RH lower side skirt -531.20
- 10) Front RH wheel banana leaf – 140.55
- 11) Front RH door side mirror glass -795.95

***Please see below door for door attachments



Thank you.

Warm regards

Inthiran

Motor Claim Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 81214600 | Fax (+65)64794601
Inthiran.thurasamy@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 7 November, 2019 3:55 PM
To: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Subject: RE: CHECK PARTS PRICES-SFF 6818R

Dear Inthiran,

Kindly assist to check on the parts prices.

BMW 730i-2012, 2996 cc
CHASSIS NO- WBAKB22030C951364

- 1) Front RH fender side signal lamp -135.80
- 2) Front RH fender side signal lamp protector -72.50
- 3) Front RH door upper hinge – 58.90
- 4) Front RH door lower hinge – 53.65
- 5) Front RH door chrome protector – 173.95 (outer w/stripe with chrome moulding)
- 6) Front RH door window upper chrome ???
- 7) Front RH door window lower chrome ???
- 8) Front RH knuckle – 662.70
- 9) RH lower side skirt -531.20
- 10) Front RH wheel banana leaf – 140.55
- 11) Front RH door side mirror glass -795.95

Many thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

From: Veron Chen (LKKAuto)
Sent: Tuesday, 22 October 2019 5:33 PM
To: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Subject: RE: CHECK PARTS PRICES-SFF 6818R

Dear Inthiran,

Kindly assist to check on the parts prices.

BMW 730i-2012, 2996 cc
CHASSIS NO- WBAKB22030C951364

- 1) Front RH fender side signal lamp
- 2) Front RH fender side signal lamp protector
- 3) Front RH door upper hinge
- 4) Front RH door lower hinge
- 5) Front RH door chrome protector
- 6) Front RH door window upper chrome
- 7) Front RH door window lower chrome
- 8) Front RH knuckle
- 9) RH lower side skirt
- 10) Front RH wheel banana leaf
- 11) Front RH door side mirror glass

Many thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Sent: Wednesday, 9 October 2019 8:49 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Subject: RE: check part price

Good morning Guo Qiang,

SFF6818R

1. Front Door RH inner rubber- 225.10
2. Front Door RH outer rubber -173.95
3. Front Fender RH Top rubber – 107.75
4. Front Fender RH Top Garnish Clips -0.50 X 6pcs
5. Wiper Washer Tank -133.40
6. Wiper Washer Tank Neck – 81.80

Thank you.

Warm regards

Inthiran

Motor Claim Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 81214600 | Fax (+65)64794601

Inthiran.thurasamy@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Guo Qiang (LKKAUTO) [<mailto:GuoQiang@lkkauto.com>]

Sent: Monday, 30 September, 2019 11:22 AM

To: Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>

Subject: check part price

Dear Inthiran,

SFF6818R

1. Front Door RH inner rubber
2. Front Door RH outer rubber
3. Front Fender RH Top rubber
4. Front Fender RH Top Garnish Clips
5. Wiper Washer Tank
6. Wiper Washer Tank Neck

Thanks for your help.

Regards,
Guo Qiang

From:

Sent: Thursday, 14 November 2019 5:28 PM

To: Francis Lim <francis@bcc.sg>

Cc:

Subject: RE: PARTS QUOTATION

Hi Francis,

Please refer below.

1. Front RH Fender Side Signal Lamp	135.80 + 72.50	Out of stock	
2. Front RH Door Upper Hinge	58.90	Out of stock	
3. Front RH Door Lower Hinge	58.90	Out of stock	
4. Front RH Door Chrome Protector	173.95	Out of stock	
5. Front RH Knuckle	662.70	Out of stock	
6. RH Lower Side Skirt	531.20	Out of stock	
7. Front RH Wheel Arc Shield	140.55 + 140.55	Out of stock	
8. Front RH Door Side Mirror Assembly	1179.50 + 118.30 + 795.95	Out of stock	

9. RH Door Inner Rubber Seal	226.25	Out of stock	
10. RH Door Outer Rubber Seal	55.45 + 152.40 + 94.20	Out of stock	
11. RH Fender Top Rubber Seal	105.60	Stock available	Limited
12. Wiper Washer Tank	134.10	Stock available	Limited
13. Wiper Washer Tank Neck	82.20	Out of stock	

Currently most of items are out of stock, the order lead time is estimate 2-3 weeks from BMW Germany. Let me know if got any queries, thank you.

Thanks & Regards,

Performance Motors Limited
280 Kampong Arang Road – East Coast Centre
Singapore 438180

THE 8
GRAN COUPÉ

Find out more

BMW Group Singapore



Please consider the environment before printing this e-mail.

Veron Chen (LKKAuto)

From: Christina Lim <christina@bcc.sg>
Sent: Thursday, 12 March 2020 10:26 AM
To: Veron Chen (LKKAuto); Guo Qiang (LKKAuto); 'Francis Lim'
Subject: RE: SFF6818R-DOA: 17/8/2019

Hi Veron,

We confirmed COR \$14,677.28 before GST.
Shall submit our claims document direct to MSIG.

Best Regards

Christina LIM


POINT S SINGAPORE (Master Franchise)

BCC Automotive Pte Ltd (HQ)

Blk 1 Sin Ming Industrial Estate Sector C, #01-101/103/105 S575636

T : 65 6552 5588 F : 65 6552 7750

www.bcc.sg



50 Old Toh Tuck Road, S(597657), Cynergy Gas Station T: 6468 5588
13 Kaki Bukit Road 4 #01-03, Bartley Biz Centre, S(417807) T: 6702 5588
255 Paya Lebar Road S(409037), SHELL AutoServ T: 96558475
143 Bukit Timah Road S(229843), SHELL AutoServ T: 9773 3228

Operating Hours : Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm) | Closed on Sun and Public Holidays

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: 12 March, 2020 9:46 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Francis Lim <francis@bcc.sg>; Christina Lim <christina@bcc.sg>
Subject: RE: SFF6818R-DOA: 17/8/2019

Dear Christina,

WITHOUT PREJUDICE

Re-finalise amount \$14,677.28 @ 8 working days.

Kindly confirm

Best Regards,
Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Sent: Tuesday, 10 March 2020 11:16 AM

To: Francis Lim <francis@bcc.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: christina@bcc.sg

Subject: RE: SFF6818R

Hi Francis,

I will submit report COR \$14250.35 before GST @ 8 working days.

Regards,
Guo Qiang

From: Francis Lim [mailto:francis@bcc.sg]

Sent: Friday, 6 March, 2020 11:42 AM

To: Veron Chen (LKKAuto); Guo Qiang (LKKAuto)

Cc: christina@bcc.sg

Subject: RE: SFF6818R

Hi Veron/Guo Qiang,

We maintain on our pricing.

But as a gesture of goodwill, we will provide a further 5% discount.

Kindly let us have your confirmation soonest.

Thank you.

Best regards,

Francis LIM

Managing Director


POINT S SINGAPORE (Master Franchise)

BCC Automotive Pte Ltd (HQ)

Blk 1 Sin Ming Industrial Estate Sector C, #01-101/103/105 S575636

T : 65 6552 5588 F : 65 6552 7750

www.bcc.sg



50 Old Toh Tuck Road, S(597657), Cynergy Gas Station T: 6468 5588

13 Kaki Bukit Road 4 #01-03, Bartley Biz Centre, S(417807) T: 6702 5588

255 Paya Lebar Road S(409037), SHELL AutoServ T: 96558475
143 Bukit Timah Road S(229843), SHELL AutoServ T: 9773 3228

Operating Hours : Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm) | Closed on Sun and Public Holidays

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: 12 November, 2019 2:28 PM
To: christina@bcc.sg; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: 'Francis Lim' <francis@bcc.sg>
Subject: RE: SFF6818R

Dear Christina,

WITHOUT PREJUDICE

Below is the part price :

- 1) Front RH fender side signal lamp -135.80
- 2) Front RH fender side signal lamp protector -72.50
- 3) Front RH door upper hinge – 58.90
- 4) Front RH door lower hinge – 53.65
- 5) Front RH door chrome protector – 173.95 (outer w/stripe with chrome moulding) (Item no.2 on diagram)
- 6) Front RH door window upper chrome ???
- 7) Front RH door window lower chrome ???
- 8) Front RH knuckle – 662.70
- 9) RH lower side skirt -531.20
- 10) Front RH wheel banana leaf – 140.55
- 11) Front RH door side mirror glass -795.95

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Christina Lim <christina@bcc.sg>
Sent: Monday, 4 November 2019 9:07 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: 'Francis Lim' <francis@bcc.sg>
Subject: FW: SFF6818R

Hi Guo Qiang,

May I know when can we finalise?

Thanks
Christina Lim | +65 6552 5588

BCC Automotive Pte Ltd | www.bcc.sg
Blk 1 Sin Ming Industrial Estate
Sector C #01-101/103/105/107/109
Singapore 575636

Tel : +65 6552 5588 (5 lines) | Fax : +65 6552 7750 Operating Hours : Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm)
| Closed on Sun and Public Holidays

-----Original Message-----

From: Christina Lim [mailto:christina@bcc.sg]
Sent: 17 September, 2019 9:32 AM
To: 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>
Subject: FW: SFF6818R

Hi Guo Qiang,

Please help to finalise.

Thanks
Christina Lim | +65 6552 5588

BCC Automotive Pte Ltd | www.bcc.sg
Blk 1 Sin Ming Industrial Estate
Sector C #01-101/103/105/107/109
Singapore 575636
Tel : +65 6552 5588 (5 lines) | Fax : +65 6552 7750 Operating Hours :
Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm) | Closed on Sun and Public Holidays

-----Original Message-----

From: Christina Lim [mailto:christina@bcc.sg]
Sent: 04 September, 2019 2:42 PM
To: 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>
Subject: FW: SFF6818R

Hi Guo Qiang,

Please see photographs attached taken after repair.

Christina Lim | +65 6552 5588

BCC Automotive Pte Ltd | www.bcc.sg
Blk 1 Sin Ming Industrial Estate
Sector C #01-101/103/105/107/109
Singapore 575636
Tel : +65 6552 5588 (5 lines) | Fax : +65 6552 7750 Operating Hours :
Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm) | Closed on Sun and Public Holidays

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Aug 2019 18:44		20 Aug 2019 16:39 Edit Adj Rpt	S\$14,677.28 Edit Estimates	S\$14,677.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GAN KEAT NENG , ID: S8032746C								
Main Claimant:	TAN CHENG LYE , ID: S7514771F								
Vehicle Reg. No.:	SFF6818R	Date of Loss:	17/08/2019 14:00 - :59 [89 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603344	Policy/Cover Note No.:	A29081596AVW (Comprehensive) Coverage: 30/04/2019 - 29/04/2020						
Vehicle Reg. No. (Insured):	SLZ3716U	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101, 575636 Sin Ming - Tel: 6552 5588								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/09/2019]								
Driver/Custodian (Insured):	SAMANTHA CHUA XIN YIN (/ Female) , NRIC: S8031439F Email:								
Adj Asg. Remarks:	on WP. Liab: Dispute. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Christina Lim @ 6552 5588. Please survey vehicle by today.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFF6818R (603344)
[SLZ3716U]**

TP

TAN CHENG LYE

Aug 17 2019 2:00PM

[GAN KEAT NENG]

BCC Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/08/19 15:48	Adjuster Immediate Advice	1	Load HTM <input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
2	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
3	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
4	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
5	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
6	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
7	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
8	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
9	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
10	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
11	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
12	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
13	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
14	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
15	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
16	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
17	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
18	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
19	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
20	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
21	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
22	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
23	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
24	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
25	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
26	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
27	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
28	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
29	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
30	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
31	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>
32	27/09/19 10:05	General View	1	Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
34	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
35	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
36	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
37	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
38	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
39	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
40	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
41	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
42	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
43	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
44	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
45	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
46	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
47	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
48	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
49	27/09/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
50	27/09/19 10:05	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
51	27/09/19 10:05	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
52	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	27/09/19 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	27/09/19 10:06	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
60	27/09/19 10:06	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
61	27/09/19 10:06	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
62	27/09/19 10:06	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
63	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
64	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
65	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
66	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
67	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
68	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
69	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
70	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
71	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
72	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
73	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
74	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
75	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
76	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
77	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
78	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
79	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
80	27/09/19 10:07	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
82	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
83	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
84	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
85	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
86	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
87	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
88	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
89	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
90	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
91	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
92	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
93	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
94	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
95	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
96	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
97	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
98	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
99	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
100	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
101	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
102	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
103	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
104	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
105	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
106	27/09/19 10:07	Replacement Part Photo		<input checked="" type="checkbox"/>
107	27/09/19 10:07	After Repair Photo		<input checked="" type="checkbox"/>
108	27/09/19 10:07	After Repair Photo		<input checked="" type="checkbox"/>
109	27/09/19 10:07	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/08/19 18:47	OI SLZ3716U GIA REPORT		<input type="checkbox"/>
2	19/08/19 18:47	TP SFF6818R GIA & POLICE REPORT		<input type="checkbox"/>
3	19/08/19 18:47	PRI from BCC Automotive Pte Ltd		<input type="checkbox"/>
4	20/08/19 14:31	Agree on SJE		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014556/GVF3S2
Date: 13/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29081596AVW
Claimant Vehicle No :	SFF6818R	Insured Vehicle No :	SLZ3716U
Date of Loss:	17/08/2019	Nature of Claim:	TP
		Claim No:	603344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF6818R	Engine No:	11207951N52B30AF
Make & Model:	BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)	Chassis No:	WBAKB22030C951364
Reg. Date:	05/03/2012 (Man. Year: 2011)	Odometer:	62556 km
Colour:	White		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R20	Rear Tyre Size:	245/40 R20
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,285.00	12,332.28	4,952.72	28.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,135.00	2,345.00	790.00	25.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,420.00	14,677.28	5,742.72	28.12
+ GST 7.00/7.00% (S\$)	1,429.40	1,027.41	401.99	28.12
Nett Amount (S\$)	21,849.40	15,704.69	6,144.71	28.12

INSPECTION

Date of Assignment:	20/08/2019		
Date Inspected:	21/08/2019	Inspected At:	BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101 Singapore 575636
Estimated Period of Repair:	8.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2020)

Parts: 143 BMW 730LI 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFF6818R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	2,218.00 F	*2,218.00 FL
2	1		*FRONT RH DOOR HANDLE	Cut	595.00 F	*595.00 FL
3	1		*FRONT RIGHT SIDE MIRROR ASSY	Cut	1,174.00 F	*1,174.00 FL
4	1		*FRONT RH FENDER SIDE SIGNAL LAMP	Missing	158.00 F	*72.95 FL
5	1		*FRONT RH FENDER SIDE SIGNAL LAMP PROTECTOR	Missing	102.00 F	*72.95 FL
6	1		*FRONT RH DOOR UPPER HINGE	Bent	170.00 F	*58.00 FL
7	1		*FRONT RH DOOR LOWER HINGE	Bent	170.00 F	*58.00 FL
8	1		*FRONT RH DOOR LOCK W/MOTOR	Not Necessary	705.00 F	*- FL
9	1		*FRONT RH DOOR CHROME PROTECTOR	Missing	299.00 F	*173.95 FL
10	1		*FRONT RH DOOR WINDOW UPPER CHROME	Deformed	376.00 F	*376.00 FL
11	1		*FRONT RH DOOR WINDOW LOWER CHROME	Deformed	376.00 F	*376.00 FL
12	1		*FRONT BUMPER	Repair	1,570.00 F	*- FL
13	1		*FRONT BUMPER RH RETAINER	No such part	97.00 F	*- FL
14	1		*FRONT RH LOWER ARM	Bent	618.00 F	*618.00 FL
15	1		*FRONT RH KNUCKLE	Bent	897.00 F	*659.50 FL
16	1		*FRONT WHEEL BEARING	Necessary	470.00 F	*470.00 FL
17	1		*TRUST ARM	Bent	520.00 F	*520.00 FL
18	1		*RH LOWER SIDE SKIRT	Cracked	727.00 F	*528.50 FL
19	1		*FRONT RH WHEEL BANANA LEAF	Torn	208.00 F	*139.85 FL
20	1		*FRONT RH TYRE RIM	Cut	500.00 F	*500.00 FL
21	1		*FRONT RH SHOCK ABSORBER	Bent	1,386.00 F	*1,386.00 FL
22	1		*FRONT RH UPPER ARM	Bent	567.00 F	*567.00 FL
23	1		*FRONT FENDER RH	Buckled	1,237.00 F	*1,237.00 FL
24	1		*FRONT RH DOOR SIDE MIRROR GLASS	Missing	890.00 F	*422.60 FL
25	1		*RH DOOR INNER RUBBER SEAL	Necessary	310.00 F	*225.10 FL
26	1		*RH DOOR OUTER RUBBER SEAL	Necessary	180.00 F	*180.00 FL
27	1		*RH FENDER TOP RUBBER SEAL	Cracked	185.00 F	*107.75 FL
28	10		*RH FENDER CLIPS	Necessary	80.00 F	*30.00 FL
29	1		*WIPER WASHER TANK	Deformed	355.00 F	*133.40 FL
30	1		*WIPER WASHER TANK NECK	Deformed	145.00 F	*81.80 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	17,285.00	12,981.35
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	649.07
Total Parts (S\$)	17,285.00	12,332.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DOOR TRIM BOARD, TRANSFER ALL WIRE HARNESS & ALL MECHANISM PARTS FROM OLD DOOR TO NEW DOOR.	New	250.00	80.00
2	LABOUR TO REPLACE FRONT SHOCK ABSORBER, WHEEL BEARING, & ALL ARM.	New	300.00	250.00
3	TOWING CHARGE.	New	55.00	55.00
4	TO SPRAY PAINT ON THE AFFECTED AREA.	New	1,200.00	1,100.00
5	TO PANEL BEAT THE AFFECTED AREA.	New	1,000.00	700.00
6	DIAGNOSE WHOLE VEHICLE ELECTRICAL FUNCTION.	New	250.00	100.00
7	WHEEL ALIGNMENT.	New	80.00	60.00
Gross Labour Cost (\$\$)			3,135.00	2,345.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >