

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0980/2019/NS
Date : 19-Aug-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured veh no. : PC 4126 P

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : MR CHUA SWEE HEE
Address : BLK 642 PASIR RIS DRIVE 10
#07-36
Singapore 510642
Telephone : 96868474
Type of Claim : Third Party Claims
Policy No. : 1800126073
Vehicle No : **SLC 7327 D**
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : Oct-18
Engine No : CVK 069074
Chassis No : WAUZZZF40JA232991
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Aug-19
Place of Accident : CECIL ROAD NEAR LAMP POST 24/1 JUNCTION

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 7327 D

S/n	Nature of Jobs		Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function	S/N \$	360.00	✓
2	To renew windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspectr for damages.	S/N \$	280.00	X
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical audio equipment.	S/N \$	1,400.00	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbaq etc.	S/N \$	1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	\$	<u>4,040.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 7327 D

S/n	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
6	To dismantle rear bumper, rear lid and rhs rear door. Cut outr and weld rhs rear fender. Renew rhs rear door and rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 6,300.00	4200 .
7	To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,500.00	700X4 = 2800
8	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
9	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,312.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 7327 D

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
1	REAR BUMPER <i>Delnd</i>	\$	2,015.00	✓
2	BUMPER FIXING PARTS <i>men</i>	\$	66.00	✗
3	REAR BUMPER SECURING STRIP ?	NEC \$	203.00	?
4	REAR BUMPER SPOILER <i>men</i>	\$	227.00	✗
5	REAR LIGHT REFLECTOR - RH <i>men</i>	\$	38.00	✗
6	REAR BUMPER GUIDE SECTION - RH ?	\$	41.00	?
7	REAR BUMPER GUIDE SECTION - RH ?	\$	20.00	?
8	REAR FENDER SIDE PANEL <i>Distorted</i>	\$	2,443.00	✓
9	RIVETTED CAP NUT ?	NEC \$	2.00	✓
10	GROMMET <i>He</i>	NEC \$	2.00	✓
11	BLIND RIVET STUD <i>He</i>	NEC \$	9.00	✓
12	REAR WINDOW <i>3 Men</i>	\$	1,049.00	✓
13	SIDE WINDOW- RH	\$	561.00	✓
14	PRIMER <i>na</i>	\$	25.00	✓
15	WHEEL HOUSING LINER - RH <i>men</i>	\$	223.00	✗
16	ALUMINIUM RIM - LH <i>cut</i>	\$	651.00	✓
17	RUBBER VALVE <i>men</i>	\$	13.00	✗
18	DOOR -RH	\$	2,152.00	✗
19	OUTER DOOR SEAL - RH <i>3 Men</i>	NEC \$	185.00	✗
20	BONDING AGENT - RH	NEC \$	45.00	✗
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 9,970.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 7327 D

S/N	Parts Description	Damaged Parts & Prices		REMARKS
			S/Nett	
21	CLEANING SOLUTION	NEC	\$ 65.00	+
22	SEALING STRIP		\$ 15.00	x
23	DOOR CATCH		\$ 109.00	x
24	DOOR ATTACHMENT PARTS		\$ 515.00	x
25	ACRYLIC SEALANT	S/N	\$ 180.00	✓
26	CAVITY WAX	S/N	\$ 140.00	✓
27	STONE CHIP	NS/N	\$ 180.00	✓
28	METAL FILLER POWDER	S/N	\$ 280.00	✓
29	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
30	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
31	SUNDRIES	S/N	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 12,254.00	
TOTAL LABOUR CHARGES			\$ 16,312.00	
GRAND TOTAL			\$ 28,566.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 20/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 days.

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant