

CARSMITH PTE LTD

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807
TEL : 6281 0087 FAX : 6281 0187 Email : sales@mia.com.sg

909/0000
Hex

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower. S068811

Email : motor.survey@axa.com.sg

Tel : 6880 4741 (Hotline)

Fax : 6880 4740 / 6880 4838

ATTN : Motor Claim Department

Your Ref No : SLC7327D

Claim Type : Third Party

Accident Date : 15.08.2019

TP Veh Reg No : PC4126P

Estimate No :

Date :

Policy No :

Veh Reg No : SLC7327D

Make/Model : Audi A4 Sedan 2.0

Chassis No : WAUZZZF40JA232991

Engine No :

Reg Date :

Estimate Repair Cost to Vehicle No : SLC7327D

Description	Quantity	Amount
SLC7327D Audi A4 Sedan 2.0 TFSI 8W		
List Price		
1 Rim, RH <i>cut</i>	1 pc	\$ 800.00 ✓
2 Rear Bumper <i>Del'd.</i>	1 pc	\$ 3,320.00 <i>2015</i>
3 Rear Fender, RH <i>Distorted</i>	1 pc	\$ 2,870.00 <i>2443</i>
4 Rear Fender Spalsh Shield, RH <i>torn</i>	1 pc	\$ 135.80 ✓
5 Liner Rear Wheelhouse, RH <i>new</i>	1 pc	\$ 380.00 <i>x</i>
6 Panel Quarter Wheelhouse Outer, RH <i>Repair</i>	1 pc	\$ 1,360.00 <i>x</i>
7 Panel Quarter Wheelhouse Inner, RH <i>Repair</i>	1 pc	\$ 1,880.00 <i>x</i>
8 Retainer Quarter Panel, RH <i>Repair</i>	1 pc	\$ 98.00 <i>x</i>
9 Rear Fender Inner Trim Clip <i>Hex</i>	1 set	\$ 45.00 <i>30</i>
10 Fender Liner Retainer Clip <i>new</i>	1 set	\$ 50.00 <i>30</i>
11 Lower Control Arms	1 pc	\$ 1,260.00 <i>x</i>
12 Upper Control Arms	1 pc	\$ 1,880.00 <i>x</i>
13 Ball Joint	1 pc	\$ 200.00 <i>x</i>
14 Sway Bar Link	1 pc	\$ 467.00 <i>x</i>
15 Streering Knuckle Spindle	1 pc	\$ 900.60 <i>x</i>
16 Bushing	1 pc	\$ 350.60 <i>x</i>
17 Disk Brake, RH	1 pc	\$ 627.60 <i>x</i>
18 Rear Windscreen <i>moulding. new</i>	180	\$ 16,624.60
19 Rear Windscreen <i>Scratch</i>	600 <i>60(SN)</i>	\$ 831.23
		\$ 15,793.37

Labour		
18 To spray painting on affected area.		\$ 1,800.00 <i>500</i>
19 To spray anti-rust coating on new and affected panels.		\$ 180.00 <i>60</i>
20 To remove and reinstall rear fender. <i>Windscreen</i>		\$ 200.00 <i>120</i>
21 To remove and reinstall rim, RH.		\$ 150.00 <i>50</i>
22 To check and replace rear sensor.		\$ 120.00 <i>60</i>
23 To conduct wheel alignment.		\$ 300.00 <i>80</i>
24 LKK Auto Electricals wiring system		\$ 160.00 <i>30</i>
25 To remove and reinstall undercarriage parts.		\$ 350.00 <i>x</i>
26 To provide labour charges, workshopmanship to dismantle above damaged parts, repair including damaged and weld, re-align body structure and damaged consistent to the accident.		\$ 1800.00 <i>600</i>

- To provide labour charges, workshopmanship to dismantle above damaged parts, repair including damaged and weld, re-align body structure and damaged consistent to the accident.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total : SINGAPORE DOLLAR TWENTY THOUSAND EIGHT HUNDRED FIFTY THREE AND CENTS THIRTY-SEVEN ONLY.

Acknowledged by Repairer

Signature:

Date:

Total

\$ 20,853.37

Total: 692.11

H/S. SSK

06 Days.

SSK