

Accident Photo



Accident Photo



**SINGAPORE
POLICE FORCE**



T20190815/7033

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No: T20190815/7033

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	TAN BEE CHU	ID No.	S7577899F
Related Vehicle	SLS5685Z (Car)	Contact No.	90902537
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	15/08/2019	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	HO KAR FATT	ID No.	S7472782D
Related Vehicle	SLS5685Z (Car)	Contact No.	94304913
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

My car was parked on Lot 62 at 7.00am. The car was being hit by someone which was discovered when I came back around 7.30am.
Notice that there was a CCTV at the corner of Block 16 which was near where I parked my car.

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 1/1

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details
Mr
HO
KAR FATT
523 WOODLANDS DRIVE 14
#09-389
Singapore 730523

Document no.
Document date 16-08-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001710/ 1
Job order date 16-08-2019
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SL5685Z	AM13HZ	28-09-2017	WVWZZZAUZGW564040	Sportsvan 1.4CLBMT 92 TSI D7F	121

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
510807217AMGRU	Cover For Bumper Primed <i>cd</i>	1	pcs.	1,080.14	#1	1,080.14	1,155.75
510805915A 9B9	Retainer For Spoiler Sali <i>?</i>	1	pcs.	170.44	#1	170.44	182.37
510807724D	Support Part <i>?</i>	1	pcs.	30.54	#1	30.54	32.68
	(bumper retainer RHS)						
510807050C	Guide Piece <i>?</i>	1	pcs.	19.18	#1	19.18	20.52
	Bumper bracket RHS						
510821022D	Fender <i>buc</i>	1	pcs.	603.41	#1	603.41	645.65
	(RHS) <i>?</i>						
5G0805970N	Wheelhouse Liner <i>?</i>	1	pcs.	152.98	#1	152.98	163.69
	(upper)						
5G0805912AA	Wheelhouse Liner <i>?</i>	1	pcs.	86.69	#1	86.69	92.76
	(lower)						
518941006C	Twin Halogen Headlamps <i>scr</i>	1	pcs.	655.66	#1	655.66	701.56
	(RHS)						
	LABOUR	5	pcs.	475.00	#1	2,375.00	2,541.25
	Spray Painting	5	pcs.	500.00	#1	2,500.00	2,675.00

Quotation valid till 23-08-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	560.00	7,674.04	7%	578.38	8,234.04	8,810.42
Total	560.00	7,674.04		578.38	8,234.04	8,810.42

Customer

Service Advisor

VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).

RASUL
Hp 90010068
5 days
21/08/19 1025
EXCESS: 500
Revers
Removal before paint

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non binding - Preview

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
HO
KAR FATT
523 WOODLANDS DRIVE 14
#09-389
Singapore 730523

Page 1/1
Document no.
Document date 16-08-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001710/ 1
Job order date 16-08-2019
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SLS5685Z	AM13HZ	28-09-2017	WVWZZZAUZGW564040	Sportsvan 1.4CLBMT 92 TSI D7F	121

Position no	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
510807217AMGRU	Cover For Bumper Primed	1	pcs.	1,080.14	#1	1,080.14	1,155.75
510805915A 9B9	Retainer For Spoiler Sati	1	pcs.	170.44	#1	170.44	182.37
510807724D	Support Part (bumper retainer RHS)	1	pcs.	30.54	#1	30.54	32.68
510807050C	Guide Piece	1	pcs.	19.18	#1	19.18	20.52
510821022D	Bumper bracket RHS	1	pcs.	603.41	#1	603.41	645.65
5G0805970N	Fender (RHS)	1	pcs.	152.98	#1	152.98	163.69
5G0805912AA	Wheelhouse Liner (upper)	1	pcs.	86.69	#1	86.69	92.76
518941006C	Wheelhouse Liner (lower)	1	pcs.	655.66	#1	655.66	701.56
	Twin Halogen Headlamps (RHS)	1	pcs.	475.00	#1	475.00	501.25
	LABOUR	5	pcs.	500.00	#1	500.00	525.00
	Spray Painting	5	pcs.		#1		

Quotation valid till 23-08-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	560.00	7,674.04	7%	576.38	8,234.04	8,810.42
Total	560.00	7,674.04		576.38	8,234.04	8,810.42

Customer

Service Advisor

LKK Auto Car

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) -----

• Parts are supplied on a "best price" basis.
• Third party claims are on a "proportionate" basis.
• No liability for consequential damages.
• Supply is subject to availability and is not a contract for insurance.
• Is subject to the terms and conditions of the insurance policy.

23/8/19

Rasul

Hp 90010068

5 days

21/08/19 #1025

EXCESS: 500

Revers

Reverses before paint

Supplementary or Omitted List



VEHICLE NUMBER: **SLS5685Z**
 MODEL **SPORTSVAN 1.4**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
1				
2				
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
1	510821136C	RHS FENDER BRACKET	1	\$ 29.14	28%	\$ 20.98
2						
3						
4						
5						
TOTAL:						\$20.98

Total Labour & Parts

\$20.98

Survey By **CHONG**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page 1/2

Document no.
Document date 16-09-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001792/ 1
Job order date 23-08-2019
Service Advisor PEARLYN CHEONG

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
HO
KAR FATT
523 WOODLANDS DRIVE 14
#09-389
Singapore 730523

License plate SLS5685Z	Model code AM13HZ	First registration 28-09-2017	VIN WWWZZZAUZGW564040	Model Sportsvan 1.4CLBMT 92 TSI D7F	Mileage 49,839
---------------------------	----------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
510807217AMGRU	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	Cover For Bumper Primed	1	pcs.	1,080.14	28.00% #1	777.70	832.14
510821022D	CD-260819						
	Fender	1	pcs.	603.41	28.00% #1	434.46	464.87
	(RHS)*CD-260819						
518941006C	Twin Halogen Headlamps	1	pcs.	655.66	28.00% #1	472.08	505.13
	(RHS)*CD-260819						
510821136C	Cross Support	1	pcs.	29.14	28.00% #1	20.98	22.45
	RHS FENDER BRACKET RH C/D-6/9/2019						
	LABOUR	2	pcs.	475.00	#1	950.00	1,016.50
	Spray Painting	2	pcs.	500.00	#1	1,000.00	1,070.00
	Insurance Excess	-1	pcs.	500.00	#1	-500.00	-535.00
	MSIG WINNER OD						
	D.O.A: 15-08-2019						
	EXCESS: \$500						
	SURVEY BY : LKK RASUL						

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	360.00	3,155.22	663.13	7%	246.07	663.13	3,515.22	3,761.29
Total	360.00	3,155.22	663.13		246.07	663.13	3,515.22	3,761.29

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice

Preview

Page 2/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
HO
KAR FATT
523 WOODLANDS DRIVE 14
#09-389
Singapore 730523

Document no.
Document date 16-09-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001792/ 1
Job order date 23-08-2019
Service Advisor PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SLS5685Z	AM13HZ	28-09-2017	WVWZZZAUZGW564040	Sportsvan 1.4CLBMT 92 TSI D7F	49,839

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Aug 2019		20 Aug 2019 16:54 Edit Adj Rpt	S\$4,015.22 Edit Estimates	S\$4,015.22 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HO KAR FATT , ID: S7472782D, Tel: +6594304913, Email: KFHO@FOAMTEC.COM.SG									
Vehicle Reg. No.: SLS5685Z		Date of Loss: 15/08/2019 07:00 - :59 [22 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 602974		Policy/Cover Note No.: 29028868AVW (Comprehensive) Coverage: 28/09/2018 - 27/09/2019							
		Excess: S\$500.00							
Repairer: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/09/2019]									
Driver/Custodian: HO KAR FATT (45 / Male) , NRIC: S7472782D, Tel: +6594304913 Email: KFHO@FOAMTEC.COM.SG									
Adj Asg. Remarks: Survey appt 21/08/19, 10am. Owner waiting at Alexandra w/shop. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (25/09/2019): Alert - Adj Mandate Approved (S\$4015.22) - SLS5685Z - Claim Handler: Pang Xiu Sh... - MSIG_SG (23/08/2019): Alert - Adj Mandate Approved (S\$4649.21) - SLS5685Z - Claim Handler: Pang Xiu Sh...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS5685Z (602974)

OD

Aug 15 2019 7:00AM

[HO KAR FATT]

Volkswagen Group Singapore Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 19:18	Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 16:56	Adjuster Immediate Advice	Load HTM	
2	20/09/19 13:06	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 18:59	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	15/08/19 18:59	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	15/08/19 18:59	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	15/08/19 18:59	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	15/08/19 18:59	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	15/08/19 19:09	Driving License [Linked Accident Report Documents]	Load JPG	☒
7	15/08/19 19:15	Driving License [Linked Accident Report Documents]	Load JPG	☒
8	15/08/19 19:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	15/08/19 19:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	15/08/19 19:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/08/19 15:17	General View	Load JPG	☒
2	22/08/19 15:17	General View	Load JPG	☒
3	22/08/19 15:17	General View	Load JPG	☒
4	22/08/19 15:17	General View	Load JPG	☒
5	22/08/19 15:17	General View	Load JPG	☒
6	22/08/19 15:17	General View	Load JPG	☒
7	22/08/19 15:17	General View	Load JPG	☒
8	22/08/19 15:17	General View	Load JPG	☒
9	22/08/19 15:17	General View	Load JPG	☒
10	22/08/19 15:17	General View	Load JPG	☒
11	22/08/19 15:17	General View	Load JPG	☒
12	22/08/19 15:17	General View	Load JPG	☒
13	22/08/19 15:17	General View	Load JPG	☒
14	22/08/19 15:17	General View	Load JPG	☒
15	22/08/19 15:17	General View	Load JPG	☒
16	22/08/19 15:17	General View	Load JPG	☒
17	22/08/19 15:17	General View	Load JPG	☒
18	22/08/19 15:17	General View	Load JPG	☒
19	22/08/19 15:17	General View	Load JPG	☒
20	22/08/19 15:17	General View	Load JPG	☒
21	22/08/19 15:17	General View	Load JPG	☒
22	22/08/19 15:17	General View	Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
23	22/08/19 15:17	General View	Load JPG	☒
24	22/08/19 15:17	General View	Load JPG	☒
25	22/08/19 15:17	General View	Load JPG	☒
26	22/08/19 15:17	General View	Load JPG	☒
27	20/09/19 12:56	Reinspection Photo	Load JPG	☒
28	20/09/19 12:56	Reinspection Photo	Load JPG	☒
29	20/09/19 12:56	Reinspection Photo	Load JPG	☒
30	20/09/19 12:56	Reinspection Photo	Load JPG	☒
31	20/09/19 12:56	Reinspection Photo	Load JPG	☒
32	20/09/19 12:56	Reinspection Photo	Load JPG	☒
33	20/09/19 12:56	Reinspection Photo	Load JPG	☒
34	20/09/19 12:56	Reinspection Photo	Load JPG	☒
35	20/09/19 12:56	Reinspection Photo	Load JPG	☒
36	20/09/19 12:56	Reinspection Photo	Load JPG	☒
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/08/19 14:00	Estimate	Load PDF	
2	19/08/19 14:00	Email to arrange survey	Load PDF	
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 19:09	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/19 16:57	ESTIMATE.pdf	Load PDF	
2	21/08/19 16:57	SLS 5685Z GIA.pdf	Load PDF	
3	23/08/19 14:12	POLICE REPORT.pdf	Load PDF	
4	20/09/19 12:55	ESTIMATE & SUPP MARKED.pdf	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 19:18	Accident Statement	Load HTM	
Photos/Images			3 per page	
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 18:59	Accident Photo	Load JPG	☒
2	15/08/19 18:59	Accident Photo	Load JPG	☒
3	15/08/19 18:59	Accident Photo	Load JPG	☒
4	15/08/19 18:59	Accident Photo	Load JPG	☒
5	15/08/19 18:59	Accident Photo	Load JPG	☒
6	15/08/19 19:09	Driving License	Load JPG	☒
7	15/08/19 19:15	Driving License	Load JPG	☒
8	15/08/19 19:15	Accident Photo	Load JPG	☒
9	15/08/19 19:15	Accident Photo	Load JPG	☒
10	15/08/19 19:15	Accident Photo	Load JPG	☒
Documentation			1 per page	
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	15/08/19 19:09	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTMSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807**Our File No:** CS/MSG19014559/R1SF3S2**Date:** 30/09/2019REFERENCE

Insured/Claimant:	HO KAR FATT	Policy No:	29028868AVW	
Date of Loss:	15/08/2019	Nature of Claim:	OD	Claim No: 602974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5685Z	Engine No:	CZC084170
Make & Model:	VOLKSWAGEN SPORTSVAN, 1.4 (A)	Chassis No:	WVWZZZAUZGW564040
Reg. Date:	28/09/2017 (Man. Year: 2015)	Odometer:	49329 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,820.02	1,705.22	1,114.80	39.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,435.00	2,310.00	3,125.00	57.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,255.02	4,015.22	4,239.80	51.36
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	7,755.02	3,515.22	4,239.80	54.67
+ GST 7.00/7.00% (S\$)	542.85	246.07	296.78	54.67
Nett Amount (S\$)	8,297.87	3,761.29	4,536.58	54.67

INSPECTION

Date of Assignment:	20/08/2019	
Date Inspected:	21/08/2019	Inspected At: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	VOLKSWAGEN SPORTSVAN 1.4 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5685Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Cut	1,080.14 F	*777.70 F
2	1		*RETAINER FOR SPOILER SATI	Serviceable	170.44 F	*- F
3	1		*SUPPORT PART (BUMPER RETAINER RHS)	Serviceable	30.54 F	*- F
4	1		*GUIDE PIECE BUMPER BRACKET RHS	Serviceable	19.18 F	*- F
5	1		*FENDER (RHS)	Buckled	603.41 F	*434.46 F
6	1		*WHEELHOUSE LINER (UPPER)	Serviceable	152.98 F	*- F
7	1		*WHEELHOUSE LINER (LOWER)	Serviceable	86.69 F	*- F
8	1		*TWIN HALOGEN HEADLAMPS (RHS)	Scratched	655.66 F	*472.08 F
9	1		*RHS FENDER BRACKET	Bent	20.98 F	*20.98 F
					Total Parts (\$\$)	2,820.02 1,705.22

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING.	New	360.00	360.00
2	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	200.00	0.00
3	LABOUR.	New	2,375.00	950.00
4	SPRAY PAINTING.	New	2,500.00	1,000.00
Gross Labour Cost (\$\$)			5,435.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >