

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 20 Sep 2019

Preliminary Advice

Vehicle No	: SLS5685Z	Accident Date	: 15/08/2019
Make	: VOLKSWAGEN SPORTSVAN	Policy No.	: 29028868AVW
Assignment Date	: 20/08/2019	Excess	: S\$500.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,255.02 (inclusive supp)
Revised Amount	:S\$	4,015.22 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,015.22
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	48,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,840.00

Remarks

- (X) The vehicle is economical for repair. We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 20.98.
- () The above survey was conducted on a 'without prejudice' basis.