

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 21 Aug 2019

Preliminary Advice

Vehicle No	: SLS5685Z	Accident Date	: 15/08/2019
Make	: VOLKSWAGEN SPORTSVAN	Policy No.	: 29028868AVW
Assignment Date	: 20/08/2019	Excess	: S\$500.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,234.04
Revised Amount	:S\$	4,649.21
Check Items (Estimated)	:S\$	459.83
Total	:S\$	5,109.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	48,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,840.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.