

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 AUG 2019

E S T I M A T E

Estimate No. : b1 52377
Date Estimated : 19/08/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Vincent Ong Weng Seng (Vincent Wang Yon
106 Jalan Rajah
#03-100

Singapore 321106

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY6747P	E491758	23/09/2010	320iA-C	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out
boot lid, tail panel and dent area caused by the accident

1700 2,975.00

To respray rear bumper, boot lid and tail panel

1730 2,666.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: **6,169.00**DESCRIPTIONQTYPRICVALUE

REAR BUMPER SET MOUNTING PAR

1

30.55

? 30.55

RR BUMPER LH GUIDE

1

50.20

? 50.20

RR BUMPER RH GUIDE

1

50.20

? 50.20

RR BUMPER CARRIER

1

458.55

? 458.55

RR BUMPER CTR GUIDE

1

50.20

? 50.20

REAR BUMPER TRIM PANEL PRIMED (PDC)

1

1,250.15

del 1,250.15

RR BUMPER TOW HOOK COVER

1

38.95

mis 38.95

RR BUMPER BOTTOM CTR GUIDE

1

54.20

? 54.20

EMBLEM GROMMET

2

0.80

new 1.60

PLAQUE

1

71.25

new 71.25

RR EMBLEM 320I

1

64.10

del 64.10

DECOUPLING RING PDC TORQUE CONVERTER

2

5.05

new 10.10

PDC SENSOR (TITANSILBER)

2

368.80

? 737.60

(DG/SL) ADHESIVE SET K6

1

53.05

? 53.05

Total Parts : **2,920.70**

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 52377**Page No. : **2 of 5**Date Estimated : **19/08/2019**Prepared By : **Han Kwan Yong**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY6747P	E491758	23/09/2010	320iA-C	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>3/9/19 @ 1045</u>	Excess S\$ _____
Surveyor's Name <u>Tan Hui</u>	Sign <u>Tan Hui</u>
Surveyor's Tel <u>97445346</u>	Authorised <u>Yes / No</u>
Authorised Date <u>'WP'</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR <u>Yes / No</u> <u>PML Yes / No</u>	
Surveyor's E-mail <u>tanhui@lkkauto.com</u>	
No. of Working Days Recommend <u>5 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	6,169.00
Parts	:	2,920.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	636.28
Grand Total	:	9,725.98

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY******** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****