

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 AUG 2019

E S T I M A T E

Estimate No. : b1 52377 Page No. : 1 of 5
Date Estimated : 19/08/2019
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -

Vincent Ong Weng Seng (Vincent Wang Yon
106 Jalan Rajah
#03-100

Singapore 321106

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY6747P	E491758	23/09/2010	320iA-C	0

DESCRIPTION

To replace rear bumper & attachments including to knock out
boot lid, tail panel and dent area caused by the accident

1700 2,975.00

To respray rear bumper, boot lid and tail panel

1730 2,666.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 6,169.00

DESCRIPTION

REAR BUMPER SET MOUNTING PAR
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
REAR BUMPER TRIM PANEL PRIMED (PDC)
RR BUMPER TOW HOOK COVER
RR BUMPER BOTTOM CTR GUIDE
EMBLEM GROMMET
PLAQUE
RR EMBLEM 320i
DECOUPLING RING PDC TORQUE CONVERTE
PDC SENSOR (TITANSILBER)
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	30.55	30.55
1	50.20	50.20
1	50.20	50.20
1	458.55	458.55
1	50.20	50.20
1	1,250.15	1,250.15
1	38.95	38.95
1	54.20	54.20
2	0.80	1.60
1	71.25	71.25
1	64.10	64.10
2	5.05	10.10
2	368.80	737.60
1	53.05	53.05

Total Parts : 2,920.70

Email to Ton
COR 95223.20, 5 days

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52377
Date Estimated : 19/08/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY6747P	E491758	23/09/2010	320iA-C	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 3/9/19 @ 1045 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97445346 Authorised Yes / No _____

Authorised Date WP Time _____

RE-SURVEY PART: PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@lkk.com.sg

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	6,169.00
Parts	:	2,920.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	636.28
Grand Total	:	<u>9,725.98</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52377**
Date Estimated : **19/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Vincent Ong Weng Seng (Vincent Wang Yongcher
106 Jalan Rajah
#03-100

Singapore 321106

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY6747P	WBADV320X0E491758	23/09/2010	320iA-C	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including make good the bootlid and knock out dented area caused by the accident.	1,700.00		1,700.00
To respray rear bumper and bootlid.	1,730.00		1,730.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00		230.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM PANEL PRIMED (PDC)	1,250.15	1.00		1,250.15
EMBLEM GROMMET	0.85	2.00		1.70
PLAQUE	71.25	1.00		71.25
DECOUPLING RING PDC TORQUE CONVERTE	5.05	2.00		10.10

SUPPLEMENTARY ITEMS

Total Labour :	3,890.00
Total Parts :	1,333.20
Total Labour & Parts :	5,223.20 #
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,223.20
GST @7%:	365.62
Grand Total :	5,588.82