



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 1

Vehicle No. SLL 3836 E TOYOTA ALTIS 1.6A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bootlid <i>HA</i>		1478.00	692
1	Rear bootlid Hinge @\$107.00 <i>X suc</i>		214.00	X
1	Rear bootlid centre chrome moulding <i>X suc</i>		254.00	X
1	Rear bootlid weatherstrip <i>ne -</i>		214.00	92
1	Rear bootlid COROLLA emblem <i>ne -</i>		108.00	48
1	Rear bootlid Altis emblem <i>ne -</i>		82.00	52
1	Rear bootlid 1.6 E emblem <i>ne -</i>		58.00	48
1	Rear bootlid VVT-I emblem <i>ne -</i>		70.00	48
1	Rear bootlid Corolla badge <i>ne X an</i>		88.00	X repeated
1	Rear bootlit lock assy <i>b+</i>		530.00	69
1	Rear bootlid reflector @\$572.40 <i>X suc suc</i>		1144.80	X
1pc	Rear taillamp @\$780 <i>LH. su/RH X @286</i>		1560.00	286 (1pc)
2	Taillamp lower panel @214.50 <i>X suc</i>		429.00	X
1	Rear end panel <i>bl</i>		982.00	602
1	Rear end panel top garnish <i>de -</i>		216.00	54
1	Rear bumper <i>de -</i>		1250.00	456
1	Rear bumper reinforcement <i>X suc an</i>		472.00	X
1	Rear bumper foam <i>X suc an</i>		310.00	X
1pc	1set Rear bumper side retainer @98.00 <i>LH/ ne / RH-X @72</i>		196.00	72
1pc	2 RHS & LHS Rear fender @782.50 <i>LH- repair / RH-X</i>		1565.00	X
1	1 RHS & LHS Rear fender inner trim @272.40 <i>X 056</i>		544.80	\$217.40 de / 56
1	1 Rear spare tyre panel <i>X suc shield 132.70</i>		980.00	X
1	1 Rear spare tyre top cover <i>X suc</i>		288.00	X
			13033.60	0.00
less 25%			3258.40	25% 0.00
			9775.20	0.00
SPECIAL NETT ITEMS				
1set	Rear bumper clips <i>ne</i>		80.00	30
1set	Inner trim clips <i>X inner shield clips ne</i>		80.00	220
1set	Taillamp clips <i>ne</i>		70.00	30
1set	Reverse sensor <i>ne</i>		220.00	
1	Rear end panel sealant <i>ne</i>		100.00	60
1	Rear number plate <i>X suc</i>		80.00	X
TOTAL PARTS			10405.20	0.00

2575
258
1931.25

360



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 2

Vehicle No. SLL 3836 E TOYOTA ALTIS 1.6A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1400.00 700	1730
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00 800	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00 30	
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	250.00 60	
5	To remove and replace reverse sensors	150.00 60	
6	To provide anti-rust treatment on affected areas	180.00 60	
Labour Total :		3580.00	
TOTAL (PARTS & LABOUR):		13985.20	

1931.25
360.00
1730.00

4021.25

20%

3217

45-3,200

6 days

Rasul 21/8/19

4p 9001.0068

6 days

45

20/08/19 @ 1250

Reay after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: