

ACC. REC. BY:

REF:

CS/MS419014579/A4vd3ⁿ²

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MS14

Date/Time: 14/8/19 @ 4.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 9718A

Insured:

GBE 6428K

at Workshop no:

Sin Yu Sin

Tel:

9199 3103

of

1 Kaki Bukit Ave 6 #01-52

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

16/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.4pm 20/8/19

Person Contacted:

Wei Leang

Vehicle IN/OUT

Date/Time

Action/Instruction

Loh Yau Jit ✓

SJU 9718A - NA/MS41901430/24

Don: 16/8/19

GBE 6428K - NA/MS41901430/24

Sin: 16/8/19

21/8/19

Informed Crystal pending workshop est by email

26/11/19

Adrian confirmed LS \$6400 (Ref T209.76, 53/9)

27/11/19

Send preli revised by merimen

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % J Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Date / Time _____ Action / Instruction

TP MSLG

mv :

PV :

Nett :

RECEIVED 27 NOV 2019

Veh No: SJ49718A Yr Regn: 2017 JulyType: M.Cat / M.Cyclal / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson cc 1591Colour: Grey A/C: Insured / Std / Nil / NASp. Reading 72557 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHJ3812VJU52A965Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R17R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /


TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 20/08/19Survey held at Sin Yu SinDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



27/11/2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 27/11 - typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

20011211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 27 Nov 2019
<u>Preliminary Advice</u>	

Insured Vehicle No	: GBE6428K	
TP Vehicle No	: SJU9718A	Accident Date : 16/08/2019
Make	: HYUNDAI TUCSON	Assignment Date : 27/08/2019
Date of Inspection	: 20/08/2019	Est. Duration of Repair : 6.00
Inspection At	: SIN YU SIN WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-52 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,609.76	
Revised Amount	:S\$	6,400.00	(LUMP SUM)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	6,400.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 21 August 2019 10:12 AM
To: 'Crystal Lee'
Cc: 'Ong Zi Hui'; SUR
Subject: RE: Survey Request - Manual Assigned-SJU 9718A

Dear Crystal,

Please be informed that we have inspected the vehicle SJU 9718A on 20/8/2019.

We are pending estimate from repairer.

Kindly create claim in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 20 August 2019 12:43 PM
To: 'Crystal Lee' <crystal_lee@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Ong Zi Hui' <zihui_ong@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Crystal Lee [mailto:crystal_lee@sg.msig-asia.com]
Sent: Monday, 19 August 2019 4:51 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG)

Manual Assigned

Dear LKK,

Refer to the email, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua

Sent: Monday, 19 August, 2019 4:06 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 19 August, 2019 4:06 PM
To: 'sinyu sin' <sinyusin@hotmail.com>
Cc: Monica Chung <Monica.Chung@sg.msig-asia.com>
Subject: RE: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Hi Weileang,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: sinyu sin [<mailto:sinyusin@hotmail.com>]
Sent: Monday, 19 August, 2019 2:24 PM
To: Winnie Chua <pingping_chua@sg.msig-asia.com>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Re: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Winnie,

We would like to choose LKK Auto Consultants Pte Ltd to be SIE.
Thank you

Regards
Weileang
Sin Yu Sin Workshop
1 Kaki Bukit Ave 6
#01-52 (Autobay)

From: Winnie Chua <pingping_chua@sg.msig-asia.com>

Sent: Monday, August 19, 2019 12:05 PM

To: sinyusin@hotmail.com <sinyusin@hotmail.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>

Subject: FW: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Hi,

We refer to your email/faxed dated 19/08/19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

- (a) *Fast lane settlement is not applicable for cases that liability is in dispute*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: sinyu sin <sinyusin@hotmail.com>

Sent: Monday, 19 August 2019 10:18 AM

To: Claims <claims@sg.msig-asia.com>

Subject: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K at kaki bukit ave 4

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs,

We are instructed to send you the attached Notice of Accident / to conduct pre-repair survey and a copy of our client's Accident Report.

Your insurer: GBE6428K

Thank you

Regards

Weileang

Sin Yu Sin Workshop

1 Kaki Bukit Ave 6

#01-52 (Autobay)

Singapore 417883

Tel: 91993103 Fax: 68163103

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 19 August 2019 4:51 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG)

Manual Assigned

Dear LKK,

Refer to the email, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 19 August, 2019 4:06 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 19 August, 2019 4:06 PM
To: 'sinyu sin' <sinyusin@hotmail.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: RE: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Hi Weileang,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: sinyu sin [<mailto:sinyusin@hotmail.com>]
Sent: Monday, 19 August, 2019 2:24 PM
To: Winnie Chua <pingping_chua@sg.msig-asia.com>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Re: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Winnie,

We would like to choose LKK Auto Consultants Pte Ltd to be SJE.

Thank you

Regards
Weileang
Sin Yu Sin Workshop
1 Kaki Bukit Ave 6
#01-52 (Autobay)
Singapore 417883

Tel: 91993103 Fax: 68163103

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Monday, August 19, 2019 12:05 PM
To: sinyusin@hotmail.com <sinyusin@hotmail.com>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: FW: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K (MSIG) at kaki bukit ave 4

Hi,

We refer to your email/faxed dated 19/08/19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: sinyu sin <sinyusin@hotmail.com>

Sent: Monday, 19 August 2019 10:18 AM

To: Claims <claims@sg.msig-asia.com>

Subject: Notice of accident/notice to conduct pre-repair survey: Accident on 16/08/2019 involving SJU9718A & GBE6428K at kaki bukit ave 4

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs,

We are instructed to send you the attached Notice of Accident / to conduct pre-repair survey and a copy of our client's Accident Report.

Your insurer: GBE6428K

Thank you

Regards

Weileang

Sin Yu Sin Workshop

1 Kaki Bukit Ave 6

#01-52 (Autobay)

Singapore 417883

Tel: 91993103 Fax: 68163103

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2019 13:57
Date Of Accident	16/08/2019 15:50
Exact Location Of Accident	KAKI BUKIT AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU9718A
Insured/Policyholder	
Name Of Registered Owner	TAN HOCK CHAI
NRIC No	S7672150E
Email Address	ERIC.TAN.HC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94235576
Alternative Phone No	OFFICE-94235576

Vehicle Particulars

Manufacturer	HYUNDAI
Model	TUCSON-1.6 GLS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1955451
Cover Note Number	

Driver

Name of Driver	TAN HOCK CHAI
NRIC No	S7672150E
Date Of Birth	30/09/1976
Occupation	INDOOR
Date Of Driving Pass	22/10/1996
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94235576
Fax Number	
Contact Number	OFFICE-94235576
Email Address	ERIC.TAN.HC@GMAIL.COM

Address	APT BLK 128A PUNGGOL FIELD WALK #12-347
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6428K
Vehicle Make/Model/Colour	NISSAN CABSTAR SILVER
Details Of Properties	DAMAGED TO FRONT DRIVER DOOR AND FRONT BUMPER
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/foresaid.
8. Consent under the Personal Data Protection Act (PDPA)
(I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law firm/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firm/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firm/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

Sketch Plan #2

Describe Circumstances of the Accident

GRE 6428R was stop at the road side with double signal.

When I overtook, it just cross the road and hit on left side of my car.

Stop with Double Signal

Declaration

We declare the foregoing particulars are true in every respect


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP MSIG.

ICM173812VJUS2 9965

Veron.

19 August 2019

QUOTATION FOR ACCIDENT REPAIR OF SJU9718A HYUNDAI TUCSON

THIRD PARTY INSURER: MSIG

S/No.	Parts List	Qty	Amount (\$)
1.	Front door LH <i>Dented.</i>	1	\$ 1930.80 <i>✓ 1261.</i>
2.	Front door window glass outer chrome moulding LH <i>cut</i>	1	\$ 208.90 <i>✓</i>
3.	Front door outer chrome handle LH <i>crack</i>	1	\$ 207.00 <i>✓</i>
4.	Front door outer chrome handle cover LH <i>crack</i>	1	\$ 57.50 <i>✓</i>
5.	Front door outer lower garnish protector LH <i>new</i>	1	\$ 420.90 <i>✓</i>
6.	Front door black tape LH <i>new</i>	2	65.80 \$ 131.60 <i>✓</i>
7.	Front door hinge U/L (LH) <i>new</i>	2	120.30 \$ 240.60 <i>✓</i>
8.	Front checker LH <i>new</i>	1	\$ 98.40 <i>✓</i>
9.	Front door weather strip LH <i>new</i>	1	\$ 145.80 <i>✓</i>
10.	Front door mechanism lock LH <i>2nd</i>	1	\$ 328.60 <i>✓</i>
11.	Front door lock striker LH <i>new</i>	1	\$ 55.00 <i>✓</i>
12.	Front door window glass regulator LH <i>2nd</i>	1	\$ 258.10 <i>✓</i>
13.	Front door window glass regulator motor LH <i>new</i>	1	\$ 189.40 <i>✓</i>
14.	Front door inner trim board LH <i>new</i>	1	\$ 980.20 <i>✓</i>
15.	Front door side mirror glass LH <i>2nd missing</i>	1	\$ 232.60 <i>✓</i>
16.	Front door side mirror covers LH <i>missing</i>	1	\$ 106.80 <i>✓</i>
17.	Front door side mirror base LH <i>2nd</i>	1	\$ 520.70 <i>✓</i>
18.	Rear door RH <i>Dented.</i>	1	\$ 1880.30 <i>✓ 1208.</i>
19.	Rear door window glass outer chrome moulding LH <i>new</i>	1	\$ 208.90 <i>✓</i>
20.	Rear door outer chrome handle LH <i>new</i>	1	\$ 102.30 <i>✓</i>
21.	Rear door outer chrome handle cover LH <i>new</i>	1	\$ 57.50 <i>✓</i>
22.	Rear door outer transparent sticker LH <i>new</i>	1	\$ 55.30 <i>✓</i>
23.	Rear door black tape LH <i>new</i>	2	65.80 \$ 131.60 <i>✓</i>
24.	Rear door outer lower garnish protector LH <i>new</i>	1	\$ 360.90 <i>✓</i>
25.	Rear door weather strip LH <i>new</i>	1	\$ 145.80 <i>✓</i>
26.	Rear door hinge U/L (LH) <i>new</i>	2	120.30 \$ 240.60 <i>✓</i>
27.	Rear door checker LH <i>new</i>	1	\$ 98.40 <i>✓</i>
28.	Rear door mechanism lock LH <i>new</i>	1	\$ 328.60 <i>✓</i>
29.	Rear door window glass regulator LH <i>2nd</i>	1	\$ 258.10 <i>✓</i>
30.	Rear door window glass regulator motor LH <i>2nd</i>	1	\$ 189.40 <i>✓</i>
31.	Rear fender outer garnish protector LH <i>cut</i>	1	\$ 369.00 <i>✓</i>
32.	Rear bumper lower diffuser <i>cut</i>	1	\$ 358.50 <i>✓</i>
33.	Rear bumper <i>2nd</i>	1	\$ 638.50 <i>✓</i>
34.	Rear wheel bearing hub LH <i>new</i>	1	\$ 230.50 <i>✓</i>
35.	Side skirt LH <i>2nd</i>	1	\$ 357.60 <i>✓</i>
Subtotal before discount			\$ 12124.70
Discount 20%			\$ 2424.94
Subtotal 1			\$ 9699.76

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

19 August 2019

QUOTATION FOR ACCIDENT REPAIR OF SJU9718A HYUNDAI TUCSON

THIRD PARTY INSURER: MSIG

<u>S/No.</u>	<u>Parts S/Nett</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear sport rim LH <i>lit</i>	1	\$ 550 ✓
2.	Rear bumper clip <i>lit</i>	1	\$ 50 30
3.	Front inner trim board clip <i>lit</i>	1	\$ 30 ✓
4.	Rear door inner trim board clip <i>lit</i>	1	\$ 30 ✓
Special Nett Sub-Total			\$ 660

Labour

To remove & transfer front and rear left door components

~~\$ 150~~ ✓

To transfer front and rear door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle

\$ 120 ✗

To rustproof affected areas

\$ 100 ✗

To remove, check & replace rear undercarriage parts.

\$ 250 ✗

To conduct wheel alignment

~~\$ 150~~ 80

To remove, replace and reinstall rear reverse sensor

~~\$ 80~~ 50

To straighten, repair, realign on front & rear affected area and replace damaged parts

~~\$ 1200~~ 800

To spray painting on affected area

~~\$ 1200~~ 1000

Total Labour Cost

\$ 3250

Total Cost Of Repairs (Total cost of parts + Total labour cost) **\$ 13609.76**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling.
H/S 20/08/19.

06 Days.
Total 2079.68.
L/S: 6.4/K.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014579/AGVD3N2

Date: 28/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29069477
Claimant Vehicle No :	SJU9718A	Insured Vehicle No :	GBE6428K
Date of Loss:	16/08/2019	Nature of Claim:	TP
		Claim No:	603150

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU9718A	Engine No:	G4FJHU532512
Make & Model:	HYUNDAI TUCSON, 1.6 TL GLS (A)	Chassis No:	KMHJ3812VJU529965
Reg. Date:	15/07/2017 (Man. Year: 2017)	Odometer:	72557 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,359.76	5,899.68	4,460.08	43.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	2,080.00	1,170.00	36.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,609.76	7,979.68	5,630.08	41.37
Approved Total (Overridden) (S\$)		6,400.00		
Nett Amount (S\$)	13,609.76	6,400.00	7,209.76	52.97

INSPECTION

Date of Assignment:	27/08/2019	
Date Inspected:	20/08/2019 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2019)
Parts:	143	HYUNDAI TUCSON 1.6 TL GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU9718A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	1,930.80 FL	*1,261.00 FL
2	1		*FRONT DOOR WINDOW GLASS OUTER CHROME MOULDING LH	Cut	208.90 FL	*208.90 FL
3	1		*FRONT DOOR OUTER CHROME HANDLE LH	Cracked	207.00 FL	*207.00 FL
4	1		*FRONT DOOR OUTER CHROME HANDLE COVER LH	Cracked	57.50 FL	*57.50 FL
5	1		*FRONT DOOR OUTER LOWER GARNISH PROTECTOR LH	Necessary	420.90 FL	*420.90 FL
6	2		*FRONT DOOR BLACK TAPE LH	Necessary	131.60 FL	*131.60 FL
7	2		*FRONT DOOR HINGE U/L (LH)	Not Necessary	240.60 FL	*- FL
8	1		*FRONT CHECKER LH	Not Necessary	98.40 FL	*- FL
9	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	145.80 FL	*- FL
10	1		*FRONT DOOR MECHANISM LOCK LH	Damaged	328.60 FL	*328.60 FL
11	1		*FRONT DOOR LOCK STRIKER LH	Not Necessary	55.00 FL	*- FL
12	1		*FRONT DOOR WINDOW GLASS REGULATOR LH	Damaged	258.10 FL	*258.10 FL
13	1		*FRONT DOOR WINDOW GLASS REGULATOR MOTOR LH	Not Necessary	189.40 FL	*- FL
14	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	980.20 FL	*- FL
15	1		*FRONT DOOR SIDE MIRROR GLASS LH	Missing	232.60 FL	*232.60 FL
16	1		*FRONT DOOR SIDE MIRROR COVERS LH	Missing	106.80 FL	*106.80 FL
17	1		*FRONT DOOR SIDE MIRROR BASE LH	Damaged	520.70 FL	*520.70 FL
18	1		*REAR DOOR RH	Dented	1,880.30 FL	*1,208.00 FL
19	1		*REAR DOOR WINDOW GLASS OUTER CHROME MOULDING LH	Not Necessary	208.90 FL	*- FL
20	1		*REAR DOOR OUTER CHROME HANDLE LH	Not Necessary	102.30 FL	*- FL
21	1		*REAR DOOR OUTER CHROME HANDLE COVER LH	Not Necessary	57.50 FL	*- FL
22	1		*REAR DOOR OUTER TRANSPARENT STICKER LH	Necessary	55.30 FL	*55.30 FL
23	2		*REAR DOOR BLACK TAPE LH	Necessary	131.60 FL	*131.60 FL
24	1		*REAR DOOR OUTER LOWER GARNISH PROTECTOR LH	Necessary	360.90 FL	*360.90 FL
25	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	145.80 FL	*- FL
26	2		*REAR DOOR HINGE U/L (LH)	Not Necessary	240.60 FL	*- FL
27	1		*REAR DOOR CHECKER LH	Not Necessary	98.40 FL	*- FL
28	1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	328.60 FL	*- FL
29	1		*REAR DOOR WINDOW GLASS REGULATOR LH	Not Necessary	258.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*REAR DOOR WINDOW GLASS REGULATOR MOTOR LH	Not Necessary	189.40 FL	*- FL
31	1		*REAR FENDER OUTER GARNISH PROTECTOR LH	Cut	369.00 FL	*369.00 FL
32	1		*REAR BUMPER LOWER DIFFUSER	Cut	358.50 FL	*358.50 FL
33	1		*REAR BUMPER	Repair	638.50 FL	*- FL
34	1		*REAR WHEEL BEARING HUB LH	Not Necessary	230.50 FL	*- FL
35	1		*SIDE SKIRT LH	Deformed	357.60 FL	*357.60 FL
36	1		*REAR SPORT RIM LH	Cut	550.00 FS	*550.00 FS
37	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
38	1		*FRONT INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
39	1		*REAR DOOR INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListitemDiac.

Sub Total (S\$) 12,784.70 7,214.60

- List Item Discount on L Items 20.00/20.00% (S\$) 2,424.94 1,314.92

Total Parts (S\$) 10,359.76 5,899.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & TRANSFER FRONT AND REAR LEFT DOOR COMPONENTS	New	150.00	150.00
2	TO TRANSFER FRONT AND REAR DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE	New	120.00	0.00
3	TO RUSTPROOF AFFECTED AREAS	New	100.00	0.00
4	TO REMOVE,CHECK & REPLACE REAR UNDERCARRIAGE PARTS	New	250.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE SENSOR	New	80.00	50.00
7	TO STRAIGHTEN,REPAIR,REALIGN ON FRONT & REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	800.00
8	TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,250.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >