



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting

Attn: The Motor Claims Department

Your Insured veh no : YN 7687 C

Lonpac Insurance Bhd

300 Beach Road,

#17-04/07 The Concourse

Singapore 199555

Jia Le.

68411972 LKK Niv.

JTFIT02P500182130

Dear Sir / Madam

**Estimate Cost repair Bill To Toyota Hiace Van No GBE 4018 Z & YN 7687 C on 03/08/2019
@17:30:00**

To Supply:-

1pc	Front bonnet <i>Dented</i>		\$ 845.10 ✓
2pcs	Front bonnet hinge <i>new</i>	65.1	\$ 130.20 ✓
1pc	Front support panel <i>Repair</i>		\$ 515.00 ✓
2pcs	Front head lamp <i>Cracked</i>	951.1	\$ 1,902.20 ✓ <i>1562.80</i>
1pc	Front grille <i>Cracked</i>		\$ 588.10 ✓
1pc	Front lower grille <i>Cracked</i>		\$ 498.10 ✓
1pc	Front bumper <i>Dented</i>		\$ 531.10 ✓
10pcs	Front bumper clips <i>new</i>		\$ 50.00 <i>30</i>
2pcs	Front bracket <i>new</i>	148.1	\$ 296.20 ✓
2pcs	Front bumper side bracket <i>new that can be</i>	158.1	\$ 316.20 <i>158.10</i>
			\$ 5,672.20
<i>4762.10</i> less 25%			\$ 1,418.05
<i>3571.57</i>			\$ 4,254.15

To dismantle & replace damage parts, panel beat where necessary.

To putty, apply primer & spray paint on the affected portion.

To check wiring functions.

To top up air con gas

LKK Auto Consultants hence notify
the Repairer of the following:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation on the "without prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 950.00 *500*

\$ 1,000.00 *400*

\$ 80.00 *30*

\$ 150.00 *x*

\$ 6,434.15

toll: 450.57

HS 3.6K

1pc Bonnet Lock and key 118 ✓

Bonnet Logo *new* 98.20 ✓

Front LH corner Panel. 309.50 ✓

Dented

Adrian L

4/8 20/0

0400