

22/07/2012

ASS. REC. BY:

REF:

CF/MSU19014583/Cgd302

Special Instructions:

Surveyor: Simon

ASSIGNMENT (Office)

Meinman

From (Person):

Chhia Nyule Pui

of

MS19

Date/Time:

14/8/19 @ 4.49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 7470E

Insured:

G2 9665C

at Workshop m/s

N-S1 Automotive

Tel:

68420051

of

2 Leekie Buleit

Policy No:

A28897769MKC

Claim No:

598918

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.41pm

Person Contacted:

zi ting

Vehicle: IN/OUT

Date/Time

Action/Instruction

Voluntary

SMD 7470E-X

G2 9665C-NA/MSU19003942/24

Don: 4/3/2019

20/9/19 @ 4.53pm confirmed with Mr Yeo US \$10700, 7 days.
(Red \$ 15699.82, 59%.)

RECEIVED 23 SEP 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	✓

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

SND 7470E
Jaguar
XE 2.0A
05
black

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / No

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

55371 km

Vehicle Condition:

Seviceable Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Front right
Front left
Rear left
Rear right

Tread mm	Size	Condition
5	Pirelli 245 / 45 / 18	
5	"	
5	"	
5	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

28-06-19
04-07-19
03-07-19
Twincar.

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised

Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jul 2019		14 Aug 2019 16:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN KHIAM SOON UNDERTAKER, Co. Reg. No.: 24016300A	
Main Claimant:	LIAW RICHARD, ID: S7242000D	
Vehicle Reg. No.:	SMD7470E	Date of Loss: 28/06/2019 18:00 - :59 [49 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 598918	Policy/Cover Note No.: A28897769MKC (Comprehensive) Coverage: 03/03/2019 - 02/03/2020
Vehicle Reg. No. (Insured):	GZ9665C	Policy No. (Claimant):
		Excess: S\$600.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]	
Driver/Custodian (Insured):	WENG BAOXIONG (34 / Male), NRIC: S8420594Z Email:	
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case, on WP. Liab: 100%. TP Agree on IHS. Contact: Zi Ting @ 6842 0051 / 6744 0510	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Friday, 20 September 2019 4:53 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: Finalise

Dear Shiau Chan

SMD7470E L/S \$10700.00 7 days confirm

SLR8112X L/S \$5700.00 5 days confirm

Thanks

On Thu, 19 Sep 2019 at 2:54 PM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Mr Yeo,

WITHOUT PREJUDICE

Offer of below vehicles:

- | | |
|-------------|-----------------------------------|
| 1. SKE7231Y | L/S \$ 4,300.00 and 5 repair days |
| 2. SMD7470E | L/S \$10,700.00 and 7 repair days |
| 3. SLR8112X | L/S \$ 5,700.00 and 5 repair days |

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Yeo Poh Kheng <yeopk@n51.com.sg>
Sent: Saturday, 31 August 2019 11:06 AM
To: SUR
Cc: Shiau Chan (LKKAuto)
Subject: Finalise

Dear Shiau Chan

Can finalise below vehicles

SKE7231Y L/S \$ 7900.00 6 days

SMD7470E L/S limit \$11500.00 8 days

SLR8112X L/S \$ 5700.00 5 days


Pls check and let me know

Thanks

--

Regards,

Yeo Poh Kheng
N-51 Automotive Pte Ltd
Mobile : 8823 5151
Office : 6842 0051
www.n51.com.sg




MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Chhia Nyuk Pui

Date: 08 Jul 2019

Preliminary Advice

Insured Vehicle No	: GZ9665C	Accident Date	: 28/06/2019
TP Vehicle No	: SMD7470E	Assignment Date	: 03/07/2019
Make	: JAGUAR XF	Est. Duration of Repair	: 8.00
Date of Inspection	: 05/07/2019		
Inspection At	: N-51 AUTOMOTIVE PTE LTD (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion.

Repairer's Estimate (Gross)	:S\$	26,399.82
Revised Amount	:S\$	20,945.91
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$	16,700
-----------------	------	--------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000
COE / PARF Rebate	:S\$	93,663
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is ~~economical~~/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
- (X) Other:
 - Repairer agree \$11,500 all in repair.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	000D
Vehicle Details	
Vehicle No.:	SMD7470E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	JAGUAR
Vehicle Model:	XF 2.0P TSS
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	041214113235204PT
Chassis No.:	SAJAC05M3FPU67437
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$51,328.00
Original Registration Date:	30 Apr 2015
First Registration Date:	30 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$64,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2025
PARF Rebate Amount:	\$48,293.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$43,680.00
Total Rebate Amount:	\$91,973.00

The information contained herein is correct as at 23 Sep 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SMD7470E

Make / Model
JAGUAR / XF 2.0P TSS

Vehicle Type :
P10 - Passenger Motor Car

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
SAJAC05M3FPU67437

Propellant :
Petrol

Engine No. :
041214113235204PT

Motor No. :
-

Engine Capacity :
1999 cc

Power Rating :



Maximum Power Output :
177.0 kW (237 bhp)

Maximum Laden Weight :

2230 kg

Unladen Weight :

1873 kg

Year Of Manufacture :

2015

Original Registration Date :

30 Apr 2015

Lifespan Expiry Date :

-

COE Category :

B - Car above 1600cc or 97kW (130bhp)

Quota Premium :

\$78,001.00

COE Expiry Date :

29 Apr 2025

Road Tax Expiry Date :

29 Oct 2019

PARF Eligibility Expiry Date :

29 Apr 2025

Inspection Due Date :

29 Apr 2020

Intended Transfer Date :

23 Sep 2019

CO2 Emission :

189.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-



NOx Emission :

PM Emission :

-

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (30 Oct 2019 to 29 Apr 2020)	\$606.00
Road Tax Renewal - 12 months (30 Oct 2019 to 29 Oct 2020)	\$1,212.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

OK →

Save as PDF

Copy as Text





MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____

Date : _____

Policy No : _____

Claim No : _____

Insured Vehicle No : GZ 9665C Date of Accident : 28-06-19

TP Vehicle No : SMD 7470E Place of Survey : Twin car

Make & Model : Jaguar XF 2.0 Date of Survey : 04-07-19

Point of Impact / Damages :



Rear

Recommended Reserve :

Repairer's Estimate : \$ 26399.82.

Interim Adjustment : \$ 20945.91

Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair \$16700/- Excess : \$ -

Estimate Repair Period : 08 days

Pre-accident Market Value (for total loss consideration) : \$ 105000/-

COE / PARF to owner : \$ 93663/-

Vehicle within / not within limit of economical repair.

Others :

* Repairer agree ~~for~~ \$11500 all in repair.

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. SMD 7470 E

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after Painting photos

Number of Repair Days 08

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 04 - 07 - 19.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIAW RICHARD
39 JALAN LENGKOK SEMBAWANG
SINGAPORE 759223

Contact : 90684171

ESTIMATE

Repair Code : CLM14605

Date in : 03/07/2019

Vehicle Num. : SMD7470E

Model : JAGUAR XF 2.0P TSS

Chassis/Eng# : SAJAC05M3FPU67437/041214113235204PT

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID / <i>Deformed</i>	1	2363.22	2,363.22
REAR BOOTLID 'JAGUAR' EMBLEM / <i>necc</i>	1	209.20	209.20
REAR BOOTLID 'LOGO' EMBLEM / <i>necc</i>	1	223.15	223.15
REAR BOOTLID 'XF' EMBLEM / <i>necc</i>	1	109.03	109.03
REAR BOOTLID CAMERA / <i>Faulty X NN</i>	1	1098.70	750 1,098.70
REAR BOOTLID CENTER LOCK CONTROL / <i>cracked X NN</i>	1	199.89	199.89
REAR BOOTLID DAMPER L/R X <i>NN</i>	2	208.60	417.20
REAR BOOTLID HINGE L/R X <i>NN</i>	2	181.57	363.14
REAR BOOTLID INNER TRIM BOARD / <i>tear X NN</i>	1	986.04	986.04
REAR BOOTLID LOCK STRIKER X <i>NN</i>	1	37.93	37.93
REAR BOOTLID MECHANISM LOCK / <i>dents</i>	1	233.59	233.59
REAR BOOTLID NUMBER PLATE LAMP L/R X <i>NN</i>	2	138.60	277.20
REAR BOOTLID OUTER CHROME HANDLE / <i>Graved</i>	1	798.70	798.70
REAR BOOTLID OUTER LOCK SWITCH X <i>NN</i>	1	79.90	79.90
REAR BOOTLID REFLECTOR L/R / <i>cracked</i>	2	375.79	751.58
REAR BOOTLID WEATHER STRIP / <i>Deformed</i>	1	158.85	158.85
REAR BUMPER / <i>Deformed</i>	1	2149.83	2,149.83
REAR BUMPER ANTENNA SENSOR X <i>NN</i>	1	30.64	30.64

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.LIAW RICHARD

39 JALAN LENGKOK SEMBAWANG

SINGAPORE 759223

Contact : 90684171

ESTIMATE

Repair Code : CLM14605

Date in : 03/07/2019

Vehicle Num. : SMD7470E

Model : JAGUAR XF 2.0P TSS

Chassis/Eng# : SAJAC05M3FPU67437/041214113235204PT

REAR BUMPER CENTER BRACKET / <i>cracked</i>	1	154.40	154.40
REAR BUMPER LOWER LID / <i>Grazed CUT</i>	1	646.33	646.33
REAR BUMPER REINFORCEMENT / <i>Dented</i>	1	841.20	841.20
REAR BUMPER REVERSE SENSOR / <i>Short</i>	<i>4</i>	219.04	<i>800 876.16 400</i>
REAR BUMPER REVERSE SENSOR HOLDER / <i>piece</i>	4	45.56	182.24
REAR BUMPER SIDE RETAINER L/R / <i>cracked</i>	2	71.32	142.64
REAR BUMPER WIRE HARNESS X <i>NN</i>	1	701.76	701.76
REAR END PANEL / <i>Dented photo? R</i>	1	1339.69	1,339.69
REAR END PANEL INNER TOP GARNISH / <i>cracked photo? NN</i>	1	259.33	259.33
REAR EXHAUST HEAT COVER L/R X <i>NN</i>	2	176.26	352.52
REAR EXHAUST RUBBER MOUNTING X <i>NN</i>	4	60.57	242.28
REAR EXHAUST SILENCER BOX L/R / <i>Dented photo? STE</i>	<i>2 1</i>	1384.78	<i>1584.78 2,769.56</i>
REAR FENDER INNER TRIM L/R / <i>Torn -RH, LH - NN</i>	<i>2 1</i>	306.63	613.26
REAR FLOOR PANEL TOP BOARD COVER X <i>NN</i>	1	696.70	696.70
REAR TAILLAMP L/R / <i>cracked photo? NN</i>	2	940.41	1,880.82
REAR TAILLAMP SIDE GARNISH L/R / <i>Torn</i>	2	74.07	148.14

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIAW RICHARD
39 JALAN LENGKOK SEMBAWANG
SINGAPORE 759223

Contact : 90684171

ESTIMATE

Repair Code : CLM14605

Date in : 03/07/2019

Vehicle Num. : SMD7470E

Model : JAGUAR XF 2.0P TSS

Chassis/Eng# : SAJAC05M3FPU67437/041214113235204PT

Subtotal before discount		22,334.82
Percentage discount	0%	0.00
Sub-total 1		22,334.82
REAR BOOTLID INNER TRIM BOARD CLIPS - SET <i>necc</i>	1	60.00 <i>30 60.00</i>
REAR BOOTLID NUMBER PLATE <i>cracked</i>	1	25.00 <i>340 25.00</i>
REAR BOOTLID NUMBER PLATE HOLDER <i>BT</i>	1	50.00 <i>50.00</i>
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET <i>necc</i>	1	60.00 <i>30 60.00</i>
REAR BUMPER CLIPS - SET <i>necc</i>	1	100.00 <i>40 100.00</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>necc</i>	1	50.00 <i>20 50.00</i>
REAR FENDER INNER TRIM CLIPS L/R - SET <i>necc</i>	2 <i>2 2</i>	60.00 <i>40 60 120.00</i>
REAR FLOOR PANEL INSULATOR MAT <i>X NN</i>	1	300.00 <i>150 300.00</i>
REAR TAILLAMP CLIPS L/R - SET <i>X NN</i>	2	40.00 <i>40 80.00</i>
REAR TAILLAMP SIDE GARNISH CLIPS L/R - SET <i>NGC</i>	2	20.00 <i>20 40.00</i>
Subtotal before discount		885.00
Percentage discount	0%	0.00
Sub-total 2		885.00
Parts-total		23,219.82

LABOUR

To Transfer Rear Bootlid Michanism Lock Outer Handle Reflector	<i>40 80.00</i>
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	<i>50 120.00</i>

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.LIAW RICHARD

39 JALAN LENGKOK SEMBAWANG

SINGAPORE 759223

Contact : 90684171

ESTIMATE

Repair Code : CLM14605

Date in : 03/07/2019

Vehicle Num. : SMD7470E

Model : JAGUAR XF 2.0P TSS

Chassis/Eng# : SAJAC05M3FPU67437/041214113235204PT

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 ~~140.00~~

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

800 1100 ~~1,500.00~~

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

80 ~~120.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

700 900 ~~1,100.00~~

To apply anti-rust chemical on repaired and replaced panel.

40 ~~120.00~~

Labour Total

3,180.00

Parts & Labour Total

26,399.82

*** This is a computer-generated document which requires no signature.***

page 4

08 days. 7 days.
05/07/19 @ 1530 hrs.
Victor - Seung @ sg.msig-asia-com
87747011
L/S After paint

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jul 2019		14 Aug 2019 16:49 Edit Adj Rpt	S\$10,700.00 Edit Estimates	S\$10,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN KHIAM SOON UNDERTAKER, Co. Reg. No.: 24016300A								
Main Claimant:	LIAW RICHARD, ID: S7242000D								
Vehicle Reg. No.:	SMD7470E	Date of Loss:	28/06/2019 18:00 - :59 [49 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598918	Policy/Cover Note No.:	A28897769MKC (Comprehensive) Coverage: 03/03/2019 - 02/03/2020						
Vehicle Reg. No. (Insured):	GZ9665C	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	WENG BAOXIONG (34 / Male) , NRIC: S8420594Z Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. TP Agree on IHS. Contact: Zi Ting @ 6842 0051 / 6744 0510								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD7470E (598918)
[GZ9665C]
TP
LIAW RICHARD
Jun 28 2019 6:00PM
[TAN KHIAM SOON UNDERTAKER]
N-51 Automotive Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	08/07/19 10:55	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images			3 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
2	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
3	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
4	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
5	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
6	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
7	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
8	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
9	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
10	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
11	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
12	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
13	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
14	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
15	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
16	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
17	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
18	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
19	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
20	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
21	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
22	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
23	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
24	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
25	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
26	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
27	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
28	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
29	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
30	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
31	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
32	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
33	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
34	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
35	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
36	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
37	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
38	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒
39	05/07/19 00:07	SURVEY PHOTO	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/07/19 14:39	PRI	 Load PDF	
2	03/07/19 14:39	OI Accident Report	 Load PDF	
3	03/07/19 14:39	TP SMD7470E E-REPORT	 Load PDF	
4	03/07/19 15:17	Agree on SJE - workshop details	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	08/07/19 11:56	Preliminary Loss Advise	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014583/CQD3E2

Date: 24/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28897769MKC

Claimant SMD7470E

Insured Vehicle No : GZ9665C

Vehicle No : SMD7470E

Nature of Claim: TP

Claim No: 598918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD7470E

Make & Model: JAGUAR XF, 2.0 GTDI Luxury (A)

Engine No: 041214113235204PT

Reg. Date: 30/04/2015 (Man. Year: 2015)

Chassis No: SAJAC05M3FPU67437

Colour: Black

Odometer: 55371 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,219.82	11,613.51	11,606.31	49.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,770.00	1,410.00	44.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,399.82	13,383.51	13,016.31	49.30
Approved Total (Overridden) (S\$)		10,700.00		
(S\$)	26,399.82	10,700.00	15,699.82	59.47
+ GST 7.00/7.00% (S\$)	1,847.99	749.00	1,098.99	59.47
Nett Amount (S\$)	28,247.81	11,449.00	16,798.81	59.47

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 04/07/2019 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2019)
Parts:	143	JAGUAR XF 2.0 GTDI Luxury (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7470E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Deformed	2,363.22 F	*2,363.22 F
2	1		*REAR BOOTLID JAGUAR EMBLEM	Necessary	209.20 F	*209.20 F
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	223.15 F	*223.15 F
4	1		*REAR BOOTLID XF EMBLEM	Necessary	109.03 F	*109.03 F
5	1		*REAR BOOTLID CAMERA	Not Necessary	1,098.70 F	*- F
6	1		*REAR BOOTLID CENTER LOCK CONTROL	Not Necessary	199.89 F	*- F
7	2		*REAR BOOTLID DAMPER L/R	Not Necessary	417.20 F	*- F
8	2		*REAR BOOTLID HINGE L/R	Not Necessary	363.14 F	*- F
9	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	986.04 F	*- F
10	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	37.93 F	*- F
11	1		*REAR BOOTLID MECHANISM LOCK	Dented	233.59 F	*233.59 F
12	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	277.20 F	*- F
13	1		*REAR BOOTLID OUTER CHROME HANDLE	Grazed	798.70 F	*798.70 F
14	1		*REAR BOOTLID OUTER LOCK SWITCH	Not Necessary	79.90 F	*- F
15	2		*REAR BOOTLID REFLECTOR L/R	Cracked	751.58 F	*751.58 F
16	1		*REAR BOOTLID WEATHER STRIP	Deformed	158.85 F	*158.85 F
17	1		*REAR BUMPER	Deformed	2,149.83 F	*2,149.83 F
18	1		*REAR BUMPER ANTENNA SENSOR	Not Necessary	30.64 F	*- F
19	1		*REAR BUMPER CENTER BRACKET	Cracked	154.40 F	*154.40 F
20	1		*REAR BUMPER LOWER LID	Cut	646.33 F	*646.33 F
21	1		*REAR BUMPER REINFORCEMENT	Dented	841.20 F	*841.20 F
22	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Shorted-2pcs only	876.16 F	*400.00 F
23	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	182.24 F	*182.24 F
24	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	142.64 F	*142.64 F
25	1		*REAR BUMPER WIRE HARNESS	Not Necessary	701.76 F	*- F
26	1		*REAR END PANEL	Repair	1,339.69 F	*- F
27	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	259.33 F	*- F
28	2		*REAR EXHAUST HEAT COVER L/R	Not Necessary	352.52 F	*- F
29	4		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	242.28 F	*- F
30	1		*REAR EXHAUST SILENCER BOX L/R (2PCS)	Dented-1pc only	2,769.56 F	*1,384.78 F
31	1		*REAR FENDER INNER TRIM L/R	O/S Torn / N/S Not Necessary	613.26 F	*306.63 F
32	1		*REAR FLOOR PANEL TOP BOARD COVER	Not Necessary	696.70 F	*- F
33	2		*REAR TAILLAMP L/R	Not Necessary	1,880.82 F	*- F
34	2		*REAR TAILLAMP SIDE GARNISH L/R	Torn	148.14 F	*148.14 F
35	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
36	1		*REAR BOOTLID NUMBER PLATE }	Cracked	25.00 FS	*40.00 FS
37	1		*REAR BOOTLID NUMBER PLATE HOLDER }	Bent	50.00 FS	*- FS
38	1		*SET REAR BOOTLID OUTER CHROME HANDLE CLIPS	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
40	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
41	2		*SET REAR FENDER INNER TRIM CLIPS L/R	Necessary	120.00 FS	*40.00 FS
42	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	300.00 FS	*150.00 FS
43	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	80.00 FS	*40.00 FS
44	2		*SET REAR TAILLAMP SIDE GARNISH CLIPS L/R	Necessary	40.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.					Total Parts (S\$)	23,219.82 11,613.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	60.00
2	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,500.00	800.00
3	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	80.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	700.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
6	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	40.00
7	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	50.00
Gross Labour Cost (S\$)			3,180.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >