

22/01/2019

ASS. REC. BY:

REF: CF/MSG/19014585/Cqd362

Instruction:

Assigner: Simon

ASSIGNMENT (Office)

From (Person):

Pauline Them

of

MSU

Date/Time:

14/8/19 @ 4.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SMF 92484

Insured:

SJB 89669

at Workshop in/s

Team Autopro

Tel:

90927279

of

160 Sir Ming Drive #01-14

Policy No:

28808188

Claim No:

599653

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Adelle

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SMF 92484 - NBA / A19/19012401/Y	DOA: 11/7/2019
	SJB 89669 - NBA / A19/19012401/Y	DOA: 11/7/2019
18/10/19 @ 6.00pm	confirmed with Adel is \$2900, 4 days.	
	(incl \$4268.45, 60%)	

RECEIVED 21 OCT 2019

150
11
161



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	✓

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

SME 9248H
Mazda
3
05
blue

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / No

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

53537 km

Vehicle Condition:

Seviceable Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Front right
Front left
Rear left
Rear right

Tread mm	Size	Condition
5	Bridgestone 205 / 60 / 16	
5	"	
4	"	
4	"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

11-07-2019
22-07-2019
14-07-2019
Team Auto pro

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repaier	Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised
Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019		14 Aug 2019 16:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KOH BOON KENG, MALCOLM, ID: S7922894Z, Tel: +6594896024, Email: NOEMAIL			
Main Claimant:	ALAGAPPAN S/O CHIDAMBARAM, ID: S2196624Z			
Vehicle Reg. No.:	SMF9248H	Date of Loss:	11/07/2019 18:00 - :59 [7 Months and 12 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 599653	Policy/Cover Note No.:	28808188 (Comprehensive) Coverage: 30/09/2018 - 29/09/2019	
Vehicle Reg. No. (Insured):	SJB8966G	Policy No. (Claimant):		
		Excess:		
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]			
Driver/Custodian (Insured):	KOH BOON KENG, MALCOLM (39 / Male), NRIC: S7922894Z, Tel: +6594896024 Email: NOEMAIL			
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. Agree on SJE. Assign: IHS (Victor). Contact: Alan @ 9092 7279 / Federick @ 9674 6635.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Team Auto Pro <estimate.tap@gmail.com>
Sent: Friday, 18 October 2019 6:22 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: Finalization: SMF 9248H / DOA: 11/07/2019 (MSIG)

Dear Shiau Chan,

Without Prejudice

Thank You for assisting to nego for the subject vehicle.

We are pleased to confirm our acceptance to your proposed COR @ **\$2900 .00 / 04 Repair Days**.

Kindly advise OIC and reference number (if any) for our submission of LOD.

On Fri, 18 Oct 2019 at 10:48, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Adel,

WITHOUT PREJUDICE

Re-offer Lump Sum 2,900.00 before GST and 4 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TeamAuto Pro <teamautooffice@gmail.com>
Sent: Wednesday, 16 October 2019 6:02 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: TAP FINALIZE <estimate.tap@gmail.com>
Subject: Re: Finalization: SMF 9248H / DOA: 11/07/2019 (MSIG)

Dear Shiau Chan,

Refer to our earlier tele-discussion, we are not able to accept \$2700.

For the sake of a swift finalization, we are prepared to further compromise from the calculated amount of \$3410 to \$3000.

Pls consider COR at \$3000 / 4 working days.

Thank you and we await soonest your favorable reply.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Adel

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

On Wed, Oct 16, 2019 at 4:50 PM Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Adel,

WITHOUT PREJUDICE

Offer Lump Sum 2,700.00 before GST and 4 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TeamAuto Pro <teamautooffice@gmail.com>

Sent: Tuesday, 15 October 2019 11:16 AM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: Re: Finalization: SMF 9248H / DOA: 11/07/2019 (MSIG)

Part 2 of dismantled photos

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Adel

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

On Tue, Oct 15, 2019 at 11:14 AM TeamAuto Pro <teamautooffice@gmail.com> wrote:

Dear Shiau Chan,

Refer to our earlier tele-conversation, kindly see attached question marks photos fyn.

Do let me know if there is anything else required to soonest finalised COR of this claim.

Thank you.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Adel

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

----- Forwarded message -----

From: **TeamAutoPro North** <teamautopl@gmail.com>

Date: Thu, Aug 22, 2019 at 3:25 PM

Subject: Re: KINDLY ADVISE THE STATUS OF SMF 9248H (DOA: 11/07/2019)

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>, TeamAuto Pro <teamautooffice@gmail.com>

Dear Adel,

Below for your information.

Thank you.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Peach

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

160 Sin Ming Dr
#01-14 Sin Ming AutoCity
Singapore 575722

On Thu, Aug 22, 2019 at 1:11 PM Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Sir/Madam,

Kindly advise the status of SMF 9248H (MSIG-TP).

If done of repair, kindly send us the before or after paint photos and final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Eric Lee

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
Date : _____ Claim No : _____


Insured Vehicle No : 5JB8966G Date of Accident : 11-07-19
TP Vehicle No : SMF 9248H Place of Survey : Team Autopro
Make & Model : Mazda 3 Date of Survey : 22-07-19

Point of Impact / Damages :

Rear

Recommended Reserve :

Repairer's Estimate : \$ 7168.45
Interim Adjustment : \$ 2644.00
Check Items : \$ 1621.44



Proposed : Part by Part / Lump Sum Repair \$3400/- Excess : \$ -

Estimate Repair Period : 04 days

Pre-accident Market Value (for total loss consideration) : \$ -

COE / PARF to owner : \$ -

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐

OD Claim
Excess : \$ _____
(Authorised / Revert)

☒

TP Claim
(Without Prejudice)

Vehicle No. SME 9248H

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 04

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 22-07-19

Victor - Seng @ sg.msig-asia.com


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Pauline Tham

Date: 23 Jul 2019

Preliminary Advice

Insured Vehicle No	: SJB8966G	Accident Date	: 11/07/2019
TP Vehicle No	: SMF9248H	Assignment Date	: 19/07/2019
Make	: MAZDA 3	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/07/2019		
Inspection At	: TEAM AUTOPRO PTE LTD - SIN MING (HQ) 160 SIN MING DRIVE #01-14 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages Rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,168.45
Revised Amount	:S\$	2,644.00
Check Items (Estimated)	:S\$	1,621.44
Total	:S\$	

Lump Sum Repair	:S\$	3,400.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (x) The vehicle is economical/~~not economical~~ for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	624Z
Vehicle Details	
Vehicle No.:	SMF9248H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT LED EU6
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	P520550279
Chassis No.:	JM6BN22A8K0251116
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,753.00
Original Registration Date:	29 Nov 2018
First Registration Date:	29 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$17,753.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2028
PARF Rebate Amount:	\$13,314.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,000.00
COE Rebate Amount:	\$25,526.00
Total Rebate Amount:	\$38,840.00

The information contained herein is correct as at 16 Oct 2019

OK

> Back to OneMotoring

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. SMF9248H
Make / Model MAZDA / MAZDA3 SEDAN 1.5 AT LED EU6
Vehicle Type : Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1 : With Sun Roof
Vehicle Scheme : Normal
Chassis No. : JM6BN22A8K0251116
Propellant : Petrol
Engine No. : P520550279
Motor No. : -
Engine Capacity : 1496 cc
Power Rating : -
Maximum Power Output : 88.0 kW (118 bhp)

Maximum Laden Weight :

1835 kg

Unladen Weight :

1331 kg

Year Of Manufacture :

2018

Original Registration Date :

29 Nov 2018

Lifespan Expiry Date :

-

COE Category :

A - Car up to 1600cc & 97kW (130bhp)

Quota Premium :

\$28,000.00

COE Expiry Date :

28 Nov 2028

Road Tax Expiry Date :

28 Nov 2019

PARF Eligibility Expiry Date :

28 Nov 2028

Inspection Due Date :

28 Nov 2021

Intended Transfer Date :

16 Oct 2019

CO2 Emission :

131.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

0.049030 (g/km)

HC Emission :

0.023080 (g/km)

NOx Emission :

0.008150 (g/km)

PM Emission :

1.220000 (mg/km)

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (29 Nov 2019 to 28 May 2020)	\$341.00
Road Tax Renewal - 12 months (29 Nov 2019 to 28 Nov 2020)	\$682.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

OK →

Save as PDF

Copy as Text

SJE : _____ Vehicle Nos : **SMF 9248H**
Date of Survey : _____ Model : **Mazda 3**
Date of ReSurvey: _____ After-Paint: _____ Year : _____
Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid X repair	1	\$ 856.70	\$ 856.70
2	Bootlid logo NECC	1	\$ 53.80	\$ 53.80
3	Bootlid emblem 'Mazda' NECC	1	\$ 45.60	\$ 45.60
4	Bootlid emblem '3" NECC	1	\$ 43.10	\$ 43.10
5	Bootlid emblem 'Skyactiv' NECC	1	\$ 55.40	\$ 55.40
6	Bootlid reflector XX ND LH-CRA RH-ND	2	\$ 198.60	\$ 397.20
7	Rear bumper deformed	1	\$ 688.16	\$ 688.16
8	Rear bumper side retainer ? X SJC NEC	2	\$ 63.50	\$ 127.00
9	Rear bumper reinforcement ? DD	1	\$ 212.00	\$ 212.00
10	Rear bumper reflector ? X ND	2	\$ 63.50	\$ 127.00
11	Rear bumper tow cap missing	1	\$ 53.50	\$ 53.50
12	Rear end panel ? X R	1	\$ 314.60	\$ 314.60
13	Rear end panel top garnish ? ✓ CRA	1	\$ 145.00	\$ 145.00
14	Taillamp ? ✓ CRA	2	\$ 352.00	\$ 704.00

Parts Sub Total : \$ 3,823.06
Discount : \$ 764.61
PARTS TOTAL : \$ 3,058.45

check parts prices

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries NU	1	\$ 60.00	\$ 30 60.00
2	Rear bumper clips NU	1	\$ 50.00	\$ 30 50.00
3	Taillamp clips NU	2	\$ 50.00	\$ 50 100.00
4	Bootlid reflector seal X ND	2	\$ 60.00	\$ 40 120.00
5	Taillamp seal NU	2	\$ 50.00	\$ 40 100.00
6	Reverse sensor with module short	2	\$ 200.00	\$ 200 400.00
7	Rear end panel sealant X ND	1	\$ 100.00	\$ 60 100.00
SPECIAL NETT TOTAL :				\$ 930.00

Nos.	LABOUR	S\$
1	R&R wire harness and check function	\$ 50 80.00
2	R&R upholstery	\$ 50 150.00
3	R&R bootlid component	\$ 40 100.00
4	R&R reverse sensor and check function	\$ 50 100.00
5	Panel beat	\$ 600 1,400.00
6	Rust proofing	\$ 50 150.00
7	Spray painting	\$ 600 1,200.00
LABOUR TOTAL :		\$ 3,180.00

*04 days.
22/07/19 @ 10am
Victor - Seng @ sg.msig-asia.com
87747011
w10 prejudice*

PARTS TOTAL : \$ 3,058.45
SPECIAL NETT TOTAL : \$ 930.00
LABOUR TOTAL : \$ 3,180.00
GRAND TOTAL : \$ 7,168.45

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jul 2019		14 Aug 2019 16:51 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH BOON KENG, MALCOLM, ID: S7922894Z, Tel: +6594896024, Email: NOEMAIL								
Main Claimant:	ALAGAPPAN S/O CHIDAMBARAM, ID: S2196624Z								
Vehicle Reg. No.:	SMF9248H	Date of Loss:	11/07/2019 18:00 - :59 [7 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 599653	Policy/Cover Note No.:	28808188 (Comprehensive) Coverage: 30/09/2018 - 29/09/2019						
Vehicle Reg. No. (Insured):	SJB8966G	Policy No. (Claimant):							
		Excess:							
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	KOH BOON KENG, MALCOLM (39 / Male) , NRIC: S7922894Z, Tel: +6594896024 Email: NOEMAIL								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP, Liab: 100%. Agree on SJE. Assign: IHS (Victor). Contact: Alan @ 9092 7279 / Federick @ 9674 6635.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF9248H (599653)
[SJB8966G]

TP






















ALAGAPPAN S/O CHIDAMBARAM

Jul 11 2019 6:00PM

[KOH BOON KENG, MALCOLM]

Team Autopro Pte Ltd - Sin Ming

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/07/19 11:35	Accident Statement From: SC - Reg. No: SJB8966G, Claimant: KOH BOON KENG, MALCOLM		Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	23/07/19 11:45	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
6	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
7	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
8	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
9	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
10	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
11	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
12	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
13	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
14	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
15	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
16	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
17	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
18	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
19	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
20	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
21	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
22	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
23	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
24	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
25	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
26	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
27	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
28	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
29	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
30	22/07/19 20:10	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
31	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
32	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
33	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
34	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
35	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
36	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
37	22/07/19 20:11	SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	22/07/19 20:11	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
39	22/07/19 20:11	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
40	22/07/19 20:11	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
41	22/07/19 20:11	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
42	22/07/19 20:11	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
43	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
44	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
45	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
46	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
47	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
48	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
49	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
50	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
51	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
52	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
53	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
54	25/07/19 23:00	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/07/19 11:35	TP SMF9248H E-REPORT From: SC - Reg. No: SJB8966G, Claimant: KOH BOON KENG, MALCOLM	 Load PDF	
2	19/07/19 11:35	PRI From: SC - Reg. No: SJB8966G, Claimant: KOH BOON KENG, MALCOLM	 Load PDF	
3	19/07/19 11:56	Agree on SJE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	23/07/19 14:20	Preliminary Loss Advise	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014585/CQD3E2

Date: 22/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28808188

Claimant SMF9248H

Insured Vehicle No : SJB8966G

Vehicle No : SMF9248H

Date of Loss: 11/07/2019

Nature of Claim: TP

Claim No: 599653

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF9248H

Make & Model: MAZDA 3, 1.5 (A)

Engine No: P520550279

Reg. Date: 29/11/2018 (Man. Year: 2018)

Chassis No: JM6BN22A8K0251116

Colour: Blue

Odometer: 53537 km

Engine Capacity: 1496 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,988.45	2,181.73	1,806.72	45.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,440.00	1,740.00	54.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,168.45	3,621.73	3,546.72	49.48
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	7,168.45	2,900.00	4,268.45	59.54

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 22/07/2019 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)

160 SIN MING DRIVE

#01-14 SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2019)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF9248H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Repair	856.70 FL	*- FL
2	1	*BOOTLID LOGO	Necessary	53.80 FL	*53.80 FL
3	1	*BOOTLID EMBLEM MAZDA	Necessary	45.60 FL	*45.60 FL
4	1	*BOOTLID EMBLEM 3	Necessary	43.10 FL	*43.10 FL
5	1	*BOOTLID EMBLEM SKYACTIV	Necessary	55.40 FL	*55.40 FL
6	1	*BOOTLID REFLECTOR	N/S Cracked / O/S No Damaged	397.20 FL	*198.60 FL
7	1	*REAR BUMPER	Deformed	688.16 FL	*688.16 FL
8	2	*REAR BUMPER SIDE RETAINER	Necessary	127.00 FL	*127.00 FL
9	1	*REAR BUMPER REINFORCEMENT	Dented	212.00 FL	*212.00 FL
10	2	*REAR BUMPER REFLECTOR	No Damaged	127.00 FL	*- FL
11	1	*REAR BUMPER TOW CAP	Missing	53.50 FL	*17.00 FL
12	1	*REAR END PANEL	Repair	314.60 FL	*- FL
13	1	*REAR END PANEL TOP GARNISH	Cracked	145.00 FL	*145.00 FL
14	2	*TAILLAMP	Cracked	704.00 FL	*704.00 FL
15	1	*SUNDRIES	Necessary	60.00 FS	*30.00 FS
16	1	*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	2	*TAILLAMP CLIPS	Necessary	100.00 FS	*50.00 FS
18	2	*BOOTLID REFLECTOR SEAL	No Damaged	120.00 FS	*- FS
19	2	*TAILLAMP SEAL	Necessary	100.00 FS	*40.00 FS
20	2	*REVERSE SENSOR WITH MODULE	Shorted	400.00 FS	*200.00 FS
21	1	*REAR END PANEL SEALANT	No Damaged	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,753.06	2,639.66
- List Item Discount on L Items 20.00/20.00% (\$\$)	764.61	457.93
Total Parts (\$\$)	3,988.45	2,181.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R WIRE HARNESS AND CHECK FUNCTION	New	80.00	50.00
2	R&R UPHOLSTERY	New	150.00	50.00
3	R&R BOOTLID COMPONENT	New	100.00	40.00
4	R&R REVERSE SENSOR AND CHECK FUNCTION	New	100.00	50.00
5	PANEL BEAT	New	1,400.00	600.00
6	RUST PROOFING	New	150.00	50.00
7	SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,180.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >